

# GEOTECHNICAL ENGINEERING ASSESSMENT REPORT – PARTS A AND B

# **NEW BILLS STADIUM**

# **ORCHARD PARK, NEW YORK**

Prepared for:

Pegula Sports + Entertainment Buffalo Bills, LLC 79 Perry Street, Suite 400 Buffalo, New York 14203

Prepared by:

McMahon & Mann Consulting Engineeing and Geology, P.C. 2495 Main Street, Suite 432 Buffalo, New York

> File: 22-011 JULY 2022



### McMahon & Mann Consulting Engineering and Geology, P.C.



Donald R. McMahon, P.E., F. ASCE Michael J. Mann, P.E. Kenneth L. Fishman, Ph.D., P.E. Shawn W. Logan, P.E. Andrew J. Nichols, P.E. Todd Swackhamer, P.E. James J. Janora, P.G. Susanne J.M. George, P.E. Andrew J. Klettke, P.E. Kaitlyn M. Murray, P.E.

July 26, 2022 File: 22-011 Sent via E-mail

Mr. Ron Raccuia c/o Dave Hatheway, Legends Project Development Pegula Sports + Entertainment Buffalo Bills, LLC 79 Perry Street, Suite 400 Buffalo, New York 14203

RE: Geotechnical Engineering Assessment Report – Parts A and B, New Bills Stadium, Orchard Park, New York

Dear Mr. Raccuia:

McMahon & Mann Consulting Engineering and Geology, P.C. (McMahon & Mann) has prepared this report to Pegula Sports + Entertainment (PS+E) describing our findings from the subsurface explorations and field and laboratory testing programs and our geotechnical design and construction considerations for the proposed stadium in Orchard Park, New York.

We appreciate the opportunity to work on this project and are available to discuss this information or to answer questions.

Sincerely yours,

McMAHON & MANN CONSULTING ENGINEERING AND GEOLOGY, P.C.

Jon K. Whiting, E.I.T.

Todd Swackhamer, P.E.

Enclosure

GEOTECHNICAL ENGINEERING ASSESSMENT REPORT PART A

# **CONTENTS**

1.0	INTRODUCTION	1	
2.0	INFORMATION REVIEWED	2	
3.0	SITE CONDITIONS	3	
3.1	GENERAL SITE CONDITIONS AND TOPOGRAPHY		
3.2	HIGHMARK STADIUM		
4.0	SUMMARY OF SUBSURFACE CONDITIONS	5	
4.1	GEOLOGIC SETTING	5 5 6 6	
4.2	SITE SPECIFIC INFORMATION.4.2.1Soil and Rock Descriptions4.2.2Groundwater Conditions4.2.3Subsurface Geometry	7 8 8 9	
5.0	ENGINEERING IMPLICATIONS	9	
5.1	EXCAVATION CONSIDERATIONS	0	
5.2	GROUNDWATER CONSIDERATIONS1	0	
5.3	FOUNDATION TYPES1	1	
5.4	RETAINING STRUCTURES1	2	
6.0	CONCLUSION1	2	
7.0	NEXT STEPS1	2	

# LIST OF FIGURES

- Figure 1:Site Location MapFigure 2:Site PlanFigure 3:East-West SectionFigure 4:Boring Location Plan



## PRELIMINARY GEOTECHNICAL ENGINEERING ASSESSMENT REPORT NEW BILLS STADIUM ORCHARD PARK, NEW YORK

### 1.0 INTRODUCTION

The Buffalo Bills, LLC (Team) is planning on building a new stadium to replace Highmark Stadium in Orchard Park (refer to Figure 1 for a site location map). The Team has engaged Legends Project Development (LPD) to coordinate the planning, design, and construction of the facility. To date, the design team consists of Populous as the stadium architect, Walter P. Moore (WPM) as the structural engineer, and McMahon & Mann Consulting Engineering and Geology, P.C. (McMahon & Mann) as the geotechnical engineer.

The new stadium will be located on the west side of Abbott Road, across from Highmark Stadium. The playing field will be roughly oriented in a north-south direction, parallel to Abbott Road. The site is currently occupied by event parking lots and athletic fields on the campus of Erie Community College – South Campus (ECC). We understand that the ground surface slopes down approximately 14 feet from north to south in the area of the proposed new stadium.

Based on conversations with the design team, we understand that, conceptually, the new stadium will be an open-air, approximately 1.35 million square-foot structure that will seat approximately 60,000 people. A few options are being considered for the stadium's configuration. The first option is a stadium with its playing field depressed below the existing grade. This stadium configuration will consist of at least five levels, with possibly a sixth level around only a portion of the stadium. The main concourse will be at roughly the existing grade at either the second or third level. As such, we understand that the playing field will be approximately 20 feet below existing grade at the south end of the new stadium and 35 feet below grade at the north end [at about elevation (EI.) 735] due to the differences in the ground surface elevation at the site.

Another option is to have the playing field near the existing grade at about El. 755. Although this option has not been developed to the extent as the first, the idea is that this option will require significantly less excavation and dewatering.

The project will also consist of an auxiliary building to provide event staging and storage to support stadium operations. This building will be a single-story, 75,000 square-foot (minimum), rectangular building to be located south of the new stadium. LPD indicated that a second story might be added to this structure during the program or design phase that could bring its size to up to 150,000 square feet.

LPD has requested that McMahon & Mann collect available information about the site and existing stadium and summarize our assessment of the site to understand how the ground conditions will impact the design, construction, and performance of the new stadium. This is referred to as "Part A" of the geotechnical portion of the project.



To accomplish this, McMahon & Mann completed the following:

- 1. Reviewed its project records for subsurface data collected at Highmark Stadium and the surrounding area,
- 2. Visited Highmark Stadium to meet with stadium operations personnel to discuss the existing stadium, collect available subsurface data and historical information, and observe site and stadium conditions,
- 3. Considered the anticipated conditions at the proposed new stadium site and the implications for design and construction of the new structures, and
- 4. Prepared this report summarizing the information collected and our opinion on its implications for design and construction of the new stadium.

The next part of the project (Part B) will include geotechnical explorations of the proposed site, laboratory and field testing, analyses, and recommendations for conceptual design of the stadium, auxiliary building, and support structures.

# 2.0 INFORMATION REVIEWED

McMahon & Mann reviewed the following information in preparation of this report:

- Historical photographs of stadium construction, from 1972 and 1973, provided by Team personnel,
- Excerpts from the original stadium plans, including subsurface boring logs and plans depicting a portion of the proposed stadium site,
- Bid Package No. 3 Foundation Work (Contract C-301) Practice Fieldhouse at Rich Stadium, February 1995,
- "Proposed Practice Building Rich Stadium Geotechnical Analysis and Foundation Report" Glynn Geotechnical Engineering, January 1995,
- "Geotechnical Engineering Report Erie County Stadium Lease Improvements" McMahon & Mann Consulting Engineers, P.C., May 1998,
- "Geotechnical Engineering Report Erie County Stadium Lease Improvements Projects New Training Facility / Operations Facility" McMahon & Mann Consulting Engineers, P.C., August 1998,
- "Geotechnical Evaluation Report for Proposed Operations Building" Empire Geo-Services, Inc., May 2013,
- "Geotechnical Evaluation Report for Proposed Commissary Building" Empire Geo-Services, Inc., May 2013,
- "Geotechnical Evaluation Report for Proposed Team Store" Empire Geo-Services, Inc., May 2013,
- "Geotechnical Evaluation Report for Proposed Entry Gates" Empire Geo-Services, Inc., May 2013,
- "Geotechnical Evaluation Report for Proposed Training Facility Additions" Empire Geo-Services, Inc., June 2013,
- "Geotechnical Evaluation Report for Proposed Video Boards" Empire Geo-Services, Inc., June 2013,



- "Geotechnical Evaluation Report for Proposed Monumental Stairs" Empire Geo-Services, Inc., March 2014, and
- Geotechnical Engineering Report New Era Field Training Facility Addition" McMahon & Mann Consulting Engineering and Geology, P.C., July 2018.

### 3.0 SITE CONDITIONS

### 3.1 GENERAL SITE CONDITIONS AND TOPOGRAPHY

The existing stadium and supporting structures are located on the east side of Abbott Road between Southwestern Boulevard (US Route 20) and Big Tree Road (US Route 20A). The proposed new stadium will be located across Abbott Road, directly to the west of Highmark Stadium. Erie Community College's South Campus (ECC) borders the west side of the proposed stadium site. Refer to Figure 2 for a site plan showing the Highmark Stadium site, the proposed site, and the surrounding area.

Excluding the stadium and support structures, the ground surface at the Highmark Stadium site (east of Abbott Road) is generally covered with paved parking lots. Various landscaped or grass covered areas are present but take up a small proportion of the site. A valley containing Smoke Creek, which flows from south to north, borders the east side of the site.

The proposed stadium site is mostly covered by paved parking lots with the western side covered by athletic fields. A bath house for overnight parking is located near the south end of the site.

The ground surface slopes away from Abbott Road to the east and west. On the east side of Abbott Road, it generally slopes down from between El. 760 to 770 (at Abbott Road) to the top of the Smoke Creek valley (on the east side of the stadium) at about El. 750, and then down the steep valley sides to about El. 710 at the creek.

On the west side of Abbott Road, the ground surface slopes from its highest at about El. 760 to 770 to about El. 750 on the west side of the proposed site. The ground continues to slope downward to the west to about El. 720 on the west side of the ECC campus. The proposed site also slopes from north to south within the footprint of the new stadium, from a reported El. 772 to El. 758. Surface water at this location is collected in drop inlets.

### 3.2 HIGHMARK STADIUM

Highmark Stadium (originally Rich Stadium) was constructed in the early 1970's. It is partially buried below the surrounding ground surface, with the playing field at around El. 720. Construction photographs show that most of the excavation was in rock. Most of the stadium, including the 100 level and footings for heavier structures (upper deck, restroom towers, light towers, field house) are generally supported directly on the rock. Lighter structures (stairways, foundations for the Team Store and administrative buildings) are typically supported on native soil or fill. In speaking with stadium operations personnel, they reported that they knew of no major settlement issues with the existing structure.





Aerial view of Highmark Stadium (originally Rich Stadium) during construction in 1972. This view is looking from north to south. The proposed site is in the fields on the right side of Abbott Road (vertically bisecting the photograph). Southwestern Boulevard is in the foreground and Smoke Creek can be seen on the left side of the photograph.

The below-grade portion of the stadium bowl is drained by gravity through pipes leading to Smoke Creek. Team personnel indicated that flow from the drainage system continues year-round, even during seasonally dry seasons. However, they also indicated that this system has seemed to be sufficient to keep the stadium and playing surface drained.

Team personnel reported that they have frequently seen a silty discharge coming from various below-grade drainpipes around the site, including the tunnel area on the southeast end of the stadium, where it was creating voids behind the tunnel concrete. Rehabilitation of the tunnel to fill the void areas and limit further erosion, by placing screens over the drain pipe outlets, occurred several years ago and appeared to be effective.



## 4.0 SUMMARY OF SUBSURFACE CONDITIONS

### 4.1 GEOLOGIC SETTING

Understanding the geological history of the area surrounding the proposed new stadium is important at this stage of the project as it informs us as to what we expect to find during the subsurface exploration program. Further, the elements described below need to be considered to ensure the efficient and successful design and construction of the new stadium.

This section begins with a discussion about the formation of the rock found beneath the site, provides a brief narrative of the relevant tectonic history that stressed and strained the rock, and describes the surface processes that placed soil over top of the rock.

### 4.1.1 Bedrock Geology

The ground beneath the proposed stadium has a mantle of glacial till soil resting on top of Devonian-age sedimentary rock. The rock types vary with depth and lateral extent, but shale is the most predominant rock type. The shale is made of thin beds, commonly less than an inch thick, that are stacked together into units ranging up to 15 feet thick. Occasional layers of harder limestone are encountered between shale beds, typically occurring in single beds ranging from 4 to 18 inches thick.



Thin-bedded and jointed shale exposed in a mechanical room at the existing stadium, approximately 1,000 feet east of the proposed stadium. Similar rock mass conditions are expected at the proposed stadium location.



The shale in the area is derived from clay or silt that were subjected to pressure from being buried beneath subsequent sediments. The burial pressure converted the clay or silt into shale. This process leaves the shale in a "fissile" state, meaning that the shale can be broken along existing planes with relative ease. The limestones in the area were cemented by calcium carbonate and they are harder to break compared to the shale. Both the shale and limestone are horizontally bedded.

During a site visit, we were able to observe an exposure of the shale rock in a mechanical room on the western side of the stadium. The photograph above shows the thin-bedded nature of the shale rock below the weathered zone.

### 4.1.2 Tectonic History

Western New York is several hundred miles inland from the passive continental margin of the east coast of North America. The tectonic forces that built the Appalachian Mountains also uplifted the rock of Western New York into an elevated plateau but left the horizontally bedded sedimentary rock relatively undeformed compared to the folded-rock belt regions to the southeast in Pennsylvania.

Past tectonic forces caused the beds to tilt slightly downward toward the south at an average of 30 feet per mile. The same tectonic forces broke the rock into systematic patterns of joints. The joint patterns correlate to the direction of the tectonic forces, which at the proposed stadium site caused one prominent joint set approximately east-west and another prominent set approximately north-south. Intersecting joints effectively reduce the effort required to excavate the rock.

### 4.1.3 Regional Seismicity

Western New York experienced a series of continental-scale glacial oscillations (i.e., north-to-south advances and then retreats). As thick ice advanced into the area, the earth's crust subsided from the massive weight. The glaciers deposited a mantle of soil over top of the Devonian shales and limestones (i.e., the glacial till). The most recent glaciers melted and retreated from the area at least 12,000 years ago.

Seismic activity in the area is often attributable to the surface of the earth rebounding since the glaciers retreated and the load was removed. Seismic events in this region, though minor, are concentrated on the Niagara Peninsula and within the Clarendon-Linden seismic zone as shown in the map below. The stadium is several miles away from these areas.

The stadium personnel recalled three notable seismic events over the last few decades. They indicated that they know of no damage caused by these events.

In our opinion, the seismic setting of the site needs to be considered but will not likely drive the overall design of the stadium. Anecdotally, only minor, if any, damage to local structures has been attributed to seismic activity.





Western New York map showing the Clarendon-Linden seismic zone (excerpted from the New York State Department of Transportation Geotechnical Design Manual).

### 4.2 SITE SPECIFIC INFORMATION

A review of the available boring information shows that the subsurface conditions observed at the stadium are consistent with our understanding of the geologic setting. Generally, the stadium site is underlain by varying amounts of fill soil over glacial till. The glacial till is underlain by shale bedrock. The shale can be generalized as being "weathered" or "competent", with the softer, more fractured weathered shale directly below the till and the harder, competent shale below the weathered zone. The transition between weathered and competent shale is often gradual and can be difficult to distinguish.



## 4.2.1 Soil and Rock Descriptions

Fill soils, primarily consisting of sand, silt, and shale stone fragments, were observed in all of the borings across the site. The depth of the fill varies from typically just a few feet (2 to 4 feet) under parking lots to upwards of 40 feet in some locations close to Highmark Stadium, where fill was placed to level the site (particularly closer to the Smoke Creek Valley) during construction to accommodate the stadium.

The glacial deposits observed in the borings consist primarily of sandy silt or silty sand with varying amounts of gravel and shale stone fragments. Observations of this layer, and similar formations in this region, generally indicate that these are dense to very dense soil deposits.

The weathered shale rock was observed below the native glacial deposits in nearly all borings. This layer is distinguished by generally being easy to auger through and sample using split-spoon samplers, which are typically used to sample soil. The rock crumbles easily during sampling. Based on the sampling efforts and observations recorded, the weathered shale has properties close to hard/very dense soil. According to the boring logs reviewed, the weathered shale ranged in thickness from non-existent to about 12 feet, but is typically 4 to 6 feet thick.

Horizontally bedded "competent" shale rock underlies the weathered shale zone. This is distinguished as causing refusal to advancing augers and requiring rock coring to collect samples. It is much harder than the weathered zone and samples are generally collected intact.

The quality of the competent shale appears to increase with depth. Unconfined compressive strength values obtained from laboratory testing of rock core samples from the data reviewed ranged from 3,880 pounds per square inch (psi) to 17,740 psi, with most values falling between 4,000 and 9,000 psi, indicating very hard rock<sup>1</sup>. The rock specimens with higher unconfined compressive strengths are likely limestone inclusions.

### 4.2.2 Groundwater Conditions

We understand that groundwater in the area of the existing stadium generally flows either to the stadium drainage system or directly to Smoke Creek, with flow primarily occurring through the relatively permeable weathered rock layer or through the joints in the more competent rock. Measurements of two groundwater monitoring wells that were installed in 2014 (since decommissioned) show that groundwater is in, or within a few feet of, the weathered rock layer near the existing stadium, approximately between EL. 740 and El. 750.

<sup>&</sup>lt;sup>1</sup> "Geological Factors Significant in the Assessment of Rippability", J.M. Weaver, Civil Engineer in South Africa, December 1975



The measurements also show that groundwater is influenced by the presence of the Smoke Creek valley. We expect that water flows downward toward the valley and creek. This was confirmed by the lower levels measured in the monitoring well closer to the creek.

Measurements made during drilling, which are less reliable but still valuable when considered in aggregate for identifying groundwater trends, support the observations from the groundwater monitoring wells. These measurements show that water levels dropped in borings made closer to the stadium, indicating that the stadium drainage system acts as a sink and locally depresses the groundwater levels.

A 48-inch diameter culvert, with an invert approximately 8 feet below grade and oriented east to west along Bills Drive, reportedly flows year-round, indicating relatively shallow groundwater levels.

We estimate that the groundwater table will roughly coincide with the weathered rock layer at the proposed stadium site, likely a few feet deep. This is consistent with observations made by stadium personnel of signs of shallow groundwater (e.g., slow drainage, water flow in shallow drop inlets, etc.) at the proposed site.

### 4.2.3 Subsurface Geometry

Using the information collected from the available borings and topography obtained from Google Earth, we created a subsurface cross section across the site (east to west) from Smoke Creek to the west side of the proposed stadium location (see Figure 3, attached). The boring data is concentrated on the east side of the section, near Highmark Stadium, but shows trends that provide clues as to what we expect to encounter at the proposed stadium.

The most significant trend relates to the surface of the rock from east to west. The borings show that the top of rock is getting deeper toward the east and Smoke Creek. This is expected, as the creek has eroded the rock to form the valley. These also show that the rock surface is trending upward from east to west and that the top of rock could be within a few feet of the existing ground surface at the proposed site. This is consistent with stadium operations personnel's observations of encountering shale rock just a few feet deep during excavation of the foundations for the bath house on the west side of Abbott Road (south of the proposed stadium site).

The data and information provided show that the proposed stadium location is likely underlain by a few feet of fill and glacial till over 4 to 6 feet of weathered shale. We estimate that competent shale will be encountered 10 to 20 feet deep at this location and limestone might be encountered within the shale.

### 5.0 ENGINEERING IMPLICATIONS

Based on the information collected and our understanding of the project, it is our opinion that the most significant subsurface conditions that will affect design, construction, and operation of the new stadium will be the geometry and condition of the rock and the



elevation of groundwater. This section presents our opinion of how this will affect the excavation for the stadium, temporary and permanent dewatering issues, foundations of the existing stadium and support structures, and retaining structures. These will be described with respect to both stadium options currently being considered, the "depressed configuration" with the playing surface around El. 735 and the "at-grade configuration" with the stadium constructed close to existing grade with the playing surface around El. 755.

## 5.1 EXCAVATION CONSIDERATIONS

Excavations will be required for both stadium configurations, but we expect that both will extend into the competent shale at least at some locations. The fill soil, glacial till, and weathered shale will all be relatively easy to excavate with standard equipment.

Though more difficult than the soil and weathered zones, the fissile nature of the competent shale makes the rock easier to excavate than harder rock types. The tightly spaced joint patterns in the rock combine to make excavation less difficult than a more massive (i.e., less jointed) rock. Our experience is that it can be removed using excavators, possible with a hydraulic hammer attachment at some locations, but may also be rippable by a large bulldozer.

We expect that the thinner (generally less than 2 feet deep) beds of limestone will be harder to excavate but can also be removed using an excavator with a hydraulic hammer attachment. Identifying the frequency and depths of these zones will be part of the subsurface exploration program planned for Part B.

If the quality of the shale improves such that it is increasingly difficult to excavate, or that the limestone layers become thicker and harder than expected, portions of these formations can be blasted. Though not ordinarily required for most excavations in shale to the depths expected for either option, blasting is viable in Western New York to fracture harder formations. There are local contractors that are equipped to use this technique. Blasting would add some costs to the excavation, but these are not expected to be prohibitive considering the scale of the project.

### 5.2 GROUNDWATER CONSIDERATIONS

Based on the information available, we estimate that groundwater could be within a few feet of the existing ground surface at the proposed stadium site. As described above, groundwater has been observed to be near the top of the weathered shale at the Highmark Stadium site. At the new facility, we expect groundwater to flow into the stadium excavation through the weathered shale and along the horizontal bedding planes and along the joint patterns of the competent rock.

In our estimation, both temporary and permanent dewatering systems will be required to some extent with both configurations. However, it will be more substantial for the "depressed configuration" where the excavation will be about 20 feet deeper.



Dewatering should begin before excavations are advanced below the weathered shale. Although data on the permeability of the formations below the site aren't available, it's plausible that groundwater will be entering the stadium excavation faster than it can easily and cost effectively be pumped, especially as the excavation becomes deeper. However, since the elevation of both configurations set the playing field subgrade above the level of Smoke Creek, we recommend draining the site by gravity.

Gravity draining will require coordination and planning but can be used for the temporary and permanent cases for both configurations. Drainage pipes should be installed in advance of the stadium excavation. The pipes need to extend from the stadium subgrade, below Abbott Road, to the creek. These will need to be placed in a trench, most of which will be excavated in rock.

Alternatively, the pipes might be able to be installed with directional/horizontal drilling techniques. If the pipes will need to be larger than a few feet in diameter, directional/horizontal drilling might not be a viable option.

More information is required to characterize the permeability of the rock and groundwater levels. Data for this will be collected for Part B. This will help us better estimate the dewatering efforts that will be required.

Shallower excavations, such as those for support structures or for shallow footings might be able to be temporarily dewatered by pumping.

## 5.3 FOUNDATION TYPES

We estimate that the new stadium, the auxiliary building, and other support structures can be supported by spread footings bearing on either glacial till, weathered shale, or competent rock. Most of the stadium foundations for the "depressed configuration" will likely be deep enough to bear directly on competent rock. The bearing materials for the "at-grade configuration" will depend on the foundation loading, depth of the structure, and geometry of the subsurface conditions.

The allowable bearing capacities will depend on the bearing material, the geometry of the footing, and the bearing elevation. A review of reports prepared for the Highmark Stadium site indicate that footings bearing on the till or weathered rock should be designed for a net allowable bearing pressure of 6,000 to 8,000 pounds per square foot. We anticipate that footings bearing on competent rock will be greater than that value.

Shallow spread footings will provide little, if any, resistance to uplift forces. This resistance might be required for lighter structures such as the auxiliary building, light posts, or other support structures. Drilled piers, or caissons, socketed into competent rock could be used to provide uplift resistance, if necessary.



## 5.4 RETAINING STRUCTURES

Permanent retaining structures might be required, particularly if the "depressed configuration" is selected. Retaining walls that can't economically be cantilevered, or supported internally with floor slabs acting as struts, should be tied back. Tie backs should be anchored into competent rock.

The "at-grade configuration" should have shorter retaining structures, most of which could be designed as cantilevered or gravity walls.

All retaining walls should be designed to collect groundwater and direct it to the permanent dewatering system.

### 6.0 CONCLUSION

Based on the data and information available to review, it is our opinion that both stadium configurations, the "depressed" and "at-grade", are feasible from a geotechnical standpoint. Excavation efforts and quantities and dewatering efforts will be greater with the "depressed configuration", but we do not expect that this effort will be prohibitive. Conditions will be similar to those encountered at Highmark Stadium, which was constructed successfully in the 1970's. A benefit of the "depressed configuration" is that it will provide opportunities to support the stadium structure on more competent rock with little, if any, additional excavation.

### 7.0 NEXT STEPS

The next phase of this project (Part B) begins with a subsurface exploration and laboratory testing program. These programs will include drilling about 33 bore holes, collecting soil and rock samples, installing groundwater monitoring wells, and laboratory testing selected soil and rock samples.

We've prepared a proposed boring location plan for the Part B explorations (refer to Figure 4). These are based on the most current stadium and auxiliary building layout. Generally, borings are spaced on a 200-foot grid within the limits of the stadium. We also propose 8 borings within the auxiliary building.

Information from ECC's South Campus could be valuable to understand the subsurface conditions and potential geotechnical issues encountered. We will request access to boring logs for work completed on the campus. We will also request to meet with maintenance personnel to discuss potential geotechnical issues.

Observations and data collected during these programs will provide information required to estimate engineering properties of the soil and rock formations and to develop recommendations for design of the new stadium, auxiliary building, and other support structures.



Specifically, we intend to collect data to estimate:

- The effort required for rock excavation,
- The permeability of each soil and rock zone encountered for dewatering planning,
- Allowable bearing pressures for each soil and rock zone encountered,
- Lateral pressures to be applied by soil and rock,
- Rock capacity for anchor design,
- Uplift capacities for foundations embedded in rock, and
- Other engineering properties required for design of the new stadium facility.

We will prepare a design report summarizing the data collected and providing recommendations for the conceptual design of the stadium. As described in our proposal, once the conceptual design is completed and the locations and depths of the structures' foundations are known, additional explorations and testing will be needed for design.



Figures



FIGURE 1





830							
820		PROPOSED					
810				<b>}</b>			
800							
790							
780							
770						HIGHM	ARK STAL
760							
750				$\int$			 
740						/	
730						,	
720							
710							
700							
690							
680	500 1000	1500 2000	2500	3000	3500	4000	5000
	ST - WEST PROFILE		7				
		LEGEND EXISTING GROUND SURFACE WATER TABLE TOP OF WEATHERED ROCK TOP OF COMPETENT ROCK					
		NOTES:					

- 1. Approximate Existing Ground Surface Profile obtained from Google Earth.
- 2. Water table elevation, top of weathered rock elevation, and top of competent rock elevation estimated from a review of previously-collected subsurface information.

NOTE: UNAUTHORIZED ALTERATION OR ADDITION TO ANY SURVEY, DRAWING, DESIGN, SPECIFICATION, PLAN, OR REPORT IS A VIOLATION OF SECTION 7209 PROVISION 2 OF THE NEW YORK STATE EDUCATION LAW.



**BUFFALO BILLS STADIUM** 

ERIE COUNTY

(716) 834-8932 www.mmce.net



# EAST-WEST SECTION

NEW YORK

DWG. NO. 22011-003

FIGURE 3



400



SCALE: 1" = 400'

NOTE: UNAUTHORIZED ALTERATION OR ADDITION TO ANY SURVEY, DRAWING, DESIGN, SPECIFICATION, PLAN, OR REPORT IS A VIOLATION OF SECTION 7209 PROVISION 2 OF THE NEW YORK STATE EDUCATION LAW.



**BUFFALO BILLS STADIUM** ERIE COUNTY

# LEGEND

PROPOSED BORE HOLE LOCATION PROPOSED GROUNDWATER MONITORING WELL LOCATION PROPOSED GEOTHERMAL TEST BORE HOLE LOCATION PROPOSED STADIUM SITE LIMIT

#### NOTES:

•

- 1. Base map image acquired at Google Earth. Photo date September 22, 2018.
- 2. Proposed structural layout and stadium site limit based on drawing titled, "Property Ownership Diagram Bills Campus", provided by Legends Project Development, dated March 8, 2022.
- Bore hole and groundwater monitoring well designations will be based on their respective locations on the grid shown.

# SMOKE CREEK

NEW YORK

# **PROPOSED BORING** LOCATION PLAN

DWG. NO. 22011-002

FIGURE 4

GEOTECHNICAL ENGINEERING ASSESSMENT REPORT PART B

# **CONTENTS**

1.0	INTRODUCTION	1				
1.1	BACKGROUND AND REPORT FORMAT 1					
1.2	NOTES ON THE REPORT					
2.0	SUBSURFACE EXPLORATIONS AND FIELD AND LABORATORY TESTING 2					
2.1	SUBSURFACE EXPLORATION PROGRAM					
2.2	FIELD TESTING					
2.3	LABORATORY TESTING					
3.0	SUBSURFACE CONDITIONS	4				
3.1	FILL AND OVERBURDEN	5				
3.2	ROCK   3.2.1 Weathered Rock   3.2.2 Competent Rock	6 6 7				
3.3	GROUNDWATER CONDITIONS	8				
3.4	SEISMIC SITE CLASSIFICATION	9				
4.0	GEOTECHNICAL DESIGN AND CONSTRUCTION RECOMMENDATIONS	9				
4.1	STADIUM STRUCTURE	10 13 16 18 20				
4.2	AUXILIARY BUILDING AND OTHER STRUCTURES. 2   4.2.1 Design Considerations.   4.2.2 Construction Considerations.	21 21 23				
5.0	ENVIRONMENTAL ASSESSMENT FORM	25				
6.0	LIMITATIONS	25				



### LIST OF TABLES

- Table 1: Materials Type and Recommended Excavation Methods
- Maximum Allowable Bearing Grade at Stadium Structure Table 2:
- Table 3: Maximum Allowable Bearing Grade at Auxiliary Building

### LIST OF FIGURES

- Thickness of Fill and Overburden Figure 1:
- Figure 2: Thickness of Weathered Rock
- Figure 3: Thickness of Competent Rock
- Figure 4: Groundwater Contour Map
- Figure 5: **Geological Section**

### LIST OF APPENDICES

- Summary of Subsurface Explorations Appendix A: Appendix B: Summary of Geotechnical Tests and Results
- Appendix C: Material and Placement Requirements
- Appendix D: **Environmental Assessment Form**
- Appendix E: Limitations



### GEOTECHNICAL ENGINEERING REPORT – PART B NEW BILLS STADIUM ORCHARD PARK, NEW YORK

### 1.0 INTRODUCTION

### 1.1 BACKGROUND AND REPORT FORMAT

This is Part B of the Geotechnical Engineering Report for the New Bills Stadium to be constructed in Orchard Park, New York.

Part A of this report was prepared and submitted to the Buffalo Bills, LLC (Team) and Legends Project Development (LPD), the project management consultant for the Team, in March 2022 and is considered, along with Part B and future addenda, the complete geotechnical engineering report for this project.

Part A includes:

- 1. An introduction describing the project as it had been developed by the end of March 2022,
- 2. A list of available background information reviewed to support the preparation of Part A.
- 3. A description of the site conditions for the existing and proposed stadium locations and surrounding area,
- 4. A description of the geologic setting for the new stadium and our understanding of site-specific subsurface conditions based on our background review, and
- 5. Our estimate of the engineering implications of the ground conditions based on our review.

We concluded in the Part A report that the construction of the stadium as planned would be feasible from a geotechnical perspective. In our opinion, the biggest geotechnical challenges will be related to excavation of the rock underlying the site and control of groundwater during construction and through the lifetime of the stadium.

Since the completion of Part A, we have completed the following tasks:

- 1. Worked with the project architect (Populous), structural engineer (Walter P. Moore [WPM]), the Team, and LPD to develop a subsurface exploration program to characterize the subsurface conditions across the proposed site,
- 2. Worked with Foit-Albert Associates (Foit-Albert), the project surveyor, to locate and mark proposed boring and monitoring well locations,
- 3. Engaged Ground Penetrating Radar Systems, LLC (GPRS) to clear proposed boring and test pit locations of underground utilities,
- 4. Engaged Earth Dimensions, Inc. (EDI) to complete 38 borings with rock cores and install 19 monitoring wells (described in Section 2.1),
- 5. Monitored the drilling on a part-time basis,



- 6. Sent selected soil and rock core samples to 3<sup>rd</sup> Rock, LLC (3<sup>rd</sup> Rock) for laboratory testing (described in Section 2.3),
- 7. Observed the excavation of test pits at two locations within the project limits (described in Section 2.2),
- 8. Completed rising and falling head permeability (i.e., slug) testing at the wells (described in Section 2.2), and
- 9. Prepared this report describing our findings and recommendations for the construction of the new stadium, auxiliary building, and appurtenant structures.

# 1.2 NOTES ON THE REPORT

Refer to Part A for the project background, a description of site conditions, and a description of the geologic setting, including information on local bedrock geology, tectonic history, and regional seismicity. Most of this information is unchanged since Part A was issued in March 2022. Other information, such as the stadium location and depths, site-specific information on the ground conditions, and the engineering implications have evolved since March 2022 as data were collected. Discrepancies of data or recommendations between Parts A and B are always superseded by information presented in Part B (or future addenda) unless specifically stated otherwise.

### 2.0 SUBSURFACE EXPLORATIONS AND FIELD AND LABORATORY TESTING

McMahon & Mann Consulting Engineering and Geology, P.C. (McMahon & Mann) developed and implemented subsurface exploration, field testing, and laboratory testing programs to better characterize the subsurface conditions at the proposed site.

### 2.1 SUBSURFACE EXPLORATION PROGRAM

We engaged EDI to complete 38 borings across the site. Generally, the borings were spaced evenly on a 200 by 200-foot grid (approximately one boring per acre) across and surrounding the proposed stadium footprint, as shown on Figures 1 through 4. Some borings were moved to avoid surface or buried obstructions that were present at several of the grid locations.

The borings were advanced from the ground surface until split-spoon refusal was encountered. Soil and weathered rock samples were retrieved using a split-spoon sampler on a continuous basis (i.e., 2-foot interval). Upon encountering split-spoon refusal, EDI cored the rock. A minimum of approximately 10 feet of rock was cored in most borings, and a maximum of 49.5 feet of rock was cored in one boring. Rock coring was extended below Elevation (EI.) 730 (approximate planned bottom of excavation) in several borings, extending as low as El. 696.5.

Standpipe piezometers (i.e., monitoring wells) were installed at 19 of the boring locations. These were either installed in the bore holes or in separate holes (no sampling) made next to the parent holes.



Monitoring wells consist of a slotted section of 2-inch inside diameter PVC pipe (various lengths) placed at the bottom of the selected bore holes. The annulus between the slotted section of pipe (i.e., the "screened zone") and surrounding rock is backfilled with sand. This allows groundwater in the surrounding formations to enter the well and equalize with the surrounding groundwater level in the formation. A solid PVC riser pipe is attached to the top of the slotted pipe section and extends to the ground surface. Groundwater readings are then made by measuring the distance from the ground surface to the water level in the well.

All of the monitoring wells were either screened in weathered rock or competent rock. Flush-mounted protective casing was installed over each of the monitoring wells.

Two test pits were completed at the site near boring locationsBH-B4-22 and BH-F6-22. One test pit (TP-2-22) was completed towards the north end (BH-B4-22) of the proposed stadium footprint, and the other (TP-1-22) was completed towards the south end (BH-F6-22).

The boring logs and test pit logs and further details on the subsurface exploration program are presented in Appendix A, and summarized in Tables A-1 and A-2, respectively. The boring location plan is included in Appendix A as Figure A-1.

### 2.2 FIELD TESTING

McMahon & Mann developed each of the monitoring wells by removing water from the well using a bailer. This is done to agitate, suspend, and remove fine-grained particles and to check that the wells are operating properly. All wells had the equivalent of at least five times its volume (cross sectional area of the inside of the pipe times the height of water in the well), or more, removed for development.

Following development, we measured the groundwater levels in each well. These measurements provide the piezometric head in the rock formation adjacent to the screen zone.

In addition to groundwater levels, we also performed rising and falling head permeability tests. These tests provide data to estimate the hydraulic conductivity of the rock formations adjacent to each screen zone. The hydraulic conductivity values can be used to estimate dewatering efforts that will be required during and after construction.

The field-testing program is described in detail in Appendix A, and the hydraulic conductivity estimates are summarized in Table A-3.

### 2.3 LABORATORY TESTING

We sent selected soil and rock core samples to 3<sup>rd</sup> Rock for laboratory testing. The results of the laboratory testing program were used to confirm the soil classifications made in the field and for estimating properties of the different soil and rock layers observed.



In summary, 3<sup>rd</sup> Rock performed the following:

### Soil Samples

- 65 samples for moisture content (ASTM D 2216),
- 48 samples for gradation with 30 of these including hydrometer analyses (ASTM D 422), and
- 10 samples for Atterberg limits (ASTM D 4318)

### Rock Core Samples

• 38 samples for unconfined compression (ASTM D 7012)

The laboratory test results are included in Appendix B.

### 3.0 SUBSURFACE CONDITIONS

Generally, the material underlying the site of the proposed stadium consists of road base fill overtop of fine-grained native deposits (i.e., slackwater sediment) and glacial deposits (collectively referred to as "overburden") overtop of bedrock (see Diagram 1). We compiled the subsurface exploration data to estimate the depths at which material transitions occur in each of the 38 borings. The characteristics and depths of the fill, native overburden, and bedrock are described in Sections 3.1 and 3.2, respectively. The groundwater conditions are described in Section 3.3. Refer to the borings and test pit logs in Appendix A for more details.







# 3.1 FILL AND OVERBURDEN

The material immediately underlying the site for the proposed stadium consists of a thin layer of tar and chip parking lot (0.1 to 0.2 feet) and up to approximately 4 feet of road base fill (e.g., crushed concrete, gravelly, sandy silt, etc.) overtop of slackwater sediment and glacial till. The slackwater sediment is generally thinly laminated silty-clay or clayey-silt, while the glacial till has varying proportions of fine (clay and silt) and coarse (sand and gravel) sediments, typically with shale stone fragments mixed into the matrix. Photograph 1 shows the fill and overburden encountered during excavation of TP-1-22.



<u>Photograph 1</u> – TP-1-22 excavated to a depth of approximately 11.3 feet. Road base fill material transitions to native overburden material at approximately 1.6 feet, which transitions to weathered rock at approximately 10.0 feet. Transition from weathered rock to competent rock is at approximately 10.7 feet.



The thickness of the fill and native overburden material is the distance between the ground surface and the top of the weathered rock. The average thickness of the fill and native overburden within the proposed stadium footprint is approximately 8 feet, however it ranges from less than 1 foot to over 12 feet. The overburden is thinnest at the north end of the proposed stadium and generally increases in thickness toward the south, as shown on Figure 1.

Laboratory test results from selected soil samples will be used in the future to estimate the compatibility of selected backfill with different native soil deposits as necessary. The soil testing results are included in Appendix B and summarized in Table B-1.

# 3.2 ROCK

Bedrock, primarily consisting of shale, with occasional pyrite and calcite deposits and limestone nodules (i.e., gravel size pieces), lies below the native overburden. The shale is generally soft<sup>1</sup> and thinly laminated to thinly bedded (i.e., bedding thickness ranges between 0.1 and 4 inches thick). At least two near-vertical joint sets were identified during observations of the test pits and outcrops in Smoke Creek. These joint sets are observed to cause varying degrees of fracturing throughout the observed rock core. Additional joint sets were observed; however, these sets were less predictable in terms of frequency, spacing, and orientation.

The rock can further be described as either "weathered" or "competent," as previously discussed in Report A and shown in Diagram 1. The weathered rock is underlain by competent rock.

### 3.2.1 Weathered Rock

For the purposes of this report, we have defined the weathered rock at the site as the zone of shale encountered between the bottom of the overburden and the top of the competent rock. The weathered rock is typically very soft<sup>2</sup> to soft, fragmented and broken shale with varying degrees of iron staining (an indication of varying groundwater levels). It has typical characteristics of the competent shale below (i.e., cemented sediment aligned in bedding planes), however natural processes (i.e., freeze-thaw cycles, groundwater flow, and chemical dissolution) have weathered the rock into fractured and broken pieces. A representative picture of the weathered rock is shown in Photograph 2.

<sup>&</sup>lt;sup>2</sup> "Very soft" was defined in The New York State Department of Transportation, "Rock Core Evaluation Manual," dated August 2015, as "Can be scratched with fingernail. Slight indentation produced by light blow of point of geologic pick. Requires power tools for excavation."



<sup>&</sup>lt;sup>1</sup> "Soft" was defined by EDI and in The New York State Department of Transportation, "Rock Core Evaluation Manual," dated August 2015, as "Handheld specimen crumbles under firm blows with point of geologic pick." <sup>2</sup> "Very soft" was defined in The New York State Department of Transportation, "Rock Core



<u>Photograph 2</u> –TP-2-22 excavated to a depth of approximately 10.0 feet. Road base fill material transitions to weathered rock at 0.8 feet. Weathered rock continues to a depth of 9.2 feet and transitions to competent rock.

The thickness of the weathered rock within the proposed stadium footprint is on average about 4.5 feet and ranges from less than 1 foot to nearly 14 feet. The zone of the weathered rock is generally the thickest toward the north end of the proposed stadium where the overburden is thinnest. As the overburden thickness increases toward the south, the zone of weathered rock tends to thin out as shown on Figure 2.

### 3.2.2 Competent Rock

The competent rock at the site is defined as the rock underlying the weathered rock. It is typically soft shale, very intensely to slightly fractured horizontally along bedding planes, with high angle to near-vertical fractures throughout. Fracture intensity decreases with depth, therefore the rock quality designation (RQD)<sup>3</sup>, a measure of the frequency of rock fractures, increases with depth. Photograph 3 shows a typical rock core of competent rock along with descriptions of fracture intensity.

<sup>&</sup>lt;sup>3</sup> RQD is defined as the cumulative length of intact pieces 4 inches or longer from a core run divided by the total length of the core run, expressed as a percentage. It is a measure of the quality of the rock.





<u>Photograph 3</u> – Rock core photograph for BH-E4-22 showing the transitions in fracture density for competent rock.

The thickness of competent rock that will require excavation is the difference between the elevation of the top of competent rock and the bottom of the proposed excavation (approximately El. 730). The average thickness of competent rock requiring excavation within the proposed stadium footprint is about 19 feet, however it ranges from about 14.5 to 30 feet as shown on Figure 3.

Unconfined compressive strength (UCS) values ranged from approximately 900 to 6,050 pounds per square inch (psi) and averaged around 2,400 psi. In general, the strength of the rock core samples increased with depth, particularly below El. 730. The UCS test results are included in Appendix B and summarized in Table B-2.

# 3.3 GROUNDWATER CONDITIONS

Groundwater elevations were measured at the site on June 10, 2022 and June 15, 2022. Using these data, we created a groundwater contour map for the site, as shown on Figure 4. The groundwater contours generally follow the topography of the site, with a hydraulic gradient to the south or southwest. For these dates in June, the groundwater within the proposed stadium footprint is on average about 4 feet deep, but ranges between less than 1 foot and over 8 feet deep. Due to the variable nature of groundwater, we expect that these values will fluctuate throughout the year, although the direction of the hydraulic gradient is likely to remain to the south or southwest until the site is developed.

We completed rising and falling head permeability (i.e., slug) tests in the wells in June 2022. Data from these tests are used to estimate the permeability of the formations



adjacent to the well screened zones. Permeability (or hydraulic conductivity) is a property that indicates water's ability to flow through the formation. It can be used to estimate the required dewatering efforts. Data from the tests yielded an average hydraulic conductivity of  $1.5 \times 10^{-3}$  centimeters per second (cm/s), with a range between  $1.1 \times 10^{-4}$  and  $4.2 \times 10^{-3}$  cm/s. A summary table of hydraulic conductivity estimates and groundwater elevations is included in Appendix A in Table A-3.

Groundwater entered both test pits during excavation. Infiltration of groundwater into the southern test pit (TP-1-22) was at a rate such that pumping was not necessary to keep the excavation from filling with water in the time that the test pit was left open (approximately 1-hour). Infiltration in the northern test pit (TP-2-22) was at a rate such that standing water was about 1 foot deep at the bottom of the excavation upon completion. These were slower infiltrations than were qualitatively expected based on the rapid recovery (returning to equilibrium conditions) of the wells during development.

### 3.4 SEISMIC SITE CLASSIFICATION

We evaluated the conditions in BH-I3-22 (boring with thickest overburden material encountered at the site), to estimate the seismic site class following the procedures in the American Society of Civil Engineers (ASCE) 7-16 "Minimum Design Loads and Associated Criteria for Buildings and Other Structures." Based on the Standard Penetration Test (SPT) N-values and conditions observed in the boring, the Site Class is C. Using the Site Class C designation, we recommend the following parameters for design:

Peak ground acceleration (PGA<sub>M</sub>) = 0.114g (adjusted for site class effects) MCE<sub>R</sub> spectral response acceleration for short periods,  $S_S = 0.159g$ MCE<sub>R</sub> spectral response acceleration at 1 second period,  $S_1 = 0.044g$ Short-period site coefficient (Table 11.4-1),  $F_a = 1.3$ Long-period site coefficient (Table 11.4-2),  $F_v = 1.5$ 

The soils encountered during the subsurface exploration program are not susceptible to settlement due to liquefaction.

### 4.0 GEOTECHNICAL DESIGN AND CONSTRUCTION RECOMMENDATIONS

The subsurface conditions at this site are well suited to support the new stadium, auxiliary building, and associated structures. We anticipate that the most significant geotechnical issues facing construction and operation of the stadium will be excavation of the competent shale rock and temporary and permanent dewatering of the stadium.

This section provides further details and recommendations for the design and construction of the new facility.



# 4.1 STADIUM STRUCTURE

We recommend that the new stadium structure be supported by spread footings bearing directly on the competent shale encountered in all the borings.

For the field level to be at El. 735, a significant amount of excavation (up to about 40 feet deep) will be required to accommodate the foundations and drainage system. For the required excavation and operation of the stadium, construction and permanent dewatering plans should be developed based on the groundwater measurements and the conditions presented in this report. Dewatering plans might need to be refined during construction as we observe actual groundwater inflow into the excavations.

This section provides geotechnical design and construction recommendations for the stadium structure.

### 4.1.1 Excavation Considerations

We evaluated the test boring and test pit information along with the laboratory testing results to estimate the level of difficulty of excavation of the overburden, the underlying weathered rock, and the underlying competent rock. We made the following observations throughout the subsurface explorations:

- The SPT N-values<sup>4</sup> typically increased as the material description transitioned to "shale stone fragments," which is the transition to weathered rock. EDI typically was able to advance through the weathered rock with the split spoon sampler.
- EDI typically started coring rock when it encountered one, or more consecutive, split spoon refusals. This is generally where we designated the transition from weathered rock to competent rock.
- Test pits were advanced until it was too difficult to proceed, given the size of the excavator (Kobelco SK210 LC) and the size of the test pit. The depth of completion was approximately at the transition between weathered and competent rock.

### 4.1.1.1 Fill and Overburden Materials

Test pits were completed at two of the borings (BH-B4-22 and BH-F6-22) using a 200series excavator. We observed the excavated materials, relative ease of excavation, and final depth of the excavation. Observations throughout the completion of the test pits indicate that a 200-series excavator is sufficient for excavating the overburden material (i.e., road base fill, slackwater sediment, and glacial till).

<sup>&</sup>lt;sup>4</sup> N-values are an indication of the relative density or consistency of geologic deposits. Higher numbers generally correlate to higher strengths and density.



## 4.1.1.2 Weathered Rock

Observations from the test pits indicate that a 200-series excavator is generally capable of excavating the weathered rock to a depth that approximately corresponds with the transition to competent rock. It should be noted, however, that this excavator was operating near the limit of its boom and in a confined space. It is likely that the same excavator could advance deeper in a more open excavation and with a shorter required reach. Further, it is also likely that the test pits could have been advanced deeper with a larger excavator (i.e., 300-series), rock chipper (jack hammer attachment), or specialized rock ripping equipment.

### 4.1.1.3 Competent Rock

Competent rock was generally not able to be excavated in the test pits using a 200series excavator from the existing grade and within the confined conditions. Therefore, information from the boring logs and rock core testing was used to estimate the rippability of the competent rock.

Rock rippability was estimated using the rock mass characteristic index method<sup>5</sup>. This method considers the following parameters:

- UCS,
- RQD, and
- Joint presence and condition.

Estimation of the prevalence, orientation, and conditions of joints were made based on observations from the test pits, outcrops along Smoke Creek, and rock cores collected during test borings. RQD and UCS are based on laboratory data and observations of the rock core. This information was used along with engineering experience in rock excavations to estimate rock rippability across the footprint of the proposed new stadium.

As discussed in Section 3.0, we reviewed the subsurface exploration and laboratory testing data to estimate the depths at which materials transition from fill and native overburden to weathered rock to competent rock at each of the 38 borings. This information was used to complete color-coded tick maps showing the estimated thickness of each material type as follows:

• Figure 1: Thickness of Fill and Overburden – This figure shows the depth between the existing ground surface and the top of the weathered rock. We expect that this material may be excavated using a 200-series excavator.

<sup>&</sup>lt;sup>5</sup> "Rock Classification Systems for Engineering Purposes," American Society for Testing and Materials (ASTM), dated 1988.


- Figure 2: Thickness of Weathered Rock This figure shows the depth between the top of the weathered rock and the top of the competent rock. We expect that this material may be excavated with a 200- or 300-series excavator.
- Figure 3: Thickness of Competent Rock This figure shows the depth between the top of the competent rock and the proposed bottom of excavation. We expect that this material may require a 300-series excavator and/or a D8/D9 bulldozer with specialty ripping/chipping attachments designed to fracture the rock before excavation. Based on our observations during the subsurface explorations and analyses of the data, we do not expect that blasting will be required for excavation of this material.

Our recommended excavation methods for the types of materials encountered are summarized in Table 1.

Material Type	Description <sup>1</sup>	Excavation Method <sup>2</sup>
	Road base fill, slackwater	
Fill and Overburden	sediment, glacial deposits.	200-series excavator
	N-Values typically less	
	than 35.	
	Shale stone fragments. N-	
Weathered Rock	values typically greater	200- or 300-series excavator
	than 35, or refusal.	
	Shale typically ranging	300-series excavator or D8/D9
	from very intensely to	bulldozer with specialty
Competent Rock	slightly fractured. Typically	ripping/chipping attachments
	retrieved in borings with	designed to fracture rock
	coring apparatus.	before excavation

# TABLE 1 MATERIALS TYPE AND RECOMMENDED EXCAVATION METHODS

Notes:

1. Material description is based on the boring logs and our observations during advancement of the test pits.

2. Equipment size and excavation methods are based on our observations during advancement of the test pits and reference from American Society for Testing and Materials (ASTM), "Rock Classification Systems for Engineering Purposes," 1988.



We also compiled a section (oriented generally north to south across the site) to illustrate the excavation limits, as shown on Figure 5. The section shows the existing ground surface (April 2022 survey), the transition from the overburden to the weathered rock, the transition from the weathered rock to the competent rock, and the estimated bottom of excavation at El. 730. Based on this figure, we expect:

- The greatest volume of overburden excavation will be at the southern end of the proposed stadium.
- The greatest volume of rock excavation (both weathered and competent) will be at the northern end of the proposed stadium.
- Groundwater will be encountered within the upper 10 feet of excavation.

#### 4.1.1.4 Excavation Considerations

We recommend sloping the excavation banks in the overburden and weathered shale for the footings for stability and worker safety. All excavations should be made in accordance with standards set by the Occupational Safety and Health Administration (OSHA). For estimating purposes, excavations should be planned considering the soil as Soil Type C. For Soil Type C, the slopes should be no steeper than 1.5 horizontal to 1 vertical (1.5H:1V).

Excavations in the competent rock can be maintained in a near vertical condition on a temporary basis. Once exposed, the excavation face will degrade over time and may slake. This should be monitored as degrading walls could be a safety risk or could damage completed work.

The toe of the overburden/weathered shale excavation should be offset from the top of the competent shale excavation. We recommend this separation be at least equal to the height of the excavation in competent rock.

The contractor should assign a "competent person" during construction to make the OSHA required field observations and tests. Excavation slopes should be flattened as necessary, based on the results of those observations and tests, to maintain stability of the excavation slopes, and to protect workers.

#### 4.1.2 Dewatering Considerations

Based on the groundwater measurements summarized in Section 3.3 and shown on Figure 4, the excavation for the new stadium will be up to about 30 feet below the groundwater level. Furthermore, the proposed field elevation of El. 735 will be up to about 25 feet below the surrounding groundwater elevation. To accommodate construction and operation of the stadium over its lifespan, the footprint of the stadium will need to be dewatered.



Highmark Stadium is currently dewatered by gravity with drainpipes collecting groundwater and directing it to Smoke Creek to the east. We recommend a similar method for the new stadium. In our opinion, the most feasible way to achieve this is by collecting groundwater in a sump in the northeast corner of the stadium footprint and directing it north of Highmark Stadium to Smoke Creek. All drainage features for the stadium should direct collected groundwater and run-off to this sump.

Drainpipes in the sump should then direct the collected water to the northeast, below Abbott Road and north of Highmark Stadium, to discharge into Smoke Creek, about 2,300 feet to the east. The flood plain of Smoke Creek is at about El. 707 in this area. Considering the alignment and elevation drop of about 23 feet available, the drainpipes from the stadium to the creek could be sloped up to about 1.0 percent.

The quantity and number of drainpipes will need to be determined based on the anticipated flow from groundwater and potential run-off. The contract documents should allow for a provision to adjust the number of drainpipes needed during construction as conditions are evaluated based on the observed groundwater inflow. Initial inflow estimates to size the drainpipes should be based on the groundwater and permeability data collected during the subsurface exploration and monitoring program (refer to Section 3.3.) and the final excavation configuration. McMahon & Mann can assist with a detailed seepage analyses to estimate groundwater inflow once the design is developed.

Most of the alignment of the drainpipes between the stadium and Smoke Creek will be installed in the competent shale. In our opinion, installing the pipes using horizontal directional drilling (HDD) techniques is preferable to a cut and cover method. HDD will be less disruptive at the surface, especially considering the alignment of Abbott Road and parking lots north of Highmark Stadium that will need to be maintained throughout construction.

#### 4.1.2.1 Horizontal Directional Drilling

The HDD process begins with the drilling of a pilot hole along the planned horizontal and vertical alignment. Drilling equipment should be located such that the drainpipe alignment reaches maximum stadium excavation depth (about El. 730) at the planned sump location. We recommend that excavation for the stadium begin at this location and the drainage system be installed as soon as practical. Therefore, as the excavation for the remainder of the stadium proceeds, the permanent dewatering system can be utilized to control groundwater throughout construction.

The pilot drill hole is initiated from the starting location and advanced along the planned alignment, through the sump, and to the planned exit location. The pilot drill bit has a geometry that is biased in one direction. While the pilot drill stem is rotated and pushed into the ground, it travels in a generally straight direction. The horizontal and vertical locations of the drill bit are monitored from the surface using remote sensing techniques. The drill stem is pushed but not rotated when the direction of the drill bit needs to be adjusted. This process is continued until the pilot drill bit exits the ground at the outlet. At



this point, the bore diameter will then be increased using a reamer. This process is repeated until the hole diameter is sufficient for installation of the drainpipe.

We recommend that the alignment be made through the competent rock along its entire length until overburden is encountered at the exit location. Passing through different strata (e.g., from rock to soil and back) is problematic to maintain the desired vertical alignment and can create bellies in the pipe. Additional borings along the planned alignment might be required to further characterize the ground conditions along the planned HDD alignment.

#### 4.1.2.2 Temporary Dewatering

The advantage to draining the stadium by gravity using HDD techniques is that, if installed early in construction, this system can also be used for dewatering as the excavation proceeds.

To accommodate this, the earliest excavations should be for the sump. Sump excavation will need to be pumped until the drains are installed. Once completed, however, the excavation can proceed to the south and west with the subgrade sloping toward the drainpipes or perimeter drainage trenches.

#### 4.1.2.3 Other Dewatering Options

Our recommendation is to both temporarily and permanently dewater the stadium as described in the previous sections. While, in our opinion, gravity draining is the most reliable and cost-effective method over the lifespan of the stadium, other dewatering options are available.

#### 4.1.2.3.1 Sumps and Pumps

One option discussed early in the process is to collect the groundwater in underground holding tanks and using riser pumps to direct it to shallower drainpipes that would be installed in the overburden and that would drain towards Smoke Creek. The alignment of the new drainpipes would likely have to be through the existing campus, along Bills Drive, between Highmark Stadium and the training facility, and to the creek.

While this eliminates the need for HDD and might accommodate steeper grades for the drainpipes, we do not recommend this option. This will require primary and redundant pumps to be maintained online and operating throughout the life of the stadium. Operation and maintenance of these will have a significant cost.

This plan will also be more disruptive at the surface during construction as it will require excavations along the planned alignment to Smoke Creek, much of which will be through the Teams' current campus.



### 4.1.2.3.2 Connecting to the Highmark Stadium System

Highmark Stadium's dewatering system appears to still be effective. There have been discussions of connecting the new stadium's system to Highmark's. This could be feasible, but more details on the operation and condition of the system are required to decide if this is feasible for the long-term.

The capacity, condition, alignment, and consideration of it supporting both stadiums throughout construction need to be explored. The connection would also require disturbance at Highmark Stadium and either cut and cover or HDD installation across Abbott Road. Furthermore, to utilize this system during construction, it would all have to be installed early to limit pumping.

Finally, we understand that Highmark Stadium will be demolished once the new stadium is completed. If the drainage system is utilized, special provisions will be needed to protect the system and allow access for maintenance throughout its service life.

#### 4.1.3 Foundations

#### 4.1.3.1 Bearing Grades and Capacities

The bearing grade for the spread footings should be competent shale bedrock, free of loose rock particles and debris.

For the stadium, we recommend that spread footings bear at least 2 feet below the top of the competent shale. The elevation of this zone varies across the proposed stadium footprint. The maximum recommended bearing grades at borings located within or adjacent to the stadium footprint are listed in Table 2.

Even within the competent rock, however, the net allowable bearing pressure varies with elevation, increasing with depth as the rock quality and strength generally increases. Footings supported on competent rock above El. 730 should be designed with a maximum allowable pressure of 11,000 pounds per square foot (psf). Below El. 730, the footings can be designed with a maximum allowable pressure of 15,000 psf.



Boring Designation	Maximum Allowable Bearing Grade Elevation
BH-B3-22	752.8
BH-B4-22	756.1
BH-B5-22	750.2
BH-B6-22	753.1
BH-C3-22	742.4
BH-C4-22	749.2
BH-C5-22	746.7
BH-C6-22	748.2
BH-D3-22	744.0
BH-D4-22	746.3
BH-D5-22	745 4

TABLE 2
MAXIMUM ALLOWABLE BEARING GRADE
AT STADIUM STRUCTURE

Boring Designation	Maximum Allowable Bearing Grade Elevation
BH-D6-22	747.1
BH-D7-22	747.6
BH-E3-22	745.8
BH-E4-22	745.8
BH-E5-22	744.1
BH-E6-22	746.3
BH-E7-22	749.3
BH-F4-22	743.8
BH-F5-22	742.5
BH-F6-22	744.6

Notes:

- 1. This table shows the elevation 2 feet below where competent rock was encountered in borings made within or adjacent to the proposed limits of the stadium.
- 2. Actual bearing grade will likely be deeper than the elevations in this table. The footings should be designed with a maximum allowable bearing pressure of 11,000 psf for footings bearing above El. 730 and 15,000 psf for footings bearing below El. 730.

Footings loaded to these pressures will settle, but we estimate that the total settlement will be less than 1 inch.

Footings for lightly loaded structures with the limits of the stadium could bear above competent rock and in the glacial deposits/weathered shale. These should be designed as recommended in Section 4.2.1.1.

All footings for the stadium should be embedded at least 4 feet below the final grade for frost considerations.

### 4.1.3.2 Uplift and Lateral Loading

The disadvantage of spread footings is that they do not provide uplift resistance beyond their dead weight. If a net uplift is anticipated, we recommend developing this resistance by using vertical or inclined rock anchors bonded in the competent shale.

Some lateral load can be resisted due to friction between the concrete and competent shale and the shale bedding planes below the footing. The frictional resistance between the bedding planes will likely be about the same as those between the placed concrete



and the prepared shale. We recommend using an allowable horizontal frictional resistance of 35 degrees below the foundations to develop lateral resistance.

If needed, the resistance to lateral loading can be developed by several methods. Footings with lateral loading, but little or no uplift, can be designed with steel bars doweled into the shale and integrated in the footings. For a combination of lateral and uplift, post-tensioned rock anchors will provide an increase in the normal stress between the footing and the competent rock and rock bedding planes, thus increasing the lateral capacity due to friction. By inclining the anchors, a horizontal component of the anchor capacity can be used to resist lateral loading, as well. Additional recommendations for the design of rock anchors are provided in Section 4.1.4.2.

#### 4.1.4 Retaining Structures

Since the stadium will be embedded about 35 feet below existing grades, exterior foundation walls for the event (i.e., field) level should be designed to resist lateral pressures from exterior backfill and surcharge loading. Access ramps will also require retaining walls to accommodate grade changes.

#### 4.1.4.1 Foundation Walls

The perimeter of the excavation in the competent shale will be close to vertical. Preliminary plans indicate that the foundation walls will be constructed a few feet inside of the excavation around the entire perimeter to accommodate drainage. We recommend that enough space be provided between the rock excavation and the interior foundation wall to allow access to construct forms, place waterproofing, etc. The space between the walls and excavation should be backfilled with free draining, granular stone (i.e., drainage stone, refer to Appendix C) to collect groundwater and direct it to a drainage system (described in Section 4.1.2). These walls should be designed to resist loads applied from the backfill around the stadium perimeter, including planned surcharge loading. Lateral earth pressures to be used for design are described in Section 4.1.4.

The perimeter foundation walls will be up to 35 feet high and can be supported internally with floor slabs. If the span between slabs is large enough to make this concept prohibitive, lateral support can alternatively be achieved by post-tensioned rock anchors embedded in the competent shale.

#### 4.1.4.2 Rock Anchors/Tie-Backs

Rock anchors (i.e., tie-backs) should gain their capacity from embedment in the competent shale. The bond zone should be below El. 730. Below this elevation, the bond zone should be designed with an allowable bond stress of 50 pounds per square inch (psi).



Rock anchors should be designed and installed in general accordance with the recommendations found in *Recommendations for Prestressed Rock and Soil Anchors* (*PTI DC35.1-14*) published by the Post-Tensioning Institute.

#### 4.1.4.3 Other Walls

Other walls, such as those for access ramps or to accommodate other grade changes can generally be designed as cantilevered retaining walls or walls with tiebacks, depending on the height, anticipated surcharge, and space for construction.

Cantilevered walls should be designed using the allowable bearing pressures for the planned bearing stratum as described in Section 4.1.3.1 for rock or Section 4.2.1.1 for till or weathered shale.

Tiebacks for walls, where required, should extend into the competent shale. These should be designed as described in Section 4.1.4.2.

#### 4.1.4.4 Earth Pressures

We recommend designing the foundation walls considering the at-rest condition. For drainage stone, the at-rest earth pressure coefficient ( $k_0$ ) will be 0.5 and the stone should be assigned a unit weight of 120 pounds per cubic foot (pcf). In areas, where there will be a narrow space between the foundation wall and competent rock, the earth pressure will be lower than those calculated using the at-rest condition. The magnitude, however, is dependent on the height of the zone, width of the space, and anticipated surcharge. McMahon & Mann can assist the structural engineer with estimating earth pressures applied to the foundation walls at these locations.

Cantilevered walls or walls with a single row of tie-backs can be designed considering the active-earth pressure condition. We recommend using an active earth pressure coefficient ( $k_a$ ) of 0.33 and a unit weight of 120 pcf for design.

A passive earth pressure coefficient of 3.0 should be used for walls embedded in overburden or weathered rock. A factor of safety of 1.5 should be applied to this value for the design of permanent structures. Walls embedded in competent rock should be designed according to the procedures defined by the *American Association of State Highway and Traffic Officials (AASHTO) LRFD Bridge Design Specifications.* 

We recommend a coefficient of friction of 0.5 (i.e.26.6 degrees) for concrete structures bearing on glacial till or weathered rock and 0.7 (i.e.,35 degrees) for concrete structures bearing on clean (free from loose particles or debris) competent rock.

Multiple rows of slabs or bracing from anchors can alter the lateral earth pressures imparted on the retaining or foundation walls. McMahon & Mann should review the planned configuration to assist with estimating the lateral pressures on these types of walls.



All walls should be designed to collect and direct groundwater away from the structure. With adequate drainage, no consideration for groundwater pressure against the wall above the drainpipe will be necessary.

#### 4.1.4.5 Waterproofing

The exterior of the foundation walls should be waterproofed below El. 765.

#### 4.1.5 Backfill and Drainage Considerations

#### Foundation Walls

The area between the stadium foundation walls and rock excavations should be backfilled with drainage stone. A perforated pipe should be embedded in the drainage stone below the floor slab elevation to direct groundwater to the permanent dewatering system (described in Section 4.1.2).

#### Event Level

The bottom of the excavation will be several feet below the planned event level and playing surface at El. 735. The event level and playing surface subgrade, in competent rock, should be sloped to direct runoff toward the dewatering system.

Drainage Stone should be used to backfill between the top of competent rock and event level floor slabs and the playing surface subgrade. A network of perforated drainage pipes should be embedded in the drainage stone to direct groundwater and run-off to the dewatering system.

#### Other Backfill

The remainder of the excavations, and any excavations that will support structures (e.g., concession stands, concrete sidewalks, etc.) should be backfilled with structural fill (refer to Appendix C).

Excavation spoil, including the excavated shale, might have uses for grading across the site. Most likely, it can be used to raise site grades at locations where no structures are planned (i.e., landscaping) or for areas with a higher tolerance for settlement (e.g., flexible pavement, gravel parking areas, etc.). It could also be stockpiled and used as backfill following the demolition of Highmark Stadium. Any material that will be used for these purposes should be treated as suitable fill (refer to Appendix C) and will need to be evaluated before being used. Suitable fill should be free of deleterious materials (e.g., frozen soil, organics, construction debris, particles larger than 4 inches, etc.).

Excavation spoil not suitable for use on site will need to be disposed of or recycled. If the material is not contaminated (no contamination was detected during the subsurface exploration program), a nearby disposal location should be identified. Alternatively, the material might be suitable for use as daily cover at a local landfill. Often, landfill facilities



will waive tipping fees or even subsidize shipping costs for the spoil. McMahon & Mann can assist with identifying acceptable disposal options.

#### 4.2 AUXILIARY BUILDING AND OTHER STRUCTURES

The auxiliary building will be a one, or possibly two, story building located directly to the south of the new stadium. We recommend that this structure be supported by spread and strip footings. There will also be other support structures, parking lots, roadways, and landscaping across the site.

Additional geotechnical recommendations for these structures are included in the next section.

#### 4.2.1 Design Considerations

#### 4.2.1.1 Foundations

#### Auxiliary Building

Since weathered rock is estimated to be between 9 to 13 feet within the limits of the auxiliary building, we recommend the footings bear on the native glacial till. The maximum suitable bearing grades based on the borings made near the proposed auxiliary building footprint are summarized in the following table.

#### TABLE 3 MAXIMUM ALLOWABLE BEARING GRADE AT AUXILIARY BUILDING

Boring Designation	Maximum Allowable Bearing Grade Elevation	Boring Designation	Maximum Allowable Bearing Grade Elevation
BH-G3-22	751.6	BH-13-22	750.0
BH-G4-22	752.9	BH-14-22	753.2
BH-H3-22	750.5	BH-15-22	755.0
BH-H5-22	758.8		

Note: These elevations represent the top of the glacial till/weathered shale at these locations.

Spread and strip footings bearing on the till (or weathered shale, if encountered) should be designed with a maximum allowable bearing capacity of 8,000 psf. Footings loaded to this pressure will settle, but we expect the total settlement to be about one inch, or less.

Footings should be embedded at least 4 feet below the final grade for frost protection.

Spread footings should have a minimum dimension of 4 feet in either direction in plan. Strip footings should have a minimum width of 2 feet.



#### Other Support Structures

Foundations and slabs for other support structures should be designed similar to those for the auxiliary building. McMahon & Mann can assist with estimating the maximum suitable bearing grade at the selected locations. Additional borings might be required if the planned structure locations are outside of the limits of the subsurface exploration program.

#### 4.2.1.2 Concrete Slab Design

A 1-foot-thick layer of structural fill shall be placed over the subgrade following proof rolling (see Section 4.2.2.2) within the limits of the auxiliary building and other planned concrete slabs on grade. The structural fill should be covered with a vapor retarder that complies with the American Society for Testing and Materials (ASTM) E 1745-17 "Standard Specifications for Plastic Water Vapor Retarders Used in Contact with Soil or Granular Fill Under Concrete Slabs" prior to the placement of concrete.

The concrete slab should be designed and constructed following the procedure outlined in the ACI 302.1R "Guide for Concrete Floor and Slab Construction." In particular, the mix design should comply with the requirements to limit slab curling. Refer also to the procedures outlined in ACI 302.2R-06 "Guide for Concrete Slabs that receive Moisture-Sensitive Flooring Materials."

The slab should be constructed after the footings have been built and loaded with the weight of the building. This will limit the effect on the slab from subgrade elastic compression caused by the footing loads.

We recommend using a modulus of subgrade reaction of 200 pounds per cubic inch (pci) for designing the concrete slab.

#### 4.2.1.3 Pavement Design

Grades below the planned pavement limits should be raised with compacted structural fill, as necessary. The pavement subgrade should be prepared by clearing it of deleterious and unsuitable material and proofrolled as described in Section 4.2.2.2. The subbase below the asphalt pavement should also be structural fill.

The subgrade should be lined with a stabilization geotextile (refer to Appendix C) prior to placing the structural fill subbase layer. We recommend a minimum subbase thickness of 1-foot. However, more may be necessary depending on the traffic loads and pavement analysis. We recommend using a modulus of subgrade reaction of 200 pci for designing the pavement.

The subgrade for all pavement areas should be pitched to direct water collected in the subbase to drainage structures.



### 4.2.1.4 Light Posts

We recommend supporting light posts using drilled piers socketed in competent shale rock. With this construction technique, they will develop axial resistance from adhesion and friction between the concrete and rock on the sides of the socket. Lateral and flexural resistance is developed based on the strength of rock and depth and diameter of the socket. Therefore, dimensions of the drilled piers will depend on the anticipated overturning moment.

We can assist with the design of the light post foundations. Additional borings might be required if the planned structure locations are outside of the limits of the subsurface exploration program.

Once drilled, concrete should be placed using the tremie method of concrete placement as outlined in ACI 336.1-01.

The drilled piers should also be designed and constructed in accordance with ACI 336.3R-14 publication, "Report on Design and Construction of Drilled Piers." These manuals state allowable construction tolerances and procedures. It is recommended that appropriate reinforcing steel be included in the design to resist overturning moments that result from applied lateral loads and due to construction eccentricities.

#### 4.2.2 Construction Considerations

#### 4.2.2.1 Utility Relocation and/or Protection

Multiple utilities, including sewer, water, and overhead utilities, are located within the vicinity of the project site. Contract documents should alert the contractor to the location of any existing utilities. The contractor should relocate, decommission, or protect the existing utilities that will be within the construction limits.

### 4.2.2.2 Subgrade Preparation

The footprint of the auxiliary building, support structures, pavements, and other structures should be prepared by removing asphalt, soil with debris, soil containing deleterious materials, etc. to expose the planned subgrade elevation.

Once the subgrade elevation is reached, it should be proofrolled using either a smooth drum roller with an operating weight of at least 10 tons or a loaded 10-wheel dump truck. The proofrolling should be used to identify soft and/or unstable areas. The roller should be driven slowly over the subgrade and its response should be observed. A subgrade deflection of less than 1 inch is acceptable. Larger deflections, rutting, and/or pumping are signs of subgrade instability. These areas should be compacted until they are stable or overexcavated and replaced with compacted structural fill.

Grades should be raised with compacted structural fill as necessary.



### 4.2.2.3 Excavation Considerations

The depth of excavations for structures, pavement, and utilities will likely vary across the site. We recommend that these excavations be sloped. The sloped excavations will likely extend through the fill and native deposits into the glacial deposits or weathered shale. For estimating purposes, excavations should be planned considering the soil as Soil Type C. For Soil Type C, the slopes should be no steeper than 1.5H:1V. However, the slopes may need to be flatter to maintain stability and for worker safety.

Excavations should be dewatered until they are backfilled. If access to the dewatering system for the stadium is not possible, the excavations will likely be able to be sloped to a low area and pumped.

#### 4.2.2.4 Backfill and Placement

Backfill for the structures' (i.e., auxiliary building, other structures) foundation walls, floor slabs, and utility excavations below future structures should be structural fill.

On the exterior side of buildings or for utilities where no structures will be constructed, the excavations can be backfilled with suitable fill.

The ground surface adjacent to backfilled structures should be sloped to direct surface water away from the structures.

### 4.3 CONSTRUCTION MONITORING

McMahon & Mann should monitor geotechnical aspects of construction including the following:

- Review design drawings and specifications before construction begins,
- Review the plans for excavation and dewatering,
- Review the plans for installing rock anchors/tiebacks,
- Observe the excavation as it proceeds to see if there are adjustments in estimated excavation efforts or dewatering,
- Observe the excavation spoil for appropriateness for use as suitable fill,
- Observe the subgrade prior to construction of the footings and slabs,
- Observe the installation of rock anchors/tiebacks,
- Observe the installation of the footings and slabs, and
- Observe backfill placement and compaction.



#### 5.0 ENVIRONMENTAL ASSESSMENT FORM

LPD requested that McMahon & Mann assist it in completing a portion of the Full Environmental Assessment Form (FEAF) as part of the State Environmental Quality Review (SEQR) Act for environmental permit submission to the New York State Department of Environmental Conservation (NYSDEC). Specifically, McMahon & Mann completed Section E.2a through E.2g.

The completed form is included in Appendix D, with our responses to Sections E.2a through E.2g outlined in red. These responses are based on our observations of site conditions, results of the subsurface exploration program, and a review of published data<sup>6</sup>.

#### 6.0 LIMITATIONS

Limitations to this report are included in Appendix E.

<sup>&</sup>lt;sup>6</sup> Soil Survey of Erie County, New York, published by the United States Department of Agriculture and the Soil Conservation Service, issued December 1988.



**FIGURES** 







ST	Ā	DI	U	Μ
-		-	-	



LEGENE	)	
GROUND CONTOURS	TP-1-22	TEST PIT DESIGNATION AND APPROXIMATE LOCATION (SEE NOTE 3)
WATER CONTOURS TE 2)		BORE HOLE LOCATION
ED STADIUM FOOTPRINT TE 4)	æ	(SEE NOTE 3)
ED AUXILIARY 3 FOOTPRINT		MONITORING WELL LOCATION (SEE NOTE 3)
TE 4)	-5	DEPTH FROM GROUND SURFACE TO GROUNDWATER
ES FOR BORING AND		(FEET)
RING WELL DESIGNATION		

Existing ground surface based on topographic survey provided by Foit-Albert Associates, Architecture,

Water elevations were measured in monitoring wells on June 10 and 15, 2022. The groundwater contours are based on linear interpolations between the monitoring wells.

Borings and monitoring wells completed by Earth Dimensions, Inc. in April - May 2022. See grid lines for designations. Test pits completed by McMahon & Mann Consulting Engineering and Geology, P.C. with assistance from Pinto Construction Services on June 15, 2022. See Appendix A for the boring location plan (Figure A-1) and boring, monitoring well, and test pit logs.

Proposed stadium and auxiliary building footprint provided by Legends Project Development in drawing titled, "BBS - Site Base 2022.0428 with stadium location," dated April 28, 2022.

	GROUNDW	/ATER
TADIUM	CONTOUR	R MAP
NEW YORK	DWG. NO. 22011-012	FIGURE 4



# APPENDIX A

SUMMARY OF SUBSURFACE EXPLORATIONS NEW BILLS STADIUM ORCHARD PARK, NEW YORK

### **APPENDIX A**

#### SUMMARY OF SUBSURFACE EXPLORATIONS NEW BILLS STADIUM ORCHARD PARK, NEW YORK

#### I. BORINGS

In April and May 2022, Earth Dimensions, Inc. (EDI) advanced 38 borings at the site after Ground Penetrating Radar Systems, LLC (GPRS) cleared each location for underground utilities. EDI used a track mounted drill rig to complete the borings and monitoring wells, which are designated as shown in Table A-1, included in this appendix. The designations are in relation to the coordinates of the 200 by 200-foot grid layout. The locations of the borings and wells are shown on Figure A-1 in this appendix and are presented on the grid layout in Figures 1 through 4.

Foit-Albert Associates, Architecture, Engineering and Survey, P.C. (Foit-Albert) provided a topographic survey of the stadium site which included the boring locations and the adjacent ground surface elevations. Legends Project Development (LPD) provided the proposed stadium and auxiliary building limits.

The borings were drilled with 4-1/4 inch inside diameter hollow stem augers. Soil samples were collected in the borings from below the bottom of the augers. All of the borings were sampled at 2-foot intervals to split-spoon or auger refusal. Rock core samples were retrieved from all of the borings except for BH-I4-22. The boring logs are included in Appendix A-1 and the boring locations are summarized in Table A-1.

#### II. SOIL SAMPLING

Soil samples were collected using a 1-3/8 inch inside diameter, 24-inch long split-spoon sampler in general accordance with ASTM D 1586. Samples were obtained by driving the sampler into the ground with a 140-pound hammer falling 30 inches. The sampler was driven 24 inches, the soil sample was removed from the sampler, and a description of the sample was recorded on the boring log.

The number of hammer blows required to drive the sampler through each 6-inch interval was recorded. The sum of the number of blows required to advance the sampler in the second and third 6-inch interval is the Standard Penetration Test (SPT) N-value.

Consistency	N-value
Very Soft	<2
Soft	2-4
Medium Stiff	5-8
Stiff	9-15
Very Stiff	16-30
Hard	>30

The SPT N-values are correlated to the consistency of plastic soils, as shown below:

The SPT N-values are also correlated to the density of granular soils, as shown below:

Density	N-value
Very Loose	0-4
Loose	5-10
Medium Dense	11-30
Dense	31-50
Very Dense	>50

### III. ROCK CORING

EDI cored a minimum of approximately 10 feet of rock in most borings using a NQ-2 size double tubed wireline core barrel and diamond bit, which yields a 2-inch diameter core sample. The rock type and the condition of the cores are recorded on the boring logs. Photographs of the rock core are included following each boring log (See Appendix A-1).

The core recovery and the Rock Quality Designation (RQD) for the core runs are also recorded on the boring logs. Core recovery is the length of core retrieved from the boring compared to the actual length of rock that was cored, expressed as a percentage. The RQD is a measure of the frequency of discontinuities and is defined as the sum of the core pieces that are 4 inches or greater in length divided by the length of the core run.

### **IV. TEST PITS**

In June 2022, Pinto Construction Services (Pinto) used a Kobelco SK210 LC excavator to complete two (2) test pits at the site adjacent to existing test borings. Test pits are designated as TP-1-22 and TP-2-22 and their locations are shown on Figure A-1.

McMahon & Mann Consulting Engineering and Geology, P.C. observed the advancement of the test pits and prepared test pit logs. The test pit logs are included in Appendix A-2. The approximate ground surface elevations and test pit depths are summarized in Table A-2.

### V. GROUNDWATER MONITORING WELLS

Upon completion of select borings, groundwater monitoring wells were installed in the bore holes, as noted in Table A-1. The monitoring wells are constructed of 2-inch diameter PVC well screen and riser pipe. Refer to the attached boring logs for details of installation.

McMahon & Mann developed the monitoring wells by removing water from the well using a bailer. This is done to agitate, suspend, and remove fine-grained particles and to check that the wells are operating properly. All wells had the equivalent of at least five times its volume (cross sectional area of the inside of the pipe times the height of water in the well), or more, removed for development.

Designation	Groundwater Elevation, ft	Designation	Groundwater Elevation, ft
BH-A4-22	762.1	BH-E3-22	756.9
BH-A6-22	763.4	BH-F4-22	751.4
BH-B3-22	761.1	BH-F5-22	752.2
BH-B6-22	762.7	BH-F7-22	755.5
BH-C3-22	760.5	BH-G6-22	754.4
BH-C5-22	759.3	BH-H3-22	745.2
BH-C7-22	758.0	BH-H5(D)-22	745.5
BH-D2-22	756.6	BH-H5(S)-22	759.0
BH-D4-22	757.5	BH-15-22	752.3
BH-D6-22	757.7		

Following development, we measured the groundwater levels in the wells. These measurements are summarized in the table below:

### VI. HYDRAULIC CONDUCTIVITY ESTIMATES

Monitoring wells were developed after installation by removing a minimum of five (5) well volumes of water to ensure that the well was hydraulically connected to the formation and operating properly. Following well development, groundwater was allowed to return to an equilibrium elevation in the wells.

Rising and falling head tests (i.e., slug tests) were then performed at the monitoring wells. A slug was either added or removed to induce a change in head and the water level was measured as it returned to the equilibrium elevation. These data were then used to estimate the hydraulic conductivity of the rock formations adjacent to the wells' screened interval. The estimated hydraulic conductivities are summarized in Table A-3.

FIGURE A-1

BORING LOCATION PLAN



	LEGEND
-760 - — — — —	EXISTING GROUND CONTOURS (SEE NOTE 1)
	PROPOSED STADIUM FOOTPRINT (SEE NOTE 3)
	PROPOSED ANCILLARY BUILDING FOOTPRINT (SEE NOTE 3)
P-1-22	TEST PIT DESIGNATION AND APPROXIMATE LOCATION (SEE NOTE 2)
H-B3-22	BORE HOLE DESIGNATION AND LOCATION (SEE NOTE 2)
H-A4-22	MONITORING WELL DESIGNATION AND LOCATION (SEE NOTE 2)
A 	GRID LINES FOR BORING AND MONITORING WELL DESIGNATION

1. Existing ground surface based on topographic survey provided by Foit-Albert Associates, Architecture, Engineering and Survey, P.C. (Foit-Albert), dated April 29, 2022.

2. Borings and monitoring wells completed by Earth Dimensions, Inc. in April - May 2022, and locations and elevations surveyed by Foit-Albert. Boring designations based on 200 x 200 ft. grid. Test pits completed by McMahon & Mann Consulting Engineering and Geology, P.C. with assistance from Pinto Construction Services on June 15, 2022. See Appendix A for boring, monitoring well, and test pit logs.

3. Proposed stadium and ancillary building footprint provided by Legends Project Development in drawing titled, "BBS - Site Base 2022.0428 with stadium location,"dated April 28, 2022.

## **BORING LOCATION PLAN**

NEW YORK

DWG. NO. 22011-013

FIGURE A-1

**APPENDIX A-1** 

SUMMARY TABLE, BORING LOGS, AND ROCK CORE PHOTOGRAPHS

Boring	Northing <sup>2</sup>	Easting <sup>2</sup>	Ground Surface Elevation, ft <sup>2</sup>	Total Depth, ft
BH-A4-22 <sup>1</sup>	1011031.00	1092206.00	770.7	41.4
BH-A6-22 <sup>1</sup>	1010954.00	1092599.00	769.5	32.3
BH-B3-221	1010873.00	1091970.68	764.0	24.2
BH-B4-22	1010835.10	1092168.00	767.3	39.1
BH-B5-22	1010796.00	1092364.00	767.4	25.0
BH-B6-22 <sup>1</sup>	1010800.00	1092569.00	766.0	25.9
BH-C2-22	1010715.00	1091736.00	758.9	23.7
BH-C3-221	1010677.00	1091933.00	762.6	27.2
BH-C4-22	1010638.00	1092129.00	762.2	26.0
BH-C5-22 <sup>1</sup>	1010600.00	1092325.00	762.5	42.1
BH-C6-22	1010561.00	1092521.00	761.4	21.2
BH-C7-22 <sup>1</sup>	1010523.00	1092718.00	761.6	26.2
BH-D2-22 <sup>1</sup>	1010573.44	1091708.19	759.8	24.0
BH-D3-22	1010480.83	1091893.74	760.0	63.5
BH-D4-22 <sup>1</sup>	1010442.00	1092090.00	760.3	26.5
BH-D5-22	1010404.00	1092287.00	761.1	23.7
BH-D6-22 <sup>1</sup>	1010365.00	1092483.00	760.3	29.5
BH-D7-22	1010327.00	1092679.00	760.7	20.4
BH-E2-22	1010322.68	1091659.00	760.1	21.6
BH-E3-22 <sup>1</sup>	1010270.70	1091924.51	759.8	31.7
BH-E4-22	1010246.00	1092052.00	757.4	29.4
BH-E5-22	1010207.00	1092248.00	759.9	23.8
BH-E6-22	1010169.00	1092445.00	760.4	27.0
BH-E7-22	1010130.00	1092641.00	760.4	23.0
BH-F3-22	1010088.00	1091817.00	757.5	24.2
BH-F4-22 <sup>1</sup>	1010050.00	1092013.00	757.8	32.0
BH-F5-22 <sup>1</sup>	1010011.00	1092210.00	758.0	24.0
BH-F6-22	1009973.00	1092406.00	760.5	23.9
BH-F7-22 <sup>1</sup>	1009934.00	1092602.00	761.6	25.5
BH-G3-22	1009880.00	1091840.00	757.1	24.3
BH-G4-22	1009853.35	1091974.61	758.9	34.0

Table A-1Boring Locations, Elevations, and Total Depths

Boring	Northing <sup>2</sup>	Easting <sup>2</sup>	Ground Surface Elevation, ft <sup>2</sup>	Total Depth, ft
BH-G6-22 <sup>1</sup>	1009776.00	1092367.00	760.6	28.8
BH-H3-22 <sup>1</sup>	1009637.00	1091724.00	756.5	24.2
BH-H5(D)-22 <sup>1</sup>	1009593.00	1092127.00	760 6	34.1
BH-H5(S)-22 <sup>1</sup>	1009582.94	1092193.30	700.0	15.5
BH-13-22	1009499.15	1091701.37	754.0	27.3
BH-14-22	1009460.68	1091897.64	757.2	14.8
BH-15-221	1009421.95	1092093.90	761.0	34.0

Table Note:

A monitoring well was installed following the completion of the boring. A well log is included with the boring log.
 Boring locations and elevations were provided by Foit-Albert.

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting

1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>	Hole Number <u>BH-A4-22</u>	Surface Elevation: 770.7
Project Name: Proposed Site Developm	ent Northing: <u>1011</u>	031 Easting:
Project Location: Town of Orchard Par	k, Erie County, NY	Date Started:
Client: McMahon & Mann Consulting Eng	ineering & Geology, P.C.	Date Completed: <u>4/13/2022</u>

<b>.</b>		<b>D</b>	Blows on Sampler									
Depth (ft)	SN	(in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	Water Table and Remarks		
	1	20	7	6	6	13	12		Tar and chip surface. Moist brownish gray very gravelly (SAND) fill with 40 to 60% mostly angular gravel, trace silt and slag, compact, massive soil structure,	Tar and chip surface to 0.1 feet over sandy soil fill with some gravel, trace silt and slag to 0.4 feet over shaley soil fill with little to some sand, trace to little clay to 1.8 feet over apparent shale bedrock to 4.2 feet		
-	2	22	13	27	30	50/4	57		(SM), (GM). Dry to moist dark gray very gravelly (SAND-SILT-CLAY) fill with 30 to 50% mostly shale stone fragments, little to some sand, trace to little clay, stiff, massive soil structure.	over shale bedrock to end of coring. Note: Advanced bore hole with 4 1/4" ID x 8" OD hollow stem auger casing with continuous split spoon		
5_	^Run		#1						(GM),(GC).	sampling to auger refusal at 4.2 feet. Removed rods and installed a bentonite seal. Continued below with a NQ-2 size double tubed wireline core barrel with diamond bit to 7.0 feet. Removed core equipment and advanced bore hole with hollow stem auger casing to 7.0		
-	Run		#2						fractured in all directions, some iron staining, core lengths range from (0.01-0.05'). Dark gray shale bedrock, soft, thinly laminated, intensely fractured, dense, no iron staining, core breaks appear fresh, core lengths range from (0.01-0.07').	tri-cone roller bit using fluid rotary techniques. Removed rods and continued below with a NQ-2 size double tubed wireline core barrel with diamond bit to coring completion at 41.4 feet. Reamed core hole with a 3 7/8" tricone roller bit and installed a 2-inch PVC		
10	v ARun		#3							standpipe piezometer to 27.0 feet in completed bore hole.		
_	Run		#4							Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % % gal		
-										4.2 1 to 2.8 2.0 71 0 35 7.0		
15_									laminated, moderately fractured horizontally along bedding planes with high angle fractures at 15.0 to 15.6, 16.4 to 16.5, 18.0 to 18.2,	7.0 2 to 4.7 3.5 74 13 110 11.7		
-									18.7 to 18.8, 19.1 to 19.2, 19.5 to 19.8, 20.2 to 20.4, 20.7 to 21.7, 22.2 to 22.8, 25.0 to 25.1, 26.2 to 26.5, 27.1 to 27.2, 28.3 to 28.7,	11.7 3 to 1.2 1.2 100 0 40 12.9		
-	Run		#5						and 29.2 to 29.3 feet, dense, no iron staining, core breaks appear fresh, core lengths range from (0.02-1.3').	12.9 4 to 4.6 4.6 100 39 45 17.5		
20										17.5 5 to 4.1 4.1 100 20 35 21.6		

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>	Hole Number <u>BH-A4-22</u>	Surface Elevatio	on: <u>770.7</u>
Project Name: Proposed Site Developm	ent Northing:	1011031 Easting:	1092206
Project Location: Town of Orchard Par	k, Erie County, NY	Date Started:	4/12/2022
Client: McMahon & Mann Consulting Eng	ineering & Geology, P.C.	Date Completed	4/13/2022

		D	Blows on Sampler															
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	Water Table and Remarks								
	Run		#5						Dark gray shale bedrock, soft, thinly	Run Depth Length REC REC RQD WL								
									laminated, moderately fractured	# (ft) (ft) (ft) % % gal								
-								<u> </u>	with high angle fractures at 15.0 to	17 5								
	<u> </u>								15.6, 16.4 to 16.5, 18.0 to 18.2,	5 to 4.1 4.1 100 20 35								
-	Dur								18.7 to 18.8, 19.1 to 19.2, 19.5 to 21.6									
	Run		#6						19.8, 20.2 to 20.4, 20.7 to 21.7,									
									22.2 to 22.8, 25.0 to 25.1, 26.2 to	21.6								
									and 29 2 to 29 3 feet dense no iron									
									staining, core breaks appear fresh,									
-									core lengths range from (0.02-1.3').	26.6								
										7 to 5.0 5.0 100 78 40								
25_										31.6								
										31.6								
										8 to 5.0 5.0 100 100 45								
-										36.6								
	<u> </u>																	
-	Run		#7							9 to 4.8 4.8 100 83 45								
	Kun		π/							41.4								
-									29.3									
									Dark gray shale bedrock, soft, thinly									
30_									laminated, slightly fractured									
									horizontally along bedding planes,	Water level at 10.4 feet below								
									donso, no iron staining, coro broaks	overnight at 12.9 feet.								
1									appear fresh, core lengths range									
	*								from (0.35-1.8').									
-	Dure		"0															
	Run		#8															
_																		
										Water level at 10.8 feet below								
										bitting completion with tooling								
-										removed from bore hole.								
								<u>  </u>										
35_																		
								<u>  </u>										
L L								<u> </u>										
	¥—																	
-	<b>.</b>																	
	Kun		#9					<u></u>										
_																		
								<u>E</u>										
1								<u></u>										
4.0																		
40	1							$\vdash$										

EARTH DIMENSIONS, INC. Geotechnical and Environmental Drilling | Wetland Delineations and Consulting

Geotechnical and Environmental Drilling | Wetland Delineations and Consultin 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>	Hole Number <u>BH-A4-22</u>	Surface Elevation: 770.7
Project Name: Proposed Site Develop	ment Northing: _10110	31 <b>Easting:</b> <u>1092206</u>
Project Location: Town of Orchard Pa	ark, Erie County, NY	Date Started:
Client: McMahon & Mann Consulting En	gineering & Geology, P.C.	Date Completed: <u>4/13/2022</u>

Denth		Dee	Blows on Sampler										
Depth (ft)	(ft) SN (in		0/6	6/12	12/18	18/24	N	LITH	Description and Classification	Water Table and Remarks			
	Run		#9						Dark gray shale bedrock, soft, thinly laminated, slightly fractured horizontally along bedding planes, occasional small pyrite deposits, 41.4 dense, no iron staining, core breaks appear fresh, core lengths range	Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % % gal 			
-									from (0.35-1.8').	EDI Bedrock Hardness Classification			
-										Very Soft: Can be scratched with fingernail. Slight indentation			
45_										produced by light blow of point of geologic pick. Requires power tools for excavation.			
-										Soft: Hand-held specimen crumbles under firm blows with point of geologic pick.			
_													
-													
50_													
-													
-													
-													
55_													
-													
-													
-													
60													

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code: <u>12K93e</u> Hole Number <u>W-A4</u>	1-22	Surface Elevation: <u>770.7</u>
Project	t Name: Proposed Site Development	Northing: <u>1011031</u>	Easting:
Project	t Location: Town of Orchard Park, Erie County, NY		Date Started:
Client:	McMahon & Mann Consulting Engineering & Geology, P.C	<u>.                                    </u>	Date Completed: <u>4/13/2022</u>
Depth (ft)	Well		Remarks
Jepin (ft) 	Well       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A       A	ete	Remarks
20			

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code: <u>12K93e</u> Hole Number <u>W-A4-</u>	22	Surface Elevation:770.7								
Project	t Name: Proposed Site Development	Northing:	Easting: <u>1092206</u>								
Project	Project Location:     Town of Orchard Park, Erie County, NY     Date Started:     4/12/2022										
Client:	ent: McMahon & Mann Consulting Engineering & Geology, P.C. Date Completed: 4/										
Depth (ft)	Well		Remarks								
	#00N Size Morie Sand Pack										
- 25_	0.010 Slot Screen										
	27.0 27.5 Bentonite Seal										
- - 35 -	$\begin{array}{c} 32.0 \\ \hline 31 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 & 61 \\ \hline 1 & 5 & 61 & 5 \\ \hline 1 & 5 & 61 & 5 \\ \hline 1 & 5 & 61 & 5 \\ \hline 1 & 5 & 61 & 5 \\ \hline 1 & 5 & 61 & 5 \\ \hline 1 & 5 & 61 & 5 \\ \hline 1 & 5 & 61 & 5 \\ \hline 1 & 5 & 61 & 5 \\ \hline 1 & 5 & 61 & 5 \\ \hline 1 & 5 & 61 & 5 \\ \hline 1 & 5 & 61 & 5 \\ \hline 1 & 5 & 61 & 5 \\ \hline 1 & 5 & 61 & 5 \\ \hline 1 & 5 & 61 & 5 \\ \hline 1 & 5 & 61 & 5 \\ \hline 1 & 5 & 61 & 5 \\ \hline 1 & 5 & 61 & 5 \\ \hline 1 & 5 & 61 & 5 \\ \hline 1 & 5 & 61 & 5 \\ \hline 1 & 5 & 61 & 5 \\ \hline 1 & 5 & 61 & 5 \\ \hline 1 & 5 & 61 & 5 \\ \hline 1 & 5 & 61 & 5 \\ \hline 1 & 5 & $										
40											

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code: <u>12K93e</u> Hole Number <u>W-A4-2</u>	2 Surface Elevation: 770.7
Projec	t Name: Proposed Site Development	Northing: <u>1011031</u> Easting: <u>1092206</u>
Projec	t Location: Town of Orchard Park, Erie County, NY	Date Started: <u>4/12/2022</u>
Client:	McMahon & Mann Consulting Engineering & Geology, P.C.	Date Completed:4/13/2022
Depth (ft)	Well	Remarks
-	Rock Cuttings Backfill	
- - 45_		
-		
- 50_ -		
-		
55 - -		
-		

# BUFFALO BILLS STADIUM PROJECT NO. 22-011

BORE HOLE #	CORE RUN #	DATE	DEPTH (ft)	LENGTH (ft)	REC (ft)	REC. %	RQD. %			
BH-A4-22 BH-A4-22	1 2	4-12-22 4-12-22	4.2-7.0 7.0-11.7	2.8 4.7	2.0 3.5	71 74	0 13			
BH-A4-22 BH-A4-22 BH-A4-22	3 4 5	4-12-22 4-12-22 4-13-22	11.7-12.9 12.9-17.5 17.5-21.6	1.2 4.6 4 1	1.2 4.6 4 1	100 100 100	0 39 20			
0		1 10 22	<u>12"</u>		24"	100	20	<u>3</u> 6"	48"	60"
	0	0	1	and and a start of	1.5.0			and the second second	6	0
4.2'		SP	ANAL	EXT	1.0.1			100N	AN MARCE	AUTTER
FEIST	1.7	ET (	VCN			TURS				
States and			BA M		N NO		Rep.			A L
1 COM			( ← ℝ-4	- American	17.5	FK-14	E MANIE		A A A	
Str.		OF L	21.6							


Geotechnical and Environmental Drilling | Wetland Delineations and Consulting

1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

<b>EDI Job Code:</b> <u>12K93e</u> <b>H</b>	ole Number <u>BH-A6-22</u>	Surface Elevation:	
Project Name: Proposed Site Development	tNorthing: _	1010954 Easting:1092599	
Project Location: Town of Orchard Park,	Erie County, NY	Date Started:	
Client: McMahon & Mann Consulting Engine	ering & Geology, P.C.	Date Completed: <u>4/15/2022</u>	

		D	Blows on Sampler							
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	Water Table and Remarks
	1	21	9	13	24	40	37		Tar and chip surface.       0.1         Moist gray very gravelly (SAND) fill       0.6         with 40 to 60% mostly angular       1.3         gravel with fine to coarse size sand,       1.3         trace silt, compact, single grain,       1.3	Tar and chip surface to 0.1 feet over sandy soil fill with some gravel, trace silt to 0.6 feet over shaley soil fill with little silt to 1.3 feet over apparent shale bedrock to 9.8 feet over shale bedrock to end of coring.
-	2	18	15	26	51	50/4	77		(SW),(GW). Moist to dry brown shaley (SILTY-SAND) fill with 30 to 50% shale stone fragments, little silt, very dense and dense, massive soil structure. (SM).(GM).	
5_	3	10	23	50/5					Moist to dry, wet below 6.0 feet, gray shale stone fragments, very soft and soft.	Note: Advanced bore hole with 4 1/4" ID x 8" OD hollow stem auger casing with continuous split spoon sampling to 9.8 feet. Removed coring equipment and installed a bentonite seal. Continued below with
-	4	10	42	50/4						a NQ-2 size double tubed wireline core barrel with diamond bit to 11.3 feet. Hole caving. Removed coring equipment and advanced augers to 14.0 feet. Continued below with coring equipment to end of coring at
-	5	4	50/4						9.8	32.3 feet. Reamed core hole with 3 7/8" tricone roller bit and installed a 2-inch PVC standpipe piezometer to 26.0 feet in completed bore hole.
- 10	Run		#1						Dark gray shale bedrock, soft, thinly laminated, intensely fractured in all directions, core breaks appear fresh, core lengths range from (0.01-0.3'). 11.3	
-									Auger without split spoon sampling.	Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % % gal
15_	Run		#2						Dark gray shale bedrock, soft, thinly laminated, intensely to moderately fractured horizontally along bedding planes with biob angle to pear	9.8 1 to 1.5 1.3 87 0 15 11.3
-									planes with high angle to near         14.0           vertical fractures from 14.7 to 16.7,         14.0           17.0 to 17.2, 18.9 to 19.7, 20.7 to         2 to 3.3 3.3           21.1, and 21.6 to 22.0 feet, dense,         17.3	
-	Run		#3						fresh, core lengths range from (0.01-0.78').	17.3 3 to 5.0 5.0 100 40 50 22.3
20										

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>	Hole Number <u>BH-A6-22</u>	Surface Elevation: 769.5	
Project Name: Proposed Site Developme	ent Northing: _	1010954 <b>Easting:</b> <u>1092599</u>	
Project Location: Town of Orchard Parl	k, Erie County, NY	Date Started:	
Client: McMahon & Mann Consulting Engi	ineering & Geology, P.C.	Date Completed: <u>4/15/2022</u>	

Depth	~	Rec	Blows	s on	Sam	<u>ipler</u>									
(ft)	SN	(in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification		Water Table and Remarks				
	Run		#3						Dark gray shale bedrock, soft, thinly laminated, intensely to moderately fractured horizontally along bedding planes with high angle to near vertical fractures from 14.7 to 16.7, 17.0 to 17.2, 18.9 to 19.7, 20.7 to		Run Depth Length REC REC RQD WL           # (ft) (ft) (ft) % % gal           17.3           3         to         5.0         5.0         100         40         50           22.3				
-	Run		#4						21.1, and 21.6 to 22.0 feet, dense, no iron staining, core breaks appear fresh, core lengths range from (0.01-0.78'). Dark gray shale bedrock, soft, thinly	22.3 4 to 5.0 5.0 100 74 50 27.3					
25_									laminated, moderately to slightly fractured horizontally along bedding planes with occasional high angle to near vertical fractures from 22.8 to 22.9, 24.8 to 25.9, 27.8 to 27.9 and		27.3 5 to 5.0 5.0 100 84 80 32.3				
-									28.2 to 28.4, dense, no iron staining, core breaks appear fresh, core lengths range from (0.1-2.2').		EDI Bedrock Hardness Classification				
-	Run		#5					Very Soft: Can be scra fingernail. Slight inden produced by light blow geologic pick. Requires							
30_											Soft: Hand-held specimen crumbles under firm blows with point of geologic pick.				
_															
-	¥	-							Coring completed at 32.3 ft	32.3					
-															
35_															
-															
					<u></u>										

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code: _	12K93e	Hole Number <u>W-A6-</u>	22		Surface Elevation:	769.5
Project	t Name:_	Proposed Sit	te Development	Northing:	1010954	Easting: <u>1</u>	092599
Project	t Locatio	n: Town of	Orchard Park, Erie County, NY			Date Started:	4/2022
Client:	McMaho	n & Mann Co	nsulting Engineering & Geology, P.C.			Date Completed:	4/15/2022
Depth (ft)		١	Well			Remarks	
	5	<b></b>	8-inch Road Box Installed in Concrete	e			
_		1.0	Pad				
-			Cuttings Backfill				
-							
-			2-inch Schedule 40 FIT BVC Biser				
5_							
1							
_							
-							
10_							
-							
+		<u>al·</u> 13.0					
-			Bentonite Seal				
15_		15.0					
-		16.0					
			#00N Size Morie Sand Pack				
-							
-			0.010 Slot Screen				
20							

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code: <u>12K93e</u> Hole Number <u>W-A6-2</u>	22	Surface Elevation:
Project	t Name: Proposed Site Development	Northing: <u>1010954</u>	Easting: <u>1092599</u>
Project	t Location:Town of Orchard Park, Erie County, NY		Date Started:
Client:	McMahon & Mann Consulting Engineering & Geology, P.C.	_	Date Completed: <u>4/15/2022</u>
Depth (ft)	Well		Remarks
	#00N Size Morie Sand Pack		
- 25_ -	0.010 Slot Screen		
-	Bentonite Seal		
30	Rock Cuttings Backfill $\begin{array}{cccccccccccccccccccccccccccccccccccc$		
- 35_ - -			
40			



Unconfined Compressive Strength: 3378.3 PSI

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u> Hole Number <u>B</u>	1-B3-22	Surface Elevation: <u>764</u>	
Project Name: Proposed Site Development	_ Northing: _1010873	Easting:1091970.68	
Project Location: Town of Orchard Park, Erie County, NY	2	Date Started:	
Client: McMahon & Mann Consulting Engineering & Geology,	P.C	Date Completed: <u>5/13/2022</u>	

		Blows on Sampler				npler							
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	Water Table and Remarks			
									Gray asphalt pavement. 0.6	Note: Sample number 1 taken from 1.0 to 2.0 feet.			
-	1		2					6N	Mostly crushed concrete fill.	Grav asphalt payoment to 0.6 feet			
	-	7	2	9				Pat	1.5	over mostly crushed concrete fill to			
-									Gray and dark gray shale stone	1.5 feet over apparent shale bedrock			
	2		11						hughends, very sole and sole.	of coring.			
_		22		14			30			0. 00			
					16								
_						23							
	3		20							Note: Water level at 5.8 feet below around surface prior to coring			
5_		24		22			52			ground surface prior to comigi			
					30		52						
_						38							
	4		28							Note: Started loosing water to			
_		14		31						Tormation below 10.0 feet.			
					50/4								
-	5		50/3							Note: Advanced bore hole with 4			
		3	0070							casing with continuous split spoon			
-	≜ ≜ ARun		#1						9.2	sampling to auger refusal at 9.2			
10			"1						intensely to intensely fractured	feet. Removed drill rods and installed a bentonite seal. Continued			
10_									$\neg$ horizontally along bedding planes, $10.2$	below with a NQ-2 size double tubed			
									dense, no iron staining, core pieces	wireline core barrel with diamond bit			
-									range from (0.025-0.1').	Reamed core hole with a 3 7/8"			
									Dark gray shale bedrock, soft,	tricone roller bit and installed a			
-									intensely to moderately fractured, thickly laminated to medium	19.0 feet in completed bore hole.			
									bedding, dense, no iron staining.				
-													
-	¥												
1 5	Run		#2										
15_										Run Depth Length REC REC RQD WL			
										# (ft) (ft) (ft) % % gal			
-										9.2			
										1 to 5.0 5.0 100 42 0			
-										14.2			
										14.2			
-										2 to 5.0 5.0 100 34 30			
										17.2			
-	$\downarrow$								19.2	19.2			
	Run		#3						Coo novit choot	3 to 5.0 4.9 98 95 30 24.2			
20								F	See next sneet	E !!!E			

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>	Hole Number <u>BH-B3-22</u>	Surface Elevation: <u>764</u>
Project Name: Proposed Site Developm	Northing: <u>1010873</u>	Easting:
Project Location: Town of Orchard Par	k, Erie County, NY	Date Started: <u>5/12/2022</u>
Client: McMahon & Mann Consulting Eng	ineering & Geology, P.C.	Date Completed: <u>5/13/2022</u>

Dorth		Dec	Blows on Sampler		er l						
(ft)	SN	(in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	Water Table and Remarks	
	Run		#3						Dark gray shale bedrock, soft, slightly fractured horizontally along	Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % % gal	
-									thinly bedded, dense, no iron staining, core pieces range from	19.2 3 to 5.0 4.9 98 95 30	
-									(0.1-2.8').	24.2	
-										EDI Bedrock Hardness Classification	
-	v	-							24.2	Very Soft: Can be scratched with fingernail. Slight indentation	
25_									Coring completed at 24.2 ft	produced by light blow of point of geologic pick. Requires power tools for excavation.	
-										Soft: Hand-held specimen crumbles under firm blows with point of geologic pick.	
_											
-											
30_											
_											
-											
-											
35_											
-											
-											
-											
-											
40											

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code:	12K93e	Hole Number	-B3-22			Surface Elevatio	n: <u>764</u>
Projec	t Name:_	Proposed Si	ite Development	– North	ing: _	1010873	Easting:	1091970.68
Projec	t Locatio	n:	f Orchard Park, Erie County, NY				Date Started:	5/12/2022
Client:	McMaho	on & Mann Co	onsulting Engineering & Geology,	P.C			Date Completed	5/13/2022
Depth (ft)		,	Well				Remarks	
_			8-inch Road Box Installed in Con Pad	crete				
-			Cuttings Backfill					
- 5_ -			2-inch Schedule 40 FJT PVC Rise	r				
-			Bentonite Seal					
10		10.5						
-			# 00N Size Morie Sand Pack					
			0.010 Slot Screen					
-		<u>19.0</u> 19.5	Bentonite Seal					

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code: <u>12K93e</u> Hole Number <u>W-B3-</u>	22	Surface Elevation: 764			
Projec	t Name: Proposed Site Development	Northing: <u>1010873</u> Easting: <u>1091970.68</u>				
Projec	t Location:Town of Orchard Park, Erie County, NY		Date Started:			
Client:	McMahon & Mann Consulting Engineering & Geology, P.C.		Date Completed: <u>5/13/2022</u>			
Depth (ft)	Well		Remarks			
- - 25_ -	Bentonite Seal $\begin{array}{c} & & & & \\ & & & & \\ & & & & \\ \hline & & & &$					
- 30 -						
- 35_ - -						
40						

BORE CORE DEPTH (ft) LENGTH (ft) REC (ft) REC. % HOLE # RUN # DATE RQD. % BH-B3-22 BH-B3-22 BH-B3-22 5-12-22 5.0 5.0 42 1 9.2-14.2 100 2 3 5-12-22 34 14.2-19.2 5.0 5.0 100 5-12-22 4.9 98 95 19.2-24.2 5.0



Geotechnical and Environmental Drilling | Wetland Delineations and Consulting

1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u> Hole Number <u>BH-</u>	B4-22	Surface Elevation: 767.3	
Project Name: Proposed Site Development	Northing:1010835.1	Easting:	
Project Location: Town of Orchard Park, Erie County, NY	5	Date Started: <u>5/10/2022</u>	
Client: McMahon & Mann Consulting Engineering & Geology, P.	С.	Date Completed: 5/11/2022	

			Blow	Blows on Sampler								
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification		Well	Water Table and Remarks
	1	22	7	8	16	31	24		Tar and chip surface.       0.1         Mostly crushed concrete fill.       0.6         Dry brownish gray gravelly       1.4         (SAND-SILT-CLAY) fill with 20       1.4         to 40% mostly flat sided       1.4			Tar and chip surface to 0.1 feet over mostly crushed concrete fill to 0.6 feet over silty glacial till with some mostly flat sided shale stone fragments, little sand and clay to 1.4 feet over apparent shale bedrock to
-	2	15	17	31	50/3				shale stone fragments, little sand and clay, very stiff, massive soil structure, (SC),(GC). Gray to dark gray shale stone		ackfill	9.2 feet over shale bedrock to end of coring. Note: Water level at 7.0 feet below ground surface prior to coring
- 5_	3	7	36	50/3					fragments with iron staining to 4.5 feet.	<u> </u>	Cuttings B	Note: Water level at 7.0 feet below ground surface at coring completion with tooling removed from bore hole.
-	4	4	50/5									Note: Advanced bore hole with 4 1/4" ID x 8" OD hollow stem auger casing with continuous split spoon sampling to auger refusal at 9.2 feet. Removed drill rods and installed a bentonite seal. Continued below with a NQ-2 size double tubed wireline core barrel with
- 10_ -	^Run		#1						9.2 Dark gray shale bedrock, soft, very intensely to intensely fractured becoming intensely fractured below 11.5 feet, very thin to medium bedding with		11.0	diamond bit to 11.5 feet. Experienced difficult coring with water loss and hole caving. Removed coring equipment and advanced augers to 11.5 feet. Returned to rock coring below to coring completion at 39.1 feet. Core hole was backfilled with bentonite and the
-	Run		#2						occasional gray shale beds, dense, no iron staining, core breaks appear fresh, core lengths range from (0.025-0.7').	<u> </u>		remainder of the bore hole was backfilled with cuttings and ground surface repaired to match surronding conditions upon completion.
-	× Pup		#2								nite Sea	Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % % gal
15_			#3								Bento	1 to 2.3 2.1 91 0 - 11.5
-											- - -	11.5 2 to 2.9 2.6 90 0 20 14.4
-												14.4 3 to 5.0 5.0 100 23 60 19.4
-	Run		#4								, , ,	19.4 4 to 5.0 5.0 100 49 45 24.4
20			1							1/		

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93</u>e Hole Number <u>BH-B4-22</u> Surface Elevation: 767.3 Project Name: Proposed Site Development Northing: \_\_\_\_\_\_1010835.1 \_\_ Easting: <u>1092168</u> Project Location: \_\_\_\_\_\_ Town of Orchard Park, Erie County, NY **Date Completed:** <u>5/11/2022</u>

Client: McMahon & Mann Consulting Engineering & Geology, P.C.

Sampler <u>Blows on</u> Depth Rec SN Ν LITH Description and Classification Well Water Table and Remarks (ft) (in) 0/6 6/12 12/18 18/24 Dark gray shale bedrock, Run Depth Length REC REC RQD WL Run #4 soft, very thin to medium (ft) (ft) % % gal # (ft) bedding, moderately \_\_\_\_ fractured horizontally to 20.6 19.4 feet below ground surface 5.0 5.0 100 49 45 4 to becoming slightly to 24.4 moderately fractured below \_ \_ \_ with high angle fractures 24.4 from 20.7 to 21.0, 23.1 to 5 4.7 4.7 100 98 45 to 23.4, 32.8 to 33.1, and 36.0 29.1 to 36.7 feet, dense with no iron staining, limestone nodule from 25.30 to 25.45 29.1 5.0 5.0 100 86 45 6 to feet, core breaks appear 34.1 25 Run #5 fresh, core pieces range from (0.05-1.65'). 34.1 7 to 5.0 5.0 100 90 45 39.1 EDI Bedrock Hardness Classification Soft: Hand-held specimen crumbles under firm blows with point of Seal geologic pick. Bentonite Run #6 30 Run #7 35\_ 39.1 39.1 Coring completed at 39.1 ft 40



## **BUFFALO BILLS STADIUM**

PROJECT NO. 22-011

BORE HOLE #	CORE RUN #	DATE	DEPTH (ft)	LENGTH (ft)	REC (ft)	REC. %	RQD. %
BH-B4-22	6	5-11-22	29.1-34.1	5.0	5.0	100	86
BH-B4-22	7	5-11-22	34.1-39.1	5.0	5.0	100	90



Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u> Hole Number <u>BH-</u>	-B5-22	Surface Elevation: <u>767.4</u>
Project Name: Proposed Site Development	Northing:	6 <b>Easting:</b> <u>1092364</u>
Project Location: Town of Orchard Park, Erie County, NY	2	Date Started:
Client: McMahon & Mann Consulting Engineering & Geology, P	.C.	Date Completed: <u>5/10/2022</u>

			Blow	s on	Sam	pler						
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	Ν	LITH	Description and Classification		Well	Water Table and Remarks
	1	16	5	8	15	10/24	23		Tar and chip surface. Mostly crushed concrete fill. Dry brown gravelly (SILTY-SAND) with 20 to			Tar and chip surface to 0.1 feet over mostly crushed concrete fill to 0.4 feet over sandy glacial till with some mostly flat sided shale stone fragments, little silt to 1.5 feet over
-	2	21	20	22	40		62		40% mostly flat sided shale stone fragments, little silt, compact, massive soil structure, (SM),(GM). Gray and dark brown shale stone fragments, very soft to			apparent shale bedrock to 15.2 feet over shale bedrock to end of coring.
5_	3	11	29	50/5					soft.	<u>-</u> - - - - - - - - - - - - - - - - - -		
_	4	18	18	19	41	50/4	60					Note: Water level at 7.0 feet below ground surface prior to coring.
-	5	4	50/5								ings Backfill	Note: Water level at 6.0 feet below ground surface at coring completion with tooling removed from bore hole.
-	6	22	16	19	29	20	48			·	Cutt	Note: Advanced bore hole with 4 1/4" ID x 8" OD hollow stem auger casing with continuous split spoon sampling to auger refusal at 15.2 feet. Removed drill rods and installed a bentonite seal. Continued
-	7	20	12	20	22	50/5						below with a NQ-2 size double tubed wireline core barrel with diamond bit to end of coring at 25.0 feet. Core hole was backfilled with bentonite and the remainder of the bore hole was backfilled with cuttings and
15_	8	7	27	50/1					15.2		15.0	ground surface repaired to match surrounding conditions upon completion.
-	Run		#1						Dark gray shale bedrock, soft, intensely fractured, very thin to thinly bedded. dense.			Run Depth Length RFC RFC ROD WI
									no iron staining, core breaks appear fresh, core pieces		Seal	# (ft) (ft) (ft) % % gal
-									range from (0.025-0.6').	ראראראראר	Bentonite	15.2 1 to 4.8 4.8 100 12 15 20.0
20	$\downarrow$								20.0	k		

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI J	ob Co	ode:	12K	(93e			Но	ole Nu	Imber BH-B5-22			Surfa	ce Elevation: <u>767.4</u>			
Proje	ct Na	ame:	Prop	osed S	Site De	evelop	ment		Northin	g: <u>1010796</u>	5	Easting:1092364				
Proje	ct Lo	catio	on:	Town c	of Orch	nard Pa	ark, E	rie Co	unty, NY			Date Started:				
Clien	t:M	cMah	on & I	Mann C	Consult	ting Er	ginee	ering 8	& Geology, P.C.			Date	<b>Completed:</b> <u>5/10/2022</u>			
			Blow	s on	Sam	nler										
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classi	fication		Well	Water Table and Remarks			
(ft) - - - - - - - - - - - - - - - - - - -	Run		0/6 #2	6/12					Dark gray with occasio beds of gray shale bed soft, intensely to mode fractured to moderately fractured horizontally a bedding planes with hig angle to almost vertica fractures from 20.5 to and 23.0 to 23.4 feet, thin to medium bedding dense, no iron staining breaks appear fresh, co pieces range from (0.025-0.9'). Coring completed at 25	nal rock, rately / long jh 21.2 very J, , core pre 25 ft	20 <u>(1)(1)(1)(1)(1)(1)(1)(1)(1)</u>	Bentonite Seal	Run Depth Length REC REC RQD WL         # (ft) (ft) (ft) % % gal         20.0         2 to 5.0 5.0 100 60 35         25.0			
- 35_ - - - - 40							-									





EARTH DIMENSIONS, INC. Geotechnical and Environmental Drilling | Wetland Delineations and Consulting

1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u> Hol	e Number <u>BH-B6-22</u>	Surface Elevation: <u>766</u>
Project Name: Proposed Site Development	Northing:101080	D Easting:
Project Location: Town of Orchard Park, Er	ie County, NY	Date Started:5/11/2022
Client: McMahon & Mann Consulting Engineer	ing & Geology, P.C.	Date Completed: <u>5/12/2022</u>

			Blow	s on	Sam	nler	Í –			
Depth	SN	Rec	BIOW		<u>5an</u>		Ν	LITH	Description and Classification	Water Table and Remarks
(11)		(11)	0/6	6/12	12/18	18/24				
	1		4						Tar and chip surface.	Tar and chip surface to 0.1 feet over
_		15		9			16		Mostly crushed concrete fill.	feet over coarse silty soil fill with
					7			201	Dry gray gravelly (SANDY-SILT) fill	some gravel and flat sided shale
-						8			$  \  $ shale stone fragments, some sand, $  \frac{2.0}{2.0}  $	silty soil fill with little to some gravel
	2		20					0.0.0	Compact, massive soil structure,	and flat sided shale stone fragments,
-		22		22			41	0.0	Dry light gravish brown gravelly	feet over shaley glacial till with some
					19			0.00	(SANDY-SILT) fill with 15 to 25%	sand, little silt, trace clay to 9.3 feet over apparent shale bedrock to 10.9
-						21		P.O. 0	gravel and flat sided shale stone	feet over shale bedrock to end of
	3		12					0 (	clay, massive soil structure, (ML-CL).	coring.
5_		20		11	16		27		Dry, moist below 5.0 feet, dark gray	
					10			0. (	50% mostly flat sided shale stone	
-			17			24			fragments, little silt, trace clay,	Note: Advanced bore hole with 4
	4	17	16	10				60 (	structure, (SM),(GM).	1/4" ID x 8" OD hollow stem auger
-		1/		10	15		31	0.00		sampling to auger refusal at 10.9
						21		000		feet. Removed drill rods and installed a bentonite seal. Continued
_	5		11					$\circ$		below with a NQ-2 size double
_		19		22			47	0.0		diamond bit to end of coring at 25.9
					25		<b>,</b> ''		9.3 Grav shale stone fragments verv	feet. Reamed core hole with a 3 7/8"
10_						50/3			soft to soft.	2-inch PVC standpipe piezometer to
	6		50/3							18.5 feet in completed bore hole.
-	<sup>↑</sup> Run	2	#1					==	Grav limev shale bedrock	
									effervesces without etching, thinly	
-									\laminated, slightly porous, single /	
								<u> </u>	Dark gray shale bedrock, soft, very	
-								<u></u>	intensely to intensely fractured to	
								<u></u>	thinly laminated to thinly bedded,	
-							1	<u> </u>	dense, no iron staining, core breaks appear fresh, core pieces range from	
15.								<u> </u>	(0.025-0.65').	
										Run Depth Length REC REC RQD WL
_	¥							<u> </u>		π (it) (it) 70 70 gai
	Run		#2					<u> </u>		10.9 1 to 5.0 4.8 96 23 35
-								<u> </u>		15.9
								<u> </u>		15.9
-									18.2	2 to 5.0 5.0 100 59 35
										20.9
-								<u> </u>		
20								<u> </u>	See next sheet	
	LL	1				1	I	F		

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>	Hole Number <u>BH-B6-22</u>	Surface Elevation:
Project Name: Proposed Site Develo	pment Northing: _101	10800 <b>Easting:</b> <u>1092569</u>
Project Location: Town of Orchard I	Park, Erie County, NY	Date Started:
Client: McMahon & Mann Consulting E	ngineering & Geology, P.C.	Date Completed: <u>5/12/2022</u>

			Blows on Sampler		Blows on Sampler									
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	Ν	LITH	Description and Classification	Water Table and Remarks				
	Run		#2						Dark gray with occasional gray layers of shale bedrock, soft,	Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % % gal				
-	Run		#3						fractured horizontally along bedding planes with a vertical fracture from	15.9 2 to 5.0 5.0 100 59 35 20 9				
-									soft shale bed at 20.6 feet, dense, core breaks appear fresh, no iron	20.9 3 to 5.0 5.0 100 70 30				
-									staining, core pieces range from (0.2-1.5').	25.9 EDI Bedrock Hardness Classification				
25_										Very Soft: Can be scratched with				
-	<u> </u>	-							25.9 Coring completed at 25.9 ft	produced by light blow of point of geologic pick. Requires power tools for excavation.				
- - 30_ - -									Completed at 23.9 ft	for excavation. Soft: Hand-held specimen crumbles under firm blows with point of geologic pick.				
35_														
-														
40														

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code:	12K93e	Hole Number	/-B6-22	_		Surface Elevation	n: <u>766</u>
Project	t Name:_	Proposed Si	ite Development	_ Nor	thing: _	1010800	Easting:	1092569
Project	t Locatio	n:	Orchard Park, Erie County, NY				Date Started:	5/11/2022
Client:	McMaho	on & Mann Co	onsulting Engineering & Geology,	P.C.			Date Completed:	5/12/2022
Depth (ft)		,	Well				Remarks	
-			8-inch Road Box Installed in Cor Pad Cuttings Backfill	ncrete				
5				-1				
10_ - - -			Bentonite Seal					
		18.5	0.010 Slot Screen					
20			Bentonite Seal					

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code: <u>12K93e</u> Hole Number <u>W-B6-</u>	22	Surface Elevation:
Projec	t Name: Proposed Site Development	Northing: <u>1010800</u>	<b>Easting:</b> <u>1092569</u>
Projec	t Location:Town of Orchard Park, Erie County, NY		Date Started:
Client:	McMahon & Mann Consulting Engineering & Geology, P.C.		Date Completed: <u>5/12/2022</u>
Depth (ft)	Well		Remarks
	Bentonite Seal		
- 30_ -			
- 35_ - -			
40			



Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u> Hole Number <u>B</u>	BH-C2-22	Surface Elevation:
Project Name: Proposed Site Development	Northing:1010715	Easting:
Project Location: Town of Orchard Park, Erie County, NY	-	Date Started: <u>4/22/2022</u>
Client: McMahon & Mann Consulting Engineering & Geology,	P.C.	Date Completed:

		_	Blows on Sampler											
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification		Well	Water Table and I	Remarks	;
	1	6	1	3	3	9	6		Wet to moist dark brown (SANDY-SILT) topsoil fill with 0.7 0 to 3% gravel, little sand, trace to little organic matter, very loose, weakly granular soil structure, (ML).			Coarse silty topsoil fill v sand, trace to little org- trace gravel to 0.7 feet silty galcial till with som flat sided shale stone fr little sand, trace clay to	with little anic mat over co ne grave ragments o 4.6 fee	e ter, arse I and S, t over
-	2	20	6	9	12	14	21		Moist to dry brown and grayish brown (SANDY-SILT) with 20 to 40% mostly flat sided shale stone fragments, little sand, trace clay,		3ackfill	apparent shale bedrock over shale bedrock to e	to 8.6 f	eet oring.
5_	3	11	16	50/5					compact, dense below 3.5 feet, massive soil structure, (SM),(GM). Gray shale stone fragments, very soft to soft.		Cuttings E	Note: No water in bore taking sample number at 4.0 feet below groun after taking sample nur	hole pri 4. Watei id surfac nber 4.	or to - level :e
_	4	з	50/4									Note: Water level at 3.4 ground surface prior to Note: Water level at 3.1 ground surface at corin with tooling removed fr	4 feet be coring. 0 feet be g compl	elow elow etion
_	5		50/2						8.6	2 2 2 4		hole.		
	^Run  Run	2	#1				-		Dark gray shale bedrock, soft, very intensely to intensely fractured below 10.0 feet, very thin to medium bedding, dense, no iron staining, core breaks appear fresh, core pieces range from (0.025-0.4').	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	entonite Seal	Note: Advanced bore h 1/4" ID x 8" OD hollow casing with continuous sampling to auger refus feet. Continued below v size double tubed wirel barrel with diamond bit coring at 23.7 feet. Co backfilled with bentonit remainder of the bore f backfilled with cuttings surface repaired to mat surrounding conditions completion.	ole with stem au split spoc sal at 8.0 with a N0 ine core to end re hole and th hole was and gro tch upon	4 Jger 5 Q-2 of was e und
-											B	# (ft) (ft) (ft)	% %	gal
-									16.9			1 to 5.0 4.9 13.9	98 0	20
-												13.9 2 to 4.8 4.8 1 18.7	LOO 45	30
20	Run		#3						See next sheet			18.7 3 to 5.0 5.0 1 23.7	LOO 77	30

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

Project Name:         Project Location:         Town of Orchard Park, Erie County, NY         Date State(s):         (101715         Easting:         (101726           Project Location:         Town of Orchard Park, Erie County, NY         Date State(s):         /////22222         Date Completed:         ////22222           Deck         Minima & Mann Consulting Engineering & Geology, P.C.         Date Completed:         ////22222           Deck         Minima & Mann Consulting Engineering & Geology, P.C.         Date Completed:         ////22222           Deck         Minima & Mann Consulting Engineering & Geology, P.C.         Dark State(State)         Well         Water Table and Remarks           Minima & Mann Consulting Engineering & Geology, P.C.         Dark state(State)         Well         Water Table and Remarks           Minima & Mann Consulting Engineering & Geology, P.C.         Dark gray shale bedrock;         Soft, Indepative fractured from 19.1 to 19.8         Feet and a high angle fractured from 19.1 to 19.8           Fracture Fish, Core picces         23.7         Soft, Indepative fractured from 19.1 to 19.8         Feet and a high angle fractured from 19.1 to 19.8         Feet and a high angle fracture from 19.2 to 19.8           25-         Image from 10.2 -1.0 //.         Coring completed at 23.7 ft         Viscoff Core picce fracture fractu	EDI J	ob Co	ode:	_12K	93e			Но	ole N	umber <u>BH-C2-22</u>	Surfa	ace Elevation: <u>758.9</u>
Project Location: Turn of Orchard Park, Eric Courty, NY       Date Strated: 4/22/2022	Proje	ct Na	ame:	Prop	osed S	Site De	evelop	ment		<b>Northing:</b> <u>1010715</u>		Easting:
Citent:     McMahon 8. Mann Consulting Engineering 8. Geology, P.C.     Date Completed:     4/22/2022       Depth (1)     N     Ron     4000000000000000000000000000000000000	Proje	ct Lo	catio	on:	Town o	of Orch	nard Pa	ark, E	rie C	ounty, NY	Date	Started:
Deputi (ft)         SN         Rec (n)         Blows         or         Sampler         N         LITH         Description and Classification         Well         Water Table and Remarks           Run         #3	Clien	t: <u>M</u>	cMah	on & I	Mann C	Consult	ing En	ginee	ering	& Geology, P.C.	Date	Completed: <u>4/22/2022</u>
Run       #3	Depth (ft)	SN	Rec (in)	<u>Blow</u>	s on	Sam	18/24	N	LITH	Description and Classification	Well	Water Table and Remarks
10	(ft) 	Run		0/6 #3	6/12					Description and classification Dark gray shale bedrock, soft, moderately fractured horizontally along bedding planes with a near vertical fracture from 19.1 to 19.8 feet and a high angle fracture from 19.8 to 20.0 feet, very thin to thinly bedded, dense, no iron staining, core breaks appear fresh, core pieces range from (0.2-1.0'). Coring completed at 23.7 ft 23.7		Run Depth Length REC REC RQD WL         # (ft) (ft) (ft) % % gal         18.7         3 to 5.0 5.0 100 77 30         23.7         EDI Bedrock Hardness Classification         Very Soft: Can be scratched with fingernail. Slight indentation produced by light blow of point of geologic pick. Requires power tools for excavation.         Soft: Hand-held specimen crumbles under firm blows with point of geologic pick.
	40											



Geotechnical and Environmental Drilling | Wetland Delineations and Consulting

1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>	Hole Number <u>BH-C3-22</u>	Sur	face Elevation: 762.6
Project Name: Proposed Site Develo	pment No	rthing:	Easting:
Project Location: Town of Orchard	Park, Erie County, NY	Dat	e Started: <u>4/25/2022</u>
Client: McMahon & Mann Consulting	Engineering & Geology, P.C.	Dat	e Completed: <u>4/25/2022</u>

<b>.</b>		D	Blow	Sam	pler					
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	Water Table and Remarks
	1	16	2	3	4	8	7		Moist dark brown (SANDY-SILT) 0.4 topsoil fill with 0 to 3% gravel, little sand, trace to little organic matter, very loose, granular soil structure, (ML).	Coarse silty topsoil fill with little sand, trace to little organic matter, trace gravel to 0.4 feet over silty soil fill with little sand and clay, trace to little flat sided shale stone fragments to 0.8 feet over coarse silty
-	2	21	9	12	23	36	35		Moist to dry brown (SAND-SILT-CLAY) fill with 5 to 15% flat sided shale stone fragments, little sand and clay, trace organic matter, firm, massive soil structure, (ML-CL).	slackwater sediment with little sand, trace clay to 1.8 feet over shaley glacial till with little sand to 6.5 feet over apparent shale bedrock to 18.2 feet over shale bedrock to end of coring.
5_	3	18	36	33	25	24	58		Moist brown (SANDY-SILT) with little mostly fine size sand, trace clay, loose, blocky soil structure, (ML). Dry to moist brownish gray shaley (SANDY-SILT) with 40 to 60%	
_	4	24	21	25	40	29	65		mostly flat sided shale stone fragments, little sand, dense, very dense below 4.0 feet, massive soil structure, (SM),(GM). Gray shale stone fragments, very	Note: No water in bore hole prior to taking sample number 5. Water level at 4.0 feet below ground surface.
- 10	5	18	17	21	23	13	44		sort to sort, wet below 7.5 feet.	Note: Water level at 6.5 feet in bore hole prior to coring. Note: Water level at 7.2 feet below ground surface at coring completion with tooling removed and hole sitting
-	6	15	12	19	12	13	31			idle for 45 minutes.
-	7	24	24	31	35	23	66			Note: Advanced bore hole with 4 1/4" ID x 8" OD hollow stem auger casing with continuous split spoon sampling to 18.2 feet. Removed drill rods and installed a bentonite seal. Continued below with a NQ-2 size
15_	8	20	16	12	12	8	24			double tubed wireline core barrel with diamond bit to coring completion at 27.2 feet. Core hole was backfilled with bentonite and a 2-inch PVC standpipe piezometer was installed to 18.0 feet in
-	9	9	12	50/3					18.2	Completed bore hole.
20	<sup>1</sup> Run		#1						See next sheet	#       (ft)       (ft)       %       gal         18.2         1       to       4.0       3.9       98       75       0         22.2       22.2       22.2       23       24       24       24       24       25       24       24       24       24       24       24       24       24       24       24       25       25       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24       24

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>	Hole Number <u>BH-C3-22</u>	Surface Elevation: <u>762.6</u>
Project Name: Proposed Site Developm	ent Northing:	1010677 <b>Easting:</b> 1091933
Project Location: Town of Orchard Par	k, Erie County, NY	Date Started:
Client: McMahon & Mann Consulting Eng	ineering & Geology, P.C.	Date Completed: <u>4/25/2022</u>

		<b>_</b>	Blows	s on	Sam	pler				
Deptn (ft)	SN	KeC					N	LITH	Description and Classification	Water Table and Remarks
(11)		(11)	0/6	6/12	12/18	18/24				
									Dark gray shale hadreek, soft	Due Doeth Longth DEC DEC DOD WI
	Run		#1						intensely to moderately fractured	# (ft) (ft) (ft) % % gal
_									horizontally along bedding planes.	# (it) (it) it) it gai
									moderately fractured horizontally	18.2
									below 22.5 feet, thin to medium	1 to 4.0 3.9 98 75 0
-	V								bedding, dense, core breaks appear	22.2
	1								fresh, core pieces range from	
_	Kun		#2						(0.05-1.5).	22.2
										2 10 5.0 5.0 100 87 0
										2712
-										
25										
-										EDI Bedrock Hardness Classification
-									27.2	Very Soft: Can be scratched with
		1							Coring completed at 27.2 ft	produced by light blow of point of
									5 5 F F F F F F F F F F F F F F F F F F	aeologic pick. Requires power tools
_										for excavation.
-										Soft: Hand-held specimen crumbles
										under firm blows with point of
30_										geologic pick.
-										
-										
-										
35_										
-										
-										
_										
40										

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code:	12K93e	Hole NumberV	V-C3-22			Surface Elevatio	n: <u>762.6</u>
Project	t Name:_	Proposed Si	te Development	No	thing: _	1010677	Easting:	1091933
Project	t Locatio	n: Town of	Orchard Park, Erie County, NY	_			Date Started:	l/25/2022
Client:	McMaho	n & Mann Co	nsulting Engineering & Geology,	, P.C.			Date Completed:	4/25/2022
Depth (ft)		١	Well				Remarks	
_			8-inch Road Box Installed in Co Pad	ncrete				
-		$\begin{array}{c} \cdot & \cdot \\ \bullet & \bullet \\$	Cuttings Backfill	or				
5_				e				
- - - - -		8.0	Bentonite Seal					
10_		10.0						
- - - - - - - - - - - - - - - - - - -			#00N Size Morie Sand Pack					
			0.010 Slot Screen					
-		18.0	Bentonite Seal					

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code: <u>12K93e</u> Hole Number <u>W-C3-22</u>	Surface Elevation: 762.6
Projec	t Name: <sup>Proposed</sup> Site Development N	orthing: <u>1010677</u> Easting: <u>1091933</u>
Projec	t Location:Town of Orchard Park, Erie County, NY	Date Started: <u>4/25/2022</u>
Client:	McMahon & Mann Consulting Engineering & Geology, P.C.	Date Completed: <u>4/25/2022</u>
Depth (ft)	Well	Remarks
 - 25 - -	Bentonite Seal	
- 30_ -		
- - 35_ - -		
40		

BORE HOLE #	CORE RUN #	DATE	DEPTH (ft)	LENGTH (ft)	REC (ft)	REC. %	RQD. %
BH-C3-22	1	4-25-22	18.2-22.2	4.0	3.9	98	75
BH-C3-22	2	4-25-22	22.2-27.2	5.0	5.0	100	87



Geotechnical and Environmental Drilling | Wetland Delineations and Consulting

1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u> Hole Nu	Imber <u>BH-C4-22</u>	Surface Elevation: <u>762.2</u>
Project Name: Proposed Site Development	Northing:1010638	Easting:
Project Location: Town of Orchard Park, Erie Co	unty, NY	Date Started: <u>5/5/2022</u>
Client: McMahon & Mann Consulting Engineering &	k Geology, P.C.	Date Completed: 5/5/2022

			Blows on Sampler								
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	Well	Water Table and Remarks
	1	17	7	8	10	14	18		Tar and chip surface.     0.       Mostly crushed concrete fill.     0.       Moist dark brownish gray     1.       gravelly (SAND-SILT-CLAY)     fill with 15 to 25% mostly flat	e Grout	Tar and chip surface to 0.1 feet over mostly crushed concrete fill to 0.6 feet over silty soil fill with little to some mostly flat sided stone fragments, little sand, trace to little clay to 1.3 feet over shaley soil fill
-	2	24	12	29	35	41	64		sided shale stone fragments, little sand, trace to little clay, very stiff, massive soil structure, (ML-CL).	in the sectorit	with some sand, little silt to 4.3 feet over water sorted and deposited sand with some flat sided shale stone fragments, little silt to 7.0 feet over coarse silty glacial till with some sand and flat sided stopp
5_	3	16	14	10	7	7	17		brown gravelly (SILTY-SAND) 4. fill with 30 to 50% flat sided shale stone fragments, little silt, very dense, massive soil structure, (SM),(GM).	Cen	fragments to 9.0 feet over apparent shale bedrock to 11.0 feet over shale bedrock to end of coring.
-	4	21	7	12	21	27	33		Wet gray and brown mixed gravelly (SILTY-SAND) with 20 to 40% mostly flat sided shale stone fragments, little silt, compact, weakly stratified, massive soil structure (SM) (GM)		Note: Advanced bore hole with 4 1/4" ID x 8" OD hollow stem auger casing with continuous split spoon
- 10_	5	24	14	27	21	22	48		Moist to dry gray gravelly (SANDY-SILT) with 20 to 1 40% mostly flat sided shale 1 stone fragments, some sand, 1 dense, massive soil structure,		sampling to auger refusal at 11.0 feet. Removed drill rods and installed a bentonite seal. Continued below with a NQ-2 size double tubed wireline core barrel with diamond bit to end of coring at 26.0 feet. Core
-	6 ∱Run	8	25 #1	_50/3_					Gray shale stone fragments, very soft to soft.	0 <u>11.0</u>	hole was backfilled with bentonite and the remainder of the bore hole was backfilled with cuttings and ground surface repaired to match surrounding conditions upon
-									Dark gray shale bedrock, soft, intensely fractured, intensely to moderately fractured below 13.9 feet, very thin to thinly bedded, dense, no iron staining, core breaks appear fresh, core	<u> </u>	Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % % gal 
15_	¥								(0.025-0.75').	Bento	16.0 2 to 5.0 4.9 98 42 30
-	( `Run		#2								21.0
-									19. See next sheet		
20										11	

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI J	ob C	ode:	12k	(93e			Но	ole N	umber <u>BH-C4-22</u>	Sur	face Elevation: <u>762.2</u>					
Proje	ct Na	ame:	Prop	bosed S	Site De	evelop	ment		Northing:1010638		Easting:					
Project Location: Town of Orchard Park,								rie C	ounty, NY	Started: 5/5/2022						
Clien	t:M	cMah	on & I	Mann C	Consult	ing En	iginee	ering	& Geology, P.C.	Dat	e Completed: <u>5/5/2022</u>					
			Blow	s on	Sam	pler										
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	Well	Water Table and Remarks					
	Run		#2						Dark gray shale bedrock, soft, moderately to moderately to slightly fractured herizentally along		Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % % gal					
_	Run		#3						bedding planes with a short vertical fracture from 21.35 to 21.45 and short high angle		2 to 5.0 4.9 98 42 30 21.0					
-									to 21.45 and snort high angle fracture from 23.05 to 23.15 feet, very thin to thinly bedded, no iron staining, core breaks appear fresh, core		21.0 3 to 5.0 5.0 100 77 30 26.0					
25_									(0.35-2.05').	UNUN Ben						
-	$\downarrow$								26.	0 26.0	) EDI Badwadi Hardraan Classification					
									Coring completed at 26 ft		Very Soft: Can be scratched with fingernail. Slight indentation produced by light blow of point of geologic pick. Requires power tools for excavation. Soft: Hand-held specimen crumbles under firm blows with point of geologic pick.					

# **BUFFALO BILLS STADIUM**

PROJECT NO. 22-011



Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u> Hole Number <u>BH-0</u>	<u>Surface Elevation: 762.5</u>	
Project Name: Proposed Site Development	Northing:1010600 Easting:1092325	
Project Location: Town of Orchard Park, Erie County, NY	Date Started: 4/26/2022	
Client: McMahon & Mann Consulting Engineering & Geology, P.	<b>Date Completed:</b> <u>4/27/202</u>	2

	SN	D	Blows on Sampler												
Depth (ft)		Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	Water Table and Remarks					
	1	20	8	6	8	6	14		Tar and chip surface. Mostly crushed concrete fill. Moist to dry brownish gray to grayish brown gravelly (SANDY-SILT) with 15 to 25% gravel	Tar and chip surface to 0.1 feet over mostly crushed concrete fill to 0.7 feet over coarse silty glacial drift with little to some gravel and flat sided shale stone fragments, little sand, trace clay to 4.4 feet over					
-	2	24	9	6	8	7	14		and flat sided shale stone fragments, little sand, trace clay, compact, massive soil structure, (ML). 4 Moist brownish gray (SILTY-SAND) with mostly fine to medium size sand, trace to little silt, loose, thinly bedded, (SM). Moist brown to olive brown (SAND-SILT-CLAY) with little mostly (SAND-SILT-CLAY) with little mostly (SAND-SILT-CLAY) with little mostly (SAND-SILT-CLAY) with little mostly (ML-CL).	water sorted and deposited sand with trace to little silt to 5.3 feet over silty slackwater sediment with little sand and clay to 6.0 feet over water sorted and deposited coarse silt with little sand and clay to 7.0					
5_	3	21	5	5	4	4	9	0		reet over coarse silty glacial till with some flat sided shale stone fragments, little sand, trace clay to 9.0 feet over apparent shale bedrock to 13.8 feet over shale bedrock to 22.7 feet over limey shale bedrock					
-	4	14	2	2	5	9	7			to 23.6 feet over shale bedrock to end of coring. Note: No water in bore hole prior to taking sample number 4. Water					
- 10_	5	20	7	18	32	25	50		Wet light grayish brown (SAND-SILT-CLAY) with 5 to 15% gravel and flat sided shale stone fragments, little sand and clay, soft,	Note: Water level at 6.5 feet below ground surface prior to coring.					
	6	15	20	22	50/5				Meakly thinly bedded, (ML-CL).	Note: Advanced bore hole with 4 1/4" ID x 8" OD hollow stem auger casing with continuous split spoon sampling to auger refusal at 13.8 feet. Removed drill rods and installed a bentonite seal. Continued					
_	7	3	50/4						trace clay, compact, massive soil structure, (ML). Gray shale stone fragments, very soft to soft.	below with a NQ-2 size double tubed wireline core barrel with diamond bit to coring completion at 42.1 feet. Reamed core hole with a 3 7/8" tricone roller bit and installed a					
- 15_	Run		#1						Dark gray shale bedrock, soft, very intensely to intensely fractured horizontally along bedding planes, thinly bedded, dense, no iron staining, core breaks appear fresh, core pieces range from (0.025-0.25'). 163	2-inch PVC standpipe piezometer to 34.5 feet in completed bore hole.					
-	Run		#2						Dark gray shale bedrock, soft, intensely to moderately fractured horizontally along bedding planes, thinly bedded, dense, no iron staining, core breaks appear fresh, core pieces range from (0.1-0.8').	$\begin{array}{c}  (ft) beptil length keeke k$					
20										22.3					

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>	Hole Number <u>BH-C5-22</u>	Surface Elevation: <u>762.5</u>
Project Name: Proposed Site Developm	ent Northing:10106	00 <b>Easting:</b> <u>1092325</u>
Project Location: Town of Orchard Par	k, Erie County, NY	Date Started: <u>4/26/2022</u>
Client: McMahon & Mann Consulting Eng	ineering & Geology, P.C.	Date Completed: <u>4/27/2022</u>

Donth		Doc	Blows	s on	Sam	pler											
(ft)	SN	(in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification		Water Table and Remarks						
	Run		#2						Dark gray shale bedrock, soft, intensely to moderately fractured borizontally along bedding planes	Run #	Depth (ft)	Lengt (ft)	th RE (ft)	C REC	RQD %	WL gal	
-									thinly bedded, dense, no iron staining, core breaks appear fresh, core pieces range from (0.1-0.8').	2	17.3 to 22.3	5.0	5.0	100	78	0	
	Run		#3						Light gray limey shale bedrock, effervesces without etching, moderately soft to moderately hard, non-fractured, very thin to thinly bedded, slightly porous with gypsum nodules.	3	22.3 to 27.3	5.0	4.9	98	88	0	
										4	27.3 to 32.1	4.8	4.8	100	82	0	
25_									Dark gray shale bedrock, soft, moderately to slightly fractured horizontally along bedding planes with a biob social fracture from 27.0	 5	32.1 to 37.1	5.0	4.9	98	75	0	
-	¥								to 28.3 feet, thinly bedded, dense, no iron staining, core breaks appear fresh, core pieces range from	 6	37.1 to	5.0	5.0	100	100	0	
_	Run		#4						(0.5-1.6').		72.1						
- 30_																	
_																	
									32.1								
_	Run		#5						Dark gray shale bedrock, soft, intensely to intensely to moderately fractured horizontally and at high angles, thinly bedded, dense, no iron								
-									staining, core pieces range from (0, 1-0, 6') 34.2								
35_									Dark gray shale bedrock, soft, very slightly fractured horizontally along bedding planes, thinly laminated to								
									thinly bedded, dense, no iron staining, with occasional thin pyrite								
-									deposits, core pieces range from (1.6-3.4').								
	Run		#6														
-																	
_40																	
Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>	Hole Number <u>BH-C5-22</u>	Surface Elevation: <u>762.5</u>
Project Name: Proposed Site Developm	ent Northing: <u>101</u>	0600 <b>Easting:</b> <u>1092325</u>
Project Location: Town of Orchard Par	k, Erie County, NY	Date Started: <u>4/26/2022</u>
Client: McMahon & Mann Consulting Eng	ineering & Geology, P.C.	Date Completed: <u>4/27/2022</u>

			Blows on Sampler									
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	Water Table and Remarks		
	Run		#6						Dark gray shale bedrock, soft, very slightly fractured horizontally along bedding planes, thinly laminated to thinly bedded, dense, no iron staining, with occasional thin pyrite deposits, core pieces range from 42.1	Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % % gal 		
_									Coring completed at 42.1 ft			
- 45_ -										EDI Bedrock Hardness Classification Very Soft: Can be scratched with fingernail. Slight indentation produced by light blow of point of geologic pick. Requires power tools for excavation.		
-										Soft: Hand-held specimen crumbles under firm blows with point of geologic pick.		
- 50 -										Moderately Soft: Shallow indentations (0.04 to 0.12 inch (1 to 3 mm)) can be made by firm blows with point of geologic pick. Can be peeled with pocket knife with difficulty.		
-										Moderately Hard: Cannot be peeled or scraped with knife. Can be distinctly scratched with a steel nail.		
55_												
-												
-												

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code:	12K93e Hole Number <u>W-C5-22</u>	Surface Elevation: 762.5
Projec	t Name:_	Proposed Site Development Northing: <u>101</u>	0600 <b>Easting:</b> <u>1092325</u>
Projec	t Locatio	n: Town of Orchard Park, Erie County, NY	Date Started: <u>4/26/2022</u>
Client:	McMaho	on & Mann Consulting Engineering & Geology, P.C.	Date Completed: <u>4/27/2022</u>
Depth (ft)		Well	Remarks
	>		
	2 4	8-inch Road Box Installed in Concrete	
-	$ \xrightarrow{1}{1} \xrightarrow{1} \xrightarrow$	$  \geq 1.0$ Pad	
-			
-			
		Cuttings Backfill	
5_			
-			
-			
-		2-inch Schedule 40 FJT PVC Riser	
-			
10_			
-			
-			
-			
-			
15_			
-			
-			
-			
-	()		
20	조죄	Bentonite Seal	

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code: <u>12K93e</u> Hole Number <u>W-C</u>	5-22	Surface Elevation: <u>762.5</u>
Project	t Name: Proposed Site Development	Northing:	1010600 Easting: 1092325
Project	t Location: Town of Orchard Park, Erie County, NY		Date Started: <u>4/26/2022</u>
Client:	McMahon & Mann Consulting Engineering & Geology, P.C	<u>.                                    </u>	<b>Date Completed:</b> <u>4/27/2022</u>
Depth (ft)	Well		Remarks
25_	20.5       Bentonite Seal         2-inch Schedule 40 FJT PVC Riser         21.5         #00N Size Morie Sand Pack         0.010 Slot Screen		
30			
35	34.5 35.0 Bentonite Seal		
40	$ \begin{array}{c} a & a & a & a & a \\ \hline & 1 & a & a & a & a \\ \hline & 1 & a & a & a & a \\ \hline & a & a & a & a & a \\ \hline & 1 & a & a & a & a \\ \hline & 1 & a & a & a & a \\ \hline & 1 & a & a & a & a \\ \hline & 1 & a & a & a & a \\ \hline & 1 & a & a & a & a \\ \hline & 1 & a & a & a & a \\ \hline & 1 & a & a & a & a \\ \hline & 1 & a & a & a & a \\ \hline & 1 & a & a & a & a \\ \hline & 1 & a & a & a & a \\ \hline & 1 & a & a & a & a \\ \hline & 1 & a & a & a & a \\ \hline & 1 & a & a & a & a \\ \hline & 1 & a & a & a & a \\ \hline & 1 & a & a & a & a \\ \hline & 1 & a & a & a & a \\ \hline & 1 & a & a & a & a \\ \hline & 1 & a & a & a & a \\ \hline & 1 & a & a & a & a \\ \hline & 1 & a & a & a & a \\ \hline & 1 & a & a & a & a \\ \hline & 1 & a & a & a & a \\ \hline & 1 & a & a & a & a \\ \hline & 1 & a & a & a & a \\ \hline & 1 & a & a & a & a \\ \hline & 1 & a & a & a & a \\ \hline & 1 & a & a & a & a \\ \hline & 1 & a & a & a & a \\ \hline & 1 & a & a & a & a \\ \hline & 1 & 1 & a & a & a \\ \hline & 1 & 1 & 1 & a \\ \hline & 1 & 1 & 1 & a \\ \hline & 1 & 1 & 1 & a \\ \hline & 1 & 1 & 1 & a \\ \hline & 1 & 1 & 1 & a \\ \hline & 1 & 1 & 1 & 1 \\ \hline & 1 & 1 & 1 & 1 \\ \hline & 1 & 1 & 1 & 1 \\ \hline & 1 & 1 & 1 & 1 \\ \hline & 1 & 1 & 1 & 1 \\ \hline & 1 & 1 & 1 & 1 \\ \hline & 1 & 1 & 1 & 1 \\ \hline & 1 & 1 & 1 & 1 \\ \hline & 1 & 1 & 1 & 1 \\ \hline & 1 & 1 & 1 & 1 \\ \hline & 1 & 1 & 1 & 1 \\ \hline & 1 & 1 & 1 & 1 \\ \hline & 1 & 1 & 1 & 1 \\ \hline & 1 & 1 & 1 & 1 \\ \hline & 1 & 1 & 1 & 1 \\ \hline & 1 & 1 & 1 & 1 \\ \hline & 1 & 1 & 1 & 1 \\ \hline & 1 & 1 & 1 & 1 \\ \hline & 1 & 1 & 1 & 1 \\ \hline & 1 & 1 & 1 & 1 \\ \hline & 1 & 1 & 1 & 1 \\ \hline & 1 & 1 & 1 & 1 \\ \hline & 1 & 1 & 1 & 1 \\ \hline & 1 & 1 & 1 & 1 \\ \hline & 1 & 1 & 1 & 1 \\ \hline & 1 & 1 & 1 & 1 \\ \hline & 1 & 1 & 1 & 1 \\ \hline & 1 & 1 & 1 & 1 \\ \hline & 1 & 1 & 1 & 1 \\ \hline & 1 & 1 & 1 & 1 \\ \hline & 1 & 1 & 1 & 1 \\ \hline & 1 & 1 & 1 & 1 \\ \hline & 1 $		

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code: <u>12K93e</u> Hole Number <u>W-C5-</u>	22	Surface Elevation: <u>762.5</u>
Projec	t Name: Proposed Site Development	Northing: <u>1010600</u>	Easting:
Projec	t Location: Town of Orchard Park, Erie County, NY		Date Started: <u>4/26/2022</u>
Client:	McMahon & Mann Consulting Engineering & Geology, P.C.		Date Completed: <u>4/27/2022</u>
Depth (ft)	Well		Remarks
- - 45 -	$ \begin{array}{c} a & a & a & a & a & a \\ \hline 1 & a & a & a & a & a \\ \hline 1 & a & a & a & a & a \\ \hline 1 & a & a & a & a & a \\ \hline 1 & a & a & a & a & a \\ \hline 1 & a & a & a & a & a \\ \hline 1 & a & a & a & a & a \\ \hline 1 & a & a & a & a & a \\ \hline 1 & a & a & a & a & a \\ \hline 1 & a & a & a & a & a \\ \hline 1 & a & a & a & a & a \\ \hline 1 & a & a & a & a & a \\ \hline 1 & a & a & a & a & a \\ \hline 1 & a & a & a & a & a \\ \hline 1 & a & a & a & a & a \\ \hline 1 & a & a & a & a & a \\ \hline 1 & a & a & a & a & a \\ \hline 1 & a & a & a & a & a \\ \hline 1 & a & a & a & a & a \\ \hline 1 & a & a & a & a & a \\ \hline 1 & a & a & a & a & a \\ \hline 1 & a & a & a & a & a \\ \hline 1 & a & a & a & a & a \\ \hline 1 & a & a & a & a & a \\ \hline 1 & a & a & a & a & a \\ \hline 1 & a & a & a & a & a \\ \hline 1 & a & a & a & a & a \\ \hline 1 & a & a & a & a & a \\ \hline 1 & a & a & a & a & a \\ \hline 1 & a & a & a & a & a \\ \hline 1 & a & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a \\ \hline 1 & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a & a \\ \hline 1 & a & a & a \\ \hline 1 & a & a & a \\ \hline 1 & a & a & a \\ \hline 1 & a & a & a \\ \hline 1 & a & a & a \\ \hline 1 & a & a & a \\ \hline 1 & a & a & a \\ \hline 1 & a & a & a \\ \hline 1 & a & a & a \\ \hline 1 & a & a & a \\ \hline 1 & a & a & a \\ \hline 1 & a & a & a \\ \hline 1 & a & a & a \\ \hline 1 & a & a & a \\ $		
- - 50 - -			
- - 55_ - -			
-			

### BUFFALO BILLS STADIUM PROJECT NO. 22-011



#### **BUFFALO BILLS STADIUM** PROJECT NO. 22-011 BORE CORE HOLE # RUN # DATE DEPTH (ft) LENGTH (ft) REC (ft) REC. % RQD. % BH-C5-22 BH-C5-22 5 6 4-26-22 32.1-37.1 37.1-42.1 5.0 5.0 4.9 98 75 Sample 22-292 4-26-22 5.0 100 100 Unconfined Compressive Strength: 1603.5 PSI 12" 24" 36" 0 32.1'

48"

60"

37.1'

12.1

37.1'

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting

1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u> Hole Number	BH-C6-22	Surface Elevation: <u>761.4</u>
Project Name: Proposed Site Development	Northing:1010561	Easting:
Project Location: Town of Orchard Park, Erie County, I	NY	Date Started: <u>4/27/2022</u>
Client: McMahon & Mann Consulting Engineering & Geolo	ogy, P.C	Date Completed: <u>4/27/2022</u>

			Blow	s on	Sam	pler				
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	Ν	LITH	Description and Classification We	I Water Table and Remarks
	1	19	7	11	9	4	20		Mostly clean fine size gravel	Gravel fill to 0.2 feet over mostly crushed concrete fill to 0.6 feet over sandy soil fill with some gravel and flat sided shale stone fragments, little silt to 1.4 feet over silty soil fill with little sand and clay, trace to
-	2	20	5	6	8	8	14		40% gravel and flat sided shale stone fragments, little silt, compact, massive soil structure, (GM),(SM). Moist dark brownish gray	little gravel to 3.0 feet over silty slackwater sediment with some sand, trace to little clay and gravel to 5.5 feet over silty glacial till with little to some gravel and flat sided shale stone fragments little sand
5_	3	18	2	2	5	6	7		(SAND-SILT-CLAY) fill with 20 to 40% gravel, little sand and clay, stiff, massive soil structure, (ML-CL).	and clay to 8.0 feet over coarse silty glacial till with some sand, little to some gravel, trace clay to 10.4 feet over apparent shale bedrock to 11.2 feet over shale bedrock to end of coring.
_	4	21	8	9	13	14	22		15% gravel, little sand and clay, very stiff, thinly laminated and thinly bedded, (ML-CL).	Note: Water level at 7.5 feet in bore hole prior to coring. Note: Lost no water to formation
-	5	24	13	13	14	14	27		I (SAND-SILT-CLAY) with 5 to 15% gravel, little to some Isand, trace to little clay, firm, Istratified, (ML-CL).	above 17.0 feet. Note: Advanced bore hole with 4 1/4" ID x 8" OD hollow stem auger
10_	6	7	12	50/3		10			Moist to dry brownish gray to gray gravelly (SAND-SILT-CLAY) with 15 to 11.2	casing with continuous split spoon sampling to auger refusal at 11.2 feet. Removed drill rods and installed a bentonite seal. Continued below with a NO-2 size double tubed
- -	<sup>^</sup> Run		#1						25% gravel and flat sided shale stone fragments, little sand and clay, very stiff, massive soil structure, (ML-CL). grades downward to Moist gray gravelly (SANDY-SILT) with 15 to 25% gravel, some sand,	wireline core barrel with diamond bit to end of coring at 21.2 feet. Core hole was backfilled with bentonite and the remainder of the bore hole was backfilled with cuttings and ground surface repaired to match surrounding conditions upon completion.
-	Run		#2						soil structure, (SM). Gray shale stone fragments, very soft to soft.	Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % % gal
-										11.2 1 to 5.0 5.0 100 0 30 16.2
									See next sheet	16.2 2 to 5.0 4.9 98 52 45 21.2

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI :	lob Co	ode:	<u> </u>	93e osed 9	— Site De	evelop	<b>Ho</b> ment	ole N	umber	BH-C	C6-22	-	1010	561	Su	rfa	<b>ce Elevation:</b> <u>761.4</u>
Proje	ect I o	catio	n: 7	Town c	of Orch	nard Pa	ark, E	rie Co	ounty, N	Y	NOR	.ning: _	1010		Da	te 9	Started: 4/27/2022
Clien	t: M	cMah	on & N	1ann C	Consult	ing En	iginee	ering a	& Geolo	 gy, P.C	C.				Da	te (	Completed: 4/27/2022
Depth (ft)	SN	Rec (in)	<b>Blow:</b> 0/6	<b>5 01</b> 6/12	<b>Sam</b>	18/24	N	LITH	Dese	criptior	n and C	lassificat	ion		Well	I	Water Table and Remarks
- - 25_ - - - 30_	Run		#2						Dark soft, inten fractu bedd feet v high thinly bedd staini from Dark soft, fractu bedd staini from Dark soft, fractu bedd staini from Corin	gray s very ir sely fr. ured hd ing pla with ar angle (0.025 gray s intens ured hd ing pla hated t e, no in s rang 5-0.85 <sup>-1</sup> ig com	shale be ntensely actured orizonta anes bel n occasi vertical nated to nose, no orre pieco 5-0.3'). shale be ely to n orizonta anes, th no thinly ron stai le from ').	drock, v to , intense illy along ow 12.4 onal sho fracture thinly iron es range drock, hoderate inly bedded ning, col at 21.2 f	ely ort , , re	21.2			<ul> <li>(1) Bentonite Seal</li> <li>Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % % gal</li> <li>16.2</li> <li>2 to 5.0 4.9 98 52 45 21.2</li> <li>EDI Bedrock Hardness Classification</li> <li>Very Soft: Can be scratched with fingernail. Slight indentation produced by light blow of point of geologic pick. Requires power tools for excavation.</li> <li>Soft: Hand-held specimen crumbles under firm blows with point of geologic pick.</li> </ul>
- 35_ - -																	

#### N = Number of Blows to Drive 2" Spoon 12" with 140lb. Weight Falling 30" per Blow

40

# BUFFALO BILLS STADIUM

PROJECT NO. 22-011

BORE HOLE #	CORE RUN #	DATE	DEPTH (ft)	LENGTH (ft)	REC (ft)	REC. %	RQD. %
BH-C6-22	1	4-27-22	11.2-16.2	5.0	5.0	100	0
BH-C6-22	2	4-27-22	16.2-21.2	5.0	4.9	98	52



Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u> Hole N	umber <u>BH-C7-22</u>	Surface Elevation: <u>761.6</u>
Project Name: Proposed Site Development	Northing:1010523_	Easting:
Project Location: Town of Orchard Park, Erie Co	ounty, NY	Date Started: 5/6/2022
Client: McMahon & Mann Consulting Engineering	& Geology, P.C.	Date Completed: <u>5/6/2022</u>

Denth		Blows on Sampler														
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	Water Table and Remarks						
	1	6	7	11	18	21	29		Tar and chip surface. Mostly crushed concrete fill. Dry grayish brown and brownish gray mixed gravelly (SANDY-SILT) fill with 15 to 25% mostly flat sided	Tar and chip surface to 0.1 feet over mostly crushed concrete fill to 0.5 feet over coarse silty soil fill with little to some gravel, little sand, trace clay to 4.0 feet over silty soil fill with little sand and clay, trace to						
_	2	20	8	7	5	6	12		shale stone fragments, little sand, trace clay, compact, massive soil structure, (ML). 4.0 4.0 4.0 4.0 4.0							
5_	3	10	3	5	4	0	9		Moist grayish brown and brownish gray (SAND-SILT-CLAY) fill with 5 to 15% gravel, little sand and clay, stiff, massive soil structure, (ML-CL). 5.7	shale bedrock to end of coring.						
-	4	22	5	6	8	9	14		Dry faintly mottled olive gray to olive brown gravelly (SAND-SILT-CLAY) with 15 to 25% mostly flat sided shale stone fragments, little sand, trace to little 7.5 (lay, stiff, massive soil structure,	Note: Water at 10.2 feet below ground surface prior to coring. Note: Started loosing water below 14.5 feet.						
- 10_	5	24	9	13	15	13	28		Dry, wet below 9.5 feet, gravelly (SANDY-SILT) with 30 to 50% mostly flat sided shale stone fragments, some sand, compact, massive soil structure, (SM),(GM).							
-	6	8	19	50/3					Gray shale stone fragments, very soft to soft.	Note: Advanced bore hole with 4 1/4" ID x 8" OD hollow stem auger casing with continuous split spoon sampling to auger refusal at 11.4						
- - 15	<sup>^</sup> Run		#1						Gray shale bedrock, soft, very intensely to intensely fractured, very thin to thinly bedded, no iron staining, dense, core breaks appear fresh, core pieces range from (0.025-0.9').	1.4 sampling to auger refusal at 11.4 feet. Removed drill rods and installed a bentonite seal. Continued below with a NQ-2 size double tubed wireline core barrel with diamond bit to coring completion at 26.2 feet. Reamed core hole with a 3 7/8" tricone roller bit and installed a 2-inch PVC standpipe piezometer to 21.0 feet in completed bore hole.						
- 15										Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % % gal						
-	Run		#2						17.2	1 to 5.0 4.9 98 18 25 16.4						
_ 20									See next sheet	2 to 4.9 4.9 100 71 100 21.3						

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>	Hole Number <u>BH-C7-22</u>	Surface Elevation: <u>761.6</u>
Project Name: Proposed Site Developm	nent Northing: _10	010523 <b>Easting:</b> <u>1092718</u>
Project Location: Town of Orchard Par	rk, Erie County, NY	Date Started: <u>5/6/2022</u>
Client: McMahon & Mann Consulting Eng	jineering & Geology, P.C.	Date Completed: <u>5/6/2022</u>

			Blows	s on	Sam	pler										
Depth (ft)	SN	Kec					Ν	LITH	Description and Classification		Wate	r Table	and R	lema	rks	
(11)		(m)	0/6	6/12	12/18	18/24			·							
	Run		#2						Dark gray with occasional thin gray	Rur	i Depth	Length	NREC I	RECI	RQD	WL
									beds of shale bedrock, soft,	#	(ft)	(ft)	(ft)	%	%	gal
_									intensely to moderately fractured							
	$\checkmark$								horizontally along bedding planes		16.4					
	∱Run		#3						becoming moderately to clightly to	2	to	4.9	4.9 1	100	71	100
									alightly fractured below 21 EE feet	_	213					
-									Signity fractured below 21.55 feet,							
									very thin to mealum bedding, dense,		213					
									no iron staining, core breaks appear	3	21.J	10	101		02	100
-									fresh, core pieces range from	5	26.2	4.9	4.9 1	100	92	100
									(0.1-2.9').		20.2					
-																
25																
25_											Dedue	مادالمسط			£:	
										EDI	веаго	ск паго	iness c	lassi	incat	ion
_	N/								26.2	Ver	y Soft:	Can be	scrate	ched	with	
	¥								Caring completed at 20.2 ft	fing	ernail.	Slight i	ndenta	ation		
									Coring completed at 26.2 ft	pro	duced b	by light	blow of	of po	int o	f
_										geo	logic pi	ck. Rec	uires	powe	er to	ols
										for	excava	tion.				
										Sof	t: Hand	-held s	pecime	en cr	umb	les
										unc	ler firm	blows	with p	oint d	of	
										aec	loaic pi	ck.	•			
-										5						
30																
50_																
-																
-																
_																
_																
35.																
-																
-																
-		$\left  \right $														
_																
_40																

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code:	12K93e	Hole Number	I-C7-22		Surface Elevation: <u>761.6</u>	
Projec	t Name:_	Proposed Site [	Development	Northi	ng: <u>1010523</u>	B <b>Easting:</b> <u>1092718</u>	
Projec	t Locatio	n:Town of Or	chard Park, Erie County, NY			Date Started: <u>5/6/2022</u>	
Client:	McMaho	on & Mann Consu	Ilting Engineering & Geology,	P.C.		Date Completed: <u>5/6/2022</u>	
Depth (ft)		Wel	I			Remarks	
(ft) 		A	nch Road Box Installed in Cor 1 ttings Backfill nch Schedule 40 FJT PVC Rise ntonite Seal	er			
15_ - - -		0.0	101 Slot Screen				

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code: <u>12K93e</u> Hole Number <u>W-C7-</u>	22	Surface Elevation: <u>761.6</u>
Projec	t Name: Proposed Site Development	Northing: <u>1010523</u>	Easting:
Projec	t Location:Town of Orchard Park, Erie County, NY		Date Started:
Client	McMahon & Mann Consulting Engineering & Geology, P.C.		Date Completed: <u>5/6/2022</u>
Depth (ft)	Well		Remarks
    	#00N Size Morie Sand Pack 0.010 Slot Screen 21.5 Bentonite Seal 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 23.5 25.2 25.2		
- - 35_ - - -			

### BUFFALO BILLS STADIUM PROJECT NO. 22-011

PROJECT NO. 22-011

BORE HOLE #	CORE RUN #	DATE	DEPTH (ft)	LENGTH (ft)	REC (ft)	REC. %	RQD. %
BH-C7-22	1	5-6-22	11.4-16.4	5.0	4.9	98	18
BH-C7-22	2	5-6-22	16.4-21.3	4.9	4.9	100	71
BH-C7-22	3	5-6-22	21.3-26.2	4.9	4.9	100	92



Geotechnical and Environmental Drilling | Wetland Delineations and Consulting

1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>	Hole Number <u>BH-D2-22</u>	Surface	Elevation: 759.8
Project Name: Proposed Site Developme	ent Northing:	1010573.44 <b> E</b>	asting:
Project Location: Town of Orchard Park	, Erie County, NY	Date Sta	rted:
Client: McMahon & Mann Consulting Engi	neering & Geology, P.C.	Date Cor	npleted: <u>5/18/2022</u>

		D	Blow	s on	Sam	<u>ipler</u>								
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	Water Table and Remarks				
	1	17	1	1	3	2	4	00	Moist dark brown (SANDY-SILT) topsoil fill with 0 to 3% gravel, little 0.8 sand and organic matter, very loose, granular soil structure, (ML). Moist to dry brown 2.0	Coarse silty topsoil fill with little sand and organic matter to 0.8 feet over silty soil fill with trace to little sand and clay, trace gravel to 2.0 feet over sandy glacial till with some gravel and flat sided shale stone				
_	2	22	11	9	16		25		(SAND-SILI-CLAY) fill with 0 to 3% gravel, trace to little sand and clay, firm, massive soil structure, (ML-CL).	fragments, little silt to 5.0 feet over shaley glacial till with some silt, little sand to 6.6 feet over apparent shale bedrock to 9.0 feet over shale				
-	3	24	10			25			(SÍLTY-SAND) with 20 to 40% gravel and flat sided shale stone fragments, little silt, compact, massive soil structure, (SM),(GM).	bedrock to end of coring.				
5_		24		20	20	26	40	0000	Dry to moist gray shale (SANDY-SILT) with 30 to 50% mostly flat sided shale stone	Note: Advanced bore hole with 4				
_	4	8	16	50/3					Gray shale stone fragments, very soft to soft.	1/4" ID x 8" OD hollow stem auger casing with continuous split spoon sampling to auger refusal at 9.0 feet. Removed drill rods and installed a bentonite seal. Continued				
	5	2	50/2						9.0	below with a NQ-2 size double tubed wireline core barrel with diamond bit to coring completion at 24.0 feet				
10_	^Run		#1						Dark gray shale bedrock, soft, very intensely to intensely fractured, becoming intensely fractured below	Installed a 2-inch PVC standpipe piezometer to 18.0 feet in completed bore hole.				
-									11.0 feet, thinly laminated to thinly bedded, no iron staining, core breaks appear fresh, core pieces range from (0.025-0.25').					
-	×													
15_	Run		#2							Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % % gal				
-										9.0 1 to 5.0 5.0 100 0 0 14.0				
-										14.0 2 to 5.0 5.0 100 70 30 19.0				
20	Run		#3						19.8	19.0 3 to 5.0 5.0 100 93 50 24.0				

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

Project Name:       Proposed Site Development       Northing:       1010573.44       Easting         Project Location:       Town of Orchard Park, Erie County, NY       Date Started:         Client:       McMahon & Mann Consulting Engineering & Geology, P.C.       Date Complete         Blows on Sampler       Image: Complete       Image: Complete	g: <u>1091708.19</u> <u>5/18/2022</u> ed: <u>5/18/2022</u>												
Project Location:Town of Orchard Park, Erie County, NY       Date Started:         Client:McMahon & Mann Consulting Engineering & Geology, P.C       Date Complete         Blows on Sampler	5/18/2022 ed:5/18/2022												
Client:       McMahon & Mann Consulting Engineering & Geology, P.C.       Date Complete         Blows on Sampler       Image: Complete	ed:5/18/2022												
Blows on Sampler	lient: <u>McMann &amp; Mann Consulting Engineering &amp; Geology, P.C.</u> Date Completed: <u>5/18/2022</u>												
<u>Diows on Sumpler</u>													
Depth (ft)     SN     Rec (in)     6/12     12/18     N     LITH     Description and Classification     Wate	r Table and Remarks												
Run       #3       Gray shale bedrock, soft, moderately planes with a very intensely reduced to reduce the form (22.35 to 20.26 Sha (22.95 to 23.20) rest, thickly laminated to medium bedding, dense, no iron staining, core breaks appear fresh, core places range from (0.2-0.7).       EDI Bedroc Very Soft: fingernal.         25	Length REC REC RQD WL (ft) (ft) % % gal												

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code:	12K93e	Hole NumberV-D	02-22			Surface Elevation	n: <u>759.8</u>
Project	t Name:_	Proposed Si	ite Development	North	ing: _	1010573.44	Easting:	1091708.19
Project	t Locatio	n: Town of	Orchard Park, Erie County, NY				Date Started:5	/18/2022
Client:	McMaho	on & Mann Co	onsulting Engineering & Geology, P.	<u>C.</u>			Date Completed:	5/18/2022
Depth (ft)			Well				Remarks	
-			8-inch Road Box Installed in Concr Pad Cuttings Backfill	rete				
5			2-IIICH SCHeddie 40 FJT FVC Riser					
			Bentonite Seal					
- - - - -			- #00N Size Morie Sand Pack - 0.010 Slot Screen					
15		18.0						
20			Bentonite Seal					

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code: <u>12K93e</u> Hole Number <u>W-D2-</u>	-22	Surface Elevation: 759.8
Projec	t Name: Proposed Site Development	Northing:	<u>1010573.44</u> <b>Easting:</b> <u>1091708.19</u>
Projec	t Location:Town of Orchard Park, Erie County, NY		Date Started:
Client:	McMahon & Mann Consulting Engineering & Geology, P.C.		Date Completed: <u>5/18/2022</u>
Depth (ft)	Well		Remarks
	Bentonite Seal $\begin{array}{c ccccccccccccccccccccccccccccccccccc$		
25 - - -			
30 - - -			
35_ - - - - -			

## BUFFALO BILLS STADIUM PROJECT NO. 22-011

BORE HOLE #	CORE RUN #	DATE	DEPTH (ft)	LENGTH (ft)	REC (ft)	REC. %	RQD. %
BH-D2-22	1	5-18-22	9.0-14.0	5.0	5.0	100	0
BH-D2-22 BH-D2-22	3	5-18-22	19.0-24.0	5.0	5.0	100	93



Geotechnical and Environmental Drilling | Wetland Delineations and Consulting

1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u> Hole Num	berBH-D3-22	Surface Elevation: 760
Project Name: Proposed Site Development	Northing:10	10480.83 <b>Easting:</b> <u>1091893.74</u>
Project Location: Town of Orchard Park, Erie Cour	ity, NY	Date Started: <u>5/20/2022</u>
Client: McMahon & Mann Consulting Engineering & G	eology, P.C.	Date Completed: <u>5/23/2022</u>

			Blows	s on	Sam	npler									
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	We	ell	Water Table and Remarks			
	1	18	2	3	5	9	8		Moist to dry dark brown (SANDY-SILT) topsoil fill with 3 to 7% gravel, some sand, trace to little organic matter, very loose, granular soil 1.8			Coarse silty topsoil with some sand, trace to little organic matter, trace gravel to 0.5 feet over silty soil fill with little sand and clay, trace to little gravel to 0.9 feet over silty slackwater sediment with little sand			
-	2	22	4	6	8	15	14		brucker (ML). Dry brown (SAND-SILT-CLAY) fill with 5 to 15% gravel, little sand and clay, firm, massive soil structure, (ML-CL). Dry distinctly mottled brown			and clay, trace gravel to 1.8 feet over silty glacial till with little to some gravel and flat sided shale stone fragments, little sand, trace to little clay to 6.0 feet over sandy glacial till with some gravel and flat			
5_	3	14	7	5	4	5	9		(SÁND-SILT-CLAY) with 0 to 3% gravel, little sand and clay, stiff, blocky soil structure, (ML-CL). Dry to moist grayish brown to <u>6.0</u>	3ackfill		sided shale stone fragments, some silt to 8.5 feet over apparent shale bedrock to 14.0 feet over shale bedrock to 43.0 feet over shale bedrock with an occasional thin siltstope interbed to end of coring			
-	4	24	11	15	16	17	31		brownish gray gravelly   (SAND-SILT-CLAY) with 15 to   25% gravel and flat sided   stone fragments, little sand,   trace to little clay, stiff   massive soil structure,	Cuttings F		Note: No water in bore hole prior to taking sample number 8. Water level up to 5.0 feet below ground surface.			
- 10_	5	24	11	16	18	20	34		(ML-CL). 8.5 grades downward to Moist grayish brown to gray gravelly (SILTY-SAND) with 20 to 400% grayed part			Note: Water level at 5.5 feet below ground surface prior to coring. Note: Water level at 3.8 feet below ground surface at coring completion with tooling removed from bore			
-	6	8	8	50/4					sided shale stone fragments, some silt, dense, massive soil structure, (SM),(GM). Gray shale stone fragments, verv soft and soft.			hole. Note: Advanced bore hole with 4 1/4" ID x 8" OD hollow stem auger casing with continuous split spoon			
-	7	3	50/3						14.0		14.0	sampling to auger refusal at 14.0 feet. Removed drill rods and installed a bentonite seal. Continued below with a NQ-2 size double tubed wireline core barrel with diamond bit to coring completion at 63 5 feet			
15_	Run		#1						Dark gray shale bedrock, soft, intensely fractured to intensely to moderately fractured, thinly laminated to thinly bedded, dense, no iron staining, core breaks appear			Core hole was backfilled with bentonite and the remainder of the bore hole was backfilled with cuttings and ground surface repaired to match surrounding conditions upon completion.			
-									(0.025-1.0').	<u> </u>		Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % % gal 14.0			
-									18.5	Bentc		1 to 5.0 4.8 96 30 20 19.0			
20	Run		#2						See next sheet			19.0 2 to 5.0 5.0 100 70 20 24.0			

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI J	lob C	ode:	_12K	93e			Но	ole N	umber <u>BH-D3-22</u>	Surf	ace E	levati	on:	760			
Proje	ect Na	ame:	Prop	osed S	Site De	evelop	ment		Northing:1010480.8	33	Ea	sting:	109	1893	.74		
Proje	ect Lo	catio	on:	Fown c	of Orch	nard Pa	ark, E	rie C	punty, NY	Date	Star	rted: _	5/20/	2022		_	
Clien	t:M	cMah	on & N	1ann C	Consult	ting En	iginee	ering	& Geology, P.C.	Date	Con	pleted	<b>i:</b> _ 5,	/23/2	)22	_	
Depth (ft)	SN	Rec (in)	<u>Blows</u> 0/6	<b>5 ON</b> 6/12	<b>Sam</b>	18/24	N	LITH	Description and Classification	Well		Wate	r Tabl	e and	Rema	arks	
	Run		#2						Dark gray shale bedrock, soft, intensely to moderately fractured to moderately fractured horizontally along		Run # 	Depth (ft) 19.0	Lengt (ft)	h REC (ft) 	REC %	RQD %	WL gal
-									bedding planes with high angle fractures from 19.0 to 19.5, 24.9 to 25.1, and 28.7 to 29.0 feet with near vertical fractures at 22.6 to 23.0,		3	24.0 24.0 24.0	5.0	5.0 5.0	100	76	20

			 	soft, intensely to moderately	스	_	# (TC)	(ft)	(ft)	%	% 	gai
-				fractured to moderately fractured horizontally along bedding planes with high angle fractures from 19.0 to		-	19. 2 to 24.	0 5.0 0	5.0	100	70	20
_				19.5, 24.9 to 25.1, and 28.7 to 29.0 feet with near vertical fractures at 22.6 to 23.0, 23.4 to 24.0 and 26.85 to			24. 3 to 29.	0 5.0 0	5.0	100	76	20
- 25	Run	#3		27.1 feet, thinly laminated to medium bedding with a limey shale interbed, effervesces without etching, with a calcite		-	29. 4 to 34.	0 5.0 0	5.0	100	70	20
				deposit from 20.6 to 21.2 feet, dense, no iron staining, core breaks appear fresh, thin pyrite deposit at 28.3		-	34. 5 to 39.	0 5.0 0	5.0	100	92	20
_				feet, core pieces range from (0.1-1.0').		_	39. 6 tc 44.	0 5.0 0	4.95	99	95	20
-	*				29.0	e Seal						
30_	Run	#4	_	Gray shale bedrock, soft, moderately to slightly fractured horizontally along bedding planes with	<u>NNN</u>	entonite						
-				occasional zones of moderately fractured rock with high angle fractures from 30.6 to 31.1, 32.8 to								
-				32.9, 33.1 to 33.3, and 33.7 to 34.0 feet, thinly laminated to medium bedding, dense, no iron staining, core breaks appear fresh, core pieces range from (0.025-1.75').								
- 35_	Run	#5		Dark gray shale bedrock, soft, slightly fractured horizontally along bedding planes, thinly laminated to medium bedding, dense, no								
-				appear fresh, core pieces range from (0.51-3.16').								
_												
40	Run	#6			21212							

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting

1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI J	ob C	ode:	_12K	.93e			Но	ole N	umber <u>BH-D</u>	3-22		Surfa	ace E	levati	on: _	760			
Proje	ct Na	ime:	Prop	osed s	Site De	evelop	ment	iria (		Northing: _	1010480.83		_ Ea	sting:	<u>10</u>	91893	3.74		
Proje	ct Lo	catio	on:	John C			агк, с 		Coology DC			Date	Star	ted: _	5/20	12022	077	—	
Clien	t:	CMan			Jonsun	ung Ei	gine	ering	a Geology, P.C.	• <u> </u>		Date	Com	pleteo	d:	0/23/2	022		
Depth (ft)	SN	Rec (in)	<u>Blow</u> 0/6	s on 6/12	San 12/18	18/24	N	LITH	Description	and Classificat	ion	Well		Wate	r Tab	le and	Rem	arks	
	Pup		#6						Dark gray sl soft, slightly	nale bedrock, fractured	/		Run #	Depth (ft)	Leng (ft)	th REO (ft)	C REC %	RQD %	WL gal
-			#0						horizontally planes, thinl medium bed iron staining	along bedding y laminated to lding, dense, n	0		6	39.0 to 44.0	5.0	4.95	99	95	20
_									appear fresh range from	, core pieces (0.51-3.16').	43.0			44.0 to 49.0	5.0	5.0	100	100	20
_	¥						-		occasional th siltstone inte moderately	nin light gray erbeds, soft, slightly			8	49.0 to	4.9	4.9	100	98	20
45_	Run		#7						fractured ho bedding plar laminated to bedding, der	rizontally along nes, thinly medium nse, no iron			 9	53.9 53.9 to	 5.1	 5.1	100	88	20
-							-		staining, cor fresh, core p (0.17-4.49')	e breaks appe bieces range fro	ar f om 2			59.0 59.0					
-													10	to 63.5	4.5	4.5	100	100	20
-	¥—											te Seal							
50_	Run		#8				-					Bentoni							
-																			
-																			
-	¥																		
55_	Run		#9																
_							-												
-																			
-	Run		#10																

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI .	lob C	ode:	_12K	93e			Но	ole Nu	Imber <u>BH-D3-22</u>	Surfa	ace Elevation:
Proje	ect Na	ame:	Prop	osed S	Site De	evelop	ment		Northing:1010480.8	33	Easting:
Proje	ect Lo	catio	on:	Fown c	of Orch	nard Pa	ark, E	rie Co	ounty, NY	Date	Started: <u>5/20/2022</u>
Clien	t:M	cMah	on & N	1ann C	Consult	ing Er	nginee	ering 8	& Geology, P.C.	Date	<b>Completed:</b> <u>5/23/2022</u>
Depth (ft)	SN	Rec (in)	<b>Blow</b>	s on 6/12	<b>Sam</b>	18/24	N	LITH	Description and Classification	Well	Water Table and Remarks
	Run		#10						Gray shale bedrock, soft, with occasional thin light gray siltstone interbeds, moderately soft, slightly fractured horizontally along bedding planes, thinly laminated to medium bedding, dense, no iron staining, core breaks appear fresh, core pieces range from (0.17-4.49').	Bentonite Seal 8:2	Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % % gal 59.0 10 to 4.5 4.5 100 100 20 63.5 EDI Bedrock Hardness Classification
65 _ - - -									Coring completed at 63.5 ft		Very Soft: Can be scratched with fingernail. Slight indentation produced by light blow of point of geologic pick. Requires power tools for excavation. Soft: Hand-held specimen crumbles under firm blows with point of geologic pick. Moderately Soft: Shallow indentations (0.04 to 0.12 inch (1 to 3 mm)) can be made by firm blows with point of geologic pick. Can be
- 70 - - -											peeled with pocket knife with difficulty.
75_ - - -											
80											



Unconfined Compressive Strength: 899.9 PSI

### BUFFALO BILLS STADIUM PROJECT NO. 22-011

BORE HOLE #	CORE RUN #	DATE	DEPTH (ft)	LENGTH (ft)	REC (ft)	REC. %	RQD. %
BH-D3-22	5	5-23-22	34.0-39.0	5.0	5.0	100	92
BH-D3-22	6	5-23-22	39.0-44.0	5.0	4.95	99	95
BH-D3-22	7	5-23-22	44.0-49.0	5.0	5.0	100	100
BH-D3-22	8	5-23-22	49.0-53.9	4.9	4.9	100	98



### BUFFALO BILLS STADIUM PROJECT NO. 22-011

BORE HOLE #	CORE RUN #	DATE	DEPTH (ft)	LENGTH (ft)	REC (ft)	REC. %	RQD. %
BH-D3-22	9	5-23-22	53.9-59.0	5.1	5.1	100	88
BH-D3-22	10	5-23-22	59.0-63.5	4.5	4.5	100	100



EARTH DIMENSIONS, INC. Geotechnical and Environmental Drilling | Wetland Delineations and Consulting

1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u> Hole Number <u>BH-D4</u>	<b>Surface Elevation:</b> 760.3
Project Name: Proposed Site Development	Northing: <u>1010442</u> Easting: <u>1092090</u>
Project Location: Town of Orchard Park, Erie County, NY	Date Started: <u>5/4/2022</u>
Client: McMahon & Mann Consulting Engineering & Geology, P.C.	<b>Date Completed:</b> <u>5/4/2022</u>

			Blow	s on	San	npler				
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	Water Table and Remarks
	1	16	5	13	6	2	19		Tar and chip surface.       0.1/0.1/0.6         Mostly crushed concrete fill.       0.6         Moist to dry dark brownish gray       gravelly (SANDY-SILT) with 20 to         gravelly (SANDY-SILT) with 20 to       1.7	Tar and chip surface to 0.1 feet over mostly crushed concrete fill to 0.6 feet over coarse silty soil fill with some flat sided shale stone fragments, little sand, trace clay to
-	2	20	6	8	7		15		40% mostly flat sided shale stone fragments, little sand, trace clay and organic matter, compact, massive soil structure, (SM),(GM). Dry faintly mottled brown to grayish brown gravelly (SAND-SILT-CLAY)	1.7 feet over sitty glacial till with little to some flat sided shale stone fragments, little sand, trace to little clay to 5.5 feet over shaley glacial till with some sand to 8.3 feet over apparent shale bedrock to 12.0 feet over shale bedrock to end of coring
5_	3	24	7	9	11	12	20		with 15 to 25% mostly flat sided shale stone fragments, little sand, trace to little clay, very stiff, massive soil structure, (ML-CL). 5.5 Moist gray gravelly (SANDY-SILT)	
-	4	18	12	13	16	14	29		with 30 to 50% mostly flat sided shale stone fragments, some sand, compact, massive soil structure, (SM),(GM).	Note: Water level at 6.5 feet below ground surface prior to coring. Note: Water level at 2.5 feet below ground surface at coring completion with tooling removed from core hole.
- 10_	5	10	27	50/4					8.3 Dry shale stone fragments, very soft to soft.	
-	6	18	30	32	35	50/3	67		12.0	Note: Advanced bore hole with 4 1/4" ID x 8" OD hollow stem auger casing with continuous split spoon sampling to 12.0 feet. Removed drill rods and installed a bentonite seal. Continued below with a NO-2 size
-	<sup>^</sup> Run		#1			, 			Gray shale bedrock, soft, intensely fractured, thinly bedded, dense, no iron staining, core breaks appear fresh, core pieces range from (0.025-0.25').	double tubed wireline core barrel with diamond bit to coring completion at 26.5 feet. Reamed core hole with a 3 7/8" tricone roller bit and installed a 2-inch standpipe piezometer to 17.5 feet in completed
15_									15.5 Dark grav shalo bodrock, soft	bore hole. Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % % gal
-	Run		#2						intensely to moderately fractured, slightly fractured below 21.0 feet, horizontally along bedding planes, very thin to medium bedding, dense,	12.0 1 to 5.0 5.0 100 12 35 17.0
- 20									no iron staining, core breaks appear fresh, core pieces range from (0.2-3.9').	17.0 2 to 5.0 5.0 100 75 100 22.0

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>	Hole Number <u>BH-D4-22</u>	Surface Elevation: <u>760.3</u>
Project Name: Proposed Site Developm	ent Northing:1	1010442 <b>Easting:</b> <u>1092090</u>
Project Location: Town of Orchard Par	k, Erie County, NY	Date Started: <u>5/4/2022</u>
Client: McMahon & Mann Consulting Eng	ineering & Geology, P.C.	Date Completed: <u>5/4/2022</u>

			Blows	s on	Sam	pler				
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	Water Table and Remarks
	Run		#2						Dark gray shale bedrock, soft, intensely to moderately fractured, slightly fractured below 21.0 feet, horizontally along bedding planes, very thin to medium bedding, dense,	Run Depth Length REC REC RQD WL           # (ft) (ft) (ft) % % gal           17.0           2 to 5.0 5.0 100 75 100           22.0
-	Run		#3						no iron staining, core breaks appear fresh, core pieces range from (0.2-3.9').	22.0 22.0 3 to 4.5 4.5 100 100 100 26.5
25_									26.5	EDI Bedrock Hardness Classification Very Soft: Can be scratched with fingernail. Slight indentation
_	¥	-							Coring completed at 26.5 ft	produced by light blow of point of geologic pick. Requires power tools for excavation.
-										Soft: Hand-held specimen crumbles under firm blows with point of geologic pick.
30										
- 35										
- - 40										

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	<b>b Code:</b> <u>12K93e</u>	Hole Number <u>W-D4-</u>	-22		Surface Elevation: <u>7</u>	/60.3
Project	t Name: Proposed Sit	e Development	Northing:	1010442	Easting: 1092	2090
Project	t Location:	Orchard Park, Erie County, NY			Date Started:	)22
Client:	McMahon & Mann Cor	nsulting Engineering & Geology, P.C.			Date Completed: <u>5/4</u>	4/2022
Depth (ft)	V	Vell			Remarks	
(ft)	V Alt a t alt a t	<pre>vell 8-inch Road Box Installed in Concret Pad Cuttings Backfill 2-inch Schedule 40 FJT PVC Riser Bentonite Seal #00N Size Morie Sand Pack 0.010 Slot Screen</pre>	e		Kemarks	
-	17.5 18.0					
20		Bentonite Seal				

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code: <u>12K93e</u> Hole Number <u>W-D4</u>	22	Surface Elevation: 760.3
Projec	t Name: Proposed Site Development	Northing:	Easting: <u>1092090</u>
Projec	t Location:Town of Orchard Park, Erie County, NY		Date Started:
Client:	McMahon & Mann Consulting Engineering & Geology, P.C.	_	Date Completed: <u>5/4/2022</u>
Depth (ft)	Well		Remarks
  	Bentonite Seal a = a + a + a + a + a + a + a + a + a +		
- 30_ - -			
- 35_ - -			
40			

### BUFFALO BILLS STADIUM PROJECT NO. 22-011



Geotechnical and Environmental Drilling | Wetland Delineations and Consulting

1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u> Hole Number <u>BH</u>	I-D5-22	Surface Elevation: <u>761.1</u>	
Project Name: Proposed Site Development	Northing:1010404	Easting:	
Project Location: Town of Orchard Park, Erie County, NY	2	Date Started: <u>5/4/2022</u>	
Client: McMahon & Mann Consulting Engineering & Geology, F	P.C.	Date Completed: 5/5/2022	

			Blow	s on	Sam	npler					
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	Well	Water Table and Remarks
-	1	18	4	7	6	9	13		Tar and chip surface.		Tar and chip surface to 0.1 feet over mostly crushed concrete fill to 0.5 feet over coarse silty soil fill with some gravel, little sand, trace clay to 1.5 feet over mostly shale stone fragment fill to 2.2 feet over silty soil
-	2	20	4	3	4	7	7		Clay, compact, massive soil structure, (SM),(GM). Gray shale stone fragment fill. Moist to wet faintly mottled		fill with some flat sided shale stone fragments, little sand and clay to 3.0 feet over clayey slackwater sediment to 3.8 feet over silty glacial till with little sand and clay, trace to little flat sided shale stone fragments to 5.5
5_	3	24	5	6	7	13	13		grayish brown gravelly (SAND-SILT-CLAY) fill with 20 to 40% mostly flat sided shale stone fragments, little sand and clay, firm, massive soil structure, (SC),(GC).		feet over coarse silty glacial till with some flat sided shale stone fragments, some sand, trace clay to 10.2 feet over apparent shale bedrock to 13.7 feet over shale bedrock to end of coring.
-	4	20	17	18	17	19	35		Moist to dry faintly mottled alternating layers of brown and brownish gray (SILTY-CLAY) firm, thinly laminated, (CL).		Note: Water at 11.0 feet below ground surface prior to coring with augers left in overnight at 13.7 feet.
- 10_	5	22	9	8	11	23	19		Moist distinctly mottled brown to grayish brown (SAND-SILT-CLAY) with 5 to 15% mostly flat sided shale stone fragments, little sand	tings Backfil	Note: Water level at 3.3 feet below ground surface at coring completion with tooling removed from core hole.
-	6	19	17	22	49	50/3	71		structure, (ML-CL). Moist to wet brownish gray to gray very gravelly (SANDY-SILT) with 20 to 40% mostly flat sided shale	Cut	Note: Advanced bore hole with 4 1/4" ID x 8" OD hollow stem auger casing with continuous split spoon sampling to auger refusal at 13.7
-	7	15	24	33	50/3	,			stone fragments, some sand, trace clay, dense, compact below 8.0 feet, massive soil structure, (SM),(GM).		installed a bentonite seal. Continued below with a NQ-2 size double tubed wireline core barrel with diamond bit to coring completion at 23.7 feet. Core hole was backfilled with
- 15	Run		#1						very soft to soft. Gray shale bedrock, soft, very intensely to intensely fractured, very thin to thinly bedded, dense, core breaks	הלהלהלה	bentonite with the remainder of the bore hole backfilled with cuttings and ground surface repaired to match surrounding conditions upon completion.
-									appear fresh, no iron staining, core pieces range from (0.025-0.65').	e Seal	Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % % gal
-									18.7	Bentonit	1 to 5.0 5.0 100 22 0 18.7
	Run		#2						See next sheet		2 to 5.0 5.0 100 94 20 23.7

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI J	lob C	ode:	_12K	93e			Но	ole N	umber	BH-D5-22	2		Surfa	ace Elevation: <u>761.1</u>
Project Name: Proposed Site Developme				ment	ent Northing:1010404					Easting:				
Project Location:Town of Orchard Park, Erie County, N									ounty, NY	_			Date	Started:
Clien	t:M	cMah	on & N	1ann C	Consult	ing Er	iginee	ering	& Geology	, P.C.			Date	Completed: <u>5/5/2022</u>
Depth (ft)	SN	Rec (in)	<u>Blow</u>	s on 6/12	<b>Sam</b>	18/24	N	LITH	Descri	iption and	l Classifica	ation	Well	Water Table and Remarks
	Run		#2						Dark g soft, sl horizor planes, no iron nodule feet, cc fresh, c (0.35-2 Coring	ray shale ightly fra itally alor staining from 21. ore break core piece 2.1'). complete	bedrock, ctured ng bedding edded, der , calcite 4 to 21.5 s appear es range fi ed at 23.7	nse, rom 23.7 ft		Run Depth Length REC REC RQD WL         # (ft) (ft) (ft) % % gal         18.7         2 to 5.0 5.0 100 94 20         23.7         EDI Bedrock Hardness Classification         Very Soft: Can be scratched with fingernail. Slight indentation produced by light blow of point of geologic pick. Requires power tools for excavation.         Soft: Hand-held specimen crumbles under firm blows with point of geologic pick.

### BUFFALO BILLS STADIUM PROJECT NO. 22-011

PROJECT NO. 22-011

HOLE #	RUN #	DATE	DEPTH (ft)	LENGTH (ft)	REC (ft)	REC. %	RQD. %
BH-D5-22	1	5-5-22	13.7-18.7	5.0	5.0	100	22
BH-D5-22	2	5-5-22	18.7-23.7	5.0	5.0	100	94



Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u> Hole Number _	BH-D6-22	Surface Elevation: <u>760.3</u>	
Project Name: Proposed Site Development	Northing:1010365_	Easting:	
Project Location: Town of Orchard Park, Erie County, N	<u> </u>	Date Started:	
Client: McMahon & Mann Consulting Engineering & Geolog	ју, Р.С	Date Completed: <u>4/29/2022</u>	

	Blows on Sampler				pler									
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	Water Table and Remarks				
-	1	13	7	6	6	5	12		Tar and chip surface. Mostly crushed concrete fill. Moist dark brownish gray gravelly (SAND-SILT-CLAY) fill with 20 to 30% gravel and flat sided shale	Tar and chip surface to 0.1 feet over mostly crushed concrete fill to 0.7 feet over silty soil fill with some gravel, little sand and clay to 4.2 feet over clayey slackwater sediment with trace sand to 5.5 feet over silty				
_	2	15	7	5	3	3	8		stone fragments, little sand and clay, stiff, massive soil structure, (ML-CL).	glacial till with little to some mostly flat sided shale stone fragments, little sand and clay to 8.8 feet over apparent shale bedrock to 11.2 feet over shale bedrock to end of coring.				
5_	3	17	1	3	5	6	8		4.2 Moist to dry alternating layers of brown and brownish gray (CLAYEY-SILT) with some clay, trace - sand, stiff, thinly laminated, (CL).					
-	4	20	7	9	8	9	17		Moist grayish brown to olive gray gravelly (SAND-SILT-CLAY) with 15 to 25% mostly flat sided shale stone fragments, little sand and clay,	Note: Water level at ground surface prior to coring. Hole left open for thirty-six hours.				
10	5	14	8	17	25	47	42		(ML-CL) tending toward (GC),(SC). 8.8 Gray shale stone fragments, very soft to soft.	.8 Note: Advanced bore hole with 4 1/4" ID x 8" OD hollow stem auger casing with continuous split spoon sampling to 11.2 feet. Removed drill rods and installed a bentonite seal.				
-	6	8	19	50/4					double tubed with a NQ double tubed wireline core with diamond bit to coring completion at 29.5 feet. Re					
	^Run 		#1						Dark gray shale bedrock, soft, very intensely to intensely fractured, dense, no iron staining, core pieces range from (0.025-0.2').	bit to 20.0 feet and installed a 2-inch PVC standpipe piezometer to 17.5 feet in completed bore hole.				
_									15.3 Dark gray shale bedrock, soft, intensely to moderately fractured	Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % % gal				
-								horizontally along bed with high angle fractur to 15.7, 16.8 to 17.1, 17.5 feet thinly bedd	horizontally along bedding planes with high angle fractures from 15.6 to 15.7, 16.8 to 17.1, and 17.2 to 17.5 feet, thinly bedded, dense, no	11.2 1 to 3.5 3.4 97 0 0 14.7				
_									iron staining, core pieces range from (0.1-1.2').	14.7 2 to 4.8 4.7 98 53 30 19.5				
20	Run		#3						19.5 See next sheet	19.5 3 to 5.0 5.0 100 94 30 24.5				

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>	Hole Number <u>BH-D</u>	06-22		Surface Elevation	760.3
Project Name: Proposed Site Deve	elopment	Northing:	1010365	Easting:	1092483
Project Location: Town of Orchar	rd Park, Erie County, NY	2		Date Started:4/	27/2022
Client: McMahon & Mann Consultin	g Engineering & Geology, P.C	2		Date Completed:	4/29/2022

D		D -	Blow	<u>s on</u>	Sam	pler				
Depth (ft)	SN	(in)	0/6	6/12	12/18	18/24	Ν	LITH	Description and Classification	Water Table and Remarks
		<u>`</u>	0,0	0,12	12,10	10/21				
	Run		#3						Dark gray shale bedrock, soft,	Run Depth Length REC REC RQD WL
									slightly to moderately fractured	# (10) (10) (10) % 90 gai
_									becoming slightly fractured below	19.5
									24.5 feet, thin to medium bedding,	3 to 5.0 5.0 100 94 30
-									dense, no iron staining, core pieces	24.5
									range from (0.25-2.5).	24.5
-										4 to 5.0 4.95 99 88 15
										29.5
_										
	$\downarrow$									
25										
23_	Kun		#4							EDI Bedrock Hardness Classification
										Vary Coft, Con be constand with
-										fingernail. Slight indentation
										produced by light blow of point of
-								<u>  </u>		geologic pick. Requires power tools
									Tor excavation.	for excavation.
_										
								<u> </u>		Soft: Hand-held specimen crumbles
										geologic pick.
_									29.5	5 5 1
20	•	1							Coring completed at 29.5 ft	
30_									5	
-										
-										
_										
-										
25										
35_										
-										
_										
-										
-										
40										
Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code:	12K93e	_ Hole Nu	mber <u>W-D6-</u>	22		Surface Elevation	<b>:</b> 760.3
Projec	t Name:_	Proposed Si	ite Development		Northing:	1010365	Easting: _	1092483
Projec	t Locatio	n:	Orchard Park, Erie Co	unty, NY			Date Started:4	/27/2022
Client:	McMaho	n & Mann Co	onsulting Engineering 8	Geology, P.C.			Date Completed:	4/29/2022
Depth (ft)		,	Well				Remarks	
 - - 5			8-inch Road Box Insta Pad Cuttings Backfill	illed in Concrete	e			
- - - 10 -			Bentonite Seal #00N Size Morie Sand	i Pack				
- - - - -		17.5	0.010 Slot Screen					
20			Bentonite Seal					

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code: <u>12K93e</u> Hole Number <u>W-D6</u>	6-22 Surface Elevation: 760.3
Projec	t Name: Proposed Site Development	Northing: <u>1010365</u> Easting: <u>1092483</u>
Projec	t Location:Town of Orchard Park, Erie County, NY	Date Started: <u>4/27/2022</u>
Client:	McMahon & Mann Consulting Engineering & Geology, P.C.	Date Completed: <u>4/29/2022</u>
Depth (ft)	Well	Remarks
  	A     A     A     A       A     A     A     A     A       A     A     A     A     A       A     A     A     A     A       A     A     A     A     A       A     A     A     A     A       A     A     A     A     A       A     A     A     A     A       A     A     A     A     A       A     A     A     A     A       A     A     A     A     A       A     A     A     A     A       A     A     A     A       A     A     A     A       A     A     A     A       A     A     A       A     A     A       A     A     A       A     A     A       A     A     A       A     A     A       A     A     A       A     A     A       A     A     A       A     A     A       A     A     A       A     A        A     A </td <td></td>	
30_ - - 35_ - -		
40		

### BUFFALO BILLS STADIUM PROJECT NO. 22-011

BORE CORE DEPTH (ft) LENGTH (ft) REC (ft) REC. % RQD. % HOLE # RUN # DATE 4-29-22 4-29-22 11.2-14.7 14.7-19.5 BH-D6-22 BH-D6-22 3.5 3.4 97 0 1 2 4.8 4.7 98 53 BH-D6-22 4-29-22 19.5-24.5 94 5.0 5.0 100 3 BH-D6-22 4-29-22 24.5-29.5 5.0 4.95 99 88 4



Geotechnical and Environmental Drilling | Wetland Delineations and Consulting

1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>	Hole Number <u>BH-D7-22</u>	Surface Elevation: 760.7
Project Name: Proposed Site Developme	ent Northing: 1010327	Easting:
Project Location: Town of Orchard Park	<, Erie County, NY	Date Started: <u>4/29/2022</u>
Client: McMahon & Mann Consulting Engi	neering & Geology, P.C.	Date Completed: <u>5/2/2022</u>

		Blows on Sampler									
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	Well	Water Table and Remarks
	1	18	6	8	11	6	19		Tar and chip surface.		Tar and chip surface to 0.1 feet over mostly crushed concrete fill to 0.6 feet over shaley soil fill with little sand, trace clay to 3.0 feet over clayey silt topsoil with little clay, trace to little organic matter, trace
-	2	20	3	5	5	6	10		sided shale stone fragments, little sand, trace clay, compact, massive soil structure, (ML). Dry dark brown	ackfill	sand and gravel to 3.2 feet over clayey slackwater sediment to 4.0 feet over coarse silty glacial till with some gravel, little sand, trace clay to 8.5 feet over apparent shale bedrock to 11 feet over shale bedrock to
5_	3	24	2	7	9	12	16		(CLAYEY-SILT) topsoil with 0 to 3% gravel, trace to little organic matter, trace sand, loose, granular soil structure, (ML-CL).	Cuttings E	end of coring. Note: Water level at 4.0 feet below ground surface prior to coring.
-	4	24	5	7	10		17		gray to brown (SILTY-CLAY) stiff, thinly laminated with very thin coarse silt lenses, (CL).		Note: Started losing water to formation below 17.0 feet. Lost 60 gallons to formation.
-	5	20	18	24	25	50/2	49		gravelly (SANDY-SILT) with 20 to 40% mostly flat sided shale stone fragments, occasional cobble, little sand, trace clay, compact, massive soil structure (SM) (GM)		Note: Water level at 2.7 feet below ground surface at completion with tooling removed from bore hole.
10_	6	11	27	50/2		- 50/ 5			Gray shale stone fragments, very soft to soft.	· · · · · · · · · · · · · ·	Note: Advanced bore hole with 4 $1/4$ " ID x 8" OD hollow stem auger casing with continuous split spoon
- - 15_	<sup>^</sup> Run <sup>^</sup> Run		#1						Dark gray shale bedrock, soft, very intensely to intensely fractured, intensely fractured below 11.8 feet, high angle fracture in two directions from 13.4 to 13.6 feet, limey shale bedrock lense, moderately hard, from 14.8 to 15.0 feet, thinly bedded, dense, no iron staining, core pieces range from (0.025-0.5')	<u>NANANANANANA</u> e Seal	sampling to auger refusal at 11.1 feet. Removed drill rods and installed a bentonite seal. Continued below with a NQ-2 size double tubed wireline core barrel with diamond bit to end of coring at 20.4 feet. Core hole was backfilled with bentonite and the remainder of the bore hole was backfilled with cuttings and ground surface repaired to match surrounding conditions upon completion.
-										entonite	# (ft) (ft) (ft) % % gal
-									17.7	B	1 to 4.3 4.3 100 28 0 15.4
20									See next sheet		15.4 2 to 5.0 4.9 98 50 60 20.4

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI .	Job Co	ode:	_12K	93e			Но	ole Nu	Imber BH-D7-22	Surf	ace Elevation: <u>760.7</u>	
Proje	ect Na	me:	Prop	osed S	Site De	evelopi	nent		Northing:1010327		Easting:	
Project Location:Town of Orchard Park, Erie County, NY Date Started:4/29/2022												
Clien	t: <u>M</u>	cMah	on & N	1ann C	Consult	ting En	ginee	ering 8	& Geology, P.C.	Date	<b>Completed:</b> <u>5/2/2022</u>	
Depth (ft)	SN	Rec (in)	<u>Blow</u>	s on 6/12	Sam	18/24	N	LITH	Description and Classification	Well	Water Table and Remarks	
-	√Run		#2						Dark gray shale bedrock, soft, moderately fractured horizontally along bedding planes, thinly to medium bedding, dense, no iron staining, core pieces range	4 <u>2</u> 20.4	(1) Bentonite Seal Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % % gal	

#### to 5.0 4.9 98 50 60 20.4

### EDI Bedrock Hardness Classification

produced by light blow of point of geologic pick. Requires power tools for excavation.



# **BUFFALO BILLS STADIUM**

PROJECT NO. 22-011

BORE HOLE #	CORE RUN #	DATE	DEPTH (ft)	LENGTH (ft)	REC (ft)	REC. %	RQD. %
BH-D7-22	1	5-2-22	11.1-15.4	4.3	4.3	100	28
BH-D7-22	2	5-2-22	15.4-20.4	5.0	4.9	98	50



Geotechnical and Environmental Drilling | Wetland Delineations and Consulting

1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>	Hole Number	2-22	Surface Elevation: <u>760.1</u>
Project Name: Proposed Site Dev	velopment	Northing:	B Easting: <u>1091659</u>
Project Location: Town of Orcha	rd Park, Erie County, NY		Date Started:
Client: McMahon & Mann Consultin	ng Engineering & Geology, P.C	<u>.                                    </u>	Date Completed: <u>5/20/2022</u>

		_	Blow	s on	Sam	npler								
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	Well	Water Table and Remarks			
	1	15	1	1	3	_	4	• • • •	Moist to dry dark brown (SILTY-SAND) topsoil with 0.7 little silt and organic matter, very loose, granular soil structure, (ML).		Sandy topsoil with little silt and organic matter to 0.7 feet over silty soil fill with little sand and clay to 2.5 feet over coarse silty soil fill with little sand, trace clay to 4.0 feet over			
-	2	18	4	7	9	11	16		Dry brown (SAND-SILT-CLAY) fill with 0 to 3% gravel, little sand and clay, stiff, massive soil structure, (ML-CL). Moist gray gravelly		shaley glacial till with little sand, trace clay to 6.4 feet over apparent shale bedrock to 11.6 feet over shale bedrock to end of coring.			
5_	3	21	9	12	10	13	22		(SANDY-SILT) fill with 20 to 40% mostly flat sided shale stone fragments, little sand, trace clay, compact, massive soil structure, (SM),(GM). Moist gray shaley	Cuttings Back				
-	4	8	19	50/2					(SANDY-SILT) with 30 to 6.4 50% mostly flat sided shale stone fragments, little sand, trace clay, compact, massive soil structure, (SM),(GM).		Note: Water level at 7.5 feet below ground surface prior to coring. Note: Water level at 6.5 feet below ground surface after coring and tooling was removed from bore hole.			
- 10	5	20	21	17	25	28	42		very soft to soft.					
	6	15	17	29	50/5				11.6	▲I ▲I 11.0	Note: Advanced bore hole with 4 1/4" ID x 8" OD hollow stem auger casing with continuous split spoon sampling to auger refusal at 11.6 feet. Removed drill rods and			
_	Run		#1						Dark gray shale bedrock,	Ê	installed a bentonite seal. Continued			
									soft, intensely fractured with zones of very intensely to	R	below with a NQ-2 size double tubed			
_									intensely fractured rock,		to coring completion at 21.6 feet.			
									thinly laminated to thinly	A	Core hole was backfilled with			
								<u> </u>	bedded, dense, no iron staining, core breaks appear	[]	bentonite and the remainder of the			
-								<u> </u>	fresh, core pieces range from	Ê	cuttings and ground surface repaired			
1 5									(0.025-0.4').	∑) Sea	with sod upon completion.			
12										占 ig ig				
								<u> </u>		Jit L				
-								<u> </u>		ut (	Run Depth Length REC REC ROD WI			
	¥							===		₽E	# (ft) (ft) (ft) % % gal			
_	Run		#2						47.5	۴J				
								==	17.3	占				
								<u> </u>		X	16.6			
1								<u> </u>		[]				
								<u> </u>		F3				
-								<u> </u>		K	2 to 5.0 4.9 98 73 100 21.6			
									See next cheet	너				
20								<u></u>	See next sheet	11				

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI J	ob Co	ode:	12K	93e			Но	ole N	umberBH	-E2-22	_			Surfa	ace Elevation:
Project Name: Proposed Site Developm								nent Northing:1010322.68						3	Easting:
Project Location: Town of Orchard Park, Erie County, NY														Date	Started: <u>5/19/2022</u>
Client	Client: McMahon & Mann Consulting Engineering & Geology, P.C. Date Completed: 5/20/2022														
			Blow	s on	Sam	pler									
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Descripti	on and C	lassificat	ion		Well	Water Table and Remarks
	Run		#2						Dark gray soft, inter fractured bedding p vertical fr 19.1 feet, medium b iron staini appear fro range fron Coring co	v shale bo nsely to r horizonta lanes wir acture fr thinly la bedding, ing, core esh, core m (0.04- mpleted	edrock, noderate ally along th a shor om 18.9 minated dense, no breaks pieces 1.65'). at 21.6 ft		21.6	(F) 21.6	<ul> <li>(1) Bentonite Seal</li> <li>Run Depth Length REC REC RQD WL</li> <li># (ft) (ft) (ft) % % gal</li> <li>16.6</li> <li>2 to 5.0 4.9 98 73 100 21.6</li> <li>EDI Bedrock Hardness Classification</li> <li>Very Soft: Can be scratched with fingernail. Slight indentation produced by light blow of point of geologic pick. Requires power tools for excavation.</li> </ul>
															Soft: Hand-held specimen crumbles under firm blows with point of geologic pick.
40															

# BUFFALO BILLS STADIUM

PROJECT NO. 22-011

BORE HOLE #	CORE RUN #	DATE	DEPTH (ft)	LENGTH (ft)	REC (ft)	REC. %	RQD. %
BH-E2-22	1	5-20-22	11.6-16.6	5.0	4.8	98	8
BH-E2-22	2	5-20-22	16.6-21.6	5.0	4.9	98	73



Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>	Hole Number <u>BH-E3-22</u>	Surface Elevation: 759.8	
Project Name: Proposed Site Developm	ent Northing:		
Project Location: Town of Orchard Par	k, Erie County, NY	Date Started: <u>5/18/2022</u>	
Client: McMahon & Mann Consulting Eng	ineering & Geology, P.C.	Date Completed: <u>5/19/2022</u>	

Depth Poc Blows on Sample				npler								
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification		Water Table and Remarks	
_	1	15	1	1	5	8	6		Moist dark brown (SANDY-SILT) topsoil fill with 0 to 3% gravel, little silt, trace to little organic matter, very loose, granular soil structure, (ML).	0.5	Coarse silty topsoil fill with little sand, trace to little organic matter, trace gravel to 0.5 feet over coarse silty soil fill with little sand, trace clay and gravel to 1.5 feet over coarse silty soil fill with little sand.	
-	2	18	5	3	3	2	6		Moist to dry brown (SANDY-SILT) fill with 5 to 15% gravel, little sand, trace clay, compact, massive soil structure, (ML).	3.0 3.5	gravel, and flat sided shale stone fragments to 3.0 feet over silty soil fill with some clay and gravel and flat sided shale stone fragments to 3.5 feet over silty slackwater sediment with little clay	
5_	3	22	2	5	6	7	11		shale stone fragments, little sand, loose, massive soil structure, (ML). Moist to wet light gray (SAND-SILT-CLAY) fill with 10 to 20% gravel and flat sided shale	4.3 5.8	trace sand to 4.3 feet over silty glacial till with little to some gravel and flat sided shale stone fragments, little sand, trace to little clay to 5.8 feet over coarse silty glacial till with	
-	4	20	6	8	41	20	49		stone fragments, little sand and clay, firm, massive soil structure, (ML-CL). Moist distinctly mottled brown (CLAYEY-SILT) with little clay, trace sand, soft, thinly laminated,	7.0	fragments, little sand, trace clay to 7.0 feet over apparent shale bedrock to 17.0 feet over shale bedrock to end of coring.	
	5	24	15	19	14	16	33		(ML-CL). Moist to dry grayish brown to brownish gray gravelly (SAND-SILT-CLAY) with 15 to 25% gravel and flat sided shale stone fragments, little sand, trace to little		Note: Augers left in overnight at 10.0 feet, water level the next morning at 3.2 feet below ground surface. Note: Water level at 3.2 feet below ground surface prior to coring	
-	6 <sup>^</sup> Run	19	14	15	19	_50/2	34		clay, stiff, massive soil structure, (ML-CL). Moist gray gravelly (SANDY-SILT) with 20 to 40% mostly flat sided shale stone fragments, little sand, trace clay, compact, massive soil structure. (SM).(GM).	12.0	Water level at 2.9 feet below ground surface at coring completion. Note: Advanced bore hole with 4 1/4" ID x 8" OD hollow stem auger casing with continuous split spoon	
-									Gray shale stone fragments, very soft to soft. Dark gray shale bedrock, soft, intensely fractured, with zones of very intensely and very intensely to		sampling to auger refusal at 12.0 feet. Removed drill rods and installed a bentonite seal. Continued below with a NQ-2 size double tubed wireline core barrel with diamond bit to coring completion at 31.7 feet.	
15_									intensely fractured rock, thinly laminated to thinly bedded, dense, no iron staining, core breaks appear fresh, core pieces range from (0.025-0.25').		Reamed core hole with a 3 7/8" tricone roller bit and installed a 2-inch PVC standpipe piezometer to 26.0 feet in completed bore hole.	
-	Run		#2							17.2	# (ft) (ft) (ft) % % gal 12.0 1 to 5.0 5.0 100 0 100 17.0	
20									See next sheet		17.0 2 to 5.0 5.0 100 58 60 22.0	

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>	Hole Number <u>BH-E3-22</u>	Surface Elevation: 759.8
Project Name: Proposed Site Developm	ent Northing:1010270.7	<b>Easting:</b> <u>1091924.51</u>
Project Location: Town of Orchard Par	k, Erie County, NY	Date Started: <u>5/18/2022</u>
Client: McMahon & Mann Consulting Eng	ineering & Geology, P.C.	Date Completed: <u>5/19/2022</u>

Denth	~	Rec	Blows	s on	Sam	pler					
(ft)	SN	(in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification		Water Table and Remarks
	Run		#2						Dark gray shale bedrock, soft,		Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % % gal
-									horizontally along bedding planes		17.0
									from 18.65 to 18.75 and 19 to 19.05		2 to 5.0 5.0 100 58 60
-	*								feet, thickly laminated to medium		22.0
	Run		#3						core breaks appear fresh, core		22.0 2 to 4.7 4.7 100 70 20
-									pieces range from (0.025-1.0').		26.7
_									Dark grav shale bedrock, soft	23.8	26.7
									moderately to slightly fractured		4 to 5.0 5.0 100 98 30
25_									with a high angle fracture from 25 to		51.7
									25.5 feet, thickly laminated to		
-									staining, thin pyrite deposites, core pieces range from (0.5-1.75').		EDI Bedrock Hardness Classification
_	ᡟ										Very Soft: Can be scratched with
	Run		#4								produced by light blow of point of
-											geologic pick. Requires power tools
-											Soft: Hand-held specimen crumbles
30											under firm blows with point of geologic pick.
-											
	$\downarrow$									31.7	
-									Coring completed at 31.7 ft		
-											
35_											
-											
-											
-											
-											
40											

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code: _	12K93e	Hole Number	E3-22			Surface Elevation	: 759.8
Project	t Name:	Proposed Si	ite Development	No	rthing:	1010270.7	Easting: _	1091924.51
Project	t Location	: Town of	Orchard Park, Erie County, NY				Date Started: <u>5</u> ,	/18/2022
Client:	McMahon	n & Mann Co	onsulting Engineering & Geology, F	.C.			Date Completed:	5/19/2022
Depth (ft)		,	Well				Remarks	
(ft) 			Bentonite Seal	rrete				
20			0.010 Slot Screen					

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code: <u>12K93e</u> Hole Number <u>W-E3-2</u>	-22		Surface Elevation	759.8
Project	t Name: Proposed Site Development	Northing:	1010270.7	Easting:	1091924.51
Project	t Location:Town of Orchard Park, Erie County, NY			Date Started: <u>5</u> /	18/2022
Client:	McMahon & Mann Consulting Engineering & Geology, P.C.			Date Completed:	5/19/2022
Depth (ft)	Well			Remarks	
25	#00N Size Morie Sand Pack 0.010 Slot Screen 26.0 26.5 Bentonite Seal				
30 - - - 35 - - - -	All a f a f a f a f a f a f a f a f a f a				
40					

# BUFFALO BILLS STADIUM PROJECT NO. 22-011



Geotechnical and Environmental Drilling | Wetland Delineations and Consulting

1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>	Hole Number <u>BH-E4-22</u>	Surface Elevation: 757.4
Project Name: Proposed Site Developm	ent Northing: _101	0246 <b>Easting:</b> <u>1092052</u>
Project Location: Town of Orchard Par	k, Erie County, NY	Date Started: <u>4/8/2022</u>
Client: McMahon & Mann Consulting Eng	ineering & Geology, P.C.	Date Completed: <u>4/8/2022</u>

		_	Blows	s on	Sam	pler						
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	W	Vell	Water Table and Remarks
	1	18	1	6	8	6	14		Tar and chip surface.			Tar and chip surface to 0.1 feet over mostly crushed stone fill with little silt to 0.5 feet over mostly sand and shale stone fragment fill with little silt, trace clay to 1.5 feet over clavey glacial drift with little to some
-	2	12	5	5	6	11	11		Very loose, massive soil structure, (SM),(GM). Wet to moist gray and brown mixed very gravelly (SILTY-SAND) fill with 30 to 50% shale stone fragments			mostly flat sided shale stone fragments, little silt and sand to 4.5 feet over gray shale boulder to 5.5 feet over silty glacial till with some gravel, little sand and clay to 6.5 feet over apparent shale bedrock to
5_	3	15	5	15	17		32	•	little silt, trace clay, compact, massive soil structure, (SM),(GM). Moist to dry faintly mottled			<ul><li>9.6 feet over shale bedrock to end of coring.</li><li>Note: Lost no water to formation until 16.5 feet.</li></ul>
-	4	13	8	20	26	18	46		(SAND-SILT-CLAY) with 15 to 25% mostly flat sided shale stone fragments, little silt and sand, stiff, massive soil structure, (SC),(CL).			Note: Water level prior to coring 5.9 feet below ground surface. Note: Lost a total of 150 gallons of water during coring.
-	5 ABun	15	15	13	50/3				Moist gray gravelly (SANDY-SILT) with 20 to 40% gravel, little sand, trace clay, compact, massive soil			Note: Water level at ground surface at coring completion with core tooling removed from hole.
10_ - - -	×un		#1						structure, (SM). Dark gray shale stone fragments, very soft to soft. Dark gray shale bedrock, soft to moderately soft, with occasional thin beds of very soft rock, intensely fractured horizontally along bedding planes, occasional short high angle and vertical fractures, very thinly bedded to thinly bedded, dense, no iron staining, core pieces range	·\ <u>\</u> \ <u>\</u>		Note: Advanced bore hole with 4 $1/4$ " ID x 8" OD hollow stem auger casing with continuous split spoon sampling to auger refusal at 9.6 feet. Removed drill rods and installed a bentonite seal. Continued below with a NQ-2 size double tubed wireline core barrel with diamond bit to coring completion at 29.4 feet. Bore hole was backfilled with cuttings and ground surface repaired to match surrounding conditions upon completion.
15_	Run		#2						$-$ grades downward to $ \frac{15.3}{2}$	Cutt		Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % % gal
-										· • • • • • • • • • • • • • • • • • • •		9.6 1 to 4.8 4.8 100 0 0 14.4
-												14.4 2 to 5.0 5.0 100 66 30 19.4
20	Run		#3						See next sheet			19.4 3 to 5.0 5.0 100 100 60 24.4

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Job Code:12K93e	Hole NumberBH-E4-22	Surface Elevation:757.4
Project Name: Proposed Site Developme	nt Northing: 1010246	<b>Easting:</b> 1092052
Project Location: Town of Orchard Park	, Erie County, NY	Date Started: <u>4/8/2022</u>
Client: McMahon & Mann Consulting Engin	neering & Geology, P.C.	Date Completed: <u>4/8/2022</u>

		<b>_</b>	Blows	s on	Sam	pler						
Depth (ft)	SN	Kec					Ν	LITH	Description and Classification		Well	Water Table and Remarks
(11)		(11)	0/6	6/12	12/18	18/24						
	Run		#3						Dark gray with occasional		'	Run Depth Length REC REC RQD WL
									gray layers of shale bedrock,	۵	U .	# (ft) (ft) (ft) % % gal
-									moderately soft, moderately		.	
									fractured horizontally along		!	19.4
									bedding planes with a vertical	م		3 to 5.0 5.0 100 100 60
-									gray fracture from 16.5 to			24.4
									16.9 feet and a short high	Δ	U .	
									angle fracture at 19.0 feet,			24.4
-									becomes moderately to	4	' =	4 to 5.0 4.8 96 96 60
									slightly fractured below 19.0		니쥰	29.4
									feet, thinly bedded, dense, no		ac	
-	×/								iron staining, core pieces		ПШ	EDI Bedrock Hardness Classification
	Ť.								range from (0.1-1.4').		g	
25	Run		#4						<u> </u>		' . <u>-</u>	Verv Soft: Can be scratched with
20_	1 can		" 1							<u>م</u>	ΗŦ	fingernail. Slight indentation
										1	Ū	produced by light blow of point of
											'	geologic pick. Requires power tools
										۵	1	for excavation.
_												
											.	Soft: Hand-held specimen crumbles
											'	under firm blows with point of
-										<u>م</u>	1	geologic pick.
											1	
-												Madarataly Soft, Shallow
	$\vee$								2	29.4	29.4	indeptations (0.04 to 0.12 inch (1 to
20									Coring completed at 29.4 ft			$(1.04 \pm 0.12)$ mm)) can be made by firm blows
30_												with point of goologic pick. Con bo
												peoled with pecket knife with
												difficulty
-												uniculty.
-												
_												
25												
35_												
-												
-												
1												
_												
40												

## BUFFALO BILLS STADIUM PROJECT NO. 22-011

BORE CORE HOLE # RUN # DATE DEPTH (ft) LENGTH (ft) REC (ft) REC. % RQD. % BH-E4-22 BH-E4-22 BH-E4-22 4-8-22 9.6-14.4 4.8 4.8 100 0 1 4-8-22 4-8-22 5.0 5.0 14.4-19.4 19.4-24.4 5.0 66 100 2 3 100 5.0 100 4-8-22 24.4-29.4 4.8 97 BH-E4-22 4 5.0 96



Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u> Hole Numb	erBH-E5-22	Surface Elevation: 759.9
Project Name: Proposed Site Development	Northing:1010207	Easting:
Project Location: Town of Orchard Park, Erie County	/, NY	Date Started: 5/3/2022
Client: McMahon & Mann Consulting Engineering & Ge	ology, P.C	Date Completed: <u>5/3/2022</u>

		<u> </u>	Blows	s on	San	npler						
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	We	ell	Water Table and Remarks
-	1	18	8	9	9	5	18		Tar and chip surface.			Tar and chip surface to 0.1 feet over mostly crushed concrete fill to 0.5 feet over coarse silty soil fill with some flat sided shale stone fragments, little sand, trace clay and organic matter to 4.3 feet over
-	2	15	5	6	7	7	13		flat sided shale stone fragments, little sand, trace clay and organic matter, compact, massive soil structure, (SM),(GM).			clayey slackwater sediment with trace sand and gravel to 5.5 feet over silty glacial till with little to some mostly flat sided stone fragments, little sand, trace to little clay to 7.7 feet over coarse silty
5_	3	20	3	4	5	7	9		<ul> <li>clear transition to</li> <li>Moist to dry faintly mottled brownish gray to olive brown</li> <li>to olive gray (SILTY-CLAY) r</li> <li>with 0 to 3% gravel, trace I</li> </ul>			stone fragments, little sand, trace to little clay to 11.8 feet over apparent shale bedrock to 13.8 feet over shale bedrock to end of coring.
-	4	24	7	10	14	27	24		<pre>' sand, stiff, thinly laminated, /</pre>	tings Backfill		Water level at 8.0 feet below ground surface prior to coring.
-	5	17	12	18	14	16	32		(SAND-SILT-CLAY) with 15 to 25% mostly flat sided shale stone fragments, little sand, trace to little clay, very stiff, massive soil structure,			Water level at 6.3 feet below ground surface at coring completion with tooling removed from core hole.
-	6	24	9	13	18	41	31		CML-CL).			Note: Advanced bore hole with 4 1/4" ID x 8" OD hollow stem auger casing with continuous split spoon sampling to auger refusal at 13.8 feet. Removed drill rods and installed a bentonite seal. Continued
-	7	з	50/3						sided shale stone fragments, little sand, trace clay, compact to dense, massive soil structure, (SM),(GM).		13.0	below with a NQ-2 size double tubed wireline core barrel with diamond bit to coring completion at 23.8 feet. Core hole was backfilled with bentonite and the remainder of the bare backfilled with
15_	Run		#1						very soft to soft. Dark gray shale bedrock, soft, intensely fractured with numerous high angle and short vertical fractures, thinly			cuttings and ground surface repaired to match surrounding conditions upon completion.
-									laminated to thinly bedded, dense, no iron staining, core breaks appear fresh, core lengths range from			Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % gal
_									(0.025-0.25').	e Seal		13.8 1 to 5.0 5.0 100 0 45 18.8
-	Run		#2						19.0 See next sheet	Bentonit		18.8 2 to 5.0 5.0 100 86 35 23.8
	1	1			l	1				r N		

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI J	ob Co	ode:	12K93e				Но	ole Nu	umberE	3H-E5-22		Sur	Surface Elevation:759.9						
Proje	ct Na	me:	Prop	osed s	Site De	evelop	Northing: 1010207							Easting:					
Proje	ct Lo	catio	on:	Town o	of Orch	nard Pa	ark, E	rie Co	ounty, NY	_			Dat	ate Started: <u>5/3/2022</u>					
Clien	t:M	cMah	on & I	Mann C	Consult	ing Er	iginee	ering 8	& Geology	, P.C.			Dat	Completed: 5/3/	2022				
		_	Blow	s on	Sam	pler													
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Descrij	ption and	Classificat	on	Well	Water Table a	nd Remarks				
-	Run		#2						Dark gr soft, mo fracture bedding thinly b staining fresh, c (0.35-1	ray shale l oderately ed horizon g planes, v edded, de g, core bre core pieces 5').	bedrock, to slightly tally along very thinly ense, no irr eaks appea s range fro	to on ir im 23.8	UNANNANANAN Bentonite Seal	Run Depth Length F # (ft) (ft) ( 18.8 2 to 5.0 5.1 23.8	REC REC RQD WL ft) % % gal				
-									Coring	completed	1 at 23.8 ft	:		EDI Bedrock Hardno	ess Classification				
25_ - - - 30_ - -														Very Soft: Can be s fingernail. Slight ind produced by light b geologic pick. Requ for excavation. Soft: Hand-held spe under firm blows w geologic pick.	cratched with lentation low of point of ires power tools ecimen crumbles th point of				
35_																			
40																			

# BUFFALO BILLS STADIUM PROJECT NO. 22-011

BORE HOLE #	CORE RUN #	DATE	DEPTH (ft)	LENGTH (ft)	REC (ft)	REC. %	RQD. %
BH-E5-22	1	5-3-22	13.8-18.8	5.0	5.0	100	0
BH-E5-22	2	5-3-22	18.8-23.8	5.0	5.0	100	86



Geotechnical and Environmental Drilling | Wetland Delineations and Consulting

1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>	Hole Number <u>BH-E6-22</u>	Surface Elevation: <u>760.4</u>
Project Name: Proposed Site Developm	nent Northing:	1010169 Easting:1092445
Project Location: Town of Orchard Par	k, Erie County, NY	Date Started:
Client: McMahon & Mann Consulting Eng	ineering & Geology, P.C.	Date Completed: <u>5/3/2022</u>

		_	Blows	s on	Sam	<u>ıpler</u>						Water Table and Remarks				
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification		Well					
	1	16	6	8	5	4	13		Tar and chip surface.			Tar and chip surface to 0.1 feet over mostly crushed concrete fill to 0.5 feet over silty soil fill with little gravel and shale stone fragments, trace to little clay, trace organic matter to 1.8 feet over clayey				
-	2	22	2	3	6	6	9	0	sided shale stone fragments, little sand, trace to little clay, trace organic matter, stiff, massive soil structure, (ML-CL).			slackwater sediment with trace sand and an occasional dropstone to 3.5 feet over water sorted and deposited coarse silt with little sand and clay, trace to little gravel to 4.5 feet over clayey slackwater sediment to 5.7				
5_	3	24	1	1	4	6	5		Dry to moist olive brown to olive gray (CLAYEY-SILT) with 0 to 3% gravel, some clay, trace sand and organic matter, stiff, weakly thinly			feet over silty glacial till with little to some mostly flat sided shale stone fragments, little sand and clay to 6.5 feet over coarse silty glacial till with some flat sided shale stone fragments, little sand, trace clay to				
-	4	24	18	14	13	15	27		Moist to wet light grayish 6.9 brown (SAND-SILT-CLAY) 1 with 5 to 15% mostly flat 1 sided shale stone fragments, 1 little sand and clay, firm, 1 wookly stratified (ML CL)		tings Backfill	9.9 feet over apparent shale bedrock to 12.1 feet over shale bedrock to end of coring. Note: Water at 2.0 feet below				
- 10_	5	17	10	14	50/5				Moist to dry faintly mottled I alternating layers of brown I and grayish brown		Cut	Note: Water level at 3.5 feet below ground surface after coring				
_	6	2	50/3						(SILTY-CLAY) firm, thinly    aminated with very thin    coarse silt lenses, (CL).     clear transition to	$\overline{a} \cdot \overline{a} \cdot \overline{a} \cdot \overline{a} \cdot$		from bore hole. Note: Advanced bore hole with 4 1/4" ID x 8" OD hollow stem auger				
-	Run		#1						Dry highly mottled brown gravelly (SAND-SILT-CLAY) with 15 to 25% mostly flat sided shale stone fragments, little sand and clay, stiff, massive soil structure, (ML-CL).		12.1	casing with continuous split spoon sampling to auger refusal at 12.1 feet. Removed drill rods and installed a bentonite seal. Continued below with a NQ-2 size double tubed wireline core barrel with diamond bit to end of coring at 27.0 feet. Core bole was backfilled with bentonite				
15_									Dry to moist brownish gray gravelly (SANDY-SILT) with 20 to 40% mostly flat sided shale stone fragments, little sand, trace clay, compact, massive soil structure,	ערילרילר	le	and the remainder of the bore hole was backfilled with cuttings and ground surface repaired to match surrounding conditions upon completion.				
-	Run		#2						(SM),(GM). Gray shale stone fragments, very soft to soft.	<u> </u>	Itonite Se	kun Depth Length REC REC RQD WL           # (ft) (ft) (ft) % % gal				
20									See next sheet		Ben	17.1 17.1 17.1 2 to 5.0 5.0 100 32 60 22.1				

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting

1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>			Но	ole N	umber <u>BH-E6-22</u>	Surfa	Surface Elevation:								
Proje	ct Na	me:	Prop	osed s	Site De	evelopi	ment		Northing:1010169		Easting: <u>1092445</u>				
Proje	ct Lo	catio	on:	Town o	of Orch	nard Pa	irk, E	rie Co	ounty, NY	Date	Date Started: <u>5/2/2022</u>				
Clien	t: <u>M</u>	cMah	on & N	1ann C	Consult	ing En	ginee	ering	& Geology, P.C.	Date	Date Completed: <u>5/3/2022</u>				
Depth (ft)	SN	Rec (in)	<u>Blow</u>	s on 6/12	Sam	18/24	N	LITH	Description and Classification	Well	Water Table and Remarks				
(ft) 	Run		0/6 #2 #3	6/12					Description and Classification          Dark gray shale bedrock, soft, very intensely to intensely fractured with occasional high angle and vertical fractures, very thinly to thinly bedded, dense, no iron staining, core pieces range from (0.025-0.3').       22.1         Dark gray shale bedrock, soft, intensely to moderately fractured horizontally along bedding planes, high angle to near vertical fracture from 19.9 to 20.6 feet, dense, no iron staining, core pieces range from (0.025-0.65').       27.0         Dark gray shale bedrock, soft, slightly fractured horizontally along bedding planes, very thin to medium bedding, dense, no iron staining, core breaks appear fresh, core pieces range from (0.2-2.0').       27.0         Coring completed at 27 ft       27.0		Run Depth Length REC REC RQD WL         # (ft) (ft) (ft) % % gal         17.1         2 to 5.0 5.0 100 32 60         22.1         3 to 4.9 4.9 100 90 100         27.0         EDI Bedrock Hardness Classification				
40															

## BUFFALO BILLS STADIUM PROJECT NO. 22-011

\_ \_ \_ \_

HOLE #	CORE RUN #	DATE	DEPTH (ft)	LENGTH (ft)	REC (ft)	REC. %	RQD. %
BH-E6-22	1	5-3-22	12.1-17.1	5.0	5.0	100	0
BH-E6-22	2	5-3-22	17.1-22.1	5.0	5.0	100	32
BH-E6-22	3	5-3-22	22.1-27.0	4.9	4.9	100	90
	BORE HOLE # BH-E6-22 BH-E6-22 BH-E6-22	BORE         CORE           HOLE #         RUN #           BH-E6-22         1           BH-E6-22         2           BH-E6-22         3	BORE         CORE           HOLE #         RUN #         DATE           BH-E6-22         1         5-3-22           BH-E6-22         2         5-3-22           BH-E6-22         3         5-3-22	BORE         CORE           HOLE #         RUN #         DATE         DEPTH (ft)           BH-E6-22         1         5-3-22         12.1-17.1           BH-E6-22         2         5-3-22         17.1-22.1           BH-E6-22         3         5-3-22         22.1-27.0	BORE         CORE           HOLE #         RUN #         DATE         DEPTH (ft)         LENGTH (ft)           BH-E6-22         1         5-3-22         12.1-17.1         5.0           BH-E6-22         2         5-3-22         17.1-22.1         5.0           BH-E6-22         3         5-3-22         22.1-27.0         4.9	BORE         CORE           HOLE #         RUN #         DATE         DEPTH (ft)         LENGTH (ft)         REC (ft)           BH-E6-22         1         5-3-22         12.1-17.1         5.0         5.0           BH-E6-22         2         5-3-22         17.1-22.1         5.0         5.0           BH-E6-22         3         5-3-22         22.1-27.0         4.9         4.9	BORE         CORE           HOLE #         RUN #         DATE         DEPTH (ft)         LENGTH (ft)         REC (ft)         REC. %           BH-E6-22         1         5-3-22         12.1-17.1         5.0         5.0         100           BH-E6-22         2         5-3-22         17.1-22.1         5.0         5.0         100           BH-E6-22         3         5-3-22         22.1-27.0         4.9         4.9         100



Geotechnical and Environmental Drilling | Wetland Delineations and Consulting

1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u> He	ole Number <u>BH-E7-22</u>	Surface Elevation: <u>760.4</u>
Project Name: Proposed Site Development	t Northing:1010130	Easting:
Project Location: Town of Orchard Park, E	Erie County, NY	Date Started: <u>5/2/2022</u>
Client: McMahon & Mann Consulting Engine	ering & Geology, P.C.	Date Completed: <u>5/2/2022</u>

Dauth		Rec Blows on Sampler										
Oepth (ft)	SN	(in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	Wel	II	Water Table and Remarks
	1	19	3	11	8	5	19		Tar and chip surface. Mostly crushed concrete fill. Moist dark brownish gray gravelly (SANDY-SILT) fill with 20 to 40% gravel and		1	Tar and chip surface to 0.1 feet over mostly crushed concrete fill to 0.5 feet over coarse silty soil fill with some gravel, little sand, trace clay, organic matter, and wood fiber to 2.8 feet over coarse silty glacial till
_	2	22	8	8	10	26	18		flat sided shale stone fragments, little sand, trace 2.8 clay, organic matter, and wood fiber, compact, massive soil structure, (SM),(GM).	ackfill		with some mostly flat sided shale stone fragments, little sand, trace clay to 3.5 feet over shale channer to 4.8 feet over shaley glacial till with little sand, trace clay to 7.6 feet over annarent shale bedrock to 9 1
5_	3	24	24	13	23	14	36		Moist to dry grayish brown to brownish gray gravelly (SANDY-SILT) with 20 to 40% mostly flat sided shale stone fragments, little sand, trace clay, compact, massive	Cuttings B		feet over limey shale bedrock to 11.0 feet over shale bedrock to end of coring.
_	4	24	12	20	28		48		soil structure, (SM),(GM).      clear transition to   Shale stone fragments, very7.6 □ soft to soft (shale channer).			Water level at 2.8 feet below ground surface at coring completion with tooling removed from bore hole.
_	5 ^Run	3	50/5 #1						Moist dark gray gravelly (SANDY-SILT) with 30 to 50% mostly flat sided shale	△   · · · · · · · · · · · · ·	.1	Note: Advanced bore hole with 4 1/4" ID x 8" OD hollow stem auger casing with continuous split spoon sampling to auger refusal at 9.1 feet. Removed rods and installed a
10									stone fragments, little sand, trace clay, dense, massive soil structure, (GM),(SM). Gray shale stone fragments, very soft to soft. Gray limey shale bedrock, effervesces without etching	מאמאלאאלאל		bentonite seal. Continued below with a NQ-2 size double tubed wireline core barrel with diamond bit to end of coring at 23.0 feet. Core hole was backfilled with bentonite and the remainder of the bore hole was backfilled with cuttings and ground
-	Run		#2						moderately soft, intensely to moderately fractured horizontally along bedding planes, high angle fracture from 10.1 to 10.4 feet, very thin bedding, slighty porous	<u> </u>		Run Depth Length REC REC RQD WL
15_									no iron staining, core pieces range from (0.05-0.55'). Dark gray shale bedrock,	Bentor		9.1 1 to 3.9 3.8 97 38 20 13.0
-									horizontally along bedding planes with several high angle and vertical fractures <u>17.3</u> along with occasional layers			13.0 2 to 5.0 5.0 100 15 50 18.0
-	Run		#3						of very intensely fractured rock.			18.0 3 to 5.0 5.0 100 62 50 23.0
_20									See next sheet			

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>					Но	ole N	umber <u>BH-E7-22</u>	Surfa	Surface Elevation:					
Proje	ect Na	ame:	Prop	osed S	Site De	evelop	ment		Northing:1010130		Easting:			
Proje	ect Lo	catio	on:	Town o	of Orch	nard Pa	ark, E	rie C	ounty, NY	Date	Started:5/2/2022			
Clien	t:	cMah	on & I	Mann C	Consult	ing Er	ginee	ering	& Geology, P.C.	Date	e Completed: <u>5/2/2022</u>			
Depth (ft)	SN	Rec (in)	<u>Blow</u> 0/6	<b>s on</b> 6/12	<b>San</b>	18/24	N	LITH	Description and Classification	Well	Water Table and Remarks			
<pre>(it)</pre>	Run		0/6 #3						Dark gray shale bedrock, soft, intensely to moderately fractured horizontally along bedding planes, high angle to vertical fracture from 19.6 to 20.1 feet, very thin to thin bedding, dense, no iron staining, core breaks appear fresh, core pieces range from (0.07-0.7'). Coring completed at 23 ft	Bentonite Seal	Run Depth Length REC REC RQD WL         # (ft) (ft) (ft) % % gal         18.0         3 to 5.0 5.0 100 62 50         23.0    EDI Bedrock Hardness Classification			
40														

## BUFFALO BILLS STADIUM PROJECT NO. 22-011

BORE CORE

HOLE #	RUN #	DATE	DEPTH (ft)	LENGTH (ft)	REC (ft)	REC. %	RQD. %
BH-E7-22	1	5-2-22	9.1-13.0	3.9	3.8	97	38
BH-E7-22	2	5-2-22	13.0-18.0	5.0	5.0	100	15
BH-E7-22	3	5-2-22	18.0-23.0	5.0	5.0	100	62



Geotechnical and Environmental Drilling | Wetland Delineations and Consulting

1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>	lole Number <u>BH-F3-22</u>	Surface Elevation: 757.5
Project Name: Proposed Site Developmen	nt Northing:1	1010088 <b>Easting:</b> <u>1091817</u>
Project Location: Town of Orchard Park,	Erie County, NY	Date Started: <u>4/21/2022</u>
Client: McMahon & Mann Consulting Engin	eering & Geology, P.C.	Date Completed: <u>4/22/2022</u>

			Blows	s on	Sam	npler						
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification		Well	Water Table and Remarks
	1	16	1	1	3	4	4	0.0 0.0 0.0	Moist dark brown 0.: (SAND-SILT-CLAY) topsoil fill with 0 to 3% gravel, little sand and clay, trace to little organic matter, very soft, <u>1.</u>			Silty topsoil fill with little sand and clay, trace to little organic matter, trace gravel to 0.3 feet over silty soil fill with little sand and clay, trace organic matter to 1.6 feet over clayor, clackwater codiment with
-	2	20	5	6	4	7	10		Massive soil structure, (ML-CL). Moist brown (SAND-SILT-CLAY) fill with 3 to 7% gravel, little sand and clay, trace organic matter,			trace sand and organic matter to 2.8 feet over silty glacial drift with some gravel and flat sided stone fragments, little sand and clay to 7.0 feet over shaley glacial till with little sand, trace clay to 11.2 feet over
5_	3	20	6	7	6	8	13		firm, massive soil structure, (ML-CL). Moist to dry brown to orangish brown (CLAYEY-SILT) with some			apparent shale bedrock to 14.9 feet over shale bedrock to end of coring.
-	4	22	6	7	19		26		Clay, trace sand and organic matter, stiff, blocky soil structure, (ML). Moist gray gravelly (SAND-SILT-CLAY) with 20 to			Note: Water level at 6.0 feet below ground surface after leaving augers in overnight at 14.9 feet.
-	5	24	11	11	11		22		A0% gravel and hat sided shale stone fragments, little sand and clay, stiff, massive soil structure, (ML-CL),(GC). Moist gray very gravelly (SILTY-SAND) with 30 to		ings Backfill	Note: Water level at 8.0 feet below ground surface at coring completion with tooling removed from bore hole.
-	6	15	6	12	50/4		-		50% mostly flat sided shale stone fragments, little silt, trace clay, dense and compact, massive soil <u>11.3</u> structure, (SM).		Cutt	Note: Advanced bore hole with 4 1/4" ID x 8" OD hollow stem auger casing with continuous split spoon sampling to auger refusal at 14.9 feet. Continued below with a NQ-2 size double tubed wireline core
-	7	2	50/2						very soft to soft.			barrel with diamond bit to end of coring at 24.2 feet. Core hole was backfilled with bentonite and the remainder of the bore hole was backfilled with cuttings and ground surface renaired to match
15	8	2	50/3						14.3		14.9	surrounding conditions upon completion.
-	Run		#1						Dark gray shale bedrock, soft, very intensely fractured, very thin to thinly bedded, core pieces range from <u>16.4</u> (0.025-0.2').	ערארארא	eal	Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % % gal
-									Dark gray shale bedrock, soft, intensely fractured horizontally along bedding planes with a high angle fracture from 17.7 to 17.9	ארארא	3entonite S	14.9 1 to 4.3 4.1 95 16 30 19.2
- 20	Run		#2						feet and short vertical fractures from 18.5 to 18.6 19.3 and 19.3 to 19.4 feet, dense, /			19.2 2 to 5.0 4.9 98 82 50 24.2

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI J	ob C	ode:	12k	(93e	 Site De	evelon	<b>Ho</b> ment	ole Ni	umber <u>BH-F3</u>	<u>8-22</u>	0088	Surfa	ace Elevation: <u>757.5</u>			
Proje		ime:		Town o	of Orch	nard P	ark F	rie Co	NY NY	Northing:	0000	<b>D</b> -1-	Easting:			
Proje	CT LO	cMab	on & I	Mann (		ting Fr		ring 2				Date Statled: $\frac{4/22}{2022}$				
Clien	t:				Jonsun		igine		a deology, r.c.			Date				
Depth (ft)	SN	Rec (in)	<u>Blow</u> 0/6	<b>on</b> 6/12	<b>San</b>	18/24	N	LITH	Description	and Classification		Well	Water Table and Remarks			
	Run		#2						Dark gray sh soft, intense fractured ho bedding plan iron staining appear fresh range from (	hale bedrock, ly to moderately rizontally along nes, dense, no , core breaks , core pieces (0.2-0.8').		1.시자시자시가시가 Bentonite Seal	Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % % gal 19.2 2 to 5.0 4.9 98 82 50 24.2			
-											24.2	24.2	EDI Rodrock Hardness Classification			
25	¥								Coring comp	leted at 24.2 ft		<u>, , , , , , , , , , , , , , , , , , , </u>	<ul> <li>Di Bedrock Hardness Classification</li> <li>Very Soft: Can be scratched with fingernail. Slight indentation produced by light blow of point of geologic pick. Requires power tools for excavation.</li> <li>Soft: Hand-held specimen crumbles under firm blows with point of geologic pick.</li> </ul>			
30																
- 35_ -																
-																

# BUFFALO BILLS STADIUM

PROJECT NO. 22-011

BORE HOLE #	CORE RUN #	DATE	DEPTH (ft)	LENGTH (ft)	REC (ft)	REC. %	RQD. %
BH-F3-22	1	4-22-22	14.9-19.2	4.3	4.1	95	16
BH-F3-22	2	4-22-22	19.2-24.2	5.0	4.9	98	82



Geotechnical and Environmental Drilling | Wetland Delineations and Consulting

1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u> Hole Number _	BH-F4-22	Surface Elevation: 757.8
Project Name: Proposed Site Development	Northing:1010050	Easting:
Project Location: Town of Orchard Park, Erie County, N	<u>/</u>	Date Started:
Client: McMahon & Mann Consulting Engineering & Geolog	y, P.C.	Date Completed: <u>4/12/2022</u>

		<b>_</b>	Blow	s on	San	npler					
Depth (ft)	SN	(in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification		Water Table and Remarks
								021	Tar and chip surface.	~_0.1/	Tar and chip surface to 0.1 feet over
-	1	18	12	7	3				Moist gray very gravelly (SAND) fill with 40 to 60% mostly angular gravel, trace silt, compact, massive soil structure, (SM),(GM).	0.7 2.0	sandy soil fill with some gravel, trace silt to 0.7 feet over silty soil fill with some flat sided shale stone fragments, little sand and clay to 2.0 feet over silty topsoil with little clay,
	2		2						Moist dark gray very gravelly		trace to little sand, trace organic
_		20		2	3	ц	5		I (SAND-SILT-CLAY) fill with 30 to I 50% mostly flat sided shale stone I fragments, little sand and clay, stiff I to very stiff, massive soil structure,	3.0	matter to 3.0 feet over silty slackwater sediment with little to some clay, trace sand, gravel, and organic matter to 5.0 feet over silty alocial till with little to some flat
-	3	24	3	4					I grades downward to	5.0	sided shale stone fragments, little sand and clay to 6.0 feet over silty
5_				4	9		13	<u> </u>	I Moist dark gray (SAND-SILT-CLAY)	<u> </u>	glacial till with little to some clay, trace to little sand and flat sided shale stone fragments to 9.0 feet
_	4		3			10			Weakly thinly laminated and thinly	<u> </u>	over apparent shale bedrock to 12.0 feet over shale bedrock to end of coring.
-		20		9	9		18	بة م 0.0 1	$\begin{array}{c c c c c c c c c c c c c c c c c c c $		Note: Water pouring in at 0.8 feet upon well completion.
-						13		0.0	Moist faintly mottled olive gray		Water level at 6.8 feet below ground
-	5	22	10	19	40		59	0.0.1 • <del>0</del> •	(CLAYEY-SILT) with 0 to 3% gravel,       little to some clay, trace sand and       organic matter, firm, weakly thinly	<u>9.0</u>	surface at coring completion with tooling removed.
10_						50/5			llenses and nearly vertical gray		surface at end of day on 04/11/2022 prior to coring.
-	D	16	5	11	36		47		Illoward (CL).		Water level at 4.0 feet below ground surface after hole sat open overnight.
						50/3			IDry to moist grayish brown to olive	12.0	Note: Advanced bore hole with 4
	∱Run		#1						With 15 to 30% mostly shale stone		1/4" ID x 8" OD hollow stem auger
_									Ijfragments, little sand and clay, very    Ijstiff, massive soil structure, (ML-CL).   		sampling to auger refusal at 12.0 feet. Removed rods and installed a
_									Moist to wet olive gray to dark gray		a NQ-2 size double tubed wireline core barrel with diamond bit to
15_									to 25% mostly shale stone		coring completion at 32.0 feet. Removed tooling and installed a
_									fragments, little to some clay, trace to little sand, very stiff, massive soil structure, (ML-CL) tending toward		2-inch PVC standpipe piezometer in completed bore hole to 32.0 feet.
_	¥								(CL).		Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % % gal
	Run		#2						Wet dark gray shale stone		12.0
-									in agments, very soft to soft.		1 to 5.0 5.0 100 44 15 17.0
20									See next sheet	19.2	17.0 2 to 5.0 5.0 100 72 20 22.0

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>	Hole Number <u>BH-F4-22</u>	Surface Elevation: 757.8
Project Name: Proposed Site Developm	nent Northing:	1010050 <b>Easting:</b> <u>1092013</u>
Project Location: Town of Orchard Par	rk, Erie County, NY	Date Started:
Client: McMahon & Mann Consulting Eng	jineering & Geology, P.C.	Date Completed: <u>4/12/2022</u>

		_	Blows	s on	Sam	<u>ipler</u>				
Depth	SN	Rec					Ν	LITH	Description and Classification	Water Table and Remarks
(ft)		(in)	0/6	6/12	12/18	18/24				
	Run		#2						Dark gray shale bedrock, soft, thinly	Run Depth Length REC REC RQD WL
	-								laminated, intensely fractured	# (ft) (ft) (ft) % % gal
-									horizontally along bedding planes	
									with high angle fractures from 12.4	17.0
									to 12.5, 13.2 to 13.3, 13.8 to 15.9,	2 to 5.0 5.0 100 72 20
-	X								and 17.0 to 17.1 feet with occasional	22.0
	Run		#3						thin pyrite deposites, dense, no iron	
									staining, core breaks appear fresh,	22.0
-									core lengths range from (0.01-1.0').	3 to 5.0 5.0 100 94 35
									Dark gray shale bedrock, soft, thinly	27.0
									laminated, moderately fractured	
-									horizontally along bedding planes	27.0
									with a near vertical fracture from	4 to 5.0 5.0 100 68 40
25									27.8 to 31.5 feet, fracture is partially	32.0
25_									healed, dense, no iron staining,	
									occasional thin pyrite deposits, core	
									breaks appear fresh, core lengths	
-									range from (0.1-1.6').	EDI Bedrock Hardness Classification
	$\checkmark$									Very Soft: Can be scratched with
	$\wedge$									fingernail. Slight indentation
	Run	+	#4							produced by light blow of point of
										aeologic pick. Requires power tools
										for excavation.
_										
										Soft: Hand-held specimen crumbles
										under firm blows with point of
30_										geologic pick.
-										
									22.0	
-	V	-							52.0	
									Coring completed at 32 ft	
-										
-										
35										
_										
_										
_										
-										
40										
40										

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code:	Hole Number	22		Surface Elevation: 757.8
Projec	t Name:_	Proposed Site Development	Northing:	1010050	Easting: <u>1092013</u>
Projec	t Locatio	on: Town of Orchard Park, Erie County, NY			Date Started:
<b>Client:</b>	McMaho	on & Mann Consulting Engineering & Geology, P.C.			Date Completed: <u>4/12/2022</u>
Depth (ft)		Well			Remarks
	S J	8-inch Road Box Installed in Concret	e		
-		4 $4$ $4$ $4$ $4$ $4$ $4$ $4$ $4$ $4$			
-		Cuttings Backfill			
-		$\frac{1}{2}$			
5_					
-					
-					
-					
10					
10_					
		11.0			
-					
-		Bentonite Seal			
-					
-					
15_					
-		16.0			
-					
-		#00N Size Morie Sand Pack			
20					

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code: <u>12K93e</u> Hole Number <u>W-F4-</u>	22	Surface Elevation: <u>757.8</u>
Project	t Name: Proposed Site Development	Northing:	Easting: <u>1092013</u>
Project	t Location:Town of Orchard Park, Erie County, NY		Date Started:
Client:	McMahon & Mann Consulting Engineering & Geology, P.C.	_	Date Completed: <u>4/12/2022</u>
Depth (ft)	Well		Remarks
	2-inch Schedule 40 FJT PVC Riser		
25_	0.010 Slot Screen		
30_	#00N Size Morie Sand Pack		
- 35_ - -			
40			

# BUFFALO BILLS STADIUM PROJECT NO. 22-011

BO	RE	CORE							
HOL	_E #	RUN #	DATE	DEPTH (ft)	LENGTH (ft)	REC (ft)	REC. %	RQD. %	
BH-F	4-22	1	4-12-22	12.0-17.0	5.0	5.0	100	44	
BH-F	-4-22	2	4-12-22	17.0-22.0	5.0	5.0	100	72	
BH-F	-4-22	3	4-12-22	22.0-27.0	5.0	5.0	100	94	
BH-F	4-22	4	4-12-22	27.0-32.0	5.0	5.0	100	68	
0				10"		24"			
0				12		<u></u>			



Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>	Hole Number <u>BH-F5-22</u>	Surface Elevation: 758	
Project Name: Proposed Site Developm	ent Northing:	1010011 <b>Easting:</b> <u>1092210</u>	
Project Location: Town of Orchard Par	<, Erie County, NY	Date Started:	
Client: McMahon & Mann Consulting Eng	neering & Geology, P.C.	Date Completed: <u>4/20/2022</u>	

Denth		Blows on Sampler				<u>ipler</u>						
(ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	Water Table and Remarks		
-	1	18	6	6	18	22	24		Tar and chip surface. Wet light grayish brown very gravelly (SILTY-SAND) fill with 40 to 60% gravel and shale stone fragments, little silt, trace slag,	Tar and chip surface to 0.1 feet over sandy soil fill with some gravel and shale stone fragments, little silt, trace slag to 2.5 feet over clayey slackwater sediment with trace sand and organic matter to 3.5 feet over		
-	2	20	2	3	5	10	8			silty glacial till with little to some clay and shale stone fragments, trace sand to 6.5 feet over silty glacial till with some shale stone fragments, little to some sand, little clay to 9.0 feet over apparent shale		
5_	3	20	5	9	15		24	······	with very thin coarse silt lenses, (CL).	bedrock to 13.5 feet over shale bedrock to end of coring. Water level at 8.0 feet below ground		
-	4	24	8	27	30	20	57		Dry to moist grayish brown gravelly (CLAYEY-SILT) with 10 to 25% mostly flat sided shale stone fragments, occasional channer, little to some clay, trace sand, very stiff, massive soil structure, (ML-CL)	surface prior to coring. Water level at 6.5 feet below ground surface after coring and hole sat open overnight to 24.0 feet.		
10_	5	22	15	25	34	48	59		tending toward (GC). <u>grades downward to</u> Moist dark gray very gravelly (SAND-SILT-CLAY) with 40 to 60% mostly flat sided shale stope	Note: Advanced bore hole with 4 1/4" ID x 8" OD hollow stem auger casing with continuous split spoon		
-	6	20	26	34	30	50/3	64		fragments, little to some sand, little clay, hard, massive soil structure, (ML-CL) tending toward (GM),(GC). Moist to wet dark gray shale stone fragments, very soft to soft.	sampling to 13.5 feet. Removed rods and installed a bentonite seal. Continued below with a NQ-2 size double tubed wireline core barrel with diamond bit to coring completion at 24.0 feet. Reamed		
-	7	4	50/4						13.5	core hole with a 3 7/8" tricone roller bit and installed a 2-inch PVC standpipe piezometer to 18.0 feet in completed bore hole.		
15_	Run		#1						Dark gray shale bedrock, soft, thinly laminated, intensely fractured horizontally along bedding planes with high angle to near vertical fractures from 13.8 to 13.9, 14.6 to 14.7, 15.2 to 15.3, 15.6 to 16.4, 16.9 to 17.2 and 17.6 to 18.0 foot	Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % % gal		
-									dense, no iron staining, core breaks appear fresh, core lengths range from (0.01-0.45').	13.5 1 to 4.5 4.2 93 36 50 18.0		
-	Run		#2						18.0	2 to 1.0 0.8 80 80 10 19.0		
20	Run		#3						See next sheet	19.0 3 to 5.0 5.0 100 98 50 24.0		

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>	Hole Number <u>BH-F5-22</u>	Surface Elevation: 758
Project Name: Proposed Site Developm	ent Northing:10100	011 Easting: <u>1092210</u>
Project Location: Town of Orchard Parl	k, Erie County, NY	Date Started: 4/19/2022
Client: McMahon & Mann Consulting Eng	ineering & Geology, P.C.	Date Completed: <u>4/20/2022</u>

Denth		Dee	Blows	s on	Sam	pler				
Uepth (ft)	SN	(in)	0/6	6/12	12/10	10/24	Ν	LITH	Description and Classification	Water Table and Remarks
(10)		()	0/6	6/12	12/18	18/24				
	<b>D</b> .							<u> </u>	Dark grav shale bedrock soft thinly	Run Depth Length REC REC RQD WL
	Run		#3						laminated, moderately to slightly	# (ft) (ft) (ft) % % gal
-									fractured horizontally along bedding	
									planes, dense, no iron staining, core	19.0 2 to E.O. E.O. 100 08 EO
									breaks appear fresh, core lengths	24.0
_									Talige Itolii (0.3-1.45).	
-										EDI Bedrock Hardness Classification
_	$\checkmark$								24.0	Very Soft: Can be scratched with
									Coring completed at 24 ft	fingernail. Slight indentation
25										aeologic pick. Requires power tools
25_										for excavation.
-										Soft, Hand-hold specimen crumbles
										under firm blows with point of
										geologic pick.
-										
-										
30										
-										
-										
-										
-										
35_										
-										
_										
-										
40										
Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code: <u>12K93e</u> Ho	le Number <u>W-F5-22</u>	Surface Elevation:
Project	t Name: Proposed Site Development	Northir	ng: <u>1010011</u> Easting: <u>1092210</u>
Project	t Location: Town of Orchard Park, Er	ie County, NY	Date Started: <u>4/20/2022</u>
Client:	McMahon & Mann Consulting Enginee	ring & Geology, P.C.	Date Completed: <u>4/20/2022</u>
Depth (ft)	Well		Remarks
(ft) 	Image: Second	Installed in Concrete 40 FJT PVC Riser	
- 	18.0		
20	<u> たたたた</u> Bentonite Seal		

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code: <u>12K93e</u> Hole Number <u>W-F5-</u>	22		Surface Elevation: 758
Projec	t Name: Proposed Site Development	Northing	1010011	<b>Easting:</b> <u>1092210</u>
Projec	t Location:Town of Orchard Park, Erie County, NY			Date Started: <u>4/20/2022</u>
Client:	McMahon & Mann Consulting Engineering & Geology, P.C.			Date Completed: <u>4/20/2022</u>
Depth (ft)	Well			Remarks
  25	Bentonite Seal $\begin{array}{c} & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & & \\ & & & \\ & & & \\ & & & \\ & & & \\ & & & \\ & & & \\ & & & \\ & & & \\ & & & \\ & & & \\ & & & \\ & & & \\ & & & \\ \end{array}$			
-				
30_ - -				
35_ - - -				
40				

### **BUFFALO BILLS STADIUM** PROJECT NO. 22-011

BORE HOLE #	CORE RUN #	DATE	DEPTH (ft)	LENGTH (ft)	REC (ft)	REC. %	RQD. %
BH-F5-22	1	4-19-22	13.5-18.0	4.5	4.2	93	36
BH-F5-22	2	4-19-22	18.0-19.0	1.0	0.8	80	80
BH-F5-22	3	4-19-22	19.0-24.0	5.0	5.0	100	98



Geotechnical and Environmental Drilling | Wetland Delineations and Consulting

1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u> Hole Number <u>Bt</u>	1-F6-22	Surface Elevation: <u>760.5</u>
Project Name: Proposed Site Development	Northing: <u>1009973</u>	Easting:
Project Location: Town of Orchard Park, Erie County, NY	-	Date Started: <u>4/19/2022</u>
Client: McMahon & Mann Consulting Engineering & Geology,	P.C	Date Completed: <u>4/19/2022</u>

		-					i —			-					
Depth (ft)	SN	Rec (in)	<u>Blows</u> 0/6	<b>5 01</b> 6/12	Sam 12/18	18/24	N	LITH	Description and Classification		Well	Water Table and Remarks			
	1	20	6	9	3	4	12		Tar and chip surface.       0.1         Wet brownish gray very       1.0         gravelly (SAND) fill with 40 to       1.5         60% gravel and shale stone       1.5         fragments, trace silt and slag,       2.0			Tar and chip surface to 0.1 feet over sandy soil fill with some gravel and shale stone fragments with trace silt and slag to 1.0 feet over clayey soil fill with trace sand, gravel, and organic matter to 1.5 feet over			
-	2	24	4	6	13	10	19		Compact, massive soil     Structure, (SM),(GM).     Moist olive gray     (CLAYEY-SILT) fill with 0 to     3% gravel, some clay, trace     sand and organic matter,			sandy soil fill with some shale stone fragments, little to some silt to 2.0 feet over silty slackwater sediment, little to some clay, trace sand to 3.0 feet over shaley glacial till with little to some sand, little clay to 10.0			
5_	3	20	3	8	12	27	20		firm, massive soil structure,    (CL).    Moist to wet grayish brown    very gravelly (SILTY-SAND)    fill with 20 to 40% mostly			feet over apparent shale bedrock to 13.9 feet over shale bedrock to end of coring.			
_	4	22	21	11	14	13	25		Isole stone fragments, little Ito some silt, loose, massive Isoil structure, (SM),(GM).			No water prior to coring.			
-	5	24	13	27	34	36	61		I (CLAYEY-SILT) with little to Isome clay, trace sand, stiff, Iweakly thinly laminated with Ivery thin coarse silt lenses, I(ML-CL) tending toward (CL).		ings Backfill	Water level at 7.5 feet below ground surface at coring completion with tooling removed from bore hole.			
-	6	5	50/5						Dry dark gray (SAND-SILT-CLAY) with 40 to 60% mostly shale stone fragments, little to some		Cutt	Note: Advanced bore hole with 4 1/4" ID x 8" OD hollow stem auger casing with continuous split spoon sampling to 13.9 feet. Removed rods and installed a bentonite seal. Continued below with a NQ-2 size			
-	7	1	50/2						I sand, little clay, very stiff to I hard, massive soil structure, I(ML-CL) tending toward I(GM),(GC).		13.9	double tubed wireline core barrel with diamond bit to end of coring at 23.9 feet. Core hole was backfilled with bentonite and the remainder of the bore hole was backfilled with cuttings and ground surface			
15_	`Run		#1						Dry dark gray weathered shale stone fragments, very soft to soft. Dark gray shale bedrock,	אראראא		conditions upon completion.			
-									soft, thinly laminated, intensely to moderately fractured horizontally along bedding planes with	<u>NANA</u>	Seal	Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % % gal			
-									occasional high angle to near vertical fractures from 14.8 to 14.9 and 16.3 to 16.8 feet,	1212	entonite	13.9 1 to 5.0 5.0 100 58 0 18.9			
20	Run		#2						core breaks appear fresh, no iron staining, core lengths <u>19.0</u> range from (0.01-0.65'). See next sheet	<u> </u>	Ē	18.9 2 to 5.0 5.0 100 88 0 23.9			

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI J	ob Co	ode:	_12K	93e			Но	ole N	umber <u>BH-F6-22</u>	Surfa	ace Elevation: <u>760.5</u>	
Project Name: Proposed Site		Site De	evelop	ment		Northing:1009973_	Easting:1092406					
Proje	Project Location: Town of Orchard Parl								ounty, NY	Started:		
Clien	t:	cMah	on & I	Mann C	Consult	ting Er	nginee	ering	& Geology, P.C.	Date	Completed: <u>4/19/2022</u>	
			Blow	s on	Sam	npler	Í –					
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	Well	Water Table and Remarks	
	Run		#2						Dark gray shale bedrock, soft, thinly laminated, moderately to slightly fractured horizontally along bedding planes, occasional thin pyrite deposits, no iron staining, core breaks appear fresh, core lengths range from (0.05-0.92'). 23.5 Coring completed at 23.9 ft	Bentonite Seal	Run Depth Length REC REC RQD WL         # (ft) (ft) (ft) % % gal         18.9         2 to 5.0 5.0 100 88 0         23.9         EDI Bedrock Hardness Classification         Very Soft: Can be scratched with         fingernail. Slight indentation         produced by light blow of point of         geologic pick. Requires power tools         for excavation.         Soft: Hand-held specimen crumbles         under firm blows with point of         geologic pick.	
- 30 - - 35												
- - -												

## **BUFFALO BILLS STADIUM**

PROJECT NO. 22-011

BORE HOLE #	CORE RUN #	DATE	DEPTH (ft)	LENGTH (ft)	REC (ft)	REC. %	RQD. %
BH-F6-22	1	4-19-22	13.9-18.9	5.0	5.0	100	58
BH-F6-22	2	4-19-22	18.9-23.9	5.0	5.0	100	88



Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u> Hole Number <u>BH-F</u>	7-22	Surface Elevation: 761.6	
Project Name: Proposed Site Development	Northing:	Easting:	
Project Location: Town of Orchard Park, Erie County, NY	-	Date Started: <u>5/6/2022</u>	
Client: McMahon & Mann Consulting Engineering & Geology, P.C	<u>.                                    </u>	Date Completed: <u>5/10/2022</u>	

	Blows on Sampler									
Depth (ft)	SN	(in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	Water Table and Remarks
	1	20	7	12	12	16	24		Tar and chip surface. Mostly crushed concrete fill. Dry grayish brown and brownish gray gravelly (SANDY-SILT) with 25 to 40% mostly flat sided shale stone	Tar and chip surface to 0.1 feet over mostly crushed concrete fill to 0.4 feet over coarse silty glacial till with some mostly flat sided shale stone fragments, little sand, trace clay to 5.0 feet over shaley glacial till with
-	2	22	12	12	15	18	27		fragments, little sand, trace clay, compact, massive soil structure, (SM),(GM).	some sand, little silt with an occasional shale channer to 5.8 feet over apparent shale bedrock to 11.8 feet over shale bedrock to end of coring.
5_	3	24	18	31	35	22	66		5.0 Wet gray very gravelly (SILTY-SAND) with 40 to 60% 5.8 mostly flat sided shale stone	
-	4	24	29	39	37	48	76		fragments, occasional channer, little silt, very dense, massive soil structure, (SM),(GM). Gray shale stone fragments, very soft to soft.	Note: Water level at 4.5 feet below ground surface prior to coring. Note: Water level at 3.0 feet below ground surface after leaving hole open to 16.8 feet.
- 10_	5	24	28	35	31	47	66			Note: Water level at 3.0 feet below ground surface at coring completion with tooling removed from bore
-	6	9	27	50/3					11.8	hole. Note: Advanced bore hole with 4 1/4" ID x 8" OD hollow stem auger casing with continuous split spoop
-	Run		#1						Dark gray shale bedrock, soft, intensely fractured, very thin to thinly bedded, dense, core breaks appear fresh, no iron staining, core pieces range from (0.025-0.5').	sampling to 11.8 feet. Removed drill rods and installed a bentonite seal. Continued below with a NQ-2 size double tubed wireline core barrel with diamond bit to coring completion at 25.5 feet. Reamed
15_										core hole with a 3 7/8" tricome roller bit and installed a 2-inch PVC standpipe piezometer to 20.5 feet in completed bore hole.
-	Run		#2							Run Depth Length REC REC RQD WL           # (ft) (ft) (ft) % % gal           11.8           1
-									19.5	1 to 5.0 4.8 96 17 30 16.8 2 to 3.7 3.7 100 21 45 20.5
20								F	See next sheet	

EARTH DIMENSIONS, INC. Geotechnical and Environmental Drilling | Wetland Delineations and Consulting

Geotechnical and Environmental Drilling | Wetland Delineations and Consult 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI J	ob C	ode:	12K	93e			Но	ole N	umber <u>BH-F7-22</u>	Su	rface Elevation: <u>761.6</u>
Proje	ct Na	ame:	Prop	osed S	Site De	evelop	ment		Northing:		<b>Easting:</b> <u>1092602</u>
Proje	ct Lo	catio	on:	Town o	of Orch	nard Pa	ark, E	rie C	ounty, NY	Da	te Started: <u>5/6/2022</u>
Clien	t:M	cMah	on & I	1ann C	Consult	ing Er	nginee	ering	& Geology, P.C.	Da	te Completed: <u>5/10/2022</u>
Depth (ft)	SN	Rec (in)	<u>Blow</u> 0/6	s on 6/12	<b>Sam</b>	18/24	N	LITH	Description and Classification		Water Table and Remarks
25_	Run		#2 #3						Dark gray shale bedrock, soft, moderately fractured horizontally along bedding planes, very thin to thinly bedded with an occasional thin very soft shale interbed, dense, no iron staining, occasional thin pyrite deposits, core breaks appear fresh, core pieces range from (0.2-1.0'). Coring completed at 25.5 ft	25.5	Run Depth Length REC REC RQD WL         # (ft)       (ft)       %       gal         16.8       2       to       3.7       3.7       100       21       45         20.5       20.5       20.5       20.5       20.5       20.5         20.5       20.5       20.5       20.5       20.5       20.5         20.5       20.5       5.0       100       60       60         25.5       EDI Bedrock Hardness Classification       25.5       20.5       20.5         Very Soft: Can be scratched with fingernail. Slight indentation produced by light blow of point of geologic pick. Requires power tools for excavation.         Soft: Hand-held specimen crumbles under firm blows with point of geologic pick.       20.5

#### N = Number of Blows to Drive 2" Spoon 12" with 140lb. Weight Falling 30" per Blow

40

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code:	12K93e	Hole Number	F7-22		Surface Elevation:	761.6
Projec	t Name:_	Proposed Si	te Development	Northi	ng: <u>1009934</u>	Easting: _1	092602
Projec	t Locatio	n: Town of	Orchard Park, Erie County, NY		Date Started: <u>5/1</u>	.0/2022	
Client:	McMaho	on & Mann Co	nsulting Engineering & Geology, P	.C		Date Completed: _	5/10/2022
Depth (ft)		١	Well			Remarks	
- - - 5 - - - - - - -		1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0       1.0 </td <td>8-inch Road Box Installed in Conc Pad Cuttings Backfill 2-inch Schedule 40 FJT PVC Riser</td> <td>rete</td> <td></td> <td></td> <td></td>	8-inch Road Box Installed in Conc Pad Cuttings Backfill 2-inch Schedule 40 FJT PVC Riser	rete			
- - - 15 -			Bentonite Seal #00N Size Morie Sand Pack				
- 20							

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code: <u>12K93e</u> Hole Number <u>W-F7-</u>	22	Surface Elevation: <u>761.6</u>
Projec	t Name: Proposed Site Development	Northing: <u>1009934</u>	Easting:1092602
Projec	t Location:Town of Orchard Park, Erie County, NY		Date Started:
Client:	McMahon & Mann Consulting Engineering & Geology, P.C.		Date Completed: <u>5/10/2022</u>
Depth (ft)	Well		Remarks
(ft) 	Image: Weil     Image: Constraint of the second secon		
35_ - -			
40			

## BUFFALO BILLS STADIUM PROJECT NO. 22-011

BORE HOLE #	CORE # RUN #	DATE	DEPTH (ft)	LENGTH (ft)	REC (ft)	REC. %	RQD. %
BH-F7-2	2 1	5-6-22	11.8-16.8	5.0	4.8	96	17
BH-F7-2	22	5-9-22	16.8-20.5	3.7	3.7	100	21
BH-F7-2	23	5-9-22	20.5-25.5	5.0	5.0	100	60



Geotechnical and Environmental Drilling | Wetland Delineations and Consulting

1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u> Hole Number <u>BH-</u>	-G3-22	Surface Elevation: 757.1
Project Name: Proposed Site Development	Northing: <u>1009880</u>	Easting:
Project Location: Town of Orchard Park, Erie County, NY	2	Date Started:
Client: McMahon & Mann Consulting Engineering & Geology, P.	.C	Date Completed: <u>4/21/2022</u>

		<b>D</b>	Blows	s on	Sam	<u>pler</u>									
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification		Well	Water Table and Remarks			
	1	21	1	3	4	4	7		Moist dark brown 0.4 (SANDY-SILT) topsoil fill with little sand and organic matter, very loose, granular soil structure, (ML).			Coarse silty topsoil fill with little sand and organic matter to 0.4 feet over sandy soil fill, little to some shale stone fragments, little silt to 1.7 feet over clayey slackwater sediment with trace sand and occasional			
-	2	17	2	3	6	7	9	-0 -0 -0 -0	Moist brown gravelly (SILTY-SAND) fill with 15 to 25% mostly flat sided shale stone fragments, little silt, loose, massive soil structure, (GM).			dropstone to 5.5 feet over shaley glacial till with some sand, little silt to 12.2 feet over apparent shale bedrock to 14.9 feet over shale bedrock to end of coring.			
5_	3	22	3	5	5	7	10		Moist to dry olive gray (CLAYEY-SILT) with 0 to 3% gravel, some clay, trace sand, stiff, weakly thinly laminated with very thin coarse silt			Note: Water level prior to coring 6.0 feet below ground surface. Note: Water level at 9.5 feet below ground surface at coring completion with tooling removed from bore			
-	4	24	6	12	15	18	27		gray desiccation cracks, (CL).			hole. Note: Advanced bore hole with 4 1/4" ID x 8" OD hollow stem auger casing with continuous split spoon			
	5	20	7	18	14	21	32		(CLAYEY-SILT) with 0 to 3% gravel, some clay, trace sand, stiff, thinly laminated with very thin coarse silt lenses, (CL).	(CLAYEY-SILT) with 0 to 3% gravel, some clay, trace sand, stiff, thinly laminated with very thin coarse silt lenses, (CL).	sampling to auger refusal at 14.9 reet. Continued below with a NQ-2 size double tubed wireline core barrel with diamond bit to end of coring at 24.3 feet. Core hole was backfilled with bentonite and the				
-	6	18	10	18	33	33	51		clear transition to Dry gray to dark gray gravelly (SILTY-SAND) with 30 to 50% mostly flat sided shale stone fragments, little		Cut	remainder of the bore hole was backfilled with cuttings and ground surface was repaired to match surrounding conditions upon completion.			
-	7	8	23	50/5					silt, compact, dense below 7.0 feet, massive soil structure, (SM),(GM). Dark gray shale stone fragments, very soft to soft.						
									14 C	1	14.9				
15_	Run		#1						Dark gray shale bedrock, soft, very intensely to intensely fractured thinly	$\frac{1}{1}$	14.5	Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % % gal			
-							-		bedded, core breaks appear fresh, no iron staining, core pieces range from (0.025-0.4')		e Seal	14.9 1 to 2.9 2.2 76 13 50 17.8			
-	Run		#2						18.1		Bentonit	17.8 2 to 1.5 1.4 93 61 35 19.3			
-	Run		#3						See next sheet	<u>NANA</u>		19.3 3 to 5.0 5.0 100 72 85 24.3			
20			"5					<u></u>	See Hext Sheet	12					

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

	loh C	odou	12K	93e			Ц		mbor BH-G3-22	Surf	757.1
Proie	oct Na	oue:	Prop	osed S	— Site De	evelop	ment	ne nu	Northing: 1009880	Sulla	Easting: 1091840
Proje		catio	- -	Town o	of Orch	nard Pa	ark, E	rie Co	unty, NY	Date	Started: 4/21/2022
Clien	t: <u>M</u>	cMah	on & N	1ann C	Consult	ting Er	nginee	ering &	Geology, P.C.	Date	Completed: <u>4/21/2022</u>
			Blow	s on	San	npler					
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	Well	Water Table and Remarks
-	Run		#3						Dark gray shale bedrock, soft, very thinly to moderately bedded, moderately fractured horizontally along bedding planes, dense with occasional thin pyrite deposits, no iron staining, core pieces range from (0.05-1.2').	Free Seal       Bentonite Seal	Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % % gal 19.3 3 to 5.0 5.0 100 72 85 24.3 EDI Bedrock Hardness Classification
25_									Coring completed at 24.3 ft	<u> </u>	Very Soft: Can be scratched with fingernail. Slight indentation produced by light blow of point of geologic pick. Requires power tools for excavation. Soft: Hand-held specimen crumbles under firm blows with point of geologic pick.
30											
35_											

40

## **BUFFALO BILLS STADIUM** PROJECT NO. 22-011

BORE HOLE #	CORE RUN #	DATE	DEPTH (ft)	LENGTH (ft)	REC (ft)	REC. %	RQD. %
BH-G3-22	1	4-21-22	14.9-17.8	2.9	2.2	76	13
BH-G3-22	2	4-21-22	17.8-19.3	1.5	1.4	93	61
BH-G3-22	3	4-21-22	19.3-24.3	5.0	5.0	100	72



Geotechnical and Environmental Drilling | Wetland Delineations and Consulting

1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u> Hole Number <u>B</u>							umber _	BH-G4	H-G4-22			Surface Elevation: 758.9			
Project Name: Proposed Site Development									Northing:	1009853.35	5	Easting	: 1091974.61		
Project Location:							ounty, NY		2		Date	Started:	4/11/2022	_	
Client: McMahon & Mann Consulting Engineering & Geology								& Geology	y, P.C.			Date	Complete	ed: <u>4/11/2022</u>	_
		1		-	-										

		_	Blows	s on	Sam	npler							
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification		We	II	Water Table and Remarks
								<u> </u>	Tar and chip surface	/0.1	4		Tar and chip surface to 0.1 feet over
	4							0.03	Moist grow york grovelly	0.7	A I		sandy soil fill with some gravel, trace
_	1	4.0	14					۰	(CAND) fill with 40 to 60%		-		silt and slag to 0.7 feet over silty soil
		18		10	6		16	601	(SAND) III WILL 40 to 60%	1 10	41		fill with little to some shale stone
									silt and clag, compact				fragments, little clay, trace to little
-									i massive soil structure	li 2.2	~		sand to 1.6 feet over silty slackwater
	2		2					þ. S	(SM) (GM)	ir — — -	∆		sediment with little to some clay,
		24		4				_ م_		li –			trace sand, organic matter, and
-		24		4	7		11	<u>e</u> e	Moist dark gray to dark	li –			shale stone fragments to 2.2 feet
					'				CAND STIT CLAXA FIL with 1	li –	∆		little to some clay, trace to little
						9		0-0	to 30% mostly shale stope	li –	<u>.</u>		sand trace shale stone fragments to
-	2							- · · ·	fragments little clay trace to	1 A E			4.5 feet over silty glacial till with
	3		4					po:A	little sand very stiff massive	lii — <u>4.5</u> .	Δ		little to some shale stone fragments.
5_		22		5			9	<u>.</u>	soil structure. (MI-CI).	li	-		little sand and clay to 6.5 feet over
					4					11			sandy glacial till with some silt and
								.0.	grades downward to	11	∆∣		shale stone fragments to 10.0 feet
-						4		م م م	Moist dark gray	11	-		over silty glacial till with some sand
	4		4						(CLAYEY-SILT) with 0 to 5%	6.5	41		and shale stone fragments, trace to
		24		12					I mostly shale stone	11	Δ1		little clay to 11.9 feet over apparent
-		27		12	15		27	[°.U]	Ifragments, little to some clay,	11	-		shale bedrock to 14.0 feet over
					-10			00	Itrace sand and organic		<b>△</b>		shale bedrock to end of coring.
-						14			matter, stiff, weakly thinly		Δ		
	5		11					P.U.	llaminated to thinly bedded,		-		No water in bore hole prior to coring.
	5		11					10 Q	"I(ML-CL) tending toward (CL).	il i			
-		24		22			47	p.O.	制	ji –	Δ1		Last approximately 225 gallons of
					25			$\circ O$	grades downward to	ji –	- ·		water while coring between 19.0 and
10						26		o D	Moist faintly mottled brownish	1 10.0	41		34 0 feet below ground surface
10_	-					0		6 <del>0.</del> [-	gray (SAND-SILT-CLAY) with	l' <u></u>			54.0 reet below ground surface.
	6		3					[0]	5 to 10% mostly shale stone	胄	<u>-</u>		Water level at 7.0 feet below ground
_		22		24			10	POR	if fragments, little to some clay,	5	al a		surface at coring completion with all
					25		77	60.0	In trace to little sand, stiff to		. L		tooling removed.
								φĊ	Il very stiff, weakly blocky soll	11 0	- Du		
-						50/5			Instructure to weakly trilling		신표		Note: Advanced bore hole with 4
	7		50/2						Lucoarse silt lenses and nearly		S I		1/4" ID x 8" OD hollow stem auger
		2							uvertical gray desiccation	1	-		casing with continuous split spoon
-		2							incracks, (ML-CL) tending	1	41		sampling to auger refusal at 14.0
									itoward (CL).		Δ1		feet. Removed rods and installed a
_										14.0			a NO-2 size double tubed wireline
	Run		#1						grades downward to I		4		core barrel with diamond bit to end
								<b>  </b>	Moist dark gray gravelly		ΔΙ		of coring at 34.0 feet. Bore hole was
15_		$\left  - \right $							SAND-SILT-CLAY) with 20 to		<b>.</b>		backfilled with cuttings and ground
									40% mostly shale stone		4		surface repaired to match
									Ifragments, little sand and		Δ		surrounding conditions upon
-									Iclay, stiff, massive soil		<b>.</b>		completion.
								<u> </u>	Istructure, (ML-CL) tending	!	4		Run Denth Length DEC DEC DOD WI
_											Δ.		# (ft) (ft) (ft) % % as a
									arados downward to	1	-		" (it) (it) /0 /0 gai
											4		14.0
-											Δ		1 to 5.0 5.0 100 18 0
										i	<b>-</b>		19.0
								<u>  </u>		i	4		
-	Å.		<i>ш</i> р							I	Δ.		19.0
	Run		#2						See next sheet	19.8	<b>-</b>		2 to 5.0 5.0 100 38 75
20										15.8	41		24.0

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Co	<b>le:</b> 12K93e	Hole Number <u>BH-G4</u>	-22		Surface Elevation: 758.9	
Project Na	ne: Proposed Site Developm	nent	Northing:	1009853.35	Easting:	
Project Loc	ation: Town of Orchard Par	k, Erie County, NY	5		Date Started:	
Client: Mc	<pre>1ahon &amp; Mann Consulting Eng</pre>	ineering & Geology, P.C.			Date Completed:	

Denth		Dee	Blows on Sampler									
(ft)	SN	(in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	Well	Water Table and Remarks	
	Run		#2 #3 #4						Dry to moist dark gray very gravelly (SILTY-SAND) with 30 to 50% mostly shale stone fragments, some silt, compact to dense, massive soil structure, (SM),(GM). <u>grades downward to</u> Moist to wet dark gray very gravelly (SAND-SILT-CLAY) with 40 to 60% mostly shale stone fragments, some sand, trace to little clay, hard, massive soil structure, (GM). Dark gray shale stone fragments, very soft to soft. Dark gray shale bedrock, soft, thinly laminated, intensely fractured horizontally along bedding planes with high angle fractures at 14.7 to 14.8, 15.1 to 15.2, 15.7 to 16.2, 16.6 to 16.8, 17.3 to 17.5, 17.9 to 18.1, 18.7 to 18.8, 19.0 to 19.1, and 19.3 to 19.8 feet, dense, no iron staining, core breaks appear fresh, core lengths range from (0.01-0.5'). Dark gray to gray shale bedrock, soft, with a gray limestone nodule, moderately hard, from 26.5 to 27.2 feet, thinly laminated, moderately fractured horizontally along bedding planes with high angle fractures from 25.5 to 25.6, 31.5 to 31.6, 32.6 to 32.8, and 39.1 to 39.2 feet, dense, no iron staining, core breaks appear fresh, core lengths range from (0.12-1.3'). Coring completed at 34 ft	Cuttings Backfill 0.75	Run Depth Length REC REC RQD WL         # (ft) (ft) (ft) % % gal         19.0         2 to 5.0       5.0       100       38       75         24.0         3 to 5.0       5.0       100       84       75         29.0         4 to 5.0       5.0       100       84       75         29.0         4 to 5.0       5.0       100       88       75         34.0       5.0       5.0       100       88       75         29.0       4       to 5.0       5.0       100       88       75         29.0       4       to 5.0       5.0       100       88       75         34.0       Sol to 5.0       100       88       75         EDI Bedrock Hardness Classification       Very Soft: Can be scratched with fingernail. Slight indentation produced by light blow of point of geologic pick. Requires power tools for excavation.         Soft: Hand-held specimen crumbles under firm blows with point of geologic pick.       Moderately Hard: Cannot be peeled or scraped with knife. Can be distinctly scratched with a steel nail.	

#### BUFFALO BILLS STADIUM PROJECT NO. 22-011

CORE BORE DEPTH (ft) LENGTH (ft) REC (ft) REC. % HOLE # RUN # DATE RQD. % 14.0-19.0 19.0-24.0 18 38 84 88 BH-G4-22 BH-G4-22 4-11-22 4-11-22 5.0 5.0 100 100 1 5.0 5.0 2 BH-G4-22 BH-G4-22 4-11-22 4-11-22 24.0-29.0 100 100 3 5.0 5.0 5.0 29.0-34.0 5.0 4



Unconfined Compressive Strength: 1699.6 PSI

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting

1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

<b>EDI Job Code:</b> <u>12K93e</u> <b>Hol</b>	e Number <u>BH-G6-22</u>	Surface Elevation:
Project Name: Proposed Site Development	Northing: <sup>10</sup>	009776 <b>Easting:</b> <u>1092367</u>
Project Location: Town of Orchard Park, Er	ie County, NY	Date Started: <u>4/18/2022</u>
Client: McMahon & Mann Consulting Engineer	ring & Geology, P.C.	Date Completed: <u>4/18/2022</u>

			Blows	s on	San	npler								
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	Water Table and Remarks				
_	1	22	8	10	6	9	16		Tar and chip surface.       0.1         Moist brownish gray very gravelly       0.9         (SAND) fill with 40 to 60% gravel       0.9         and flat sided shale stone fragments,       1.8         trace silt and slag, compact, massive       1.8	Tar and chip surface to 0.1 feet over sandy soil fill with some gravel and shale stone fragments, trace silt and slag to 1.8 feet over silty soil fill with little to some shale stone fragments, little sand, trace to little clay, trace				
-	2	22	7	9	9	9	18		soil structure, (SM),(GM). Dry dark grayish brown gravelly (CLAYEY-SILT) fill with 10 to 25% mostly flat sided shale stone fragments, little clay, trace sand and wood fiber, very stiff, massive soil	slag to 8.5 feet over sandy glacial till with some shale stone fragments, little to some silt, trace to little clay to 11.5 feet over apparent shale bedrock to 13.8 feet over shale bedrock to end of coring.				
5_	3	22	5	13	20	20	33		structure, (ML-ĆL). Dry to moist dark gray to dark grayish brown gravelly (SAND-SILT-CLAY) fill with 20 to 40% mostly shale stone fragments,					
-	4	24	9	10	11	14	21		little sand, trace to little clay, trace slag, very stiff to hard, massive soil structure, (ML-CL).	Note: Advanced bore hole with 4 1/4" ID x 8" OD hollow stem auger casing with continuous split spoon sampling to 13.8 feet. Removed rods and installed a bentonite seal.				
10_	5	24	12	20	32	32	52		grades downward to8.5 Dry to moist dark gray very gravelly (SAND-SILT-CLAY) with 40 to 60% mostly shale stone fragments, little	double tubed wireline core barrel with diamond bit to end of coring at 28.8 feet. Reamed core hole with a 3 7/8" tricone roller bit and installed a 2-inch PVC standpipe piezometer to 25.0 feet in completed hore hole.				
-	6	22	17	30	32	50/5	62		to some slit, trace to little clay, hard, massive soil structure, (SM),(GM).					
-	7	1	50/2			_3073_			Dark gray shale stone fragments, very soft to soft.	Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % % gal				
15_	Run		#1						Dark gray shale bedrock, soft, thinly laminated, intensely to moderately fractured horizontally along bedding planes, dense, no iron staining, core	13.8 1 to 2.1 1.9 90 17 0 15.9				
	Run		#2						breaks appear fresh, core lengths range from (0.01-0.5').	15.9 2 to 3.1 3.1 100 68 0 19.0				
-										19.0 3 to 4.8 4.8 100 67 35 23.8				
20	Run		#3											

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting

1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>	Hole Number <u>BH-G6-22</u>	Surface Elevation:	
Project Name: Proposed Site Developme	ent Northing: _	1009776 Easting: 1092367	
Project Location: Town of Orchard Park	<, Erie County, NY	Date Started: <u>4/18/2022</u>	
Client: McMahon & Mann Consulting Engi	neering & Geology, P.C.	Date Completed: <u>4/18/2022</u>	

		_	Blow	s on	Sam	<u>ipler</u>				
Depth (ft)	SN	(in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	Water Table and Remarks
	Run		#3						Dark gray shale bedrock, soft, thinly	Run Depth Length REC REC RQD WL
									fractured borizontally along bedding	# (ft) (ft) (ft) % % gal
									$\neg$ planes, dense, no iron staining, core $21.3$	19.0
									breaks appear fresh, core lengths	3 to 4.8 4.8 100 67 35
-									range from (0.01-0.5°).	23.8
									Dark gray shale bedrock, soft, thinly laminated moderately to slightly	23.8
-									fractured horizontally along bedding	4 to 5.0 5.0 100 66 45
	$\checkmark$								planes with high angle to near	20.0
-	Bun		#1						25.1 to 25.2, 26.1 to 26.3, 26.6 to	
	Kull		#4						26.7, 26.9 to 27.0, and 27.2 to 27.4	
25_									feet, dense, no iron staining, core	
									range from (0.01-1.25').	
-										EDI Bedrock Hardness Classification
										Very Soft: Can be scratched with
-										fingernail. Slight indentation
										produced by light blow of point of
-										for excavation.
	$\checkmark$								28.8	
-									Coring completed at 28.8 ft	Soft: Hand-held specimen crumbles
20										under firm blows with point of
30_										geologic pick.
-										
-										
-										
-										
25										
35_										
-										
-										
-										
40										

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code: <u>12K93e</u> Hole Number <u>W-G6-</u>	-22 Surface Elevation: <u>760.6</u>
Projec	t Name: Proposed Site Development	Northing: <u>1009776</u> Easting: <u>1092367</u>
Projec	t Location: Town of Orchard Park, Erie County, NY	Date Started:
Client:	McMahon & Mann Consulting Engineering & Geology, P.C.	Date Completed: <u>4/18/2022</u>
Depth (ft)	Well	Remarks
-	8-inch Road Box Installed in Concret	ie l
-	$\begin{bmatrix} 1 & 1 & 1 & 1 \\ a_1 & a_2 & a_1 \\ a_1 & a_1 $	
-	2 - 4 3	
5_	$\begin{array}{cccccccccccccccccccccccccccccccccccc$	
-		
-		
10_	$\begin{bmatrix} a & a & b & a \\ a & b & a & b \\ a & b & a & b & a \\ a & b & a & a & b & a \\ a & b & a & a & b & a \\ a & b & a & a & b & a \\ a & b & a & a & b & a \\ a & b & a & a & b & a \\ a & b & a & a & b & a \\ a & b & a & a & b & a \\ a & b & a & b & a & b \\ a & b & a & b & a & b \\ a & b & a & b & a & b \\ a & b & a & b & a & b \\ a & b & a & b & a & b \\ a & b & a & b & a & b \\ a & b & a & b & a & b \\ a & b & a & b & a & b \\ a & b & a & b & a & b \\ a & b & a & b & a & b \\ a & b & a & b & a & b \\ a & b & a & b & a & b \\ a & b & a & b & b \\ a & b & a & b & b \\ a & b & a & b & b \\ a & b & b & a & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b & b & b & b \\ a & b $	
_	$\begin{array}{cccccccccccccccccccccccccccccccccccc$	
-	Bentonite Seal	
-		
-12	#00N Size Morie Sand Pack	
-		
-	0.010 Slot Screen	
20	[2] 2] [2] 2] 2] 2] 2] 2] 2] 2] 2] 2] 2] 2] 2] 2	

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code: <u>12K93e</u> Hole Number <u>W-G6-22</u>	Surface Elevation: 760.6
Projec	t Name:Proposed Site Development N	orthing: <u>1009776</u> Easting: <u>1092367</u>
Projec	t Location:Town of Orchard Park, Erie County, NY	Date Started: <u>4/18/2022</u>
Client:	McMahon & Mann Consulting Engineering & Geology, P.C.	Date Completed: <u>4/18/2022</u>
Depth (ft)	Well	Remarks
- - 25_ - -	#00N Size Morie Sand Pack 0.010 Slot Screen 25.0 25.5 Bentonite Seal 27.5 All a b a b a b a b a b a b a b a b a b a	
- 30_ -		
- 35_ -		
40		

### BUFFALO BILLS STADIUM PROJECT NO. 22-011



Geotechnical and Environmental Drilling | Wetland Delineations and Consulting

1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

Surface Elevation: 756.5 EDI Job Code: <u>12K93e</u> Hole Number <u>BH-H3-22</u> Project Name: Proposed Site Development Northing: \_\_\_\_\_1009637 \_\_\_\_\_ Project Location: \_\_\_\_\_\_ Town of Orchard Park, Erie County, NY Date Started: <u>4/20/2022</u> Client: McMahon & Mann Consulting Engineering & Geology, P.C.

**Date Completed:** 4/20/2022

Durth		Dee	Blow	<u>s on</u>	Sam	<u>pler</u>				
(ft)	SN	(in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	Water Table and Remarks
	1	18	4	20	21	14	41	, C , C , C	Moist brown (SANDY-SILT) topsoil fill 0.5 with 3 to 7% gravel, some sand, trace to little organic matter, loose, massive soil structure, (ML). Dry dark gray to brownish gray 2.0	Coarse silty topsoil fill with some sand, trace to little organic matter, trace gravel to 0.5 feet over sandy soil fill with little to some gravel and shale stone fragments, trace slag and organic matter to 2.0 feet over
-	2	22	3	5	5	9	10	0 0 0	gravelly (SILTY-SAND) fill with 15 to 30% gravel and flat sided shale stone fragments, trace to little silt, trace slag and organic matter, dense, massive soil structure, (SM)	silty slackwater sediment with little to some clay, trace sand, organic matter, gravel, and shale stone fragments to 3.7 feet over silty slackwater sediment with little to some clay, trace to little sand and
5_	3	20	6	8	8	13	16		I grades downward to Dry to moist dark gray (CLAYEY-SILT) with 0 to 5% gravel and flat sided shale stone fragments,6.0	shale stone fragments to 6.0 feet over silty glacial till with some shale stone fragments, little sand, trace to little clay with occasional shale channer to 14.0 feet over apparent shale bedrock to 14.8 feet over
_	4	20	14	17	24	26	41		lorganic matter, firm, weakly thinly laminated with very thin coarse silt llenses, (ML-CL).	Shale bedrock to end of coring.
	5	22	14	22	22	36 21	44		Dry faintly mottled olive brown (SAND-SILT-CLAY) with 5 to 15% mostly flat sided shale stone fragments, little to some clay, trace to little sand, stiff to very stiff, weakly thinly laminated with very	number 8. Water level at 14.4 feet below ground surface prior to coring.
-	6	20	13	17	14	15	31		thin coarse silt lenses, (ML-CL). Dry dark gray very gravelly (SAND-SILT-CLAY) with 40 to 60% mostly flat sided shale stone fragments, occasional shale channer,	Note: Advanced bore hole with 4 1/4" ID x 8" OD hollow stem auger casing with continuous split spoon sampling to 14.8 feet. Removed rods and installed a bentonite seal. Continued below with a NQ-2
-	7	24	8	13	17	19	30		little sand, trace to little clay, hard, massive soil structure, (GM),(GC). 14.0	size double tubed wireline core barrel with diamond bit to coring completion at 24.2 feet. Reamed core hole with a 3 7/8" tricone roller bit and installed a 2-inch PVC standpipe piezometer to 19.0 feet in
	8		50/5						Wet dark gray shale stone fragments, soft. 14.8	completed bore hole.
15	Run	4	#1						Dark gray shale bedrock, soft, thinly laminated, intensely fractured horizontally along bedding planes with high angle to near vertical fractures from 14.8 to 16.4, 16.6 to 16.7, 17.0 to 17.1, 17.6 to 18.2, 18.5 to 18.7, and 18.9 to 19.2 feet, dense, no iron staining, core breaks appear fresh, core lengths range from (0.01-0.35').	Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % % gal 
20	Run		#2						19.2 See next sheet	19.2 2 to 5.0 5.0 100 94 30 24.2

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>	Hole Number BH-H3-22	Surface Elevation: 756.5
Project Name: Proposed Site Developm	nent Northing: 1009	637 <b>Easting:</b> <u>1091724</u>
Project Location: Town of Orchard Par	k, Erie County, NY	Date Started:
Client: McMahon & Mann Consulting Eng	ineering & Geology, P.C.	Date Completed: <u>4/20/2022</u>

		_	Blows	s on	Sam	pler				
Depth	SN	Rec					Ν	LITH	Description and Classification	Water Table and Remarks
(π)		(in)	0/6	6/12	12/18	18/24			·	
	1									Pup Dopth Longth REC REC ROD WI
	Run		#2						Dark gray shale bedrock, soft, thinly	# (ft) (ft) (ft) % % gal
									fractured horizontally along hedding	(ic) (ic) io jo gai
-									nlanes occasional thin pyrite	19.2
									deposits, dense, no iron staining.	2 to 5.0 5.0 100 94 30
-									core breaks appear fresh, core	24.2
									lengths range from (0.05-1.5').	
-										EDI Bedrock Hardness Classification
-									24.2	Soft: Hand-held specimen crumbles
	•								Coring completed at 24.2 ft	under firm blows with point of
25									completed at 24.2 ft	geologic pick.
25_										
_										
-										
-										
_										
30_										
_										
-										
-										
-										
35_										
-										
-										
-										
40										

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	<b>b Code:</b> <u>12K93e</u>	Hole Number <u>W-H3-</u>	22	Surface Elevation: 756.5	
Project	t Name: Proposed Si	te Development	Northing:	9637 <b>Easting:</b> <u>1091724</u>	
Project	t Location:	Orchard Park, Erie County, NY		<b>Date Started:</b> <u>4/20/2022</u>	
Client:	McMahon & Mann Co	nsulting Engineering & Geology, P.C.		Date Completed: 4/20/2022	
Depth (ft)	١	Well		Remarks	
(ft) 		Well 8-inch Road Box Installed in Concrete Pad Cuttings Backfill 2-inch Schedule 40 FJT PVC Riser Bentonite Seal #00N Size Morie Sand Pack	2	Kemarks	
-		0.010 Slot Screen			
-	<u>19.0</u> 19.5				
20		Bentonite Seal			

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code: <u>12K93e</u> Hole Number <u>W-H3-</u>	22	Surface Elevation: <u>756.5</u>
Projec	t Name: Proposed Site Development	Northing:	Easting:
Projec	t Location:Town of Orchard Park, Erie County, NY		Date Started:
Client:	McMahon & Mann Consulting Engineering & Geology, P.C.	_	Date Completed:
Depth (ft)	Well		Remarks
- - 25_ - -	Bentonite Seal 21.5 $4 \cdot 6 \cdot $		
- 30 - -			
- 35 - -			
40			

# **BUFFALO BILLS STADIUM**

PROJECT NO. 22-011

BORE HOLE #	CORE RUN #	DATE	DEPTH (ft)	LENGTH (ft)	REC (ft)	REC. %	RQD. %
BH-H3-22	1	4-20-22	14.8-19.2	4.4	4.4	100	18
BH-H3-22	2	4-20-22	19.2-24.2	5.0	5.0	100	94



Geotechnical and Environmental Drilling | Wetland Delineations and Consulting

1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u> Hole Number	BH-H5(D)-22	Surface Elevation: 760.6
Project Name: Proposed Site Development	Northing:1009593	Easting:1092127
Project Location: Town of Orchard Park, Erie County, N	<u>Y</u>	Date Started: <u>4/15/2022</u>
Client: McMahon & Mann Consulting Engineering & Geolog	gy, P.C.	Date Completed:

Dauth		Dec	Blow	s on	San	pler				
(ft)	SN	(in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	Water Table and Remarks
-	1	22	4	4	8	12	12		Fine size gravel fill. Moist brownish gray very gravelly (SILTY-SAND) fill with 40 to 60% gravel, trace to little silt, trace clay, loose, massive soil structure, 1.8	Gravel fill to 0.2 feet over mostly sand and gravel fill with trace to little silt, trace slag to 0.4 feet over silty glacial till with little to some shale stone fragments, little sand and clay to 1.8 feet over apparent
-	2	22	15	25	25	26	50		(SM),(GM). Dry to moist dark gray to dark brown gravelly (SAND-SILT-CLAY) with 15 to 30% mostly shale stone fragments, little sand and clay, stiff to very stiff. massive soil structure.	shale bedrock with occasional saprolite soil interbeds to 15.8 feet over shale bedrock to end of coring.
5_	3	22	17	22	25	34	47		(ML-CL). Dry dark gray shale stone 5.0 fragments, soft to very soft, with iron staining. Wet dark gray shale stone	Note: Started losing water to formation below 23.0 feet. Water first encountered at 5.0 feet below ground surface.
-	4	17	22	42	50/5				fragments, soft, with occasional thin interbeds of (CLAYEY-SILT) saprolite soil.	Water level at 9.0 feet below ground surface at roller bit completion.
- 10	5	9	48	50/3						Note: Advanced bore hole with 4 1/4" ID x 8" OD hollow stem auger casing with continuous split spoon sampling to 15.8 feet. Removed rods and installed a bentonite seal. Continued below with a NO-2 size
	6	10	42	50/4						double tubed wireline core barrel with diamond bit to coring completion at 34.1 feet. Reamed core hole with a 3 7/8" tricone roller bit and installed a 2-inch PVC standpipe piezometer to 30.0 feet in
-	7	20	33	28	20	30	48			completed bore hole.
15_	8	4	50/4						15.8	Saprolite - soil derived from bedrock weathered in place
-	Run		#1						Dark gray shale bedrock, soft, thinly laminated slightly fractured horizontally along bedding planes with high angle to near vertical fractures from 16.8 to 17.2, 18.1 to	Run Depth Length REC REC RQD WL         # (ft) (ft) (ft) % % gal         15.8         1       to 3.3       3.3       100       73       0         10.1
-	Run		#2						18.4, 20.0 to 20.1, 20.4 to 20.6, 23.0 to 23.1, 25.9 to 27.2, and 32.5 to 32.8 feet, dense, no iron staining, core breaks appear fresh, occasional thin pyrite deposits, core lengths range from (0.02-3.6!)	19.1 19.1 2 to 5.0 5.0 100 90 25 24.1
20								<u> </u>		

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>	Hole Number <u>BH-H5(D)-22</u>	Surface Elevation: 760.6	
Project Name: Proposed Site Developm	ent Northing: _	1009593 <b>Easting:</b> <u>1092127</u>	
Project Location: Town of Orchard Par	k, Erie County, NY	Date Started: 4/15/2022	
Client: McMahon & Mann Consulting Eng	ineering & Geology, P.C.	Date Completed: <u>4/15/2022</u>	

<b>.</b>		D	Blows	<u>s on</u>	Sam	<u>ipler</u>				
(ft)	SN	(in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	Water Table and Remarks
	Run		#2						Dark gray shale bedrock, soft, thinly laminated slightly fractured	Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % % gal
-									with high angle to near vertical fractures from 16.8 to 17.2, 18.1 to 18.4 20.0 to 20.1 20.4 to 20.6	19.1 2 to 5.0 5.0 100 90 25 24.1
-									23.0 to 23.1, 25.9 to 27.2, and 32.5 to 32.8 feet, dense, no iron staining, core breaks appear fresh, occasional thin pyrite deposits, core lengths range from (0.02-3.6').	24.1 3 to 5.0 5.0 100 92 45 29.1
- 25_	Run		#3							29.1 4 to 5.0 5.0 100 96 35 34.1
-										EDI Bedrock Hardness Classification
-										Very Soft: Can be scratched with fingernail. Slight indentation produced by light blow of point of geologic pick. Requires power tools for excavation.
- 30_	Run		#4							Soft: Hand-held specimen crumbles under firm blows with point of geologic pick.
-										
-	¥								34.1	
35_									Coring completed at 34.1 ft	
-										
-										

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code:	Hole Number	D)-22	Surface Elevation: 760.6
Projec	t Name:_	Proposed Site Development	Northing: <u>1009593</u>	<b>Easting:</b> <u>1092127</u>
Projec	t Locatio	n: Town of Orchard Park, Erie County, NY	-	Date Started: 4/15/2022
Client:	McMaho	on & Mann Consulting Engineering & Geology, P.C.		Date Completed:
Depth (ft)		Well		Remarks
Depth (ft)             		Well		Remarks
-				
20		#00N Size Morie Sand Pack		

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code: <u>12K93e</u> Hole Number <u>W-H5(</u>	(D)-22	Surface Elevation: 760.6
Projec	t Name: Proposed Site Development	Northing: <u>1009593</u>	Easting: <u>1092127</u>
Projec	t Location:Town of Orchard Park, Erie County, NY		Date Started:
Client:	McMahon & Mann Consulting Engineering & Geology, P.C.		Date Completed: <u>4/15/2022</u>
Depth (ft)	Well		Remarks
-	#00N Size Morie Sand Pack		
- 25_ - - -	0.010 Slot Screen		
30_ - - -	30.0 $30.5$ $30.5$ Bentonite Seal $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$ $32.0$		
35_ - - -			
40			

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Job Code	12K93e	Hole Number _	W-H5(S)-22	-		Surface Elevation: 760.6	
Project Name	Proposed Site Developm	ent	North	hing: _	1009582.94	Easting: <u>1092193.3</u>	
Project Locati	on: Town of Orchard Par	k, Erie County, NY	/			Date Started:	
Client: McMal	ion & Mann Consulting Eng	ineering & Geology	y, P.C.			Date Completed: <u>4/18/2022</u>	

Depth (ft)	Well	Remarks
	8-inch Road Box Installed in Concrete	Note: Advanced bore hole with 4 1/4" ID x 8" OD hollow stem auger casing without sampling to 15.5 feet. Installed a 2-inch Schedule 40 PVC standpipe piezometer in completed bore hole to 15.0 feet.
_	Cuttings backfill	
-	2-inch Schedule 40 FJT PVC Riser	
5_	$\begin{array}{cccccccccccccccccccccccccccccccccccc$	
-	Bentonite Seal	
-	#00N Size Morie Sand Pack	
10_		
-		
-		
15_	15.0 15.5	
-		
-		
-		
20		

#### BUFFALO BILLS STADIUM PROJECT NO. 22-011



Unconfined Compressive Strength: 4331.9 PSI

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting

1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>	Hole Number <u>BH-I3-22</u>	Surface Elevation:
Project Name: Proposed Site Developm	ent Northing:	1009499.15 Easting: 1091701.37
Project Location: Town of Orchard Par	k, Erie County, NY	Date Started: <u>5/17/2022</u>
Client: McMahon & Mann Consulting Eng	ineering & Geology, P.C.	Date Completed: <u>5/17/2022</u>

		Blows on Sampler											
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification		Well	Water Table and Remarks	
	1	18	5	17	20	4	37	。 。 。 。 。 。 。 。 。 。 。 。 。 。 。 。 。 。 。	Tar and chip surface. Moist brown, light gray, and gray mixed, gravelly (SILTY-SAND) fill with 20 to 40% gravel and slag, little	1.5		Tar and chip surface to 0.1 feet over sandy soil fill with some gravel and slag, little silt, trace organic matter to 1.5 feet over clayey slackwater sediment with trace sand and gravel to 2.7 feet over sandy glacial till	
-	2	20	9	12	10	8	22		silt, trace organic matter, dense, massive soil structure, (SM),(GM). Moist to dry distinctly mottled brown (SILTY-CLAY) with 0 to	<u>2.7</u>		with some gravel, little silt to 6.0 feet over water sorted and deposited sand with trace silt and gravel to 10.0 feet over sandy glacial till with little to some gravel and flat sided shale stone fragments, trace silt to	
5_	3	22	8	12	16	16	28		I blocky soil structure I becoming thinly laminated I below 2.0 feet, (CL).	       6.0		12.0 feet over shaley glacial till with some silt, little sand, trace clay to 14.2 feet over apparent shale bedrock to 17.3 feet over shale bedrock to end of coring.	
_	4	24	11	15	19	20	34		I Dry faintly mottled brownish I gray gravelly I (SAND-SILT-CLAY) with 20 to I 40% gravel and flat sided I shale stone fragments, little I sand and clay, very stiff.			Note: No water in bore hole prior to coring.	
-	5	20	15	18	24	26	42		massive soil structure, (SC),(GC). grades downward to Dry to moist gray gravelly	10.0	ings Backfill	Note: Water level at 12.8 feet below ground surface at coring completion with tooling removed from core hole.	
-	6	24	18	26	28	20	54		- (SILTY-SAND) with 20 to 40% gravel, little silt, dense, massive soil structure, (SM),(GM).	12.0	Cutt	Note: Advanced bore hole with 4 1/4" ID x 8" OD hollow stem auger casing with continuous split spoon sampling to auger refusal at 17.3 feet. Removed drill rods and	
-	7	24	14	27	25	29	52		I Dry gray (SAND) with 5 to         I 10% gravel, trace silt, dense,         I 10% gravel, trace silt, dense,         I weakly stratified, (SW).         I clear transition to	     		below with a NQ-2 size double tubed wireline core barrel with diamond bit to coring completion at 27.3 feet. Core hole was backfilled with bentonite and the remainder of the	
- 15_	8	3	50/4			25			Dry gray gravelly (SAND) with 15 to 25% gravel and flat sided shale stone fragments, trace silt, very dense, massive soil structure,	14.2		bore hole was backfilled with cuttings and ground surface repaired to match surrounding conditions upon completion.	
-	9	4	50/4						grades downward to _			Run Depth Length REC REC RQD WL # (ft) (ft) (ft) % % gal	
-	Run		#1						(SANDY-SILT) with 30 to 50% mostly flat sided shale stone fragments, little sand, trace clay, dense and very dense, massive soil structure, (SM),(GM).	17.3	Bentoite Seal	17.3 1 to 5.0 5.0 100 33 40 22.3	
20													

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI J	ob C	ode:	12K	93e			Но	le N	umber <u>BH-I3-22</u>	2			Surfa	ice Elevati	<b>on:</b> 75	4		
Proje	ct Na	ame:	Prop	osed S	Site De	evelopi	ment		N	lorthing: $\_^1$	.009499.1	15		_ Easting	_10917	01.37		
Project Location: Town of Orchard Park									ounty, NY				Date Started: <u>5/17/2022</u>					
Clien	t: <u>M</u>	cMah	on & N	1ann C	Consult	ing En	ginee	ering	& Geology, P.C.				Date	Complete	<b>d:</b> <u>5/17</u>	/2022		
Depth (ft)	SN	Rec (in)	<b>Blow</b>	s on 6/12	<b>Sam</b>	18/24	N	LITH	Description and	d Classificatio	on	,	Well	Wate	er Table a	nd Rem	arks	
	Run		#1						Gray shale ston very soft to soft Gray shale bedr occasional thin soft rock, intens horizontally alor planes with occ- high angle fract laminated to me bedding, no iror core breaks app dense, core pied from (0.025-0.4 Gray shale bedr moderately to s fractured horizo bedding planes moderately fract thickly laminate bedding, dense, staining, core b fresh, core piec (0.25-1.4'). Coring complete	e fragments, t. rock, soft, ractured. rock, soft with beds of very sely fractured ng bedding asional short ures, thinly edium n staining, bear fresh, ces range 150'). rock, soft, lightly ontally along to 23.75 feed tured below, d to medium , no iron reaks appear es range fror d at 27.3 ft	t, 27.3		Bentonite Seal	Run Depth # (ft) 17.3 1 to 22.3 2 to 27.3 EDI Bedro Very Soft: fingernail. produced I geologic p for excava Soft: Hanc under firm geologic p	Length I (ft) ( 5.0 5. 5.0 5. Ck Hardn Can be s Slight ind by light b ck. Requ tion.	REC REC ft) % 	RQD % 33 88 sifica oint o ver to	WL gal 175 tion n of ols bles

## BUFFALO BILLS STADIUM PROJECT NO. 22-011

BORE HOLE #	CORE RUN #	DATE	DEPTH (ft)	LENGTH (ft)	REC (ft)	REC. %	RQD. %
BH-13-22	1	5-17-22	17.3-22.3	5.0	5.0	100	33
BH-13-22	2	5-17-22	22.3-27.3	5.0	5.0	100	88


Geotechnical and Environmental Drilling | Wetland Delineations and Consulting

1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>	Hole Number <u>BH-I4-22</u>	Surface Elevation: 757.2	
Project Name: Proposed Site Developm	nent Northi	ing:1009460.68 Easting:1091897.64	
Project Location:Town of Orchard Pa	rk, Erie County, NY	Date Started:	
Client: McMahon & Mann Consulting Eng	gineering & Geology, P.C.	Date Completed: <u>5/17/2022</u>	

			Blows	s on	Sam	pler					
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	N	LITH	Description and Classification	W	Water Table and Remarks
-	1	16	12	6	5	4	11		Tar and chip surface.       0.1         Dry light gray gravelly       (SAND) fill with 30 to 50%       1.2         gravel, trace silt, compact, single grain, (SW),(GW).      2.0		Tar and chip surface to 0.1 feet over mostly sand and gravel fill with trace silt to 1.2 feet over silty slackwater sediment with little clay, trace sand to 2.0 feet over clayey slackwater sediment with trace sand and
-	2	20	6	10	15	19	25		I Dry distinctly mottled olive     gray (CLAYEY-SILT) with little     logary (CLAYEY-SILT) with little     locky frace sand, stiff, blocky     locky     locky frace sand, stiff, blocky     locky frace sand		gravel to 3.0 feet over silty glacial till with little to some gravel, little sand, trace to little clay to 4.0 feet over sandy glacial till with some gravel and flat sided shale stone fragments, little silt to 8.0 feet over
5_	3	24	8	15	14	19	29		I Dry faintly mottled I alternating layers of brownish I gray and grayish brown I (SILTY-CLAY) very stiff, thinly I I laminated with very thin	ttings Backfil	coarse silty glacial till wtih some mostly flat sided shale stone fragments, little sand to 12.3 feet over apparent shale bedrock to spoon refusal.
-	4	22	7	11	14	13	25		Coarse slit lenses, (CL).         clear_transition_to    Dry faintly mottled grayish   brown to brownish gray	CU:	Note: No water in bore hole prior to taking sample number 8.
10_	5	19	16	20	19	22	39		with 15 to 25% gravel, little Isand, trace to little clay, very Istiff to hard, massive soil Istructure, (ML-CL).		Note: Water level at 12.0 feet below ground surface at completion. Note: Advanced bore hole with 4 1/4" ID x 8" OD hollow stem auger casing with continuous split spoon
-	6	24	13	21	26	29	47		Dry grayish brown, gray   below 4.8 feet, gravelly   (SILTY-SAND) with 20 to   40% gravel and flat sided   shale stone fragments. little		sampling to split spoon refusal at 14.8 feet. Bore hole was backfilled with cuttings and ground surface repaired to match surrounding conditions upon completion.
-	7	3	50/5						silt, compact, massive soil structure, (SM). grades downward to Dry gray gravelly		
15_	8	10	36	50/4					(SANDY-SILT) with 20 to 40% mostly flat sided shale stone fragments, little sand, dense, massive soil structure, (SM),(GM). Gray shale stone fragments,		14.8
-									verý soft to soft. Boring completed at 14.8 ft		
20											

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>	Hole Number <u>BH-I5</u>	-22		Surface Elevation	n: <u>761</u>
Project Name: Proposed	Site Development	Northing:	1009421.95	Easting: _	1092093.9
Project Location:	of Orchard Park, Erie County, NY	-		Date Started:5	5/16/2022
Client: McMahon & Mann	Consulting Engineering & Geology, P.C.	<u>.                                    </u>		Date Completed:	5/16/2022

	Blows on Sampler									
Depth (ft)	SN	Rec (in)	0/6	6/12	12/18	18/24	Ν	LITH	Description and Classification	Water Table and Remarks
-	1	18	9	12	20	6	32		Tar and chip surface.       0.1         Dry gray very gravelly       (SILTY-SAND) fill with 40 to 60%         mostly angular gravel, trace to little       1.5         silt, dense, massive soil structure,       0.1	Tar and chip surface to 0.1 feet over mostly crushed stone fill with trace to little silt to 1.5 feet over clayey slackwater sediment with trace sand and organic matter to 2.5 feet over sandy glacial till with little to some
-	2	21	12	10	9	12	19		\(SM),(GM). Dry to moist brown to dark brown (CLAYEY-SILT) with some clay, trace sand and organic matter, stiff, thinly laminated, (CL).	gravel and shale stone fragments, little silt to 7.0 feet over shaley glacial till with little sand to 9.3 feet over shale boulder to 11.0 feet over shaley glacial till with little silt to 16.6 feet over apparent shale
5_	3	24	14	7	11	9	18		Clear transition to Moist faintly mottled brown gravelly (SILTY-SAND) with 15 to 25% gravel and flat sided shale stone fragments, little silt, compact, massive soil	bedrock to 19.0 feet over shale bedrock to end of coring. Note: No water in bore hole prior to
-	4	17	11	17	21	22	38		structure, (SM). clear transition to7.0. Moist to dry dark gray gravelly (SANDY-SILT) with 30 to 50%	level at 15.0 feet below ground surface. Note: Started losing water to
-	5	11	19	50/5					mostly flat sided shale stone fragments, little sand, dense, massive soil structure, (SM),(GM). 9.3 Gray shale stone fragments, very	formation below 25.0 feet. Note: Water at 14.5 feet below ground surface prior to coring.
10_	6	4	49	50/2					soft to soft (shale boulder). 11.0 Moist gray gravelly (SILTY-SAND) with 30 to 50% gravel and flat sided	Note: Advanced bore hole with 4 1/4" ID x 8" OD hollow stem auger casing with continuous split spoon sampling to auger refusal at 19.0 feet. Removed rods and installed a
-	7	16	25	39	50/5				shale stone fragments, little silt, very dense with brittle consistence, massive soil structure, (SM),(GM).	bentonite seal. Continued below with a NQ-2 size double tubed wireline core barrel with diamond bit to coring completion at 34.0 feet. Core hole was reamed with a 3 7/8" tricone roller bit and a 2-inch PVC standnine piezometer to 28.0 feet in
15_	8	20	39	41	47	50/4	88			completed bore hole.
-	9	6	17	50/3					16.6 Gray shale stone fragments, very soft and soft.	Kun Depth Length REC REC RQD WL         # (ft) (ft) (ft) % % gal         19.0         1 to 5.0 5.0 100 71 42         24.0
-	10	1	50/2						19.0	
	Run		#1						See next sheet	

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059

(716) 655-1717 | EDI@earthdimensions.com

EDI Job Code: <u>12K93e</u>	Hole Number <u>BH-I5-22</u>	Surface Elevation: <u>761</u>
Project Name: Proposed Site Developm	ent Northing: _	1009421.95 <b>Easting:</b> <u>1092093.9</u>
Project Location: Town of Orchard Par	k, Erie County, NY	Date Started:
Client: McMahon & Mann Consulting Eng	ineering & Geology, P.C.	Date Completed: <u>5/16/2022</u>

		_	Blows	s on	Sam	<u>ipler</u>										
Depth	SN	Rec					N	і ттн	Description and Classification		Wate	r Table	and	Rema	rks	
(ft)	011	(in)	0/6	6/12	12/18	18/24			Beschption and classification		mate	i i abie	ana	i territa		
	Dum		#1						Dark grav shale bedrock, soft,	Run	Depth	Length	n REC	REC	RQD	WL
	Run		#1						intensely to intensely to moderately	#	(ft)	(ft)	(ft)	%	%	gal
_									fractured horizontally along bedding							
									planes high angle to near vertical		19.0					
									fracture from 21.7 to 21.9 foot very	1	to	5.0	5.0	100	71	42
									this to madium hadding, dance, no		24.0					
-					1				thin to medium bedding, dense, no							
									iron staining, core breaks appear		24 0					
									tresh, core pieces range from	С	24.0	50	10	08	70	50
-									(0.025-0.7').	2	20.0	5.0	4.9	90	19	50
									Dark gray shale bedrock, soft,		29.0					
									moderately fractured horizontally		20.0					
-	<del>х</del>								along bedding planes with very	-	29.0				~ -	<b>F</b> 0
	Run		#2						intensely fractured zones from 25 to	3	to	5.0	5.0	100	95	50
25	India		π Δ						2E 2 and 27 2E to 27 E fact real		34.0					
25_								<u> </u>	23.2 dilu 27.33 to 27.3 leet, rock							
								<u> </u>	Decomes slightly fractured below							
								<u></u>	29.0 reet, very thin to meaium							
-									bedding, dense, no iron staining,		D - J			CI	c:	
									core breaks appear fresh, core	EDI	Bearoo	ск наго	iness	Class	ificat	ion 
										Verv	/ Soft:	Can be	scra	tched	with	
-										fina	ernail.	Sliaht i	ndent	ation		
										nroc	luced h	v liaht	blow	of no	int o	f
										neol	ogic ni	rk Roc	illiroc	nowe	nic o	' hle
-										for	vcavat	ion	Junico	powe		513
										101 6						
	\/															
-	۸									Soft	• Hand	-held s	necim	nen cr	umb	les
	<b>D</b>									und	or firm	hlows	with i	noint i	of	
20	Run		#3							anal		ck	with p	Joint	51	
30_										yeu	ogic pi	CK.				
-																
-																
-																
								<u>  </u>								
								<u>  </u>								
-	¥							<u>  </u>	34.0							
									Coring completed at 34 ft							
35_																
_																
_																
-																
-																
_																
_																
40		1			1											

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code:	Hole Number	22	Surface Elevation: <u>761</u>
Projec	t Name:_	Proposed Site Development	Northing: <u>1009421.95</u>	Easting: <u>1092093.9</u>
Projec	t Locatio	n: <u>Town of Orchard Park, Erie County, NY</u>		Date Started:
Client:	McMaho	on & Mann Consulting Engineering & Geology, P.C.		Date Completed: <u>5/16/2022</u>
Depth (ft)		Well		Remarks
	211			
	$^{2}$	8-inch Road Box Installed in Concret	e	
-				
-		Cuttings Backfill		
_		A C Direct Cohodulo 40 EIT DVC Direct		
5_				
-				
-				
-				
-				
10_				
_				
-				
-				
-				
15				
17				
-				
_				
-				
-		Bentonite Seal		
20	스 스	<u> </u>		

Geotechnical and Environmental Drilling | Wetland Delineations and Consulting 1091 Jamison Road | Elma, NY 14059 (716) 655-1717 | EDI@earthdimensions.com

EDI Jo	b Code: <u>12K93e</u> Hole Number <u>W-I5-</u>	22	Surface Elevation:
Project	t Name: Proposed Site Development	Northing: <u>1009421.95</u>	Easting: <u>1092093.9</u>
Project	<b>t Location:</b> <u>Town of Orchard Park, Erie County, NY</u>		Date Started:
Client:	McMahon & Mann Consulting Engineering & Geology, P.C.		Date Completed: 5/16/2022
Depth (ft)	Well		Remarks
	2-inch Schedule 40 FJT PVC Riser		
- - - -	#00N Size Morie Sand Pack		
25	0.010 Slot Screen		
- - 30_	28.0 28.5 Bentonite Seal		
-	$\begin{bmatrix} a & a & a & a & a & a \\ a & a & a & a &$		
35_			

## BUFFALO BILLS STADIUM PROJECT NO. 22-011

BORE CORE

HOLE #	RUN#	DATE	DEFILI(II)			REC. %	RQD. %
BH-15-22	1	5-16-22	19.0-24.0	5.0	5.0	100	71
BH-15-22	2	5-16-22	24.0-29.0	5.0	4.9	98	79
BH-15-22	3	5-16-22	29.0-34.0	5.0	5.0	100	95



**APPENDIX A-2** 

SUMMARY TABLE, TEST PIT LOGS, AND PHOTOGRAPHS

 Table A-2

 Test Pit Locations, Approximate Elevations, and Total Depths

Test Pit	Approximate Location	Approximate Ground Surface Elevation, ft	Total Depth, ft
TP-1-22	Near BH-F6-22	760.5	11.3
TP-2-22	Near BH-B4-22	767.3	12.0



# McMahon & Mann Consulting Engineering and Geology, PC.

2495 Main Street, Suite 432 Buffalo, New York 14214

(716) 834-8932 www.mmce.net

				TEST PIT FIELD LOG					
	PROJECT	Buf	falo Bills Stadium	APPROXIMATE GROUND ELEV.	760.5		DATE	6/	15/2022
PR	ROJECT NO.		22-011		NEAR		TIME STARTED	7	:00 AM
TE	EST PIT NO.		TP-1-22	200/1101	BH-F6-22	TIN	IE COMPLETED	8	:30 AM
M	MCEG REP.		JKW, RJS	CONTRACTOR		PINTO CONS	TRUCTION SERV	VICES	
			0	OPERATOR		Geo	rge Panepinto		
	WEATHER	S	Sunny, 80-85°F	MAKE / MODEL					
				BUCKET / MAX DEPTH		4 FEEI	WIDE / 22 FEET	DEDTU	
	SYMBOL		SOIL DESCRIP	TION	EFFORT	REMARK	COUNT / SIZE	(FT)	ELEV. (FT)
			Tar & chip surfa	ce (fill)	Easy			0.2	
1_		Moist I	prownish gray gravelly sand	l with mostly gravel (fill)	Easy			0.2	_ 759 5
		[	Dry gray flat sided shale sto	ne fragments (fill)	Easy			1.6	100.0
2			Dry brownish gray clayey	-silt_trace_sand	Fasy				- 758.5
3									— 757.5 — 757
4	SS335							4.0	— 756.5
5									- 755.5
6						(1)			<u> </u>
7;		Dry to mois	st, dark gray sand-silt-clay v stone fragments (shale	vith 40-60% flat sided shale ey glacial till)	Easy				— 753.5
8						(2)			<u> </u>
9;							<u> </u>		
10		Wet, da	rk gray shale stone fragmer	nts, soft (weathered rock)	Easy to			10.0	- 750.5
11	*******	Wet, d	ark gray shale, soft, very in	tensely fractured, thinly	Difficult	(3)		10.7 11.3	<u> </u>
12		\	laminated (compet	entrocky		(4)	L/		- 748.5
13 —		Remarks:	<ul><li>(1) Material transitioned fr</li><li>(2) Water infiltrated through</li></ul>	om dry to moist at approxima gh the side wall of the excava	itely 6.0 feet. tion at a depth o	- 747.5			
14 —			<ul><li>(3) Excavation effort incre</li><li>(4) Test pit completed at a</li></ul>	ased at the transition betwee a depth of 11.3 feet due to diff	n weathered an ficulty of excava	<u> </u>			
15 —									— 745.5
16 —									<u> </u>
17 _									- 743.5
18									- 742.5
19									- 741.5
20 —									- 740.5
21									- 739.5
22 -									- 738.5
23 —			Proportions /Par ASTM D	2400).					- 737.5
Teet D	it Plan			2700). 2. <5%	1	Notes:			
	ης η τατη Ο'		Four	5-10%		Weathored har	rock anountared	at annr-	vimatoly 10.0
<u> </u>		<b>↑</b>	l ittle	15-25%		feet		at appi0	Annalely 10.0
NOF	RTH 🔶	10' ↓	Some	: 30-45% 50-100%		Water encount	ered at approxima	itely 8.5 f	eet.



TEST PIT TP-1-22. Bottom of test pit at 11.3 feet deep. Transition from overburden to weathered rock at approximately 10.0 feet, and transition to competent rock at approximately 10.7 feet.



# McMahon & Mann Consulting Engineering and Geology, PC.

(716) 834-8932 www.mmce.net

2495 Main Street, Suite 432 Buffalo, New York 14214

				TEST PIT FIELD LOG						
	PROJECT	Buff	alo Bills Stadium	APPROXIMATE GROUND ELEV.	767.3		DATE	6/	15/2022	
PR	OJECT NO.		22-011		NEAR		TIME STARTED	10	):15 AM	
TE	ST PIT NO.		TP-2-22	ECONTION	BH-B4-22	TIN	IE COMPLETED	12	2:00 PM	
M	MCEG REP.		JKW, RJS	CONTRACTOR		PINTO CONSTRUCTION SERVICES				
			0	OPERATOR		Geo	orge Panepinto			
	WEATHER	S	unny, 80-85°F	MAKE / MODEL		KOBE	LCO SK210 LC			
				BUCKET / MAX DEPTH		4 FEET WIDE / 22		DEDTU		
DEPTH (FT)	SYMBOL		SOIL DESCRIP	TION	EFFORT	REMARK	COUNT / SIZE	(FT)	ELEV. (FI)	
0-1			Tar & chip sur	Tar & chip surface					- 767.3	
1			Moist light gray silty sand v	with some gravel	Easy			0.2	766.3	
']	2222222	Moist, bro	wnish gray shale stone frag	gments, soft, iron staining	Easy	(1)		1.6	- 700.5	
2_	******	N	(weathered ro	ock)					- 765.3	
_	*****								- 100.0	
3_	******								- 764.3	
	******									
4	*****								- 763.3	
	<u>XXXXXX</u>									
5	******						6-12 boulders,		- 762.3	
	*****	Dry, da	ark gray shale stone fragme	ents, soft, iron staining	<b>F</b> eet		approximately			
6			(weathered ro	ock)	Easy		diameter		- 761.3	
	<u>aaaaaaa</u>						diamotor			
7 _	******								- 760.3	
	000000									
8 –	******								- 759.3	
	******									
9 -	******					(2)			- 758.3	
	********					(2)		9.2		
10					Easy to	(3)			- 757.3	
I E		Wet, dark	gray shale, soft, very inten	sely to intensely fractured,	Moderate					
11			thinly laminat	ted	modorato			.	- 756.3	
					Difficult	(4)		11.2		
12 _					Billoun			12.0	- 755.3	
		Remarks:	(1) Two predominant, nea	r-vertical joint sets were obse	t the bedrock, o	riented				
13			approximately northeast to	o southwest and northwest to	southeast. Joints were spread approximately				- 754.3	
			6-12 inches apart. Additio	nal random joints were also o	bserved.	750.0				
14			<ul><li>(2) Excavation effort increased at the transition between weathered and competent rock.</li><li>(3) Water infiltrated through the side wall of the excavation at a depth of approximately 10.0 feet.</li></ul>							
15										
15			(4) Excavation effort incre	ased at a depth of approxima	ed at a depth of		- 752.5			
16			12.0 feet due to difficulty of	of excavation.					751.3	
10-									- 751.5	
17 -									- 750.3	
" ]									= 100.0	
18									- 749.3	
19									_ 748.3	
20									- 747.3	
									_	
21									_ 746.3	
22									- 745.3	
23									- 744.3	
			Droportiono /Der ACTAD	2400\+						
Teet Di	t Plan			2400). 00: <5%	1	Notes:				
- 20	)' <u> </u>		Trac Few	· 5-10%		Weatherd bodr	ock encountered	at annrovi	imately 0.8	
		L ↑	Little:	15-25%		feet.		at appion		
NOR	тн /	10'	Some	: 30-45%		Water encount	ered at approxima	tely 10.0	feet.	
	/	Ļ	Mostly	: 50-100%				-		
		-								

### Page 2 of 5



TEST PIT TP-2-22. Test pit excavated to a depth of approximately 10.0 feet. Weathered rock transitions to competent rock at approximately 9.2 feet.



## Page 4 of 5



TEST PIT TP-2-22. Water began infiltrating the excavation at a depth of approximately 10.0 feet.



TEST PIT TP-2-22. Excavated weathered rock with excavator (Kobelco SK210 LC) for scale.

**APPENDIX A-3** 

HYDRAULIC CONDUCTIVITY ESTIMATES SUMMARY TABLE

Well Designation	Ground Surface Elevation, ft	Test Elevation, ft <sup>1</sup>		Hydraulic Conductivity, K (cm/s)
W-A4-22	770.7	755.7	743.2	3.5E-03
W-A6-22	769.5	754.5	743	6.9E-04
W-B3-22	764.0	753.5	744.5	6.4E-04
W-B6-22	766.0	754.5	747	9.0E-04
W-C3-22	762.6	754.6	744.1	4.2E-03
W-C5-22	762.5	742	727.5	9.3E-04
W-C7-22	761.6	749.6	740.1	1.7E-03
W-D2-22	759.8	749.8	741.3	8.6E-04
W-D4-22	760.3	748.3	742.3	2.6E-03
W-D6-22	760.3	749.3	742.3	2.1E-04
W-E3-22	759.8	742.3	733.3	1.1E-04
W-F5-22	758.0	746	739.5	2.4E-03
W-F7-22	761.6	749.1	740.6	1.5E-03
W-G6-22	760.6	746.6	735.1	1.7E-03
W-H3-22	756.5	741.5	737	2.2E-03
W-H5(D)-22	760.6	741.6	730.1	1.5E-03
W-H5(S)-22	760.6	752.6	745.1	4.2E-04
W-I5-22	761.0	741	732.5	1.2E-03

Table A-3Hydraulic Conductivity Estimates

Table Note:

1. The elevation limits of the saturated interval of screened zone, including the sand pack, is shown for slug test intervals.

## **APPENDIX B**

#### SUMMARY OF GEOTECHNICAL TESTS AND RESULTS NEW BILLS STADIUM ORCHARD PARK, NEW YORK

#### APPENDIX B

#### SUMMARY OF GEOTECHNICAL TESTS AND RESULTS NEW BILLS STADIUM ORCHARD PARK, NEW YORK

Geotechnical tests were completed on selected soil and rock samples collected during the subsurface exploration program. Samples were collected and tested to provide information necessary to confirm field soil classifications and for estimating the properties of the different soil and rock layers present in the subsurface.

Soil classification tests include moisture content, grain size distribution, and Atterberg limits. Unconfined compressive strength (UCS) testing was completed to estimate the strength of selected rock samples. A summary of test procedures and the test data is shown below.

#### I. MOISTURE CONTENT

Soil moisture content is defined as the amount of water which is contained in the voids of the soil.

3<sup>rd</sup> Rock, LLC (3<sup>rd</sup> Rock) measured the moisture content on selected soil samples. The tests were completed in general accordance with ASTM D 2216. The moisture content test results are included in Appendix B-1 and are summarized in Table B-1.

#### II. SIEVE AND HYDROMETER ANALYSIS

3<sup>rd</sup> Rock measured the grain size distribution of selected soil samples. The testing was completed in general accordance with ASTM D 422. The sieve analysis and hydrometer analysis results are included in Appendix B-1. The results are summarized in Table B-1.

#### III. ATTERBERG LIMITS

Atterberg limits are used to characterize the consistency characteristics of cohesive soils and for soil identification and classification purposes.

3<sup>rd</sup> Rock measured the Atterberg limits of selected soil samples. The testing was completed in general accordance with ASTM D 4318. The results are included in Appendix B-1 and are summarized in Table B-1.

#### IV. UNCONFINED COMPRESSION STRENGTH

3<sup>rd</sup> Rock measured the unconfined compressive strength of selected rock samples in general accordance with ASTM D 7012. The unconfined compression strength test results are included in Appendix B-2. The results are summarized in Table B-2.

## **APPENDIX B-1**

SOIL LABORATORY TESTING RESULTS

				Atterberg Limits				
Boring Designation <sup>2</sup>	Sample Depth (ft)	Moisture Content (%) <sup>1</sup>	Percent Passing No. 200 Sieve	LL (%)	PL (%)	PI (%)	USCS Symbol	
BH-A4-22	2-4	11.6	10.3	-	-	-	-	
BH-A6-22	2-6	4.4	2.1	-	-	-	GW	
BH-A6-22	6-10	6.1	6.0	-	-	-	-	
BH-B3-22	4-8	6.5	11.3	-	-	-	-	
BH-B4-22	4-8	1.8	7.3	-	-	-	-	
BH-B5-22	6-8	2.6	7.7	-	-	-	-	
BH-B6-22	4-8	4.0	15.6	-	-	-	-	
BH-C2-22	6-8.2	5.5	5.5	-	-	-	-	
BH-C3-22	2-6	8.5	18.5	-	-	-	-	
BH-C4-22	4-8	7.4	20.0	-	-	-	-	
BH-C5-22	4-6	15.3	41.1	22	14	8	SC	
BH-C5-22	10-12.3	4.8	11.8	-	-	-	-	
BH-C6-22	10-10.8	9.9	23.0	-	-	-	-	
BH-C7-22	6-8	10.5	45.8	25	16	9	SC	
BH-D2-22	4-6	7.2	26.0	-	-	-	-	
BH-D3-22	6-10	5.8	26.9	-	-	-	-	
BH-D4-22	8-12	6.0	12.8	-	-	-	-	
BH-D5-22	6-10	7.9	28.1	-	-	-	-	
BH-D6-22	8.8-10.8	6.7	6.8	-	-	-	-	
BH-D7-22	4-8	13.0	24.5	29	22	7	SC-SM	
BH-E2-22	2-6	7.1	17.7	-	-	-	-	
BH-E3-22	6-8	3.4	17.4	-	-	-	-	
BH-E4-22	6-10	9.9	13.4	-	-	-	-	
BH-E5-22	4-6	23.8	90.9	45	22	23	CL	
BH-E6-22	6-10	10.5	29.9	-	-	-	-	
BH-E7-22	6-8	-	13.3	-	-	-	-	
BH-F3-22	6-10	6.9	24.4	-	-	-	-	
BH-F4-22	4-6	14.6	63.7	36	19	17	CL	
BH-F4-22	6-8	16.9	64.3	30	19	11	CL	
BH-F4-22	9-12	8.3	13.4	-	-	-	-	
BH-F5-22	0-2	12.6	-	-	-	-	-	
BH-F5-22	2-4	17.2	-	-	-	-	-	
BH-F5-22	4-5	15.2	51.6	30	18	12	CL	
BH-F5-22	5-6	14.1	-	-	-	-	-	
BH-F5-22	6-8	9.3	17.8	-	-	-	-	
BH-F5-22	8-10	8.0	-	-	-	-	-	
BH-F5-22	10-12	8.4	-	-	-	-	-	

Table B-1Soil Testing Results Summary Table

				Atterberg Limits			
Boring Designation <sup>2</sup>	Sample Depth (ft)	Moisture Content (%) <sup>1</sup>	Percent Passing No. 200 Sieve	LL (%)	PL (%)	PI (%)	USCS Symbol
BH-F5-22	12-12.3	11.8	-	-	-	-	-
BH-F6-22	6-10	8.7	13.1	-	-	-	-
BH-F7-22	8-12	6.5	15.0	-	-	-	-
BH-G3-22	4-6	25.6	76.7	42	26	16	CL
BH-G3-22	6-10	10.5	20.1	-	-	-	-
BH-G4-22	6-10	8.1	19.2	-	-	-	-
BH-G6-22	2-6	11.4	33.8	-	-	-	-
BH-G6-22	8-12	8.5	20.3	-	-	-	-
BH-H3-22	2-6	20.5	79.5	44	27	17	ML
BH-H3-22	10-14	7.6	25.3	-	-	-	-
BH-H5-22	0-2	17.9	54.5	42	25	17	CL
BH-H5-22	2-4	8.3	-	-	-	-	-
BH-H5-22	4-6	7.8	-	-	-	-	-
BH-H5-22	6-8	9.9	11.3	-	-	-	-
BH-H5-22	8-10	8.0	11.3	-	-	-	-
BH-H5-22	10-12	7.8	-	-	-	-	-
BH-H5-22	12-14	8.4	13.8	-	-	-	-
BH-H5-22	14-14.3	11.2	13.8	-	-	-	-
BH-13-22	4-8	7.2	35.1	-	-	-	-
BH-13-22	8-10	7.2	35.1	-	-	-	-
BH-13-22	10-12	6.0	30.9	-	-	-	-
BH-14-22	0-2	18.6	-	-	-	-	-
BH-14-22	2-4	17.8	-	-	-	-	-
BH-14-22	4-6	11.6	-	-	-	-	-
BH-14-22	6-8	8.5	-	-	-	-	-
BH-14-22	8-10	5.5	31.9	-	-	-	-
BH-14-22	10-12	7.8	31.9	-	-	-	-
BH-14-22	12-14	6.7	-	-	-	-	-
BH-14-22	14-14.8	9.0	-	-	-	_	-
BH-15-22	12-16	4.7	38.5	_	-	_	-

Notes: 1. Moisture content data are included on "Water Content Test Results," if not included on Grain Size and/or Atterberg Limit Reports.2. Highlighted borings indicate outstanding laboratory data.



## Water Content Test Results by ASTM D2216

### Project: Buffalo Bills Stadium, Orchard Park, NY

Project No: 22-023

Client: McMahon & Mann Consulting Engineering & Geology, P.C. Date: 06/23/22

Borehole No.	Sample Nos.	Lab ID No.	Natural Water Content, %
BH-H5	S-2	22-207	8.3
	S-3	22-208	7.8
	S-4	22-209	9.9
	S-5	22-210	8.0
	S-6	22-211	7.8
	S-7	22-212	8.4
	S-8	22-213	11.2
BH-F5	S-1	22-214	12.6
	S-2	22-215	17.2
	S-3B	22-216	14.1
	S-5	22-217	8.0
	S-6	22-218	8.4
	S-7	22-219	11.8
BH-I4	S-1	22-220	18.6
	S-2	22-221	17.8
	S-3	22-222	11.6
	S-4	22-223	8.5
	S-5	22-224	5.5
	S-6	22-225	7.8
	S-7	22-226	6.7
	S-8	22-227	9.0

3rd Rock, LLC 580 Olean Road East Aurora, NY 14052 (716)655-4933 (716)655-8638 fax




























































# **APPENDIX B-2**

**ROCK STRENGTH TESTING RESULTS** 

Boring Designation	Sample Depth (ft)	Unconfined Compressive Strength (psi) (ASTM D7012)
BH-A4-22	25.3-25.7	1,058.1
BH-A6-22	26.2-26.6	1,968.5
BH-A6-22	31.8-32.3	3,378.3
BH-B4-22	27.8-28.2	1,320.1
BH-B5-22	21.5-21.9	939.9
BH-B5-22	24.6-25.0	6,050.4
BH-C2-22	17.3-17.7	2,100.5
BH-C2-22	23.2-23.7	2,555.1
BH-C3-22	19.7-20.1	2,347.7
BH-C4-22	19.4-19.8	2,190.0
BH-C4-22	24.4-24.8	3,939.2
BH-C5-22	23.7-24.2	2,295.7
BH-C5-22	30.1-30.5	4,406.1
BH-C5-22	40.5-40.9	1,603.5
BH-C6-22	19.5-19.9	1,653.9
BH-D3-22	61.8-62.2	2,310.8
BH-D3-22	45.3-45.7	3,342.1
BH-D3-22	35.6-36.0	3,220.2
BH-D3-22	26.4-26.8	899.9
BH-D3-22	16.7-17.1	2,198.1
BH-D4-22	20.5-20.9	2,843.5
BH-D5-22	20.0-20.5	3,135.3
BH-D6-22	25.2-25.7	2,351.3
BH-E3-22	18.2-18.6	1,698.1
BH-E3-22	30.3-30.7	3,516.4
BH-E4-22	21.0-21.4	2,165.9
BH-E5-22	21.2-21.6	962.2
BH-E6-22	24.7-25.1	2,416.9
BH-F3-22	20.7-21.1	1,925.8
BH-F4-22	20.4-20.8	1,414.3
BH-F5-22	21.8-22.3	1,393.3
BH-F6-22	20.2-20.6	2,106.0
BH-G3-22	18.4-18.9	2,676.7
BH-G4-22	24.5-24.9	1,699.6
BH-G6-22	25.2-25.6	1,814.9
BH-H3-22	22.8-23.2	2,360.6
BH-H5-22	18.5-18.9	3,126.4
BH-H5-22	33.1-33.5	4,331.9

Table B-2Unconfined Compressive Strength Summary Table



## Compressive Strength Report ASTM D2166

Project:	Buffalo Bills' Stadium McMahon & Mann Consulting Engineering and Geology, P.C.
Project No.:	22-023
Sample No.:	Various
Lab ID No.:	Various
Analyst:	EBS/JR
Date:	6/9/22-6/17/22
Specimen Type:	2"x4" Bedrock Core

Specimen Type:	2"x4" Bedrock Core
<b>Cross-Head Speed:</b>	0.05 in/min
Temp Conditioned:	70 deg. F

			Maximum
		Maximum	Compressive
		Load	Strength
Sample Name:	Sample ID:	lbf	<u>psi</u>
BH C4 19.4-19.8'	22-289	6756.9	2190.0
BH C5 23.7-24.2'	22-290	7094.8	2295.7
BH C5 30.1-30.5'	22-291	13617.1	4406.1
BH C5 40.5-40.9'	22-292	4947.2	1603.5
BH C6 19.5-19.9'	22-293	5107.9	1653.9
BH D6 25.2-25.7'	22-294	7286.3	2351.3
BH D3 61.8-62.2'	22-295	7122.2	2310.8
BH D3 45.3-45.7'	22-296	10367.0	3342.1
BH D3 35.6-36.0'	22-297	9952.1	3220.2
BH D3 26.4-26.8'	22-298	2778.4	899.9
BH D3 16.7-17.1'	22-299	6800.0	2198.1
BH E5 21.2-21.6'	22-300	2977.7	962.2
BH D4 20.5-20.9'	22-301	8790.9	2843.5
BH D5 20.0-20.5'	22-302	9673.2	3135.3
BH C4 24.4-24.8'	22-303	12169.8	3939.2
BH B4 27.8-28.2'	22-304	4076.9	1320.1
BH B5 21.5-21.9'	22-305	2912.7	939.9
BH B5 24.6-25.0'	22-306	18723.8	6050.4
BH E3 18.2-18.6'	22-307	5285.1	1698.1
BH E3 30.3-30.7'	22-308	10904.0	3516.4
BH E6 24.7-25.1'	22-309	7456.9	2416.9

Jeanne M. aspill

Respectfully Submitted, 3<sup>rd</sup> Rock, LLC

580 Olean Road East Aurora, NY 14052 Phone (716)655-4933, fax 655-8638



## Compressive Strength Report ASTM D2166

Project:	Buffalo Bills' Stadium McMahon & Mann Consulting Engineering and Geology, P.C.
Project No.:	22-023
Sample No.:	Various
Lab ID No.:	Various
Analyst:	EBS
Date:	4/27/2022-4/29/22
Specimen Type:	2"x4" Bedrock Core
Cross-Head Speed:	0.05 in/min
Temp Conditioned:	70 deg. F

			Maximum
		Maximum	Compressive
		Load	Strength
Sample Name:	Sample ID:	<u>lbf</u>	<u>psi</u>
BH G6, 25.2-25.6'	22-116	5609.1	1814.9
BH H3, 22.8-23.2'	22-117	7302.9	2360.6
BH G3, 18.4-18.9'	22-118	8289.0	2676.7
BH A6, 26.2-26.6'	22-119	6083.6	1968.5
BH A6, 31.8-32.3'	22-120	10412.6	3378.3
BH F6, 20.2-20.6'	22-121	6504.3	2106.0
BH F5, 21.8-22.3'	22-122	4327.9	1393.3
BH H5, 18.5-18.9'	22-123	9688.2	3126.4
BH H5, 33.1-33.5'	22-124	13405.7	4331.9
BH F3, 20.7-21.1'	22-125	5971.7	1925.8
BH C2, 17.3-17.7'	22-126	6513.5	2100.5
BH C2, 23.2-23.7'	22-127	7883.2	2555.1
BH C3, 19.7-20.1'	22-128	7277.6	2347.7

Jeanne M. aspit

Respectfully Submitted, 3<sup>rd</sup> Rock, LLC

580 Olean Road East Aurora, NY 14052 Phone (716)655-4933, fax 655-8638



## Compressive Strength Report ASTM D2166

Project:	Buffalo Bills' Stadium	1	
Ū	McMahon & Mann C	onsulting Engineering	and Geology, P.C.
Project No.:	22-023	0 0 0	
Sample No.:	Various		
Lab ID No.:	Various		
Analyst:	EBS		
Date:	4/20/2022		
Specimen Type:	2"x4" Bedrock Core		
Cross-Head Speed:	0.05 in/min		
Temp Conditioned:	70 deg. F		
•	0		Maximum
		Maximum	Compressive
		Load	Strength
Sample Name:	Sample ID:	lbf	<u>psi</u>
BH F4, 20.4-20.8'	22-107	4376.6	1414.3
BH A4, 25.3-25.7'	22-108	3318.4	1058.1
BH G4, 24.5-24.9'	22-109	5265.0	1699.6
BH E4, 21.0-21.4'	22-110	6691.4	2165.9

Jeanne M. aspill

Respectfully Submitted, 3<sup>rd</sup> Rock, LLC

# **APPENDIX C**

MATERIAL AND PLACEMENT REQUIREMENTS NEW BILLS STADIUM ORCHARD PARK, NEW YORK

## APPENDIX C

## MATERIAL AND PLACEMENT REQUIREMENTS NEW BILLS STADIUM ORCHARD PARK, NEW YORK

This appendix presents material types and recommended compaction requirements for various materials recommended for the new Bills Stadium facility located in the Town of Orchard Park, New York.

### I. DRAINAGE STONE

Drainage stone should be used to backfill the space between the stadium foundation walls and rock excavations behind retaining walls, backfill between the top of competent rock and event level floor slabs and playing surface subgrade, and within the groundwater collection system. The drainage stone should meet the requirements specified by New York State Department of Transportation (NYSDOT) Standard Specifications Section 703, size designation 1. It should be placed in loose lifts approximately 12 inches thick and lightly tamped into place to limit voids.

### II. STRUCTURAL FILL

Structural fill should be used below slabs-on-grade, as subbase below paved areas, to raise site grades below planned structures, to replace unsuitable materials in the subgrade, and to backfill foundation, utility, and floor slab excavations below planned structures.

Structural fill should be crushed stone, sand, gravel, or a blend of these materials satisfying the requirements specified by the NYSDOT Standard Specifications Section 304, Item No. 304.14 (no slag shall be permitted). Structural fill should be compacted in loose lifts not exceeding 6 inches in thickness. It should be compacted to 90 percent of the maximum dry density as measured in the Modified Proctor test (ASTM D 1557). Each lift of structural fill should be tested for dry density and each test result should meet or exceed the minimum requirements.

The contractor should use hand compaction equipment (e.g., vibratory plate tamper, jumping jack, etc.) to compact the structural fill within 5 feet of foundations to limit the potential for damage to the concrete. In these areas, the structural fill should be placed in loose lifts approximately 4 inches thick and compacted to a visually stable condition.

### III. SUITABLE FILL

Suitable fill should be used to raise site grades and for backfill of foundation and utility excavations not below planned structures. Excavated glacial deposits, weathered shale, or competent shale can be used as suitable fill. It should be a mixture of crushed shale, gravel, sand, silt, and clay; free of organics, topsoil, particles larger than 4 inches in

diameter, and deleterious materials (e.g., slag, frozen soil, construction debris wood, etc.). It should have a plasticity index of no greater than 10.

The contractor should place the suitable fill in loose lifts not exceeding 8 inches thick and compact the material with a compactor compatible with the material type and lift thickness. The suitable fill should be compacted to 90 percent of its maximum dry density, as measured by the Modified Proctor test (ASTM D1557).

The contractor should use hand compaction equipment (e.g., vibratory plate tamper, jumping jack, etc.) to compact the suitable fill within 5 feet of foundations to limit the potential for damage to the concrete. In these areas, the suitable fill should be placed in loose lifts approximately 4 inches thick and compacted to a visually stable condition.

## IV. STABILIZATION GEOTEXTILE

Stabilization geotextiles should be used to line the prepared subgrade for pavement. All stabilization geotextiles should satisfy the requirements specified by the NYSDOT Standard Specifications Section 207 for stabilization geotextiles. Approved products and installation requirements are given in the specifications. All overlapped seams should have a minimum overlap of 12 inches.

# APPENDIX D

ENVIRONMENTAL ASSESSMENT FORM NEW BILLS STADIUM ORCHARD PARK, NEW YORK

# Full Environmental Assessment Form Part 1 - Project and Setting

# **Instructions for Completing Part 1**

**Part 1 is to be completed by the applicant or project sponsor.** Responses become part of the application for approval or funding, are subject to public review, and may be subject to further verification.

Complete Part 1 based on information currently available. If additional research or investigation would be needed to fully respond to any item, please answer as thoroughly as possible based on current information; indicate whether missing information does not exist, or is not reasonably available to the sponsor; and, when possible, generally describe work or studies which would be necessary to update or fully develop that information.

Applicants/sponsors must complete all items in Sections A & B. In Sections C, D & E, most items contain an initial question that must be answered either "Yes" or "No". If the answer to the initial question is "Yes", complete the sub-questions that follow. If the answer to the initial question is "No", proceed to the next question. Section F allows the project sponsor to identify and attach any additional information. Section G requires the name and signature of the applicant or project sponsor to verify that the information contained in Part 1 is accurate and complete.

#### A. Project and Applicant/Sponsor Information.

Name of Action or Project: New Bills Stadium		
Project Location (describe, and attach a general location map): Towns of Orchard Park and Hamburg, Erie Co., NY (All or parts of SBLs: 160.16-1-12, 160.1 161.17-6-1, and 161.17-6-3). See attached concept plan.	9-1-4.1, 161.00-5-3.1, 161.00-5-1,	161.00-5-16.1,
Brief Description of Proposed Action (include purpose or need): See attached pr	oject description for more informatic	n.
See attached Project Description.		
Name of Applicant/Sponsor:	Telephone: (716) 312-8607	
Buffalo Bills - Kathryn D'Angelo, Assistant General Counsel E-Mail: kathryn.d'angelo@bills.nfl.net		
Address: One Bills Drive		
City/PO: Orchard Park	State: NY	Zip Code: 14127
Project Contact (if not same as sponsor; give name and title/role):	Telephone:	•
	E-Mail:	
Address:		
City/PO:	State:	Zip Code:
Property Owner (if not same as sponsor):	Telephone: (716) 858-8008	1
Erie County	E-Mail: Mark.Rountree@erie.gc	v
Address: 95 Franklin Street, 10th Floor		
City/PO: Buffalo	State: NY	Zip Code: <sub>14202</sub>

<b>B. Government Approvals, H</b> assistance.)	funding, or Spor	<b>nsorship.</b> ("Funding" includes grants, loans, ta	ax relief, and any ot	her forms of financial
Government Entity		If Yes: Identify Agency and Approval(s) Required	Application Date (Actual or projected)	
a. City Council, Town Board, or Village Board of Trustee	∐Yes <b>⊠</b> No s			
b. City, Town or Village Planning Board or Commiss	□Yes <b>☑</b> No sion			
c. City, Town or Village Zoning Board of Ap	□Yes <b>√</b> No opeals			
d. Other local agencies	□Yes∎No			
e. County agencies	<b>⊘</b> Yes⊡No	County (transfer), County DPW (planning), County Water (water/sewer), County Leg. (transfer)	TBD	
f. Regional agencies	<b>□</b> Yes <b>☑</b> No			
g. State agencies	<b>∠</b> Yes□No	ESD, ECSC, SUNY, ECC (land transfer/funding approvals);	TBD	
h. Federal agencies	□Yes <b>☑</b> No	(State cont.) SHPO (consult only), NYSDOT (stormwater discharge/traffic consult)	TBD	
<ul><li>i. Coastal Resources.</li><li><i>i</i>. Is the project site within</li></ul>	a Coastal Area, c	or the waterfront area of a Designated Inland W	/aterway?	□Yes <b>Z</b> No
<i>ii.</i> Is the project site located <i>iii.</i> Is the project site within	l in a community a Coastal Erosior	with an approved Local Waterfront Revitalizate Hazard Area?	tion Program?	☑ Yes□No □ Yes☑No

# C. Planning and Zoning

C.1. Planning and zoning actions.	
<ul> <li>Will administrative or legislative adoption, or amendment of a plan, local law, ordinance, rule or regulation be the only approval(s) which must be granted to enable the proposed action to proceed?</li> <li>If Yes, complete sections C, F and G.</li> <li>If No, proceed to question C.2 and complete all remaining sections and questions in Part 1</li> </ul>	□Yes <b>Z</b> No
C.2. Adopted land use plans.	
a. Do any municipally- adopted (city, town, village or county) comprehensive land use plan(s) include the site where the proposed action would be located?	<b>✓</b> Yes□No
If Yes, does the comprehensive plan include specific recommendations for the site where the proposed action would be located?	✓Yes□No
b. Is the site of the proposed action within any local or regional special planning district (for example: Greenway; Brownfield Opportunity Area (BOA); designated State or Federal heritage area; watershed management plan; or other?)	<b>⊿</b> Yes⊡No
If Yes, identify the plan(s):	
NYS Heritage Areas West Frie Canal Corridor	
<ul> <li>c. Is the proposed action located wholly or partially within an area listed in an adopted municipal open space plan, or an adopted municipal farmland protection plan?</li> <li>If Yes, identify the plan(s):</li> </ul>	∐Yes <b>⊠</b> No

# C.3. Zoning ✓ Yes□No a. Is the site of the proposed action located in a municipality with an adopted zoning law or ordinance. If Yes, what is the zoning classification(s) including any applicable overlay district? Town of Hamburg - R3 Town of Orchard Park - R1 b. Is the use permitted or allowed by a special or conditional use permit? ✓ Yes 🗆 No □ Yes **Z**No c. Is a zoning change requested as part of the proposed action? If Yes, *i*. What is the proposed new zoning for the site? C.4. Existing community services. a. In what school district is the project site located? Orchard Park Central School District, Hamburg Central School District b. What police or other public protection forces serve the project site? Orchard Park Police Department, Town of Hamburg Police Department, Erie County Sheriff, NYS Troopers c. Which fire protection and emergency medical services serve the project site? Orchard Park Fire District EMS, Orchard Park Fire District, Town of Hamburg Fire Chiefs Association d. What parks serve the project site? Orchard Acres Park, California Road Recreational Area, Burmon Recreational Area, Blasdell Fireman's Memorial Park, Honeycrest Playground, Yates Park, Birdsong Park Nature Trail, Penn Dixie Fossil Park and Nature Preserve

### **D.** Project Details

### **D.1. Proposed and Potential Development**

a. What is the general nature of the proposed action (e.g., residential, industrial, commercial, r components)? Construction of new athletic stadium facility (including new parking lots/impro walking connections) and demolition of existing athletic stadium facility	recreational; if mixed, include all wements to existing lots and pedestrian
b. a. Total acreage of the site of the proposed action?       +/- 1{+ acre         b. Total acreage to be physically disturbed?       +/- 185* acre         c. Total acreage (project site and any contiguous properties) owned or controlled by the applicant or project sponsor?       +/- 284 acre	<ul> <li>*Approx. 30 acres of the Erie Community</li> <li>College Campus will be used for</li> <li>construction laydown, trade contractor</li> <li>parking, and storage. Applicant does not</li> <li>intend to completely demolish and</li> <li>reconstruct those areas.</li> </ul>
<ul> <li>c. Is the proposed action an expansion of an existing project or use?</li> <li><i>i.</i> If Yes, what is the approximate percentage of the proposed expansion and identify the unisquare feet)? % Units:</li> </ul>	☐ Yes ✔ No its (e.g., acres, miles, housing units, -
<ul> <li>d. Is the proposed action a subdivision, or does it include a subdivision?</li> <li>If Yes,</li> <li><i>i</i>. Purpose or type of subdivision? (e.g., residential, industrial, commercial; if mixed, specify commercial subdivision</li> <li><i>ii</i>. Is a cluster/conservation layout proposed?</li> <li><i>iii</i>. Number of lots proposed?2</li> <li><i>iv</i>. Minimum and maximum proposed lot sizes? Minimum +/- 1.0 acres Maximum +/-243 a</li> </ul>	✓ Yes □No r types) □Yes ☑No acres land transfer
<ul> <li>e. Will the proposed action be constructed in multiple phases?</li> <li><i>i</i>. If No, anticipated period of construction:</li></ul>	Yes No ths hth <u>2022</u> year hth <u>2026</u> year gencies where progress of one phase may schedule is developed, additional detail can be
provided as required, and 2) demolition of the existing stadium and site restoration.	

f. Does the project	ct include new resid	lential uses?			☐Yes <b>7</b> No
If Yes, show num	nbers of units prope	osed.			
	<u>One Family</u>	<u>Two Family</u>	<u>Three</u> Family	<u>Multiple Family (four or more)</u>	
Initial Phase					
At completion		. <u> </u>			
of all phases					
		• • • •		1	
g. Does the propo	osed action include	new non-residenti	al construction (inclu	iding expansions)?	✓ Yes No
<i>i</i> Total number	· of structures	2			
<i>ii.</i> Dimensions (	in feet) of largest n	roposed structure:	+/- 190 height:	+/- 730 width: and +/- 880 length	
<i>iii</i> . Approximate	extent of building	space to be heated	or cooled:	+/- 700.000 square feet	
h Does the prope	sed action include	<u>construction or of</u>	her activities that wil	l result in the impoundment of any	
liquids, such a	s creation of a wate	r supply, reservoir	r. pond. lake. waste l	agoon or other storage?	
If Yes,	Biological State	rotantian facilitian undergr	aund shambara wat panda and		rates helpus evicting conditions
<i>i</i> . Purpose of the	e impoundment: and	l improve control of runoff.	bund chambers, wet ponds, and	wastewater attenuation will be designed to reduce runoi	ates below existing conditions
<i>ii</i> . If a water imp	oundment, the prin	cipal source of the	e water:	Ground water 🗌 Surface water strea	ams 🗹 Other specify:
Stor <u>mwater tormwat</u>	er runoff from the proj	ect site and tributary	surface run-on to it. So	me wastewater will also be impounded.	
<i>ui</i> . If other than v	vater, identify the t	ype of impounded	contained liquids an	d their source.	a facilities is anticipated
in addition to storm	size of the propose	d impoundment	Volume:	(of ooo) Cubic vards	
v Dimensions o	of the proposed dam	or impounding st	$\frac{1}{1}$	5' height: 500' length average dim	<u>+/-15</u> acros
vi. Construction	method/materials	for the proposed d	am or impounding st	ructure (e.g., earth fill, rock, wood, cor	ncrete):
Biorention facilities (	shallow depression ar	nd biosoil filter), un <u>de</u>	erground chambers (pre	fab underground detention system), wet por	nds (ditch with grass and
landscaping) and wa	astewater attenuation	(concrete box)	- · ·		
D.2. Project Op	erations				
a. Does the propo (Not including materials will r If Yes:	osed action include general site prepar remain onsite)	any excavation, m ation, grading or in	nining, or dredging, d nstallation of utilities	uring construction, operations, or both or foundations where all excavated	? ☑Yes□No
<i>i</i> . What is the pu	rpose of the excav	ation or dredging?	Required for constructi	on of new stadium, setback perimeter, and	ancillary building location
ii. How much ma	terial (including ro	ck, earth, sedimen	ts, etc.) is proposed t	o be removed from the site?	
Volume	(specify tons or cu	bic yards): <u>Approx</u>	. 500,000 cubic yards		
<ul> <li>Over wh</li> </ul>	nat duration of time	? <u>The duration of r</u>	mass excavation is curre	ently anticipated to be 6/1/23 - 12/1/23	
<i>iii</i> . Describe natu	re and characteristi	cs of materials to	be excavated or dred	ged, and plans to use, manage or dispo	se of them.
Soil, gravel, and sha	le will be excavated.	Any material not suita	able for re-use on this si	te will be recycled off-site.	
$\frac{1}{1}$ Will there be	onsite dewatering	or processing of e	vegygted materials?		
If yes, descri	be. Onsite watering materials suitable	will occur during cons of for re-use).	struction. Some of the e	xcavated materials may be processed (crus	hed to make excavated
v. What is the to	otal area to be dred	ged or excavated?		Approx. 14.4 acres *To mee	t project schedule requirements, it i
vi. What is the m	naximum area to be	worked at any on	e time?	* See no + acres could be	that the entire area indicated above in operation at some point in the
<i>vii</i> . What would l	be the maximum de	pth of excavation	or dredging?	approx. 35 feet excavati	on process.
<i>viii</i> . Will the exca	avation require blas	ting?			<b>∐</b> Yes <b>∠</b> No
<i>ix</i> . Summarize sit	te reclamation goal	s and plan:			
The project's objective	ves are to re-use all e	xcavated material as	fill either on the new st	adium site, on the existing stadium site, at c	ther nearby locations
	a nearby lanuillis	•			
b. Would the pro- into any existi	posed action cause ing wetland, waterb	or result in alterat ody, shoreline, be	ion of, increase or de ach or adjacent area?	crease in size of, or encroachment	∐Yes <b>∕</b> No
<i>i</i> . Identify the w description):	vetland or waterboo	ly which would be	affected (by name, v	water index number, wetland map num	ber or geographic

<i>ii.</i> Describe how the proposed action would affect that waterbody or wetland, e.g. excavation, fill, placement of alteration of channels, banks and shorelines. Indicate extent of activities, alterations and additions in square	of structures, or feet or acres:
<i>iii.</i> Will the proposed action cause or result in disturbance to bottom sediments?	□Yes □No
<i>iv.</i> Will the proposed action cause or result in the destruction or removal of aquatic vegetation? If Yes:	☐ Yes ☐ No
acres of aquatic vegetation proposed to be removed:	
expected acreage of aquatic vegetation remaining after project completion:	
• purpose of proposed removal (e.g. beach clearing, invasive species control, boat access):	
• proposed method of plant removal:	
if chemical/herbicide treatment will be used, specify product(s):	
v. Describe any proposed reclamation/mitigation following disturbance:	
c Will the proposed action use or create a new demand for water? See note below.	<b>V</b> es <b>N</b> o
If Yes:	
<i>i</i> . Total anticipated water usage/demand per day: <u>30,000 to 40,000</u> gallons/day	
<i>ii.</i> Will the proposed action obtain water from an existing public water supply?	<b>⊘</b> Yes <b>No</b>
<ul> <li>If Yes: A majority of the existing field site east of Abbott Road is in Water District #17, Name of district or service area: and all areas west of Abbott Road are in Water District #6.</li> </ul>	while the ECC Campus
• Does the existing public water supply have capacity to serve the proposal?	✔ Yes No
• Is the project site in the existing district?	✔ Yes 🗌 No
• Is expansion of the district needed?	🗌 Yes 🗹 No
• Do existing lines serve the project site?	✔ Yes□ No
<i>iii.</i> Will line extension within an existing district be necessary to supply the project? If Yes:	<b>✓</b> Yes <b>□</b> No
<ul> <li>Describe extensions or capacity expansions proposed to serve this project:</li> </ul> The existing domestic cold water service line already to the site will be extended within the same site to the point of instantium.	nterconnection at the new
Source(s) of supply for the district: Lake Erie	
<i>iv.</i> Is a new water supply district or service area proposed to be formed to serve the project site? If, Yes:	🗋 Yes 🗹 No
Applicant/sponsor for new district:	
Date application submitted or anticipated:	
Proposed source(s) of supply for new district:	
v. If a public water supply will not be used, describe plans to provide water supply for the project:	
<i>vi</i> . If water supply will be from wells (public or private), what is the maximum pumping capacity: $N/A$ gal	lons/minute.
d. Will the proposed action generate liquid wastes?	✔ Yes □No
If Yes:	
<i>i</i> . Fotal anticipated inquid waste generation per day: $27,000-35,000$ gallons/day	mnonents and
approximate volumes or proportions of each):	mponents and
Sanitary wastewater will be generated from cooling tower, bathroom, locker room showers, team facilities, and cooking facilities be managed using on-site retention that allows for timed releases within the capacity of the sewage infrastructure, including the	Peak flows will continue to servicing treatment plant.
<i>iii.</i> Will the proposed action use any existing public wastewater treatment facilities? If Yes:	<b>✓</b> Yes <b>No</b>
<ul> <li>Name of wastewater treatment plant to be used. Southtowns Advanced Wastewater Treatment Facility</li> </ul>	
Name of district: Erie County Sewer District # 3	
• Does the existing wastewater treatment plant have capacity to serve the project?	<b>✓</b> Yes <b>□</b> No
• Is the project site in the existing district?	<b>✓</b> Yes <b>□</b> No
• Is expansion of the district needed?	☐ Yes <b>∕</b> No

**D.2.c.**: No. The new stadium will have less seating and will utilize high efficiency water saving fixtures. It is anticipated that there will be additional water usage at the construction site but not during events when the peak usage at the existing stadium occurs. Daily usage is estimated at between 550,000 GPD (including irrigation) with a peak load of 1,350 GPM for a game day event.

Page 5 of 13

<ul> <li>Do existing sewer lines serve the project site?</li> <li>Will a line extension within an existing district be necessary to serve the project?</li> </ul>	✔Yes□No □Yes <b>∕</b> No
If Yes:     Describe extensions or capacity expansions proposed to serve this project:	
<i>iv.</i> Will a new wastewater (sewage) treatment district be formed to serve the project site? If Yes:	☐Yes <b>Z</b> No
<ul> <li>Applicant/sponsor for new district:</li> <li>Date application submitted or anticipated:</li> </ul>	
<ul> <li>What is the receiving water for the wastewater discharge?</li> <li>v. If public facilities will not be used, describe plans to provide wastewater treatment for the project, including speciries receiving water (name and classification if surface discharge or describe subsurface disposal plans):</li> </ul>	ifying proposed
<i>vi.</i> Describe any plans or designs to capture, recycle or reuse liquid waste:	
<ul> <li>e. Will the proposed action disturb more than one acre and create stormwater runoff, either from new point sources (i.e. ditches, pipes, swales, curbs, gutters or other concentrated flows of stormwater) or non-point source (i.e. sheet flow) during construction or post construction?</li> </ul>	<b>₽</b> Yes <b>No</b>
<i>i.</i> How much impervious surface will the project create in relation to total size of project parcel? Square feet or	xisting storm sewer ts/discharge points.
<ul> <li>iii. Where will the stormwater runoff be directed (i.e. on-site stormwater management facility/structures, adjacent pr groundwater, on-site surface water or off-site surface waters)?</li> <li>Most stormwater will be directed to on-site stormwater management facilities. Some runoff may be collected in the NYSDOT storm se existing conditions). Other runoff will be directed to existing stormwater systems or new stormwater systems similar to existing condition</li> </ul>	roperties, ewer (as under ons.
If to surface waters, identify receiving water bodies or wetlands:	SDOT storm sewer (a
• Will stormwater runoff flow to adjacent properties? The perimeter project area may have minor runoff that sheet drains over adjacent properties as with existing conditions. <i>iv.</i> Does the proposed plan minimize impervious surfaces, use pervious materials or collect and re-use stormwater?	✓ Yes □ No ✓ Yes □ No
<ul> <li>f. Does the proposed action include, or will it use on-site, one or more sources of air emissions, including fuel combustion, waste incineration, or other processes or operations?</li> <li>If Yes, identify:</li> <li>i Makila surges during mained energiate comparison (a.g., becau equipment, fleet or delivery unkieles).</li> </ul>	<b>⊿</b> Yes □No
Equipment, trucks and vehicles <i>ii.</i> Stationary sources during construction (e.g., power generation, structural heating, batch plant, crushers) Batch plant	
<i>iii.</i> Stationary sources during operations (e.g., process emissions, large boilers, electric generation) Powe <u>r generation for life safety (emergency/standby power generation)</u> , large boilers, and water heaters	
g. Will any air emission sources named in D.2.f (above), require a NY State Air Registration, Air Facility Permit, or Federal Clean Air Act Title IV or Title V Permit?	□Yes <b>☑</b> No
<ul> <li>If Yes:</li> <li><i>i</i>. Is the project site located in an Air quality non-attainment area? (Area routinely or periodically fails to meet ambient air quality standards for all or some parts of the year)</li> <li><i>ii</i> In addition to emission on calculated in the amplication the maintenance.</li> </ul>	□Yes□No
In addition to emissions as calculated in the application, the project will generate:    Tons/year (short tons) of Carbon Dioxide (CO <sub>2</sub> )    Tons/year (short tons) of Nitrous Oxide (N <sub>2</sub> O)	
<ul> <li>Tons/year (short tons) of Perfluorocarbons (PFCs)</li> <li>Tons/year (short tons) of Sulfur Hexafluoride (SF<sub>6</sub>)</li> <li>Tons/year (short tons) of Carbon Dioxide equivalent of Hydroflourocarbons (HFCs)</li> </ul>	
Tons/year (short tons) of Hazardous Air Pollutants (HAPs)	

 D.2.e.ii: Receiving Point #1: Unnamed Tributary of Rush Creek.

 Discharge Point #1A: Direct Discharge to Creek

 Discharge Point #1B: To NYSDOT St. Sewer System in S.R. 20A

 that is believed to discharge to Creek (to be confirmed).

 Receiving Point #2: Southern Branch of Smokes Creek

 Discharge Point #2A: Direct Discharge to Creek

 Discharge Point #2B: to NYSDOT St. Swr. System in S.R. 20 that is believed to discharge to Creek (to be confirmed).

h. Will the proposed action generate or emit methane (including, but not limited to, sewage treatment plants, landfills, composting facilities)?	☐Yes <b>⁄</b> No
If Ves	
<i>i</i> Estimate methane generation in tons/year (metric):	
<i>ii</i> Describe any methane canture, control or elimination measures included in project design (e.g., combustion to g	enerate heat or
electricity flaring).	enerate near or
i. Will the proposed action result in the release of air pollutants from open-air operations or processes, such as	Yes No
quarry or landfill operations?	
If Yes: Describe operations and nature of emissions (e.g., diesel exhaust, rock particulates/dust):	
i. Will the proposed action result in a substantial increase in traffic above present levels or generate substantial	Ves
new demand for transportation facilities or services? See note below.	
If Yes:	
<i>i</i> . When is the peak traffic expected (Check all that apply): $\Box$ Morning $\Box$ Evening $\Box$ Weekend	
$\square$ Randomly between hours of to .	
ii. For commercial activities only, projected number of truck trips/day and type (e.g., semi trailers and dump truck	s):
iii Parking spaces: Existing Proposed Nationary despace	
in D Proposed Net increase/decrease	
<i>IV.</i> Does the proposed action include any shared use parking?	
<i>v</i> . If the proposed action includes any modification of existing roads, creation of new roads or change in existing	access, describe:
$v_i$ Are public/private transportation service(s) or facilities available within $\frac{1}{2}$ mile of the proposed site?	
<i>vi.</i> Will the proposed action include access to public transportation or accommodations for use of hybrid electric	
or other alternative fueled vehicles?	
<i>viii</i> Will the proposed action include plans for pedestrian or bicycle accommodations for connections to existing	□Yes□No
pedestrian or bicycle routes?	
k. Will the proposed action (for commercial or industrial projects only) generate new or additional demand	∐Yes <b>∕</b> No
for energy?	
i Estimate annual electricity domand during operation of the proposed action:	
<i>i</i> . Estimate annual electricity demand during operation of the proposed action.	
<i>ii</i> . Anticipated sources/suppliers of electricity for the project (e.g., on-site combustion, on-site renewable, via grid/	ocal utility, or
other):	oour attinty, or
<i>iii.</i> Will the proposed action require a new, or an upgrade, to an existing substation?	Yes No
1. Hours of operation. Answer all items which apply.	_
<i>i.</i> During Construction: Construction team will coordinate <i>ii.</i> During Operations: Security presence is 24/7/36	5.
Monday - Friday:6 AM -11 PM Monday - Friday: Reg. business hours on car	mpus are 9 AM to 5 PM
Saturday: 7 AM to 6 PM     Saturday: Hours will vary on even	nt days
Sunday: <u>8 AM to 5 PM</u> Sunday: <u>Hours will vary on even</u>	nt days
Holidays: N/A      Holidays: Hours will vary on even	nt days

**D.2.j**:No. The function, use and operation of the new Stadium will be similar to the existing Highmark Stadium which will be demolished. The current 71,600 seat capacity of Highmark Stadium generates an established traffic demand on event days. The new Stadium will have a reduced approximate 60,000 seat capacity of about 16%. Thus, it is anticipated that trip counts on the largest events such as Bills games and concerts will be reduced accordingly. The existing site controlled by the Buffalo Bills contains approximately 9,600 public use parking spaces and the proposed action will result in approximately 10,300 public use parking spaces, therefore the parking demand on the surrounding neighborhood is anticipated to be reduced.

m. Will the proposed action produce noise that will exceed existing ambient noise levels during construction,	✔ Yes □No
operation, or both? If yes:	
<i>i</i> . Provide details including sources, time of day and duration:	
Construction activities would exceed existing ambient noise levels. Once the stadium is operational, ambient noise would be comp stadium. The partial canopy and extent of exterior envelope enclosure may help contain sound levels as compared to existing con	arable to the existing ditions.
<i>ii.</i> Will the proposed action remove existing natural barriers that could act as a noise barrier or screen?	☐ Yes <b>Z</b> No
Describe:	
n. Will the proposed action have outdoor lighting? See note below.	✓ Yes □No
If yes: <i>i</i> Describe source(a) leastion(a) height of first we(a) direction (sim and maximity to respect accumical structures	
The parking areas altered by the project will replace the existing lighting with shorter poles and will consider use of lower poles ne	ar the stadium
pedestrian pathway areas, and adjacent to the residential property near Abbott Road. All light sources will be LED.	
<i>ii.</i> Will proposed action remove existing natural barriers that could act as a light barrier or screen? Describe:	🗆 Yes 🗹 No
If Yes, describe possible sources, potential frequency and duration of odor emissions, and proximity to nearest	
occupied structures:	
Odors would be created by cooking food at the stadium. The stadium will feature concession stands will generate food odors on ga	me and event days.
Similarly, tailgating activities in parking lots on game days would generate food odors. Any odors generated would be similar to exi	sting conditions.
p. Will the proposed action include any bulk storage of petroleum (combined capacity of over 1,100 gallons)	✓ Yes □ No
or chemical products 185 gallons in above ground storage or any amount in underground storage? See note be	low.
If Yes:	
<i>i</i> . Product(s) to be stored <u>Liquid reminizer</u> , residues, and rungicides as well as #2 deservor energency power generation <i>ii</i> . Volume(s) 200 gollop per unit time <u>voor</u> (e.g. month vegr) for liquid fertilizer pesticides and fungicides	
<i>iii.</i> Generally, describe the proposed storage facilities: There will be one (1) 8,000 gallon underground diesel storage tank	Per unit time is TBD.
Restricted use products will be stored in a fertilizer/pesticide cabinet that can be locked. Other fertilizers will stored on shelving in c	ontrolled access room.
q. Will the proposed action (commercial, industrial and recreational projects only) use pesticides (i.e., herbicides, insecticides) during construction or operation?	☑ Yes □No
If Yes:	
<i>i</i> . Describe proposed treatment(s):	ne of fortilizor and
monthly applications of fundicides. Pesticide application will be completed once annually (May/June) and then done	on an as needed
basis the remainder of the year.	
<i>ii.</i> Will the proposed action use Integrated Pest Management Practices?	🔲 Yes 🗹 No
r. Will the proposed action (commercial or industrial projects only) involve or require the management or disposal	✓ Yes □No
of solid waste (excluding hazardous materials)?	
<i>i</i> Describe any solid waste(s) to be generated during construction or operation of the facility	
Construction:     approx 2100-2800 tons per construction period (unit of time)	
Operation :approx. 84 tons per vear (unit of time) Note: Assumes 12 Bills	s home games and 3
<i>ii.</i> Describe any proposals for on-site minimization, recycling or reuse of materials to avoid disposal as solid was	te:
Construction: Based on data from similar projects, demolition of the existing stadium would produce approx. 1,000 ton     recycled), approx. 18,000 tons of concrete (95% recycled), and 100 tons of aluminum and metals (100	ns of debris (55%
Operation: Becyclable materials will primarily consist of cardboard, aluminum cans and paper products. Cardboard	balers and trash and
dedicated recycling containers will be provided in the loading dock and service area of the stadium.	
iii. Proposed disposal methods/facilities for solid waste generated on-site:	
Construction: The exact disposal method will be determined by the contractor and will follow all applicable NYSDEC g     standards.	juidelines and
Operation: The Buffalo Bills are aware of NYS laws regarding food waste regulations and requires its food service comply with all applicable laws. The stadium uses Modern Waste and Disposal for trash and recycling s	operator and vendors ervices.

**D.2.n.**: The types of sources will all be LED and will include a combination of post lights, bollards, steplights, low level pathlights, integral lighting within furniture, and adjustable general illumination lights mounted within trees. Uplighting will be sensitively used to accentuate key features of the New Stadium structure as well as specific moments within the plazas/landscaped areas. Any fixture that sits close to the perimeter of site will be equipped with shielding to prevent light trespass. A lighting control system will be implemented and will play a key role in the outdoor environment, allowing fixtures to be regulated to appropriate light levels during evening hours when guests are on site as well as after hours for security.

#### Page 8 of 13

**D.2.p.**: The stadium facility currently stores diesel fuel, pesticides, and fungicides on site. With respect to pesticides and fungicides, all products, usage, frequency and process will be similar to what is currently done to the practice fields at the Training Facility. However, the existing stadium field is artificial turf so a new natural grass field at the new stadium will increase the overall quantity used annually. The new stadium will also increase the storage of diesel from existing conditions.

s. Does the proposed action include construction or modification of a solid waste management facility?	🗌 Yes 🗹 No
If Yes:	
<i>i</i> . Type of management or handling of waste proposed for the site (e.g., recycling or transfer station, composting, l	andfill, or
other disposal activities):	
<i>ii.</i> Anticipated rate of disposal/processing:	
• Tons/month, if transfer or other non-combustion/thermal treatment, or	
• Tons/hour, if combustion or thermal treatment	
<i>iii.</i> If landfill, anticipated site life: years	
t. Will the proposed action at the site involve the commercial generation, treatment, storage, or disposal of hazardous	5 ☐ Yes ✔ No
waste? Hazardous waste, if encountered during demolition, will be disposed of according to local, state, and federal guideline	es.
If Yes:	
<i>i</i> . Name(s) of all hazardous wastes or constituents to be generated, handled or managed at facility:	
ii Conorally describe processes or activities involving bezordous wester or constituents:	
<i>u</i> . Otherany describe processes of activities involving nazardous wastes of constituents.	
<i>iii.</i> Specify amount to be handled or generated tons/month	
<i>iv.</i> Describe any proposals for on-site minimization, recycling or reuse of hazardous constituents:	
v. Will any hazardous wastes be disposed at an existing offsite hazardous waste facility?	∐Yes∐No
If Yes: provide name and location of facility:	
If No: describe proposed management of any nazardous wastes which will not be sent to a hazardous waste facility:	
E. Site and Setting of Proposed Action	
E.1. Land uses on and surrounding the project site	
a. Existing land uses.	
i. Check all uses that occur_on, adjoining and near the project site.	
🔲 Urban 🔲 Industrial 🗹 Commercial 🗹 Residential (suburban) 🗌 Rural (non-farm)	
Forest Agriculture Aquatic Other (specify): Educational Facility (Erie County Community College)	

_			
	Aquatic	Other (specify): Educational Facility (Erie County Communication)	Jr

	. 01050	L 15	ilculture	Indante
ii.	If mix	of uses,	generally	describe:

<b>V</b> Other (	(specify): Education	al Facility (Erie Co	ounty Community Coll

Bills Stadium is located in a suburban area and is surrounded by residential and commercial uses and a community college.

b. Land uses and covertypes on the project site.				
	Land use or Covertype	Current Acreage	Acreage After Project Completion	Change (Acres +/-)
•	Roads, buildings, and other paved or impervious surfaces	95.0	120.0	+25.0
•	Forested	2.0	0	-2.0
٠	Meadows, grasslands or brushlands (non- agricultural, including abandoned agricultural)	0	0	
•	Agricultural (includes active orchards, field, greenhouse etc.)	0	0	
٠	Surface water features see note below (lakes, ponds, streams, rivers, etc.)	0	1.5	+1.5
٠	Wetlands (freshwater or tidal)	0		
•	Non-vegetated (bare rock, earth or fill)			
•	Other Describe: <u>manicured/dense lawn</u>	88.0	63.5	-24.5

Surface Water Features: 1.5 acres of permanent retention features are added by new stadium design.

<ul> <li>c. Is the project site presently used by members of the community for public recreation?</li> <li><i>i</i>. If Yes: explain: Highmark Stadium hosts public events at their facility.</li> </ul>	<b>✓</b> Yes□No
<ul> <li>d. Are there any facilities serving children, the elderly, people with disabilities (e.g., schools, hospitals, licensed day care centers, or group homes) within 1500 feet of the project site?</li> <li>If Yes, <ul> <li><i>i</i>. Identify Facilities:</li> </ul> </li> <li>Erie Community College is located to the west of Highmark Stadium. Windom Elementary School is located to the northwest of High Southtowns Childrens Associates is a special education school located north of Highmark Stadium.</li> </ul>	Yes∏No
e. Does the project site contain an existing dam?       Does not include impoundments discussed in D.1.h.         If Yes:       i. Dimensions of the dam and impoundment:         • Dam height:	∏Yes <b>∕</b> No
<ul> <li>f. Has the project site ever been used as a municipal, commercial or industrial solid waste management facility, or does the project site adjoin property which is now, or was at one time, used as a solid waste management facility for the solid waste management facility if Yes: <ul> <li><i>i</i>. Has the facility been formally closed?</li> <li>If yes, cite sources/documentation:</li> </ul> </li> <li><i>ii</i>. Describe the location of the project site relative to the boundaries of the solid waste management facility:</li> </ul>	□Yes <b>/</b> No lity? □Yes□ No
<i>iii.</i> Describe any development constraints due to the prior solid waste activities:	
<ul> <li>g. Have hazardous wastes been generated, treated and/or disposed of at the site, or does the project site adjoin property which is now or was at one time used to commercially treat, store and/or dispose of hazardous waste?</li> <li>If Yes: <ul> <li><i>i</i>. Describe waste(s) handled and waste management activities, including approximate time when activities occurr</li> <li>ECC handles hazardous wastes according to federal (RCRA) and state requirements.</li> </ul> </li> </ul>	✔Yes∏No ed:
<ul> <li>h. Potential contamination history. Has there been a reported spill at the proposed project site, or have any remedial actions been conducted at or adjacent to the proposed site?</li> <li>If Yes: <ul> <li><i>i</i>. Is any portion of the site listed on the NYSDEC Spills Incidents database or Environmental Site</li> <li>Remediation database? Check all that apply:</li> <li> <sup>8803429, 9214217,09055</sup></li> <li> <sup>8803429, 9214217,09055</sup></li> <li> <sup>8803429, 9214217,09055</sup></li> </ul> </li> </ul>	✓ Yes No ✓ Yes No 583,1302788,
☐ Yes – Environmental Site Remediation database Provide DEC ID number(s):	
iii. Is the project within 2000 feet of any site in the NYSDEC Environmental Site Remediation database? If yes, provide DEC ID number(s): iv. If yes to (i), (ii) or (iii) above, describe current status of site(s): No current violations or active spills	☐ Yes  No
<ul> <li>v. Is the project site subject to an institutional control limiting property uses?</li> <li>If yes_DEC site ID number:</li> </ul>	∐Yes∎No
----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--------------------------
<ul> <li>Describe the type of institutional control (e.g., deed restriction or easement):</li> <li>Describe any use limitations:</li> </ul>	
<ul> <li>Describe any engineering controls:</li></ul>	☐ Yes ☐ No
THIS PORTION OF THE FORM	
COMPLETED BY MCMAHON & MANN	
E.2. Natural Resources On or Near Project Site	
a. What is the average depth to bedrock on the project site? +/- 7.8 feet	
b. Are there bedrock outcroppings on the project site? If Yes, what proportion of the site is comprised of bedrock outcroppings?%	☐ Yes <b>⁄</b> No
c. Predominant soil type(s) present on project site: MfA - Marilla shaly silt loam 33 %	
<u>MaB - Manlius shaly silt loam</u> <u>33</u> % DbA - Darien silt loam <u>34</u> %	
d. What is the average depth to the water table on the project site? Average:	
e. Drainage status of project site soils: ✓ Well Drained: 33 % of site ✓ Moderately Well Drained: 33 % of site	
Poorly Drained <u>34</u> % of site	
f. Approximate proportion of proposed action site with slopes: $\checkmark$ 0-10%:      1(+)% of site $\square$ 10-15%:      % of site $\square$ 15% or greater:      % of site	
g. Are there any unique geologic features on the project site?	☐ Yes <b>∕</b> No
h. Surface water features.	
<i>i</i> . Does any portion of the project site contain wetlands or other waterbodies (including streams, rivers, ponds or lakes)?	<b>✓</b> Yes No
<i>ii.</i> Do any wetlands or other waterbodies adjoin the project site? see note below.	<b>∠</b> Yes <b></b> No
If Yes to either <i>i</i> or <i>ii</i> , continue. If No, skip to E.2.i.	
<i>iii.</i> Are any of the wetlands or waterbodies within or adjoining the project site regulated by any federal, state or local agency?	✓ Yes 🖾 No
<ul> <li><i>iv.</i> For each identified regulated wetland and waterbody on the project site, provide the following information:</li> <li>Streams: Name 837-226, 837-229, 837-235</li> </ul>	
Lakes or Ponds: Name     Classification	
Wetlands: Name <u>federal wetland (PFO1A)</u> Approximate Size <u>+/-4 a</u>	cres
<i>v</i> . Are any of the above water bodies listed in the most recent compilation of NYS water quality-impaired waterbodies?	✓ Yes □No
If yes, name of impaired water body/bodies and basis for listing as impaired: Name - Pollutants - Uses:Rush Creek and tribs – Pathogens;Nutrients – Recreation;Public Bathing;Aquatic Life, Name - Pollutants - Uses:South Bi Branch Smoke Creek Lower and tribs – Nutrients:Sit/Gediment – Recreation; Aquatic Life	anch Smoke Creek (lowe
i. Is the project site in a designated Floodway?	<b>✓</b> Yes <b>□</b> No
j. Is the project site in the 100-year Floodplain?	<b>✓</b> Yes No
k. Is the project site in the 500-year Floodplain?	<b>✓</b> Yes <b>N</b> o
<ul> <li>l. Is the project site located over, or immediately adjoining, a primary, principal or sole source aquifer?</li> <li>If Yes: <ul> <li>i. Name of aquifer:</li> </ul> </li> </ul>	∐Yes <b>⊠</b> No

E.2.h: The streams and wetlands listed above are located on the project site but will not be impacted by the project.

m. Identify the predominant wildlife species Typical suburban species such as rodents, deer, songbirds, crows,	that occupy or use the project site: foxes, coyotes, squirrels, rabbits, raptors, crows, frogs, and snakes	raccoons, woodchucks, may pass through the s	chipmunks,ite.
<ul> <li>n. Does the project site contain a designated if Yes:</li> <li><i>i</i>. Describe the habitat/community (composite)</li> </ul>	significant natural community? sition, function, and basis for designa	tion):	∐Yes <b>⊠</b> No
<ul> <li>ii. Source(s) of description or evaluation:</li></ul>	proposed:	acres acres acres	
<ul> <li>o. Does project site contain any species of platendangered or threatened, or does it contain If Yes:</li> <li><i>i</i>. Species and listing (endangered or threatened)</li> </ul>	ant or animal that is listed by the fed n any areas identified as habitat for a d):	eral government or NYS as n endangered or threatened spec	☐ Yes <b>⁄⁄</b> No cies?
<ul> <li>p. Does the project site contain any species of special concern?</li> <li>If Yes: <ul> <li>i. Species and listing:</li> </ul> </li> </ul>	of plant or animal that is listed by NY	S as rare, or as a species of	☐Yes <b>⁄</b> No
q. Is the project site or adjoining area current If yes, give a brief description of how the pro Recreational fishing activities take place in Smokes	ly used for hunting, trapping, fishing posed action may affect that use: Creek and Rush Creek.	or shell fishing?	<b>∅</b> Yes <b>□</b> No
E.3. Designated Public Resources On or N	lear Project Site		
a. Is the project site, or any portion of it, loca Agriculture and Markets Law, Article 25- If Yes, provide county plus district name/nu	ted in a designated agricultural distri AA, Section 303 and 304? mber:	ct certified pursuant to	∐Yes <b>∕</b> No
<ul> <li>b. Are agricultural lands consisting of highly</li> <li><i>i.</i> If Yes: acreage(s) on project site? +/- 1 ac</li> <li><i>ii.</i> Source(s) of soil rating(s): USDA Farmlan</li> </ul>	productive soils present? cre d Classification (Prime Soils)		<b>₽</b> Yes No
<ul> <li>c. Does the project site contain all or part of, Natural Landmark?</li> <li>If Yes: <ol> <li>Nature of the natural landmark:</li> <li>Provide brief description of landmark, in</li> </ol> </li> </ul>	, or is it substantially contiguous to, a Biological Community C C Concluding values behind designation and	a registered National Geological Feature nd approximate size/extent:	∐Yes <b>∕</b> No
<ul> <li>d. Is the project site located in or does it adjo</li> <li>If Yes: <ul> <li><i>i</i>. CEA name:</li> <li><i>ii</i>. Basis for designation:</li> <li><i>iii</i>. Designating agency and date:</li> </ul> </li> </ul>	in a state listed Critical Environment	al Area?	☐Yes <b>⁄</b> No

e. Does the project site contain, or is it substantially contiguous to, a building, archaeological site, or district which is listed on the National or State Register of Historic Places, or that has been determined by the Commission Office of Parks, Recreation and Historic Preservation to be eligible for listing on the State Register of Historic Places.	Yes No oner of the NYS aces?
<i>i</i> . Nature of historic/archaeological resource: Archaeological Site Historic Building or District <i>ii</i> . Name:	
<i>iii.</i> Brief description of attributes on which listing is based:	
f. Is the project site, or any portion of it, located in or adjacent to an area designated as sensitive for archaeological sites on the NY State Historic Preservation Office (SHPO) archaeological site inventory?	<b>₽</b> Yes <b>N</b> o
<ul> <li>g. Have additional archaeological or historic site(s) or resources been identified on the project site?</li> <li>If Yes: <ul> <li><i>i</i>. Describe possible resource(s):</li> <li><i>ii</i>. Basis for identification:</li> </ul> </li> </ul>	☐Yes <b>Ø</b> No
<ul> <li>h. Is the project site within fives miles of any officially designated and publicly accessible federal, state, or local scenic or aesthetic resource?</li> <li>If Yes: <ul> <li><i>i</i>. Identify resource: Woodlawn Beach State Park</li> </ul> </li> </ul>	<b>₽</b> Yes <b>□</b> No
<ul> <li>ii. Nature of, or basis for, designation (e.g., established highway overlook, state or local park, state historic trail or etc.): State Park</li> <li>iii. Dictance between project and recourses</li> </ul>	scenic byway,
<i>III.</i> Distance between project and resource: <u>approx.5</u> miles.	
<ul> <li>i. Is the project site located within a designated river corridor under the Wild, Scenic and Recreational Rivers Program 6 NYCRR 666?</li> <li>If Yes:</li> <li><i>i</i> Identify the name of the river and its designation:</li> </ul>	☐ Yes <b>Z</b> No
<i>ii.</i> Is the activity consistent with development restrictions contained in 6NYCRR Part 666?	□Yes □No

### F. Additional Information

Attach any additional information which may be needed to clarify your project.

If you have identified any adverse impacts which could be associated with your proposal, please describe those impacts plus any measures which you propose to avoid or minimize them.

### G. Verification

I certify that the information provided is true to the best of my knowledge.

Applicant/S	Sponsor Name Kathryn D'Angelo	7/1/2022 Date	
	DocuSigned by:		
Signature	tathryn D'Angelo	Title Assistant General Counsel	

PRINT FORM

# **APPENDIX E**

LIMITATIONS NEW BILLS STADIUM ORCHARD PARK, NEW YORK

## APPENDIX E

## LIMITATIONS NEW BILLS STADIUM ORCHARD PARK, NEW YORK

1. The scope of McMahon & Mann Consulting Engineering and Geology, P.C.'s services is limited to the geotechnical engineering considerations identified in our agreement.

2. The scope of work for this project does not include an evaluation of the presence of hazardous substances. The Buffalo Bills, LLC should contact McMahon & Mann Consulting Engineering and Geology, P.C. in the event that hazardous substances are encountered to evaluate the impact on the geotechnical recommendations.

3. The analyses and recommendations submitted in this report are based in part upon the data obtained from the subsurface explorations. The nature and extent of variations between these explorations may not become evident until construction. If variations then appear, it will be necessary to re-evaluate the recommendations in this report.

4. The generalized soil and rock profile described in the text is intended to convey trends in subsurface conditions. The boundaries between strata are approximate and idealized. They have been developed by interpretations of widely-spaced explorations and samples. Actual soil and rock transitions can vary.

5. Groundwater was observed at the times and under the conditions stated. Fluctuations in the groundwater levels occur from rainfall, seasonal runoff and other factors differing from the time that the observations were made.

6. In the event that any changes in the nature or design of the project are planned, the conclusions and recommendations contained in this report will not be considered valid unless the changes are reviewed and conclusions of this report are modified or verified in writing by McMahon & Mann Consulting Engineering and Geology, P.C. It is recommended that McMahon & Mann Consulting Engineering and Geology, P.C. be given the opportunity to review the final design and specifications to verify that our recommendations are properly interpreted.

7. It is recommended that McMahon & Mann Consulting Engineering and Geology, P.C. be retained to monitor geotechnical aspects of the project construction.

8. This report has been prepared for the exclusive use of Legends Project Development and the Buffalo Bills, LLC for the specific application to the proposed stadium and associate structures in Orchard Park, New York in accordance with generally accepted soil and foundation engineering practice. No other warranty, expressed or implied, is made.