



**VOLUME 4**  
**PARKS INVENTORY AND ASSESSMENT**



THIS PAGE INTENTIONALLY LEFT BLANK

THIS PAGE INTENTIONALLY LEFT BLANK

# TABLE OF CONTENTS: VOLUME 4

## VOLUME 4

1.0 INVENTORY AND ASSESSMENT OF FEATURES..... V4-6  
2.0 WPA ASSESSMENT..... V4-35



# PARKS INVENTORY AND ASSESSMENT

## 1.0 INVENTORY AND ASSESSMENT DATA

PARK NAME	FEATURE TYPE	FEATURE SUBCATEGORY	FEATURE NAME	CONDITION	COMMENT
Akron Falls Park	Infrastructure	Bridge	Bridge PK-1	Good	BIN 3362090
Akron Falls Park	Infrastructure	Bridge	Bridge PK-2	Good	BIN 3362100
Akron Falls Park	Infrastructure	Bridge	Bridge PK-3	Fair	BIN 3362110 Pedestrian bridge
Akron Falls Park	Infrastructure	Culvert	Culvert	Fair	Leaf blockage
Akron Falls Park	Infrastructure	Culvert	Culvert	Poor	
Akron Falls Park	Infrastructure	Culvert	Culvert	Fair	Old Stone WPA culvert
Akron Falls Park	Infrastructure	Culvert	Culvert	Fair	Old Stone WPA culvert
Akron Falls Park	Infrastructure	Culvert	Culvert	Good	Old Stone WPA culvert
Akron Falls Park	Infrastructure	Culvert	Culvert	Good	Old Stone WPA culvert
Akron Falls Park	Infrastructure	Culvert	Culvert	Good	Old Stone WPA culvert
Akron Falls Park	Infrastructure	Culvert	Culvert	Poor	Old Stone WPA culvert
Akron Falls Park	Infrastructure	Culvert	Culvert	Poor	Old Stone WPA culvert
Akron Falls Park	Infrastructure	Other Amenity	Dam	Good	
Akron Falls Park	Infrastructure	Other Amenity	Gate	Good	
Akron Falls Park	Infrastructure	Parking	Parking Lot 1	Good	
Akron Falls Park	Infrastructure	Parking	Parking Lot 10	Good	
Akron Falls Park	Infrastructure	Parking	Parking Lot 11	Good	
Akron Falls Park	Infrastructure	Parking	Parking Lot 2	Good	
Akron Falls Park	Infrastructure	Parking	Parking Lot 3	Good	
Akron Falls Park	Infrastructure	Parking	Parking Lot 4	Fair	
Akron Falls Park	Infrastructure	Parking	Parking Lot 5	Fair	Crushed gravel surface
Akron Falls Park	Infrastructure	Parking	Parking Lot 6	Good	Asphalt pavement
Akron Falls Park	Infrastructure	Parking	Parking Lot 7	Good	
Akron Falls Park	Infrastructure	Parking	Parking Lot 8	Good	
Akron Falls Park	Infrastructure	Parking	Parking Lot 9	Fair	
Akron Falls Park	Infrastructure	Signage	Gateway sign	Good	Park signage
Akron Falls Park	Infrastructure	Signage	Gateway sign	Good	Park entrance sign
Akron Falls Park	Infrastructure	Signage	Gateway sign	Good	Park signage and map
Akron Falls Park	Recreation	Athletic Field	Baseball - Brooklyn	Poor	Backstop poor, field lights not sure if working
Akron Falls Park	Recreation	Athletic Field	Baseball - Parkview	Poor	Backstop fair, bleachers fair, no skinned infield
Akron Falls Park	Recreation	Court Sport	Basketball	Fair	Asphalt cracking. Needs restriping
Akron Falls Park	Recreation	Court Sport	Tennis	Fair	2 courts. Some cracking in surface

PARK NAME	FEATURE TYPE	FEATURE SUBCATEGORY	FEATURE NAME	CONDITION	COMMENT
Akron Falls Park	Recreation	Other Amenity	Grill #1	Poor	Old stone BBQ grill, potential to restore
Akron Falls Park	Recreation	Other Amenity	Grill #10	Poor	Old stone BBQ grill, potential to restore
Akron Falls Park	Recreation	Other Amenity	Grill #11	Poor	Old Stone BBQ grill, not worth repairing
Akron Falls Park	Recreation	Other Amenity	Grill #12	Poor	Old Stone BBQ grill, not worth repairing
Akron Falls Park	Recreation	Other Amenity	Grill #13	Poor	Old stone BBQ grill, potential to restore
Akron Falls Park	Recreation	Other Amenity	Grill #14	Poor	Old stone BBQ grill, potential to restore
Akron Falls Park	Recreation	Other Amenity	Grill #15	Poor	Old Stone BBQ grill, not worth repairing
Akron Falls Park	Recreation	Other Amenity	Grill #16	Poor	Old stone BBQ grill, potential to restore
Akron Falls Park	Recreation	Other Amenity	Grill #17	Fair	Old stone BBQ grill, potential to restore
Akron Falls Park	Recreation	Other Amenity	Grill #18	Fair	Old stone BBQ grill, potential to restore
Akron Falls Park	Recreation	Other Amenity	Grill #19	Poor	Old stone BBQ grill, potential to restore
Akron Falls Park	Recreation	Other Amenity	Grill #2	Fair	Concrete BBQ grill, cast iron grate
Akron Falls Park	Recreation	Other Amenity	Grill #20	Poor	Old stone BBQ grill, potential to restore
Akron Falls Park	Recreation	Other Amenity	Grill #21	Poor	Old stone BBQ grill, potential to restore
Akron Falls Park	Recreation	Other Amenity	Grill #22	Poor	Old stone BBQ grill, potential to restore
Akron Falls Park	Recreation	Other Amenity	Grill #23	Poor	Old stone BBQ grill, potential to restore
Akron Falls Park	Recreation	Other Amenity	Grill #24	Fair	Old stone BBQ grill, potential to restore
Akron Falls Park	Recreation	Other Amenity	Grill #25	Fair	Old stone BBQ grill, potential to restore
Akron Falls Park	Recreation	Other Amenity	Grill #26	Poor	Old Stone BBQ grill, not worth repairing



PARK NAME	FEATURE TYPE	FEATURE SUBCATEGORY	FEATURE NAME	CONDITION	COMMENT
Akron Falls Park	Recreation	Other Amenity	Grill #27	Poor	Old stone BBQ grill, potential to restore
Akron Falls Park	Recreation	Other Amenity	Grill #28	Poor	Old stone BBQ grill, potential to restore
Akron Falls Park	Recreation	Other Amenity	Grill #29	Poor	Old stone BBQ grill, potential to restore
Akron Falls Park	Recreation	Other Amenity	Grill #3	Poor	Old Stone BBQ grill, not worth repairing
Akron Falls Park	Recreation	Other Amenity	Grill #30	Fair	Old stone BBQ grill, potential to restore
Akron Falls Park	Recreation	Other Amenity	Grill #31	Poor	Old Stone BBQ grill, not worth repairing
Akron Falls Park	Recreation	Other Amenity	Grill #4	Poor	Old Stone BBQ grill, not worth repairing
Akron Falls Park	Recreation	Other Amenity	Grill #5	Poor	Old stone BBQ grill, potential to restore
Akron Falls Park	Recreation	Other Amenity	Grill #6	Poor	Old stone BBQ grill, not worth restoring
Akron Falls Park	Recreation	Other Amenity	Grill #7	Poor	Old stone BBQ grill, potential to restore
Akron Falls Park	Recreation	Other Amenity	Grill #8	Poor	Old stone BBQ grill, potential to restore
Akron Falls Park	Recreation	Other Amenity	Grill #9	Poor	Old stone BBQ grill, potential to restore
Akron Falls Park	Recreation	Other Amenity	Overlook	Fair	Waterfall overlook point: Overlook is from behind fence
Akron Falls Park	Recreation	Other Amenity	Rock Garden	Good	
Akron Falls Park	Recreation	Other Amenity	Waterfall overlook	Fair	
Akron Falls Park	Recreation	Playground	Brooklyn Playground	Good	Swing, slide & climber
Akron Falls Park	Recreation	Playground	Cummings Playground	Fair	Climber, swings and slide
Akron Falls Park	Recreation	Playground	East End Playground	Good	Play Structure
Akron Falls Park	Recreation	Playground	Legacy Cinderella Coach	Good	no fall surface
Akron Falls Park	Recreation	Playground	Legacy climber	Fair	no fall surface
Akron Falls Park	Recreation	Playground	Legacy Tower Slide	Fair	no fall surface



PARK NAME	FEATURE TYPE	FEATURE SUBCATEGORY	FEATURE NAME	CONDITION	COMMENT
Akron Falls Park	Recreation	Playground	Legacy Truck Climber	Fair	no fall surface
Akron Falls Park	Recreation	Playground	Merry go round	Fair	Old merry go round
Akron Falls Park	Recreation	Playground	Old Slide	Poor	no fall surface, suggest removal
Akron Falls Park	Recreation	Playground	Old Slide	Poor	no fall surface, suggest removal
Akron Falls Park	Recreation	Playground	Old Slide	Poor	no fall surface, suggest removal
Akron Falls Park	Recreation	Playground	Old Slide	Poor	no fall surface, suggest removal
Akron Falls Park	Recreation	Playground	Old Slide	Poor	no fall surface, framing damaged, suggest removal
Akron Falls Park	Recreation	Playground	Old Slide	Poor	no fall surface, framing damaged, suggest removal
Akron Falls Park	Recreation	Playground	Old Slide	Poor	no fall surface, suggest removal
Akron Falls Park	Recreation	Playground	Old Slide	Poor	no fall surface, suggest removal
Akron Falls Park	Recreation	Playground	Old Slide	Poor	no fall surface, suggest removal
Akron Falls Park	Recreation	Playground	Old Slide	Poor	no fall surface, suggest removal
Akron Falls Park	Recreation	Playground	Old Swing	Poor	no fall surface, suggest removal
Akron Falls Park	Recreation	Playground	Old Swing	Poor	no fall surface, framing damaged, suggest removal
Akron Falls Park	Recreation	Playground	Old Swing	Poor	no fall surface, framing damaged, suggest removal
Akron Falls Park	Recreation	Playground	Old Swing	Poor	no fall surface, suggest removal
Akron Falls Park	Recreation	Playground	Old Swing	Poor	no fall surface, suggest removal
Akron Falls Park	Recreation	Playground	Old Swing	Poor	no fall surface, framing damaged, suggest removal
Akron Falls Park	Recreation	Playground	Old Swing	Poor	no fall surface, framing damaged, suggest removal
Akron Falls Park	Recreation	Playground	Old Swing	Poor	no fall surface, suggest removal
Akron Falls Park	Recreation	Playground	Old Swing	Poor	no fall surface, suggest removal
Akron Falls Park	Recreation	Playground	Old Swing	Poor	no fall surface, chains too short, suggest removal
Akron Falls Park	Recreation	Playground	Old Swing	Poor	no fall surface, chains too short, framing damaged, suggest removal
Akron Falls Park	Recreation	Playground	Old Swings	Poor	no fall surface, framing damaged, suggest removal
Akron Falls Park	Recreation	Playground	Parkview Playground	Good	Play Structure
Akron Falls Park	Recreation	Playground	Playground E	Good	Climber, swings and slide
Akron Falls Park	Recreation	Playground	Swings	Fair	replenish fall surface



PARK NAME	FEATURE TYPE	FEATURE SUBCATEGORY	FEATURE NAME	CONDITION	COMMENT
Akron Falls Park	Recreation	Playground	Swings	Fair	replenish fall surface
Akron Falls Park	Recreation	Playground	Swings	Fair	replenish fall surface
Akron Falls Park	Recreation	Playground	Valley Playground	Good	Climber, slide and swings
Akron Falls Park	Structure	Building	Cummings Lodge	Good	
Akron Falls Park	Structure	Building	Maintenance shops	NA	Not assessed
Akron Falls Park	Structure	Building	Superintendent Residence	NA	not assessed
Akron Falls Park	Structure	Building	Warming shelter	Poor	boarded up and not used, skating disallowed on pond
Akron Falls Park	Structure	Comfort Station	Brooklyn St Comfort Station	Good	
Akron Falls Park	Structure	Comfort Station	Falls Comfort Station	Good	
Akron Falls Park	Structure	Comfort Station	Parkview Comfort Station	Good	
Akron Falls Park	Structure	Comfort Station	Valley Comfort Station	Good	
Akron Falls Park	Structure	Other Amenity	Stone railings	Fair	WPA Stone railings
Akron Falls Park	Structure	Other Amenity	Wall	Fair	Old Stone WPA wall
Akron Falls Park	Structure	Other Amenity	Wall	Good	Old Stone WPA wall
Akron Falls Park	Structure	Other Amenity	Wall	Good	WPA Stone wall
Akron Falls Park	Structure	Other Amenity	Wall	Good	WPA stone seat wall
Akron Falls Park	Structure	Other Amenity	Wall	Good	Old Stone WPA wall
Akron Falls Park	Structure	Other Amenity	Wall	Good	Old Stone WPA wall
Akron Falls Park	Structure	Other Amenity	Wall	Good	Old Stone wall
Akron Falls Park	Structure	Shelter	Shelter #1	Good	
Akron Falls Park	Structure	Shelter	Shelter #10	Good	Recently restored
Akron Falls Park	Structure	Shelter	Shelter #11	Good	
Akron Falls Park	Structure	Shelter	Shelter #12	Good	
Akron Falls Park	Structure	Shelter	Shelter #13X	NA	Not rented
Akron Falls Park	Structure	Shelter	Shelter #14	Good	
Akron Falls Park	Structure	Shelter	Shelter #15	Good	
Akron Falls Park	Structure	Shelter	Shelter #2	Good	
Akron Falls Park	Structure	Shelter	Shelter #3	Good	
Akron Falls Park	Structure	Shelter	Shelter #4	Good	
Akron Falls Park	Structure	Shelter	Shelter #5	Good	New roof
Akron Falls Park	Structure	Shelter	Shelter #7	Good	
Akron Falls Park	Structure	Shelter	Shelter #8	Good	

PARK NAME	FEATURE TYPE	FEATURE SUBCATEGORY	FEATURE NAME	CONDITION	COMMENT
Akron Falls Park	Trail	Trailhead	Akron Falls trailhead	Good	
Akron Falls Park	Trail	Trailhead	Murder Creek Trail	Good	crushed gravel trail No signage
Akron Falls Park	Trail	Trailhead	Trailhead	Good	stone walking trail entrance
Akron Falls Park	Trail	Trailhead	Trailhead	Fair	needs signage here?
Bennett Beach	Infrastructure	Bridge	Bridge PK-19	Good	BIN 3370320
Boston Forest	Trail	Road	Old road to pond, not maintained	Poor	
Boston Forest	Trail	Signage	Beginning of snowmobile trail	Fair	
Boston Forest	Trail	Signage	Snowmobile trail sign	Good	
Boston Forest	Trail	Trailhead	Parking	Fair	Pot holes, plowed in winter
Chestnut Ridge Park	Infrastructure	Bridge	Bridge PK-12	Good	Old Stone bridge, BIN 3362260, NYSDOT Inspecting
Chestnut Ridge Park	Infrastructure	Bridge	Bridge PK-13	Good	BIN 3362270
Chestnut Ridge Park	Infrastructure	Bridge	Bridge PK-14	Good	BIN 3362281
Chestnut Ridge Park	Infrastructure	Bridge	Bridge PK-16	Good	BIN 3362290
Chestnut Ridge Park	Infrastructure	Bridge	Pedestrian bridge	Repair	Footbridge damaged by fallen tree
Chestnut Ridge Park	Infrastructure	Culvert	Culvert	Good	
Chestnut Ridge Park	Infrastructure	Culvert	Culvert	Fair	
Chestnut Ridge Park	Infrastructure	Culvert	Culvert	Fair	Old stone culvert
Chestnut Ridge Park	Infrastructure	Culvert	Culvert PK-21	Good	Stone wall and culvert
Chestnut Ridge Park	Infrastructure	Culvert	Culvert PK-22	Fair	Old stone wall and culvert
Chestnut Ridge Park	Infrastructure	Culvert	Culvert PK-23	Good	
Chestnut Ridge Park	Infrastructure	Culvert	Culvert PK-24	Fair	Not ADA compliant. Improve entry
Chestnut Ridge Park	Infrastructure	Culvert	Culvert PK-26	Fair	Old stone culvert
Chestnut Ridge Park	Infrastructure	Other Amenity	100 Stone steps	Poor	Old stone staircase, in need of extensive repairs to be safe
Chestnut Ridge Park	Infrastructure	Other Amenity	Beehives	Good	Beehive structures
Chestnut Ridge Park	Infrastructure	Other Amenity	Drinking fountain	Good	Old stone drinking fountain and seat wall
Chestnut Ridge Park	Infrastructure	Other Amenity	Fence	Fair	Fence is broken and falling apart in several areas
Chestnut Ridge Park	Infrastructure	Other Amenity	Gate	Good	
Chestnut Ridge Park	Infrastructure	Other Amenity	Gate	Good	



PARK NAME	FEATURE TYPE	FEATURE SUBCATEGORY	FEATURE NAME	CONDITION	COMMENT
Chestnut Ridge Park	Infrastructure	Other Amenity	Gate	Good	
Chestnut Ridge Park	Infrastructure	Other Amenity	Gate	Good	
Chestnut Ridge Park	Infrastructure	Other Amenity	Gate	Good	
Chestnut Ridge Park	Infrastructure	Other Amenity	Gate	Good	
Chestnut Ridge Park	Infrastructure	Other Amenity	Gate	Good	
Chestnut Ridge Park	Infrastructure	Other Amenity	Gate	Good	
Chestnut Ridge Park	Infrastructure	Other Amenity	Gate	Good	
Chestnut Ridge Park	Infrastructure	Other Amenity	Gateway	Good	Gateway pillars
Chestnut Ridge Park	Infrastructure	Other Amenity	Guardrail	Poor	Old stone guardrail
Chestnut Ridge Park	Infrastructure	Other Amenity	Guardrail	Good	Guardrail
Chestnut Ridge Park	Infrastructure	Other Amenity	Stone Retaining Wall	Good	Old stone retaining wall
Chestnut Ridge Park	Infrastructure	Other Amenity	Wall	Good	Old stone wall
Chestnut Ridge Park	Infrastructure	Other Amenity	Wall	Fair	Old Stone wall
Chestnut Ridge Park	Infrastructure	Other Amenity	Water Pump #31	Poor	manual well pump, no structure
Chestnut Ridge Park	Infrastructure	Other Amenity	Water Pump #60	Fair	Old pump, no structure
Chestnut Ridge Park	Infrastructure	Parking	Parking Lot 1	Good	
Chestnut Ridge Park	Infrastructure	Parking	Parking Lot 10	Good	
Chestnut Ridge Park	Infrastructure	Parking	Parking Lot 11	Good	
Chestnut Ridge Park	Infrastructure	Parking	Parking Lot 12	Good	crushed gravel surface
Chestnut Ridge Park	Infrastructure	Parking	Parking Lot 13	Fair	crushed gravel surface. May need to be restoned
Chestnut Ridge Park	Infrastructure	Parking	Parking Lot 2	Fair	crushed gravel surface
Chestnut Ridge Park	Infrastructure	Parking	Parking Lot 3	Fair	Fishing pier parking
Chestnut Ridge Park	Infrastructure	Parking	Parking Lot 4	Good	Accessible parking
Chestnut Ridge Park	Infrastructure	Parking	Parking Lot 5	Good	Gravel parking lot
Chestnut Ridge Park	Infrastructure	Parking	Parking Lot 6	Good	
Chestnut Ridge Park	Infrastructure	Parking	Parking Lot 7	Good	
Chestnut Ridge Park	Infrastructure	Parking	Parking Lot 8	Fair	crushed gravel surface, trailhead lot
Chestnut Ridge Park	Infrastructure	Parking	Parking Lot 9	Fair	parking along either side of park drive
Chestnut Ridge Park	Infrastructure	Road	Road F	Poor	Gravel access path needs resurfacing
Chestnut Ridge Park	Infrastructure	Signage	Commissioners Cabin Sign	Fair	James N Leary Commissioners Cabin sign
Chestnut Ridge Park	Infrastructure	Signage	Orientation sign	Good	Park signage

PARK NAME	FEATURE TYPE	FEATURE SUBCATEGORY	FEATURE NAME	CONDITION	COMMENT
Chestnut Ridge Park	Infrastructure	Signage	Orienteering trail	Good	Orienteering trail head sign
Chestnut Ridge Park	Infrastructure	Signage	Scenic byway sign	Good	Scenic byway signage
Chestnut Ridge Park	Recreation	Athletic Field	Baseball	Fair	field
Chestnut Ridge Park	Recreation	Athletic Field	Old Softball Backstop	Poor	Remove
Chestnut Ridge Park	Recreation	Athletic Field	Softball backstop	Poor	old backstop remains, no infield, suggest removal
Chestnut Ridge Park	Recreation	Court Sport	Tennis	Good	8 courts
Chestnut Ridge Park	Recreation	Court Sport	Tennis	Good	4 courts
Chestnut Ridge Park	Recreation	Disc Golf	Disk Golf Start	Good	Disk golf trailhead
Chestnut Ridge Park	Recreation	Other Amenity	Eternal Flame	Good	
Chestnut Ridge Park	Recreation	Other Amenity	Grill #1	Poor	Old brick structure
Chestnut Ridge Park	Recreation	Other Amenity	Grill #2	Fair	Grill station
Chestnut Ridge Park	Recreation	Other Amenity	Grill #3	Poor	Old stone grill
Chestnut Ridge Park	Recreation	Other Amenity	Grill #4	Poor	Old stone grill
Chestnut Ridge Park	Recreation	Other Amenity	Hamilton Ward Memorial	Good	plaque replaced 2017
Chestnut Ridge Park	Recreation	Other Amenity	Seating wall and garden	Good	Seating wall and garden
Chestnut Ridge Park	Recreation	Other Amenity	Stone Bench	Fair	Old stone bench, restore?
Chestnut Ridge Park	Recreation	Other Amenity	Toboggan chutes	Fair	Toboggan structures: only one operational. Repair or repurpose other?
Chestnut Ridge Park	Recreation	Other Amenity	Waterfall	Good	Nice small natural waterfall area
Chestnut Ridge Park	Recreation	Other Amenity	Waterfall	NA	Waterfall
Chestnut Ridge Park	Recreation	Other Amenity	Workers Memorial	Good	Workers Memorial
Chestnut Ridge Park	Recreation	Playground	Dinosaur slide	Good	Dinosaur slide
Chestnut Ridge Park	Recreation	Playground	Hunter James Kelly Playground	Good	play structure, swings
Chestnut Ridge Park	Recreation	Playground	Jungle Gym	Poor	no fall surface, equipment damaged, should be removed
Chestnut Ridge Park	Recreation	Playground	Old Glider	Poor	no fall surface, suggest removal
Chestnut Ridge Park	Recreation	Playground	Old Glider	Poor	no fall surface, suggest removal
Chestnut Ridge Park	Recreation	Playground	Old Jungle Gym	Poor	no fall surface, suggest removal
Chestnut Ridge Park	Recreation	Playground	Old Jungle gym	Poor	no fall surface, equipment damaged, suggest removal





PARK NAME	FEATURE TYPE	FEATURE SUBCATEGORY	FEATURE NAME	CONDITION	COMMENT
Chestnut Ridge Park	Recreation	Playground	Old Jungle Gym	Fair	recently painted, no fall surface, footings exposed, suggest removal
Chestnut Ridge Park	Recreation	Playground	Old play equipment	Poor	Old slide, see saw, and swingset, no swings, remove equipment
Chestnut Ridge Park	Recreation	Playground	Old Slide	Poor	no fall surface, suggest remove
Chestnut Ridge Park	Recreation	Playground	Old Slide	Fair	no fall surface, suggest removal
Chestnut Ridge Park	Recreation	Playground	Old Slide	Poor	no fall surface, suggest removal
Chestnut Ridge Park	Recreation	Playground	Old Slide	Poor	no fall surface, suggest removal
Chestnut Ridge Park	Recreation	Playground	Old Slide	Poor	no fall surface, suggest removal
Chestnut Ridge Park	Recreation	Playground	Old Slide	Poor	no fall surface, equipment damaged, suggest removal
Chestnut Ridge Park	Recreation	Playground	Old Slide	Poor	no fall surface, suggest removal
Chestnut Ridge Park	Recreation	Playground	Old Slide	Poor	no fall surface, suggest removal
Chestnut Ridge Park	Recreation	Playground	Old Swing	Poor	just swing frame, suggest removal
Chestnut Ridge Park	Recreation	Playground	Old Swing	Poor	frame only, suggest removal
Chestnut Ridge Park	Recreation	Playground	Old Swing	Poor	frame only, suggest removal
Chestnut Ridge Park	Recreation	Playground	Old Swings	Poor	no fall surface present, suggest removal
Chestnut Ridge Park	Recreation	Playground	Old Swings	Poor	Old swingset, missing swing. Suggest Removal
Chestnut Ridge Park	Recreation	Playground	Old Swings	Poor	no fall surface, missing swings, suggest removal
Chestnut Ridge Park	Recreation	Playground	Playground A	Good	slide and swings, fall surface needs replenish
Chestnut Ridge Park	Recreation	Playground	Playground B	Good	Play Structure
Chestnut Ridge Park	Recreation	Playground	Playground C	Good	slide, swings and climber
Chestnut Ridge Park	Recreation	Playground	Playground D	Good	climber, slide and swings
Chestnut Ridge Park	Recreation	Playground	Playground E	Good	slide, swings and climber
Chestnut Ridge Park	Recreation	Playground	Playground F	Good	play structure and swings
Chestnut Ridge Park	Recreation	Playground	Playground G	Good	play structure, swings, missing seats
Chestnut Ridge Park	Recreation	Playground	Playground H	Fair	Needs fall surface
Chestnut Ridge Park	Recreation	Playground	Playground I	Fair	play structure and swings, need fall surface
Chestnut Ridge Park	Recreation	Playground	Playground J	Fair	slide, swings and climber, needs fall surface
Chestnut Ridge Park	Recreation	Playground	Shoe Slide	Good	legacy play equipment
Chestnut Ridge Park	Recreation	Playground	Swings	Good	Swingset

PARK NAME	FEATURE TYPE	FEATURE SUBCATEGORY	FEATURE NAME	CONDITION	COMMENT
Chestnut Ridge Park	Recreation	Waterfront	Fishing deck	Good	Fishing Pier
Chestnut Ridge Park	Structure	Building	Barn	Fair	Old barn
Chestnut Ridge Park	Structure	Building	Casino	Good	
Chestnut Ridge Park	Structure	Building	Commissioners Cabin	Good	
Chestnut Ridge Park	Structure	Building	Garage	Good	
Chestnut Ridge Park	Structure	Building	MacKinnon Lodge	Good	
Chestnut Ridge Park	Structure	Building	Maintenance shops and parks offices	NA	Not assessed
Chestnut Ridge Park	Structure	Building	Martin Lodge	Good	
Chestnut Ridge Park	Structure	Building	Observation Tower	Fair	Stone shelter. Winter use?
Chestnut Ridge Park	Structure	Building	Stone shed	Good	Old stone shed
Chestnut Ridge Park	Structure	Building	Warming Cabin	Fair	Cabin potential?
Chestnut Ridge Park	Structure	Building	Warming shelter	Good	
Chestnut Ridge Park	Structure	Comfort Station	"Y" Comfort Station	Fair	Former concession stand now restroom
Chestnut Ridge Park	Structure	Comfort Station	Comfort Station #1	Fair	
Chestnut Ridge Park	Structure	Comfort Station	Comfort Station #10	Good	
Chestnut Ridge Park	Structure	Comfort Station	Comfort Station #11	Good	
Chestnut Ridge Park	Structure	Comfort Station	Comfort Station #12	Fair	Broken windows
Chestnut Ridge Park	Structure	Comfort Station	Comfort Station #13	Good	Broken window
Chestnut Ridge Park	Structure	Comfort Station	Comfort Station #2	Fair	CMU construction
Chestnut Ridge Park	Structure	Comfort Station	Comfort Station #3	Repair	Restored 2017
Chestnut Ridge Park	Structure	Comfort Station	Comfort Station #4	Good	
Chestnut Ridge Park	Structure	Comfort Station	Comfort Station #5	Good	
Chestnut Ridge Park	Structure	Comfort Station	Comfort Station #6	Good	
Chestnut Ridge Park	Structure	Comfort Station	Comfort Station #7	Good	
Chestnut Ridge Park	Structure	Comfort Station	Comfort Station #9	Fair	
Chestnut Ridge Park	Structure	Comfort Station	Old Comfort Station "F"	Poor	Inside is gutted. Exterior is damaged in areas. Remove?
Chestnut Ridge Park	Structure	Comfort Station	Old Comfort Station "L"	Poor	Restroom is boarded off and decommissioned. Remove?
Chestnut Ridge Park	Structure	Historic Structure	Incinerator	Fair	WPA Era
Chestnut Ridge Park	Structure	Other	Fire training	NA	Training station
Chestnut Ridge Park	Structure	Other Amenity	Pump shelter #14	Good	Old pump shelter
Chestnut Ridge Park	Structure	Other Amenity	Pump shelter #16	Good	Old pump shelter
Chestnut Ridge Park	Structure	Other Amenity	Pump shelter #17	Good	Old pump shelter
Chestnut Ridge Park	Structure	Other Amenity	Pump shelter #20	Good	Old pump shelter



PARK NAME	FEATURE TYPE	FEATURE SUBCATEGORY	FEATURE NAME	CONDITION	COMMENT
Chestnut Ridge Park	Structure	Other Amenity	Pump shelter #22	Poor	Old pump shelter
Chestnut Ridge Park	Structure	Other Amenity	Pump shelter #23	Good	Old pump shelter
Chestnut Ridge Park	Structure	Other Amenity	Pump shelter #37	Fair	Old pump shelter
Chestnut Ridge Park	Structure	Other Amenity	Pump shelter #44	Fair	Old pump shelter
Chestnut Ridge Park	Structure	Other Amenity	Pump shelter #51	Fair	Old pump shelter
Chestnut Ridge Park	Structure	Other Amenity	Pump shelter #53	Good	Old pump shelter
Chestnut Ridge Park	Structure	Other Amenity	Pump shelter #55	Fair	Old pump shelter
Chestnut Ridge Park	Structure	Other Amenity	Pump shelter #56	Fair	Old pump shelter
Chestnut Ridge Park	Structure	Other Amenity	Pump shelter #58	Fair	Old pump shelter
Chestnut Ridge Park	Structure	Other Amenity	Pump shelter #59	Good	Old pump shelter
Chestnut Ridge Park	Structure	Other Amenity	Pump shelter #62	Fair	Old pump shelter
Chestnut Ridge Park	Structure	Other Amenity	Pump shelter #64	Fair	Old pump shelter
Chestnut Ridge Park	Structure	Other Amenity	Pump shelter #65	Fair	Old pump shelter
Chestnut Ridge Park	Structure	Other Amenity	Pump shelter #70	Poor	Old pump shelter
Chestnut Ridge Park	Structure	Other Amenity	Pump shelter #71	Good	Old pump shelter
Chestnut Ridge Park	Structure	Other Amenity	Pump shelter #72	Fair	Old pump shelter
Chestnut Ridge Park	Structure	Other Amenity	Pump shelter #73	Fair	Old pump shelter
Chestnut Ridge Park	Structure	Other Amenity	Pump shelter #74	Fair	Old pump shelter
Chestnut Ridge Park	Structure	Other Amenity	Stone shed	Poor	Old stone structure, no roof or door
Chestnut Ridge Park	Structure	Shelter	Shelter #1	Good	
Chestnut Ridge Park	Structure	Shelter	Shelter #10	Good	
Chestnut Ridge Park	Structure	Shelter	Shelter #108	Good	
Chestnut Ridge Park	Structure	Shelter	Shelter #109	Good	
Chestnut Ridge Park	Structure	Shelter	Shelter #11	Good	
Chestnut Ridge Park	Structure	Shelter	Shelter #110	Good	
Chestnut Ridge Park	Structure	Shelter	Shelter #111	Fair	
Chestnut Ridge Park	Structure	Shelter	Shelter #117	Fair	
Chestnut Ridge Park	Structure	Shelter	Shelter #11A	Poor	
Chestnut Ridge Park	Structure	Shelter	Shelter #12	Fair	
Chestnut Ridge Park	Structure	Shelter	Shelter #13	Fair	
Chestnut Ridge Park	Structure	Shelter	Shelter #14	Fair	Moss growing on roof
Chestnut Ridge Park	Structure	Shelter	Shelter #15	Good	
Chestnut Ridge Park	Structure	Shelter	Shelter #18	Good	New shelter
Chestnut Ridge Park	Structure	Shelter	Shelter #19A	Fair	
Chestnut Ridge Park	Structure	Shelter	Shelter #1A	Fair	
Chestnut Ridge Park	Structure	Shelter	Shelter #2	Good	
Chestnut Ridge Park	Structure	Shelter	Shelter #20	Good	
Chestnut Ridge Park	Structure	Shelter	Shelter #21	Good	

PARK NAME	FEATURE TYPE	FEATURE SUBCATEGORY	FEATURE NAME	CONDITION	COMMENT
Chestnut Ridge Park	Structure	Shelter	Shelter #23	Good	Reconstructed 2017
Chestnut Ridge Park	Structure	Shelter	Shelter #24	Fair	
Chestnut Ridge Park	Structure	Shelter	Shelter #25	Good	
Chestnut Ridge Park	Structure	Shelter	Shelter #27	Good	
Chestnut Ridge Park	Structure	Shelter	Shelter #27A	Good	
Chestnut Ridge Park	Structure	Shelter	Shelter #28A	Good	
Chestnut Ridge Park	Structure	Shelter	Shelter #29	Good	
Chestnut Ridge Park	Structure	Shelter	Shelter #29A	Good	
Chestnut Ridge Park	Structure	Shelter	Shelter #3	Good	
Chestnut Ridge Park	Structure	Shelter	Shelter #30	Good	
Chestnut Ridge Park	Structure	Shelter	Shelter #30A	Good	Grilling shelter
Chestnut Ridge Park	Structure	Shelter	Shelter #31	Good	
Chestnut Ridge Park	Structure	Shelter	Shelter #33A	Fair	New roof needed soon
Chestnut Ridge Park	Structure	Shelter	Shelter #37	Fair	
Chestnut Ridge Park	Structure	Shelter	Shelter #37A	Good	
Chestnut Ridge Park	Structure	Shelter	Shelter #38	Good	
Chestnut Ridge Park	Structure	Shelter	Shelter #4	Good	
Chestnut Ridge Park	Structure	Shelter	Shelter #5	Good	
Chestnut Ridge Park	Structure	Shelter	Shelter #6	Good	
Chestnut Ridge Park	Structure	Shelter	Shelter #6A	Fair	Octagon shelter
Chestnut Ridge Park	Structure	Shelter	Shelter #7	Fair	Paint chipping
Chestnut Ridge Park	Structure	Shelter	Shelter #7A	Good	
Chestnut Ridge Park	Structure	Shelter	Shelter #8	Good	New construction 2017
Chestnut Ridge Park	Structure	Shelter	Shelter #9	Good	
Chestnut Ridge Park	Structure	Shelter	Shelter #9A	Good	
Chestnut Ridge Park	Trail	Trailhead	Eternal Flame Trail	Fair	Signage: no trail maps at kiosk
Como Lake Park	Infrastructure	Bridge	Bridge PK-5 "Pardee"	Fair	BIN 3362140 ADA accessibility? Steep ramp
Como Lake Park	Infrastructure	Bridge	Bridge PK-8 "Middle"	Fair	BIN 3362180 ADA accessibility? Approach is undermined
Como Lake Park	Infrastructure	Bridge	Bridge PK-9 "Shelter 20"	Good	BIN 3362190
Como Lake Park	Infrastructure	Bridge	Foot Bridge	Poor	Small foot bridge. Needs updating
Como Lake Park	Infrastructure	Bridge	Foot Bridge	Fair	Small bridge
Como Lake Park	Infrastructure	Bridge	Former bridge abutment	Fair	
Como Lake Park	Infrastructure	Bridge	Pedestrian bridge	Fair	Footbridge. ADA accessibility?
Como Lake Park	Infrastructure	Bridge	Pedestrian bridge	Fair	No railings



PARK NAME	FEATURE TYPE	FEATURE SUBCATEGORY	FEATURE NAME	CONDITION	COMMENT
Como Lake Park	Infrastructure	Culvert	Culvert	Good	
Como Lake Park	Infrastructure	Culvert	Culvert	Fair	Needs a clean out
Como Lake Park	Infrastructure	Culvert	Culvert	Good	Culvert and new drainage swale
Como Lake Park	Infrastructure	Culvert	Culvert	Good	
Como Lake Park	Infrastructure	Culvert	Culvert	Good	
Como Lake Park	Infrastructure	Culvert	Culvert	Fair	Clean out needed
Como Lake Park	Infrastructure	Culvert	Culvert	Good	
Como Lake Park	Infrastructure	Culvert	Culvert	Fair	Old Stone culvert
Como Lake Park	Infrastructure	Other Amenity	Old Stone Steps	Fair	Old Stone staircase: damage to steps
Como Lake Park	Infrastructure	Other Amenity	Old Stone Steps	Fair	Old Stone staircase: damage to steps
Como Lake Park	Infrastructure	Other Amenity	Stone columns	Good	
Como Lake Park	Infrastructure	Other Amenity	Stone steps	Poor	Old Stone staircase
Como Lake Park	Infrastructure	Parking	Parking - Shelter 50	Good	New pavement
Como Lake Park	Infrastructure	Parking	Parking Lot 1	Good	
Como Lake Park	Infrastructure	Parking	Parking Lot 2	Fair	
Como Lake Park	Infrastructure	Parking	Parking Lot 3	Good	
Como Lake Park	Infrastructure	Parking	Parking Lot 4	Good	
Como Lake Park	Infrastructure	Parking	Parking Lot 5	Good	
Como Lake Park	Infrastructure	Parking	Parking Lot 6	Fair	
Como Lake Park	Infrastructure	Parking	Parking Lot 7	Fair	
Como Lake Park	Infrastructure	Parking	Parking Lot 8	Fair	
Como Lake Park	Infrastructure	Road	Maintenance access road	Good	Maintenance access road
Como Lake Park	Infrastructure	Signage	Gateway sign	Good	
Como Lake Park	Infrastructure	Signage	Gateway sign	Good	
Como Lake Park	Infrastructure	Signage	Gateway sign	Good	Williams street entrance
Como Lake Park	Infrastructure	Signage	Gateway signage	Good	Gateway to park
Como Lake Park	Infrastructure	Signage	Lancaster Place sign	Fair	Repair top part
Como Lake Park	Recreation	Athletic Field	Baseball	Poor	not used
Como Lake Park	Recreation	Athletic Field	Baseball/softball	Fair	
Como Lake Park	Recreation	Athletic Field	Soccer	Good	
Como Lake Park	Recreation	Athletic Field	Softball	Good	
Como Lake Park	Recreation	Court Sport	Basketball	Good	2 courts
Como Lake Park	Recreation	Court Sport	Tennis	Good	4 courts
Como Lake Park	Recreation	Disc Golf	Disk golf start	Good	start and map



PARK NAME	FEATURE TYPE	FEATURE SUBCATEGORY	FEATURE NAME	CONDITION	COMMENT
Como Lake Park	Recreation	Other Amenity	Ice skating	Good	
Como Lake Park	Recreation	Other Amenity	Overlook	Fair	Dam/Lake overlook and stairs
Como Lake Park	Recreation	Other Amenity	Sledding Hill	Good	New fence
Como Lake Park	Recreation	Playground	Outdoor Fitness System	Good	installed 2017
Como Lake Park	Recreation	Playground	Playground A	Good	Climber, swings and slide
Como Lake Park	Recreation	Playground	Playground B	Good	Climber, slides, swings
Como Lake Park	Recreation	Playground	Playground C	Good	play structure, swings
Como Lake Park	Recreation	Playground	Playground D	Fair	Slide, swings and climber
Como Lake Park	Recreation	Playground	Playground E	Good	play structure, swings
Como Lake Park	Recreation	Playground	Playground F	Good	play structure, swings
Como Lake Park	Recreation	Playground	Playground G	Good	Clibers, slide and swings
Como Lake Park	Recreation	Playground	Slide	Good	Slide
Como Lake Park	Recreation	Playground	Slide and swing	Fair	Need to replace swings
Como Lake Park	Recreation	Playground	Slide and swing	Fair	New mulch at swings needed
Como Lake Park	Recreation	Trailhead	Cayuga Creek Nature Trail	Good	
Como Lake Park	Structure	Building	Former Boat House	Fair	Railing on left side is real loose
Como Lake Park	Structure	Building	Jimmy D Casino	Good	Some concrete damage on south side of building
Como Lake Park	Structure	Building	Lancaster Place	Good	restroom and lodge
Como Lake Park	Structure	Building	Park office and maintenance	NA	Old barns need repairs
Como Lake Park	Structure	Building	Storage building	Poor	wood frame with vinyl siding
Como Lake Park	Structure	Comfort Station	Comfort Station A	Good	
Como Lake Park	Structure	Comfort Station	Comfort Station B	Good	
Como Lake Park	Structure	Comfort Station	Comfort Station C	Good	
Como Lake Park	Structure	Comfort Station	Comfort Station D	Good	restroom
Como Lake Park	Structure	Comfort Station	Comfort Station E	Good	Restroom labeled E
Como Lake Park	Structure	Historic Structure	Lighthouse	Fair	
Como Lake Park	Structure	Other	Former Sheriff Substation	Poor	Remove old concrete foundation or repurpose?
Como Lake Park	Structure	Shelter	Bowen Rd Grove	Good	Shelter and comfort station
Como Lake Park	Structure	Shelter	Cooking shelter	Good	
Como Lake Park	Structure	Shelter	Rich Marino Gazebo	Good	



PARK NAME	FEATURE TYPE	FEATURE SUBCATEGORY	FEATURE NAME	CONDITION	COMMENT
Como Lake Park	Structure	Shelter	Seniors Shelter	Poor	Roof repair needed Not rented
Como Lake Park	Structure	Shelter	Shelter #1	Fair	Support pillars need new paint
Como Lake Park	Structure	Shelter	Shelter #10	Fair	Roof is warping and wood/paint is chipping
Como Lake Park	Structure	Shelter	Shelter #11	Good	Some damage to roof and stone pillars
Como Lake Park	Structure	Shelter	Shelter #13	Good	
Como Lake Park	Structure	Shelter	Shelter #14	Good	
Como Lake Park	Structure	Shelter	Shelter #15	Good	Gable ends and roof repairs required
Como Lake Park	Structure	Shelter	Shelter #16	Good	
Como Lake Park	Structure	Shelter	Shelter #17	Good	Tree next to shelter should be taken down.
Como Lake Park	Structure	Shelter	Shelter #18	Good	
Como Lake Park	Structure	Shelter	Shelter #19	Good	
Como Lake Park	Structure	Shelter	Shelter #2	Good	
Como Lake Park	Structure	Shelter	Shelter #20	Fair	Minor repairs needed
Como Lake Park	Structure	Shelter	Shelter #21	Fair	Roofing improvements needed
Como Lake Park	Structure	Shelter	Shelter #22	Fair	Roof improvements needed
Como Lake Park	Structure	Shelter	Shelter #23	Good	
Como Lake Park	Structure	Shelter	Shelter #24	Good	Minor repairs needed
Como Lake Park	Structure	Shelter	Shelter #26	Good	
Como Lake Park	Structure	Shelter	Shelter #3	Good	
Como Lake Park	Structure	Shelter	Shelter #31	Good	
Como Lake Park	Structure	Shelter	Shelter #32	Good	
Como Lake Park	Structure	Shelter	Shelter #33	Good	
Como Lake Park	Structure	Shelter	Shelter #37	Good	Roof improvements needed
Como Lake Park	Structure	Shelter	Shelter #39	Fair	
Como Lake Park	Structure	Shelter	Shelter #4	Fair	Roof repair needed
Como Lake Park	Structure	Shelter	Shelter #40	Fair	Roof is warping
Como Lake Park	Structure	Shelter	Shelter #41	Good	
Como Lake Park	Structure	Shelter	Shelter #43	Good	
Como Lake Park	Structure	Shelter	Shelter #47	Fair	Structure seems to be leaning.
Como Lake Park	Structure	Shelter	Shelter #49	Good	
Como Lake Park	Structure	Shelter	Shelter #5 Boy Scouts Shelter	Fair	Outdated picnic tables. Roof repair needed
Como Lake Park	Structure	Shelter	Shelter #50	Good	
Como Lake Park	Structure	Shelter	Shelter #51	Good	
Como Lake Park	Structure	Shelter	Shelter #52	Good	

PARK NAME	FEATURE TYPE	FEATURE SUBCATEGORY	FEATURE NAME	CONDITION	COMMENT
Como Lake Park	Structure	Shelter	Shelter #53	Good	
Como Lake Park	Structure	Shelter	Shelter #54	Poor	Roofing and foundation repairs needed
Como Lake Park	Structure	Shelter	Shelter #55	Fair	
Como Lake Park	Structure	Shelter	Shelter #56	Good	
Como Lake Park	Structure	Shelter	Shelter #57	Fair	Roof repairs needed, no picnic tables?
Como Lake Park	Structure	Shelter	Shelter #58	Good	
Como Lake Park	Structure	Shelter	Shelter #59	Good	
Como Lake Park	Structure	Shelter	Shelter #7	Fair	Some pillars are leaning
Como Lake Park	Structure	Shelter	Shelter #8	Fair	Needs roof repairs
Como Lake Park	Structure	Shelter	Shelter #9	Good	
Como Lake Park	Structure	Shelter	Shelter 29	Good	New shelter
Como Lake Park			Former concession stand	NA	Concession Stand: Removed
Como Lake Park			Former shelter	NA	Shelter removed
Como Lake Park			Former Shelter #12	NA	Shelter has been removed
County Forest #11	Recreation	Other	Pond	NA	a lot of animal tracks
County Forest #11	Trail	Other	Wetland	NA	
County Forest #13	Recreation	Other	Pond	NA	Ponds on forest lot
County Forest #2	Infrastructure	Other	Overhead electric service	NA	Electric line
County Forest #2	Infrastructure	Signage		Fair	Sign at parking area
County Forest #2	Recreation	Other Amenity	Bench	Good	Bench
County Forest #2	Recreation	Signage		Fair	Tree species sign
County Forest #2	Structure	Bridge	Pedestrian bridge	Fair	Footbridge
County Forest #2	Structure	Bridge	Pedestrian bridge	Fair	Foot bridges
County Forest #2	Structure	Bridge	Pedestrian bridge	Fair	Foot bridge
County Forest #2	Structure	Bridge	Pedestrian bridge	Fair	Foot bridge
County Forest #2	Structure	Bridge	Pedestrian bridge	Fair	Foot bridge steep incline, all ice at moment
County Forest #2	Structure	Bridge	Pedestrian bridge	Fair	Footbridge
County Forest #2	Structure	Bridge	Pedestrian bridge	Fair	Bridge
County Forest #2	Structure	Bridge	Pedestrian bridge	Fair	Bridge and hut
County Forest #2	Structure	Other	Old foundation	NA	Cement foundation
County Forest #2	Structure	Other	Outhouse	Fair	Outhouse
County Forest #2	Structure	Other Amenity	Fireplace	Fair	Stone fireplace
County Forest #2	Trail	Other	Horse trail	Fair	Horse trail, big road running through property



PARK NAME	FEATURE TYPE	FEATURE SUBCATEGORY	FEATURE NAME	CONDITION	COMMENT
County Forest #2	Trail	Other		Fair	Trails cross
County Forest #2	Trail	Signage		Fair	Trail symbol
County Forest #3	Structure	Building	Park Office	NA	Main building
County Forest #3	Structure	Building	Warming shelter	Good	with wood stove and picnic tables
County Forest #3	Structure	Culvert	Culvert	Fair	New culvert
County Forest #3	Structure	Culvert	Culvert	Fair	Older culvert
County Forest #3	Structure	Other Amenity	Outhouse	Fair	
County Forest #4	Recreation	Other	Pond	NA	
County Forest #4	Trail	Other	Gas line	NA	transects property
County Forest #4	Trail	Other	Snowmobile trail	NA	goes west through property
County Forest #4	Trail	Trailhead	Snowmobile trail	Fair	grapevines in tree canopies
County Forest #5	Structure	Bridge	Metal deck bridge	Good	
County Forest #5	Structure	Other	Deerstand	Fair	
County Forest #5	Trail	Parking	Parking/turn around area rest of road is single lane	Fair	
County Forest #6	Structure	Other	Deer stand	Good	
County Forest #6	Structure	Other	Deer stand clearing in front	Good	
County Forest #6	Trail	Other	Creek	Fair	Honeysuckle, grape vines and multiflora rose along bank
County Forest #6	Trail	Other		NA	Trail for possible source of deer stands goes to house on east side of property
County Forest #6	Trail	Signage	Posted sign	Good	plus additional deer stand
County Forest #7	Trail	Signage	Trail marker	NA	Trail doesn't appear maintained
County Forest #8	Recreation	Other		NA	Hawk nest- active
County Forest #8	Trail	Other	Spruce plantation	Fair	From road side
County Forest #8	Trail	Other	Trailhead	NA	Snowmobile trail along boundary
County Forest #8	Trail	Other		Fair	Hemlock along drainage areas
County Forest #9	Trail	Other		NA	Unstable ground in ravine along waterway
County Forest #9	Trail	Other		NA	Grapevines
County Forest #9	Trail	Other		Poor	
County Forest #9	Trail	Other			Grapevines and dead standing trees
County Forest #9	Trail	Other			Steep bank to river
County Forest #9	Trail	Other			Hemlock along ravine

PARK NAME	FEATURE TYPE	FEATURE SUBCATEGORY	FEATURE NAME	CONDITION	COMMENT
County Forest #9	Trail	Road		NA	Old forest logging road used by snowmobilers
Ellicott Creek Park	Infrastructure	Bridge	Bridge PK-4	Fair	BIN 3362120 ADA acceptable?
Ellicott Creek Park	Infrastructure	Bridge	Bridge PK-6	Good	BIN 3362150
Ellicott Creek Park	Infrastructure	Bridge	Bridge PK-7	Poor	BIN 3362160 Railings are not structurally stable, decking loose
Ellicott Creek Park	Infrastructure	Other Amenity	Drinking Fountain	Poor	
Ellicott Creek Park	Infrastructure	Other Amenity	Gateway	Fair	Old stone gateway entrance
Ellicott Creek Park	Infrastructure	Other Amenity	Old fountain	Fair	
Ellicott Creek Park	Infrastructure	Other Amenity	Old Stone Steps	Good	
Ellicott Creek Park	Infrastructure	Other Amenity	Old Stone Steps	Poor	
Ellicott Creek Park	Infrastructure	Other Amenity	Old water fountain	Good	
Ellicott Creek Park	Infrastructure	Other Amenity	Stone column	Good	
Ellicott Creek Park	Infrastructure	Other Amenity	Stone column	Fair	
Ellicott Creek Park	Infrastructure	Other Amenity	Stone column	Fair	
Ellicott Creek Park	Infrastructure	Parking	Parking Lot 1	Fair	
Ellicott Creek Park	Infrastructure	Parking	Parking Lot 10	Good	
Ellicott Creek Park	Infrastructure	Parking	Parking Lot 11	Good	
Ellicott Creek Park	Infrastructure	Parking	Parking Lot 12	Poor	Extensive pot holes. Should be paved based on use?
Ellicott Creek Park	Infrastructure	Parking	Parking Lot 13	Good	
Ellicott Creek Park	Infrastructure	Parking	Parking Lot 14	Good	
Ellicott Creek Park	Infrastructure	Parking	Parking Lot 15	Fair	crushed gravel surface
Ellicott Creek Park	Infrastructure	Parking	Parking Lot 16	Fair	crushed gravel surface
Ellicott Creek Park	Infrastructure	Parking	Parking Lot 17	Good	asphalt paved parking lot
Ellicott Creek Park	Infrastructure	Parking	Parking Lot 2	Fair	
Ellicott Creek Park	Infrastructure	Parking	Parking Lot 3	Fair	
Ellicott Creek Park	Infrastructure	Parking	Parking Lot 4	Fair	
Ellicott Creek Park	Infrastructure	Parking	Parking Lot 5	Fair	crushed gravel surface
Ellicott Creek Park	Infrastructure	Parking	Parking Lot 6	Fair	
Ellicott Creek Park	Infrastructure	Parking	Parking Lot 7	Fair	Drainage issues
Ellicott Creek Park	Infrastructure	Parking	Parking Lot 8	Fair	
Ellicott Creek Park	Infrastructure	Parking	Parking Lot 9	Good	
Ellicott Creek Park	Infrastructure	Signage	Bark Park signage	Good	Ellicott Creek Bark Park: Signage
Ellicott Creek Park	Infrastructure	Signage	Gateway sign	Good	Park entrance sign
Ellicott Creek Park	Infrastructure	Signage	Gateway sign	Good	Park entrance sign
Ellicott Creek Park	Infrastructure	Signage	Gateway sign	Good	Park Sign
Ellicott Creek Park	Infrastructure	Signage	Gateway sign	Good	Park entry sign





PARK NAME	FEATURE TYPE	FEATURE SUBCATEGORY	FEATURE NAME	CONDITION	COMMENT
Ellicott Creek Park	Infrastructure	Signage	Park sign and rules	Good	
Ellicott Creek Park	Recreation	Athletic Field	Baseball	Poor	Diamond: Remove backstop
Ellicott Creek Park	Recreation	Athletic Field	Soccer	Good	
Ellicott Creek Park	Recreation	Athletic Field	Soccer	Good	
Ellicott Creek Park	Recreation	Court Sport	Tennis and Pickelball	Good	4 courts
Ellicott Creek Park	Recreation	Disc Golf	Disc golf start	Good	Map
Ellicott Creek Park	Recreation	Other Amenity	Fire pit	Fair	Old fire pit?
Ellicott Creek Park	Recreation	Other Amenity	Garden	Fair	
Ellicott Creek Park	Recreation	Other Amenity	Garden circle	Fair	
Ellicott Creek Park	Recreation	Other Amenity	Grill #1	Poor	possible WPA era Stone BBQ grill, potential to restore
Ellicott Creek Park	Recreation	Other Amenity	Grill #2	Fair	Old brick grill
Ellicott Creek Park	Recreation	Other Amenity	Picnic Table	Fair	
Ellicott Creek Park	Recreation	Other Amenity	Picnic Table	Good	
Ellicott Creek Park	Recreation	Other Amenity	Picnic Table	Good	
Ellicott Creek Park	Recreation	Other Amenity	Stage	Poor	Repair or remove stage structure
Ellicott Creek Park	Recreation	Other Amenity	Tree Art Installation	Good	
Ellicott Creek Park	Recreation	Other Amenity	Water fountain	Poor	
Ellicott Creek Park	Recreation	Other Amenity	Water fountain	Good	
Ellicott Creek Park	Recreation	Playground	Dinosaur slide and swings	Poor	No fall surface, missing swing
Ellicott Creek Park	Recreation	Playground	Dinosaur slide and swings	Good	
Ellicott Creek Park	Recreation	Playground	Lifetrail Advanced Wellness System	Good	
Ellicott Creek Park	Recreation	Playground	Old swing	Poor	No fall surface, suggest removal
Ellicott Creek Park	Recreation	Playground	Playground A	Good	Pplay Structure
Ellicott Creek Park	Recreation	Playground	Playground B	Good	Play Structure
Ellicott Creek Park	Recreation	Playground	Playground C	Fair	Play structure
Ellicott Creek Park	Recreation	Playground	Playground D	Good	Play structure
Ellicott Creek Park	Recreation	Playground	Playground E	Fair	Missing swings. Needs new mulch. Define play surface
Ellicott Creek Park	Recreation	Playground	Playground F	Poor	Play Structure. Drainage issues. Relocate?
Ellicott Creek Park	Recreation	Playground	Playground G	Fair	Slide, swings and climber
Ellicott Creek Park	Recreation	Playground	Playground H	Good	Slide, swings and climber

PARK NAME	FEATURE TYPE	FEATURE SUBCATEGORY	FEATURE NAME	CONDITION	COMMENT
Ellicott Creek Park	Recreation	Playground	Wheelbarrow	Fair	Legacy piece of playground equipment
Ellicott Creek Park	Recreation	Waterfront	Kayak launch	Good	Floating kayak launch
Ellicott Creek Park	Recreation	Waterfront	Old boat launch	Repair	Old area. Potential to restore?
Ellicott Creek Park	Structure	Building	Boat house	Fair	Ruins: Art murals have helped make the structure more inviting
Ellicott Creek Park	Structure	Building	Friendship Center	Fair	Friendship Center
Ellicott Creek Park	Structure	Building	Jimmy D Casino	Fair	
Ellicott Creek Park	Structure	Building	Park office and maintenance	NA	
Ellicott Creek Park	Structure	Building	Superintendents Residence	NA	not reviewed
Ellicott Creek Park	Structure	Comfort Station	Comfort Station #1	Good	
Ellicott Creek Park	Structure	Comfort Station	Comfort Station #2	Good	
Ellicott Creek Park	Structure	Comfort Station	Comfort Station #3	Fair	
Ellicott Creek Park	Structure	Comfort Station	Comfort Station #4 "Signature"	Good	
Ellicott Creek Park	Structure	Comfort Station	Comfort Station #5 "Fishermans"	Good	
Ellicott Creek Park	Structure	Comfort Station	Creekside Stand	Good	roof on men's side under repair?
Ellicott Creek Park	Structure	Comfort Station	Island Comfort Station	Fair	
Ellicott Creek Park	Structure	Other Amenity	Pump shelter #1	Fair	roof repair
Ellicott Creek Park	Structure	Other Amenity	Pump shelter #2	Fair	Roof being replaced 2017
Ellicott Creek Park	Structure	Shelter	Shelter #10A	Good	
Ellicott Creek Park	Structure	Shelter	Shelter #10B	Good	
Ellicott Creek Park	Structure	Shelter	Shelter #11	Good	
Ellicott Creek Park	Structure	Shelter	Shelter #14	Good	
Ellicott Creek Park	Structure	Shelter	Shelter #15	Good	
Ellicott Creek Park	Structure	Shelter	Shelter #16	Good	
Ellicott Creek Park	Structure	Shelter	Shelter #17	Good	
Ellicott Creek Park	Structure	Shelter	Shelter #19	Fair	
Ellicott Creek Park	Structure	Shelter	Shelter #2	Good	
Ellicott Creek Park	Structure	Shelter	Shelter #20	Good	
Ellicott Creek Park	Structure	Shelter	Shelter #24	Fair	New benches at shelter
Ellicott Creek Park	Structure	Shelter	Shelter #25	Fair	Repair roof and concrete base
Ellicott Creek Park	Structure	Shelter	Shelter #26	Fair	Inner beams may need more support



PARK NAME	FEATURE TYPE	FEATURE SUBCATEGORY	FEATURE NAME	CONDITION	COMMENT
Ellicott Creek Park	Structure	Shelter	Shelter #27	Good	
Ellicott Creek Park	Structure	Shelter	Shelter #28	Poor	Extensive repairs needed
Ellicott Creek Park	Structure	Shelter	Shelter #3	Fair	Paint chipping
Ellicott Creek Park	Structure	Shelter	Shelter #30	Good	
Ellicott Creek Park	Structure	Shelter	Shelter #31	Fair	Foundation Improvements
Ellicott Creek Park	Structure	Shelter	Shelter #32	Fair	
Ellicott Creek Park	Structure	Shelter	Shelter #33	Poor	Shelter #33: Foundation issues
Ellicott Creek Park	Structure	Shelter	Shelter #34	Fair	Roof repair
Ellicott Creek Park	Structure	Shelter	Shelter #35	Fair	
Ellicott Creek Park	Structure	Shelter	Shelter #4	Good	Some roof damage
Ellicott Creek Park	Structure	Shelter	Shelter #5	Good	
Ellicott Creek Park	Structure	Shelter	Shelter #6	Good	
Ellicott Creek Park	Structure	Shelter	Shelter #7	Fair	
Ellicott Creek Park	Structure	Shelter	Shelter #8	Fair	Roof damage
Ellicott Creek Park	Structure	Shelter	Shelter #9	Good	
Ellicott Creek Park	Structure	Waterfront	Deck	Fair	Patio deck and overlook
Ellicott Creek Park			Former playground	Poor	Playground removed; repair and resurface area
Ellicott Creek Park			Former Shelter #18	NA	has been removed, summer 2017
Elma Meadows	Structure	Comfort Station	Comfort Station A	Fair	
Elma Meadows	Structure	Shelter	Shelter 1	Fair	
Elma Meadows	Structure	Shelter	Shelter 2	Fair	
Elma Meadows	Structure	Shelter	Shelter 3	Fair	
Elma Meadows	Structure	Shelter	Shelter 4	Fair	
Elma Meadows	Structure	Shelter	Shelter 5	Fair	
Elma Meadows	Structure	Shelter	Shelter 6	Fair	
Emery Park	Infrastructure	Bridge	Pedestrian bridge	Fair	Footbridge near waterfall. ADA accessibility
Emery Park	Infrastructure	Bridge	Pedestrian bridge	Fair	Foot bridge
Emery Park	Infrastructure	Bridge	Stone bridge	Poor	stone footbridge and staircase
Emery Park	Infrastructure	Culvert	Culvert	Fair	and guardrail. Guardrail needed on other side?
Emery Park	Infrastructure	Culvert	Culvert	Poor	Old stone culvert
Emery Park	Infrastructure	Culvert	Culvert	Poor	Old stone culvert
Emery Park	Infrastructure	Culvert	Culvert	Good	concrete headwalls
Emery Park	Infrastructure	Culvert	Culvert	Good	
Emery Park	Infrastructure	Culvert	Culvert	Fair	Old stone culvert
Emery Park	Infrastructure	Culvert	Culvert	Fair	Old stone culvert

PARK NAME	FEATURE TYPE	FEATURE SUBCATEGORY	FEATURE NAME	CONDITION	COMMENT
Emery Park	Infrastructure	Culvert	Culvert	Good	
Emery Park	Infrastructure	Culvert	Culvert	Good	Old stone culvert
Emery Park	Infrastructure	Culvert	Culvert	NA	Culvert appears to have been demolished
Emery Park	Infrastructure	Culvert	Culvert	Fair	Old stone culvert
Emery Park	Infrastructure	Culvert	Culvert	Poor	Old stone culvert
Emery Park	Infrastructure	Culvert	Culvert	Fair	Old stone culvert
Emery Park	Infrastructure	Culvert	Culvert	Fair	Old stone culvert
Emery Park	Infrastructure	Culvert	Culvert	Fair	Old stone culvert
Emery Park	Infrastructure	Culvert	Culvert	Fair	Old stone culvert
Emery Park	Infrastructure	Culvert	Culvert	Fair	Old stone culvert
Emery Park	Infrastructure	Culvert	Culvert	Good	Old stone culvert
Emery Park	Infrastructure	Culvert	Culvert	Good	Old stone culvert
Emery Park	Infrastructure	Culvert	Culvert	Poor	Old stone culvert
Emery Park	Infrastructure	Culvert	Culvert PK-20	Good	
Emery Park	Infrastructure	Culvert	Culvert PK-25	Good	
Emery Park	Infrastructure	Other Amenity	Fence	Poor	Wire fence needs repair.
Emery Park	Infrastructure	Other Amenity	Gate	Good	
Emery Park	Infrastructure	Other Amenity	Gate	Good	Gate and fence
Emery Park	Infrastructure	Other Amenity	Gate	Good	
Emery Park	Infrastructure	Other Amenity	Gate	Fair	Gate access to Creek.
Emery Park	Infrastructure	Other Amenity	Guardrail	Poor	Replace missing guardrail
Emery Park	Infrastructure	Other Amenity	Guardrail	Poor	Guardrails need updating.
Emery Park	Infrastructure	Other Amenity	Legacy 11 Plaque	Good	
Emery Park	Infrastructure	Other Amenity	Plaque	Fair	
Emery Park	Infrastructure	Other Amenity	Stone columns	Good	
Emery Park	Infrastructure	Other Amenity	Stone columns	Good	
Emery Park	Infrastructure	Other Amenity	Stone steps	Fair	Old stone staircase and railing
Emery Park	Infrastructure	Other Amenity	Stone steps	Poor	Old stone staircase to waterfall. Stairs need repair.
Emery Park	Infrastructure	Other Amenity	Wall	Good	Stone retaining wall and steps
Emery Park	Infrastructure	Other Amenity	Wall	Fair	Old stone retaining wall
Emery Park	Infrastructure	Parking	Parking Lot 1	Good	Striping?
Emery Park	Infrastructure	Parking	Parking Lot 2	Fair	
Emery Park	Infrastructure	Parking	Parking Lot 3	Fair	not well defined, just large intersection of park roads
Emery Park	Infrastructure	Parking	Parking Lot 4	Good	Striping needed
Emery Park	Infrastructure	Parking	Parking Lot 5	Fair	
Emery Park	Infrastructure	Parking	Parking Lot 6	Good	



PARK NAME	FEATURE TYPE	FEATURE SUBCATEGORY	FEATURE NAME	CONDITION	COMMENT
Emery Park	Infrastructure	Signage	Gateway Sign	Fair	Sign falling down.
Emery Park	Infrastructure	Signage	Gateway sign	Good	Park sign
Emery Park	Infrastructure	Signage	Gateway sign	Good	Park sign
Emery Park	Infrastructure	Signage	Historic Plaque	Fair	
Emery Park	Infrastructure	Signage	Park map	Good	
Emery Park	Infrastructure	Signage	Park map	Good	
Emery Park	Recreation	Athletic Field	Backstop	Poor	Baseball/softball backstop
Emery Park	Recreation	Athletic Field	Baseball	Good	Ballfield
Emery Park	Recreation	Court Sport	Shuffleboard	Fair	
Emery Park	Recreation	Court Sport	Tennis	Fair	6 courts
Emery Park	Recreation	Disc Golf	Disc golf	Good	Disk golf map
Emery Park	Recreation	Other Amenity	Fire pit	Fair	Old stone fire pit
Emery Park	Recreation	Other Amenity	Fire Pit	Poor	
Emery Park	Recreation	Other Amenity	Rock Garden	Poor	Historic gathering area. Large downed trees need to be removed.
Emery Park	Recreation	Other Amenity	Skiing hill	Fair	Lower ski lift. Operational?
Emery Park	Recreation	Other Amenity	Skiing hill	Good	Lower hill 2
Emery Park	Recreation	Other Amenity	Skiing hill	Good	Lower hill 3
Emery Park	Recreation	Other Amenity	Skiing hill	Good	top of hill 1
Emery Park	Recreation	Other Amenity	Skiing hill	Good	top of hill 2
Emery Park	Recreation	Other Amenity	Skiing hill	Good	top of hill 3. More difficult
Emery Park	Recreation	Other Amenity	Skiing hill	NA	Lower hill 1
Emery Park	Recreation	Other Amenity	Stage	Good	raised platform with stone wall. Stage area
Emery Park	Recreation	Other Amenity	Waterfall	NA	Nice natural waterfall
Emery Park	Recreation	Other Amenity	Waterfall	NA	Secluded waterfall
Emery Park	Recreation	Playground	Old See-saw	Poor	equipment damaged, remove
Emery Park	Recreation	Playground	Old Slide	Poor	no fall surface, equipment damaged, suggest removal
Emery Park	Recreation	Playground	Old Slide	Poor	no fall surface, suggest removal
Emery Park	Recreation	Playground	Old Swing	Poor	Frame only, suggest removal
Emery Park	Recreation	Playground	Old Swing	Poor	In woods, no fall surface, suggest removal.
Emery Park	Recreation	Playground	Old Swing	Poor	no fall surface, suggest removal
Emery Park	Recreation	Playground	Old Swing	Poor	No fall surface, suggest removal
Emery Park	Recreation	Playground	Old Swing	Poor	no fall surface, equipment damaged, suggest removal



PARK NAME	FEATURE TYPE	FEATURE SUBCATEGORY	FEATURE NAME	CONDITION	COMMENT
Emery Park	Recreation	Playground	Old Swing	Poor	no fall surface, suggest removal
Emery Park	Recreation	Playground	Old Swing	Poor	no fall surface, suggest removal
Emery Park	Recreation	Playground	Old Swing	Poor	no fall surface, suggest removal
Emery Park	Recreation	Playground	Old Swing	Poor	no fall surface, in woods, suggest removal
Emery Park	Recreation	Playground	Old Swing	Poor	no fall surface, suggest removal
Emery Park	Recreation	Playground	Old Swing	Poor	no fall surface, suggest removal
Emery Park	Recreation	Playground	Old Swing	Poor	no fall surface, suggest removal
Emery Park	Recreation	Playground	Playground A	Good	play structure, swings. New mulch needed.
Emery Park	Recreation	Playground	Playground B	Good	Slide, swings, climber
Emery Park	Recreation	Playground	Playground C	Good	slide, swings and climber
Emery Park	Recreation	Playground	Playground D	Good	swings, slide and climber
Emery Park	Recreation	Playground	Playground E	Good	play structure
Emery Park	Recreation	Playground	Playground F	Good	slide, swings, climber
Emery Park	Recreation	Playground	Playground G	Good	slide, swing, climber
Emery Park	Structure	Building	Fieldhouse	Good	
Emery Park	Structure	Building	Observation Tower	Good	
Emery Park	Structure	Building	Park Office	NA	several buildings: parks office
Emery Park	Structure	Building	Richardson Cottage	Good	New roof, restrooms
Emery Park	Structure	Building	Ski Lodge	Good	
Emery Park	Structure	Building	Stohrer's Lodge	Good	
Emery Park	Structure	Comfort Station	Comfort Station #1 "Million Dollar"	Good	Restroom
Emery Park	Structure	Comfort Station	Comfort Station #2	Good	Restrooms
Emery Park	Structure	Comfort Station	Comfort Station #4	Good	Restroom
Emery Park	Structure	Comfort Station	Comfort Station #4	Fair	
Emery Park	Structure	Comfort Station	Comfort Station #5	Good	Ramps ADA?
Emery Park	Structure	Comfort Station	Round Comfort Station	Poor	Unique circle structure. Broken windows. Graffiti
Emery Park	Structure	Historic Structure	Incinerator	Poor	WPA Era 1936
Emery Park	Structure	Historic Structure	Incinerator	Poor	WPA Era
Emery Park	Structure	Historic Structure	Incinerator	Poor	WPA Era
Emery Park	Structure	Historic Structure	Quoit Beds	Poor	Row of 5 small structures with stone columns. Roof damage.
Emery Park	Structure	Other Amenity	Arbor and garden	Fair	



PARK NAME	FEATURE TYPE	FEATURE SUBCATEGORY	FEATURE NAME	CONDITION	COMMENT
Emery Park	Structure	Other Amenity	Pump shelter #1	Fair	pump structure
Emery Park	Structure	Other Amenity	Pump shelter #10	Poor	Old pump
Emery Park	Structure	Other Amenity	Pump shelter #11	Fair	leaning
Emery Park	Structure	Other Amenity	Pump shelter #12	Good	
Emery Park	Structure	Other Amenity	Pump shelter #13	Fair	
Emery Park	Structure	Other Amenity	Pump shelter #14	Poor	Old pump, shelter not present
Emery Park	Structure	Other Amenity	Pump shelter #15	Good	
Emery Park	Structure	Other Amenity	Pump shelter #16	Fair	
Emery Park	Structure	Other Amenity	Pump shelter #17	Fair	
Emery Park	Structure	Other Amenity	Pump shelter #18	Poor	Pump structure: Hole in roof
Emery Park	Structure	Other Amenity	Pump shelter #19	Poor	Old pump shelter
Emery Park	Structure	Other Amenity	Pump shelter #2	Poor	
Emery Park	Structure	Other Amenity	Pump shelter #20	Fair	
Emery Park	Structure	Other Amenity	Pump shelter #21	Fair	Pump removed, bench on pad
Emery Park	Structure	Other Amenity	Pump shelter #3	Poor	Old water pump
Emery Park	Structure	Other Amenity	Pump shelter #4	Fair	Former pump structure
Emery Park	Structure	Other Amenity	Pump shelter #5	Fair	pump structure
Emery Park	Structure	Other Amenity	Pump shelter #6	Poor	pump structure
Emery Park	Structure	Other Amenity	Pump shelter #7	Poor	Old pump
Emery Park	Structure	Other Amenity	Pump shelter #8	Good	
Emery Park	Structure	Other Amenity	Pump shelter #9	Poor	
Emery Park	Structure	Shelter	Amphitheater Shelter	Good	No number. Some minor roof damage
Emery Park	Structure	Shelter	Elizabeth Grove Cottage	Good	
Emery Park	Structure	Shelter	Gazebo	Good	
Emery Park	Structure	Shelter	Pergola	Fair	Stone walls with arbor structure roof. Stone staircase leading to it.
Emery Park	Structure	Shelter	Richardson Shelter	Good	shelter next to cottage
Emery Park	Structure	Shelter	Shelter #1	Good	Also known as Loretta Shelter
Emery Park	Structure	Shelter	Shelter #10	Good	
Emery Park	Structure	Shelter	Shelter #100X	Good	number from 1984 mapping
Emery Park	Structure	Shelter	Shelter #102X	NA	Number from 1984 map. Shelter has been removed.
Emery Park	Structure	Shelter	Shelter #103X	Good	Number from 1984 map. Small stone wall structure with one table

PARK NAME	FEATURE TYPE	FEATURE SUBCATEGORY	FEATURE NAME	CONDITION	COMMENT
Emery Park	Structure	Shelter	Shelter #105X	Poor	Number from 1984 map. Stonework is crumbling. Roof is falling apart
Emery Park	Structure	Shelter	Shelter #108X	Good	Number from 1984 map. Fireplace on stone endwall.
Emery Park	Structure	Shelter	Shelter #108X	Fair	Asphalt floor failing
Emery Park	Structure	Shelter	Shelter #109X	Poor	Number from 1984 map. No floor
Emery Park	Structure	Shelter	Shelter #11	Fair	
Emery Park	Structure	Shelter	Shelter #113X	Fair	Number from 1984 map. Roof needs repairs
Emery Park	Structure	Shelter	Shelter #116X	Fair	Number from 1984 map
Emery Park	Structure	Shelter	Shelter #117X	Poor	Recommend demolition
Emery Park	Structure	Shelter	Shelter #11B	Good	
Emery Park	Structure	Shelter	Shelter #12	Good	
Emery Park	Structure	Shelter	Shelter #13	Poor	Recommend demolition
Emery Park	Structure	Shelter	Shelter #15	Good	
Emery Park	Structure	Shelter	Shelter #16	Good	
Emery Park	Structure	Shelter	Shelter #17	Good	
Emery Park	Structure	Shelter	Shelter #2	Good	
Emery Park	Structure	Shelter	Shelter #20	Good	Number from 1984 map
Emery Park	Structure	Shelter	Shelter #20	Fair	Needs roof repair
Emery Park	Structure	Shelter	Shelter #21	Fair	Shelter #21: Stone is breaking apart. Missing wood panels
Emery Park	Structure	Shelter	Shelter #22	Good	Shelter #22?
Emery Park	Structure	Shelter	Shelter #24	Poor	Recommend demolition
Emery Park	Structure	Shelter	Shelter #3	Good	
Emery Park	Structure	Shelter	Shelter #5	Good	No number. Remove dead tree next to shelter.
Emery Park	Structure	Shelter	Shelter #6	Good	
Emery Park	Structure	Shelter	Shelter #7	Fair	Roof overgrown with moss on one side.
Emery Park	Structure	Shelter	Shelter #8	Good	Some structural damage to stone pillar
Emery Park	Structure	Shelter	Shelter #9	Fair	sustained recent roof damage. Remove fallen tree.
Emery Park	Structure	Shelter	Small bench & shelter	Good	Small stone shelter



PARK NAME	FEATURE TYPE	FEATURE SUBCATEGORY	FEATURE NAME	CONDITION	COMMENT
Emery Park	Trail	Trailhead	Elizabeth Grove Trail	Good	
Emery Park	Trail	Trailhead	Elizabeth Grove Trail	Good	
Emery Park	Trail	Trailhead	Orienteering course	Good	
Emery Park	Trail	Trailhead	Potential Trailhead	NA	Potential trailhead
Emery Park			Former Comfort Station	NA	demolished
Emery Park			Former Shelter	NA	Old concrete pad for shelter
Emery Park			Former Shelter #14	NA	14 - DEMOLISHED: Foundation and tables remain
Isle View	Infrastructure	Other	Boat Ramp	Good	
Isle View	Infrastructure	Other	Concrete revetment	Poor	appears to be undermined
Isle View	Infrastructure	Other	Old boat ramp	NA	Not sure of utilization, no access for trailers, is it used for car top craft?
Isle View	Infrastructure	Parking	Parking Lot 1	Fair	Asphalt surface
Isle View	Infrastructure	Parking	Parking Lot 2	Fair	
Isle View	Infrastructure	Parking	Parking Lot 3	Fair	
Isle View	Infrastructure	Parking	Parking Lot 4	Fair	
Isle View	Infrastructure	Parking	Parking Lot 5	Good	
Isle View	Infrastructure	Parking	Parking Lot 6	Good	
Isle View	Infrastructure	Parking	Parking Lot 7	Fair	
Isle View	Recreation	Playground	Playground A	Fair	Fall surface needs replenishment
Isle View	Recreation	Playground	Swings	Fair	Fall surface needs replenishment
Isle View	Structure	Building	Maintenance Garage	NA	Rubble stone construction
Isle View	Structure	Building	Overlook Gazebo	Fair	
Isle View	Structure	Building	Riverdogs Concession Stand	NA	
Isle View	Structure	Comfort Station	Comfort Station A	Fair	Gutters and fascia need repair. Roof nearing useful life
Isle View	Structure	Comfort Station	Comfort Station B	Fair	Rubble stone construction
Isle View	Structure	Shelter	Gazebo	Good	
Sprague Brook Park	Infrastructure	Bridge	Bridge PK-17	Good	BIN 3367360
Sprague Brook Park	Infrastructure	Other Amenity	Dump Station	Good	
Sprague Brook Park	Infrastructure	Other Amenity	Gate	Good	
Sprague Brook Park	Infrastructure	Other Amenity	Gate	Good	

PARK NAME	FEATURE TYPE	FEATURE SUBCATEGORY	FEATURE NAME	CONDITION	COMMENT
Sprague Brook Park	Infrastructure	Other Amenity	Gate	Good	
Sprague Brook Park	Infrastructure	Parking	Parking Lot 1	Fair	
Sprague Brook Park	Infrastructure	Parking	Parking Lot 2	Fair	
Sprague Brook Park	Infrastructure	Parking	Parking Lot 3	Fair	
Sprague Brook Park	Infrastructure	Parking	Parking Lot 4	Fair	
Sprague Brook Park	Infrastructure	Parking	Parking Lot 5	Fair	
Sprague Brook Park	Infrastructure	Parking	Parking Lot 6	Good	
Sprague Brook Park	Infrastructure	Parking	Parking Lot 7	Fair	
Sprague Brook Park	Infrastructure	Parking	Parking Lot 8	Fair	
Sprague Brook Park	Infrastructure	Parking	Parking Lot 9	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 1	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 10	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 100	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 101	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 102	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 103	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 104	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 105	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 106	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 107	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 108	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 11	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 110	Good	
Sprague Brook Park	Recreation	Other Amenity	camp site 111	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 112	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 114	Good	
Sprague Brook Park	Recreation	Other Amenity	camp site 115	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 116	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 118	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 12	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 120	Good	
Sprague Brook Park	Recreation	Other Amenity	camp site 121	Good	
Sprague Brook Park	Recreation	Other Amenity	camp site 122	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 13	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 14	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 15	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 16	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 17	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 18	Good	



PARK NAME	FEATURE TYPE	FEATURE SUBCATEGORY	FEATURE NAME	CONDITION	COMMENT
Sprague Brook Park	Recreation	Other Amenity	Camp site 19	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 2	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 20	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 21	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 22	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 23	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 24	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 25	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 26	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 27	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 28	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 29	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 3	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 30	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 31	Good	
Sprague Brook Park	Recreation	Other Amenity	camp site 33	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 34	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 35	Good	
Sprague Brook Park	Recreation	Other Amenity	camp site 36	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 37	Good	
Sprague Brook Park	Recreation	Other Amenity	camp site 38	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 39	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 4	Good	
Sprague Brook Park	Recreation	Other Amenity	camp site 40	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 41	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 42	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 43	Good	
Sprague Brook Park	Recreation	Other Amenity	camp site 44	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 45	Good	
Sprague Brook Park	Recreation	Other Amenity	camp site 46	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 47	Good	
Sprague Brook Park	Recreation	Other Amenity	camp site 48	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 49	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 5	Good	
Sprague Brook Park	Recreation	Other Amenity	camp site 50	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 51	Good	
Sprague Brook Park	Recreation	Other Amenity	camp site 52	Good	
Sprague Brook Park	Recreation	Other Amenity	camp site 54	Good	
Sprague Brook Park	Recreation	Other Amenity	Camp site 55	Good	



# WPA INVENTORY AND ASSESSMENT

## 2.0 AKRON FALLS PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON-WPA)	TREATMENT OPTION	MATERIALS	ASA
Building	Warming Shelter	Yes, Maybe Prior	Yes	Preservation	Building Archaeology to Confirm	Yes
Building	Shelter #1	Yes, Maybe Later	Yes	Rehabilitation	Rusticated Stone Columns (Appears Cut), Shingled/3-Tab Roof (Cladding)	Yes
Building	Shelter #2	Yes, Maybe Later	Yes	Rehabilitation	Rusticated Stone Columns (Appears Cut), Shingled/3-Tab Roof (Cladding)	Yes
Building	Valley Comfort Station	Yes, Maybe Later	Yes	Rehabilitation	Rusticated Stone (Appears Cut), Standing Seam Sheet Metal Roof (Cladding)	Yes
Building	Brooklyn Street Comfort Station	Yes, Likely	No	Rehabilitation	Rusticated Stone Veneer/ Construction	Yes
Building	Falls Comfort Station	Yes, Likely	No	Rehabilitation	Rubble Stone Construction, Shingled/3-Tab Roof (Cladding)	Yes
Structure	Grill #1	Yes, Likely	No	Preservation (or Reuse Materials)	Dimensional Stone w/ Dimensional Fire Brick	Yes
Structure	Grill #10	Yes, Likely	No	Preservation (or Reuse Materials)	Rubble Stone w/ Dimensional Fire Brick	Yes
Structure	Grill #11	Yes, Likely	No	Preservation (or Reuse Materials)	Rubble Stone Construction w/ Dimensional Fire Brick	Yes
Structure	Grill #12	Yes, Likely	No	Preservation (or Reuse Materials)	Rubble Stone Construction w/ Dimensional Fire Brick	Yes
Structure	Grill #13	Yes, Likely	No	Preservation (or Reuse Materials)	Rubble Stone Construction w/ Dimensional Fire Brick	Yes
Structure	Grill #14	Yes, Likely	No	Preservation (or Reuse Materials)	Rubble Stone Construction w/ Dimensional Fire Brick	Yes

### KEY:

**“Preservation”** – Preservation is defined as the act or process of applying measures necessary to sustain the existing form, integrity, and materials of an historic property.

**“Rehabilitation”** – Rehabilitation is defined as the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features which convey its historical, cultural, or architectural values.

**“Restoration”** – Restoration is defined as the act or process of accurately depicting the form, features, and character of a property as it appeared at a particular period of time by means of the removal of features from other periods in its history and reconstruction of missing features from the restoration period.

**“Buildings”** – created principally to shelter any form of human activity.

**“Structures”** – functional constructions made usually for purposes other than creating human shelter.

**WPA Status** - Generally accepted as the time period in which the WPA was undertaking projects across the United States

**Historic Non-WPA** - Historically or architecturally significant building or structure that may have been constructed outside of the timeline for the WPA

**Materials** - Predominant existing materials of the building or structure

**ASA** - Archaeological Sensitive Area (NYS Designated)



## AKRON FALLS PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON-WPA)	TREATMENT OPTION	MATERIALS	ASA
Structure	Grill #15	Yes, Likely	No	Preservation (or Reuse Materials)	Rubble Stone Construction w/ Dimensional Fire Brick	Yes
Structure	Grill #16	Yes, Likely	No	Preservation (or Reuse Materials)	Rubble Stone Construction w/ Dimensional Fire Brick	Yes
Structure	Grill #17	Yes, Likely	No	Rehabilitation	Rubble Stone Construction w/ Dimensional Fire Brick	Yes
Structure	Grill #18	Yes, Likely	No	Preservation (or Reuse Materials)	Rubble Stone Construction w/ Dimensional Fire Brick	Yes
Structure	Grill #19	Yes, Likely	No	Preservation (or Reuse Materials)	Rubble Stone Construction w/ Dimensional Fire Brick	Yes
Structure	Grill #20	Yes, Likely	No	Preservation (or Reuse Materials)	Rubble Stone Construction w/ Dimensional Fire Brick	Yes
Structure	Grill #21	Yes, Likely	No	Preservation (or Reuse Materials)	Dimensional Stone w/ Dimensional Fire Brick	Yes
Structure	Grill #22	Yes, Likely	No	Preservation (or Reuse Materials)	Rubble Stone Construction w/ Dimensional Fire Brick	Yes
Structure	Grill #23	Yes, Likely	No	Preservation (or Reuse Materials)	Rubble Stone Construction w/ Dimensional Fire Brick	Yes
Structure	Grill #24	Yes, Likely	No	Preservation (or Reuse Materials)	Rubble Stone Construction w/ Dimensional Fire Brick	Yes
Structure	Grill #25	Yes, Likely	No	Preservation (or Reuse Materials)	Rubble Stone Construction w/ Dimensional Fire Brick	Yes
Structure	Grill #26	Yes, Likely	No	Preservation (or Reuse Materials)	Rubble Stone Construction w/ Dimensional Fire Brick/CMU block	Yes
Structure	Grill #27	Yes, Likely	No	Preservation (or Reuse Materials)	Rubble Stone Construction w/ Dimensional Fire Brick	Yes
Structure	Grill #28	Yes, Likely	No	Preservation (or Reuse Materials)	Rubble Stone Construction w/ Dimensional Fire Brick	Yes
Structure	Grill #29	Yes, Likely	No	Preservation (or Reuse Materials)	Rubble Stone Construction w/ Dimensional Fire Brick	Yes
Structure	Grill #3	Yes, Likely	No	Preservation (or Reuse Materials)	Rubble Stone Construction w/ Dimensional Fire Brick	Yes
Structure	Grill #30	Yes, Likely	No	Preservation (or Reuse Materials)	Rubble Stone Construction w/ Dimensional Fire Brick	Yes
Structure	Grill #31	Yes, Likely	No	Preservation (or Reuse Materials)	Rubble Stone Construction w/ Dimensional Fire Brick	Yes
Structure	Grill #4	Yes, Likely	No	Preservation (or Reuse Materials)	Rubble Stone Construction w/ Dimensional Fire Brick	Yes
Structure	Grill #5	Yes, Likely	No	Preservation (or Reuse Materials)	Rubble Stone Construction w/ Dimensional Fire Brick	Yes
Structure	Grill #6	Yes, Likely	No	Preservation (or Reuse Materials)	Rubble Stone Construction w/ Dimensional Fire Brick	Yes

## AKRON FALLS PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON-WPA)	TREATMENT OPTION	MATERIALS	ASA
Structure	Grill #7	Yes, Likely	No	Preservation (or Reuse Materials)	Rubble Stone Construction w/ Dimensional Fire Brick	Yes
Structure	Grill #8	Yes, Likely	No	Rehabilitation	Rubble Stone Construction w/ Dimensional Fire Brick	Yes
Structure	Grill #9	Yes, Likely	No	Rehabilitation	Rubble Stone Construction w/ Dimensional Fire Brick	Yes
Building	Meadow Comfort Stat.	Yes, Likely	No	Rehabilitation	Rubble Stone, Shingled/3-Tab Roof (Cladding)	Yes
Building	Shelter #10	Yes	No	Rehabilitation	Rubble Stone Columns, Character Defining Feature (Roof) Significantly Altered (Standing Seam Sheet Metal)	Yes
Building	Shelter #11	Yes	No	Rehabilitation	Rubble Stone Columns, Character Defining Feature (Roof) Significantly Altered (Standing Seam Sheet Metal)	Yes
Building	Shelter #13	Yes	No	Rehabilitation	Rubble Stone Columns, Shingled/3-Tab Roof (Cladding)	Yes
Building	Shelter #14	Yes	No	Rehabilitation	Rubble Stone Columns, Character Defining Feature (Roof) Significantly Altered (Standing Seam Sheet Metal)	Yes
Building	Shelter #15	Yes	No	Rehabilitation	Rubble Stone Columns, Character Defining Feature (Roof) Significantly Altered (Standing Seam Sheet Metal)	Yes
Building	Shelter #3	Yes	No	Rehabilitation	Rubble Stone Columns, Shingled/3-Tab Roof (Cladding)	Yes
Building	Shelter #4	Yes	No	Rehabilitation	Rubble Stone columns, Shingled/3-Tab Roof (Cladding)	Yes
Building	Shelter #5	Yes	No	Rehabilitation	Rubble Stone Columns, Character Defining Feature (Roof) Significantly Altered (Standing Seam Sheet Metal)	Yes
Building	Shelter #7	Yes	No	Rehabilitation	Rubble Stone Columns	Yes
Building	Shelter #8	Yes	No	Rehabilitation	Rubble Stone Columns	Yes
Structure	Stone Railings	Yes	No	Rehabilitation	Rubble Stone Columns	Yes
Building	Shelter #12	No	No	N/A	CMU Columns	Yes



## 2.1 CHESTNUT RIDGE PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON-WPA)	TREATMENT OPTION	MATERIALS
Infrastructure	100 Stone Steps	Yes	No	Rehabilitation	Rubble Stone, Concrete
Structure	Barn	Undetermined	Yes	Rehabilitation	English-Style Barn, Sliding Central Doors, Board and Batten Siding
Recreation	Baseball	No	No	N/A	N/A
Structure	Beehives	Yes, Likely	No	Preservation	Rubble Stone
Structure	Bench	Yes, Likely	No	Preservation	Stone
Infrastructure	Bridge	Yes, Likely	No	Rehabilitation	Rubble Stone
Infrastructure	Bridge	Yes, Likely	No	Rehabilitation	Rubble Stone (Partial))
Infrastructure	Bridge	Yes, Likely	No	Rehabilitation	Rubble Stone
Structure	Cabin	Undetermined	No	N/A	Rubble Stone End Chimney, Board and Batten Siding, Gable Roof, 3-Tab Shingles
Structure	Casino	Yes, Likely	No	Rehabilitation	Rubbles Stone, Prominent Rubble Stone Chimney, Veranda, Faux(?) Half-Timbering, Hipped Roof, 3-Tab Shingles, Windows Replaced - Fine Example
Structure	Comfort Station #1	Yes, Likely	No	Rehabilitation	Rubble Stone, Glass Block, Gable Roof, 3-Tab Shingles
Structure	Comfort Station #10	Yes, Likely	No	Rehabilitation	Rubble Stone, Glass Block, Gable Roof, Architectural Shingles
Structure	Comfort Station #11	Yes, Likely	No	Rehabilitation	Rubble Stone, Glass Block, Gable Roof, 3-Tab Shingles

**KEY:**

**“Preservation”** – Preservation is defined as the act or process of applying measures necessary to sustain the existing form, integrity, and materials of an historic property.

**“Rehabilitation”** – Rehabilitation is defined as the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features which convey its historical, cultural, or architectural values.

**“Restoration”** – Restoration is defined as the act or process of accurately depicting the form, features, and character of a property as it appeared at a particular period of time by means of the removal of features from other periods in its history and reconstruction of missing features from the restoration period.

**“Buildings”** – created principally to shelter any form of human activity.

**“Structures”** – functional constructions made usually for purposes other than creating human shelter.

**WPA Status** - Generally accepted as the time period in which the WPA was undertaking projects across the United States

**Historic Non-WPA** - Historically or architecturally significant building or structure that may have been constructed outside of the timeline for the WPA

**Materials** - Predominant existing materials of the building or structure

## CHESTNUT RIDGE PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON-WPA)	TREATMENT OPTION	MATERIALS
Structure	Comfort Station #12	Yes, Likely	No	Rehabilitation	Rubble Stone, Rough Cut Clapboards, Glass Block, Gable Roof, 3-Tab Shingles
Structure	Comfort Station #13	Yes, Likely	No	Rehabilitation	Rubble Stone, Glass Block, Gable Roof, Rough Cut Clapboards, Architectural Shingles
Structure	Comfort Station #2	Yes, Likely	No	Rehabilitation	CMU Block., Glass Block, Hipped Roof, 3-Tab Shingles
Structure	Comfort Station #3	Yes	No	Rehabilitation	Rubble Stone, Glass Block, Hipped Roof, 3-Tab Shingles
Structure	Comfort Station #4	Yes, Likely	No	Rehabilitation	Rubble Stone, Glass Block, Gable Roof, 3-Tab Shingles
Structure	Comfort Station #5	Yes, Likely	No	Rehabilitation	Rubble Stone, Glass Block, Gable Roof, 3-Tab Shingles, Board and Batten Siding
Structure	Comfort Station #6	Yes, Likely	No	Rehabilitation	Rubble Stone, Glass Block, Gable Roof, Classical Eave Returns
Structure	Comfort Station #7	Yes, Likely	No	Rehabilitation	Rubble Stone, Glass Block, Gable Roof, 3-Tab Shingles
Structure	Comfort Station #9	Yes, Likely	No	Rehabilitation	Rubble Stone, Glass Block, Gable Roof, Architectural Shingles
Structure	Comfort Station Old F	Yes, Likely	No	Rehabilitation	Rubble Stone, Glass Block, Pyramidal Roof, 3-Tab Shingles
Structure	Comfort Station Old L	Yes, Likely	No	Rehabilitation	Rubble Stone, Rough Cut Clapboards, Gable Roof, Glass Block
Structure	Comfort Station Old N	Yes, Likely	No	Rehabilitation	Rubble Stone, Rough Cut Clapboards, Cross Gable Roof

**KEY:**

**“Preservation”** – Preservation is defined as the act or process of applying measures necessary to sustain the existing form, integrity, and materials of an historic property.

**“Rehabilitation”** – Rehabilitation is defined as the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features which convey its historical, cultural, or architectural values.

**“Restoration”** – Restoration is defined as the act or process of accurately depicting the form, features, and character of a property as it appeared at a particular period of time by means of the removal of features from other periods in its history and reconstruction of missing features from the restoration period.

**“Buildings”** – created principally to shelter any form of human activity.

**“Structures”** – functional constructions made usually for purposes other than creating human shelter.

**WPA Status** - Generally accepted as the time period in which the WPA was undertaking projects across the United States

**Historic Non-WPA** - Historically or architecturally significant building or structure that may have been constructed outside of the timeline for the WPA

**Materials** - Predominant existing materials of the building or structure



## CHESTNUT RIDGE PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON-WPA)	TREATMENT OPTION	MATERIALS
Structure	Commissioners Cabin	No	No	N/A	N/A
Structure	Commissioners Cabin Sign	No	No	N/A	N/A
Infrastructure	Culvert	Yes, Likely	No	Preservation	Rubble Stone, West Side of Park
Infrastructure	Culvert	No	No	N/A	N/A
Infrastructure	Culvert	No	No	N/A	N/A
Infrastructure	Culvert	No	No	N/A	N/A
Infrastructure	Culvert	No	No	N/A	N/A
Infrastructure	Culvert	Yes, Likely	No	Preservation	Rubble Stone, Concrete, East Side of Park Near Pond
Infrastructure	Culvert	Yes, Likely	No	Preservation	Rubble Stone, East Side of Park Near Ski Trails
Recreation	Dinosaur Slide	No	No	N/A	N/A
Structure	Disk Golf	No	No	N/A	N/A
Structure	Drinking Fountain	Yes	No	Rehabilitation	Rubble Stone
Recreation	Eternal Flame	No	No	N/A	N/A
Trail	Eternal Flame Trail	No	No	N/A	N/A
Structure	Fence	No	No	N/A	N/A
Structure	Fire Training	No	No	N/A	N/A
Recreation	Fishing Deck	No	No	N/A	N/A
Structure	Gate	No	No	N/A	N/A
Structure	Gate	No	No	N/A	N/A
Structure	Gate	No	No	N/A	N/A
Structure	Gate	No	No	N/A	N/A
Structure	Gate	No	No	N/A	N/A
Structure	Gate	No	No	N/A	N/A
Structure	Gate	No	No	N/A	N/A
Structure	Gate	No	No	N/A	N/A
Structure	Gateway	Yes, Likely	No	Preservation	Rubble Stone



## CHESTNUT RIDGE PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON-WPA)	TREATMENT OPTION	MATERIALS
Structure	Grill #1	Yes, Likely	No	Preservation	Red, Clay Fired, Dimensional Brick
Structure	Grill #2	Yes, Likely	No	N/A	Rubble Stone (Partial), Brick Chimney, Gabled Roof, Architectural Shingles, Concrete Columns(?)
Structure	Grill #3	Yes, Likely	No	Preservation	Rubble Stone
Structure	Grill #4	Yes, Likely	No	Preservation	Rubble Stone
Infrastructure	Guardrail	Yes, Likely	No	Preservation	Rubble Stone, West Side of Park
Infrastructure	Guardrail	No	No	N/A	N/A
Structure	Hamilton Ward Memorial	Yes, Likely	No	Preservation	Rubble Stone, Heavy Chain Link/Rope
Recreation	Hunter James Kelly				
Structure	Incinerator	Yes, Likely	No	Preservation	Rubble Stone
Recreation	Jungle Gym	No	No	N/A	N/A
Recreation	Jungle Gym	No	No	N/A	N/A
Recreation	Jungle Gym	No	No	N/A	N/A
Structure	MacKinnon Lodge	No	No	N/A	N/A
Structure	Maintenance Shops and Parks Offices	No	No	N/A	N/A
Structure	Martin Lodge	No	No	N/A	N/A
Structure	Observation Tower	Yes, Likely	No	Rehabilitation	Rubble Stone, 6-Light Windows, Hipped Roof, Shingled/3-Tab Roof (Cladding)
Recreation	Old Shoe	No	Yes	Preservation	Steel
Structure	Orientation Sign	No	No	N/A	N/A

**KEY:**

**“Preservation”** – Preservation is defined as the act or process of applying measures necessary to sustain the existing form, integrity, and materials of an historic property.

**“Rehabilitation”** – Rehabilitation is defined as the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features which convey its historical, cultural, or architectural values.

**“Restoration”** – Restoration is defined as the act or process of accurately depicting the form, features, and character of a property as it appeared at a particular period of time by means of the removal of features from other periods in its history and reconstruction of missing features from the restoration period.

**“Buildings”** – created principally to shelter any form of human activity.

**“Structures”** – functional constructions made usually for purposes other than creating human shelter.

**WPA Status** - Generally accepted as the time period in which the WPA was undertaking projects across the United States

**Historic Non-WPA** - Historically or architecturally significant building or structure that may have been constructed outside of the timeline for the WPA

**Materials** - Predominant existing materials of the building or structure



## CHESTNUT RIDGE PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON-WPA)	TREATMENT OPTION	MATERIALS
Structure	Orienteering Trail	No	No	N/A	N/A
Infrastructure	Parking	No	No	N/A	N/A
Infrastructure	Parking	No	No	N/A	N/A
Infrastructure	Parking	No	No	N/A	N/A
Infrastructure	Parking	No	No	N/A	N/A
Infrastructure	Parking	No	No	N/A	N/A
Infrastructure	Parking	No	No	N/A	N/A
Infrastructure	Parking	No	No	N/A	N/A
Infrastructure	Parking	No	No	N/A	N/A
Infrastructure	Parking	No	No	N/A	N/A
Infrastructure	Parking 1	No	No	N/A	N/A
Infrastructure	Pedestrian Bridge	No	No	N/A	N/A
Infrastructure	Pedestrian Bridge	No	No	N/A	N/A
Recreation	Play Structure	No	No	N/A	N/A
Recreation	Play Structure	No	No	N/A	N/A
Recreation	Play Structure	No	No	N/A	N/A
Recreation	Playground	No	No	N/A	N/A
Recreation	Playground	No	No	N/A	N/A
Recreation	Playground	No	No	N/A	N/A
Recreation	Playground	No	No	N/A	N/A
Recreation	Playground	No	No	N/A	N/A
Structure	Pump Shelter # ???	Yes, Likely	No	Preservation	Rubble Stone, Pyramidal Roof, Architectural Shingles
Structure	Pump Shelter # ???	Yes, Likely	No	Preservation	Rubble Stone, Domed/Rotund Roof
Structure	Pump Shelter #14	Yes, Likely	No	Preservation	Rubble Stone, Pyramidal Roof, Shingled/3-Tab Roof (Cladding)
Structure	Pump Shelter #16	Yes, Likely	No	Preservation	Rubble Stone, Pyramidal Roof, Shingled/3-Tab Roof (Cladding)
Structure	Pump Shelter #17	Yes, Likely	No	Preservation	Rubble Stone, Pyramidal Roof, Shingled/3-Tab Roof (Cladding)
Structure	Pump Shelter #22	Yes, Likely	No	Preservation	Rubble Stone, Pyramidal Roof, No Sheathing, No Cladding
Structure	Pump Shelter #23	Yes, Likely	No	Preservation	Rubble Stone, Pyramidal Roof, Shingled/3-Tab Roof (Cladding)
Infrastructure	Pump Shelter #31	Yes, Likely	No	Preservation	Rubble Stone, Pyramidal Roof, Architectural Shingles

## CHESTNUT RIDGE PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON-WPA)	TREATMENT OPTION	MATERIALS
Structure	Pump Shelter #37	Yes, Likely	No	Preservation	Rubble Stone, No Columns, No Roof
Structure	Pump Shelter #44	Yes, Likely	No	Preservation	Rubble Stone, Gable Roof, Shingled/3-Tab Roof (Cladding)
Structure	Pump Shelter #51	Yes, Likely	No	Preservation	Rubble Stone, Pyramidal Roof, Exposed Rafters
Structure	Pump Shelter #53	Yes, Likely	No	Preservation	Rubble Stone, Gable Roof, Shingled/3-Tab Roof (Cladding)
Structure	Pump Shelter #55	Yes, Likely	No	Preservation	Rubble Stone, Gable Roof, Shingled/3-Tab Roof (Cladding)
Structure	Pump Shelter #56	Yes, Likely	No	Preservation	Rubble Stone, Pyramidal Roof, Semi-Circular Rubble Stone
Structure	Pump Shelter #58	Yes, Likely	No	Preservation	Rubble Stone, Gable Roof, Shingled/3-Tab Roof (Cladding)
Structure	Pump Shelter #59	Yes, Likely	No	Preservation	Rubble Stone, Pyramidal Roof, Architectural Shingles
Structure	Pump Shelter #60	No	No	N/A	N/A
Structure	Pump Shelter #62	Yes, Likely	No	Preservation	Rubble Stone, Pyramidal Roof, Shingled/3-Tab Roof (Cladding)
Structure	Pump Shelter #64	Yes, Likely	No	Preservation	Rubble Stone, Gable Roof, Shingled/3-Tab Roof (Cladding)
Structure	Pump Shelter #65	Yes, Likely	No	Preservation	Rubble Stone, Pyramidal Roof, Shingled/3-Tab Roof (Cladding)
Structure	Pump Shelter #70	Yes, Likely	No	Preservation	Rubble Stone, Pyramidal Roof, Shingled/3-Tab Roof (Cladding)
Structure	Pump Shelter #71	Yes, Likely	No	Preservation	Rubble Stone, Gable Roof, Shingled/3-Tab Roof (Cladding)
Structure	Pump Shelter #72	Yes, Likely	No	Preservation	Rubble Stone, Pyramidal Roof, Shingled/3-Tab Roof (Cladding)
Structure	Pump Shelter #73	Yes, Likely	No	Preservation	Rubble Stone, Gable Roof, Shingled/3-Tab Roof (Cladding)
Infrastructure	Road F	No	No	N/A	N/A
Structure	Scenic Byway Sign	No	No	N/A	N/A

**KEY:**

**"Preservation"** – Preservation is defined as the act or process of applying measures necessary to sustain the existing form, integrity, and materials of an historic property.

**"Rehabilitation"** – Rehabilitation is defined as the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features which convey its historical, cultural, or architectural values.

**"Restoration"** – Restoration is defined as the act or process of accurately depicting the form, features, and character of a property as it appeared at a particular period of time by means of the removal of features from other periods in its history and reconstruction of missing features from the restoration period.

**"Buildings"** – created principally to shelter any form of human activity.

**"Structures"** – functional constructions made usually for purposes other than creating human shelter.

**WPA Status** - Generally accepted as the time period in which the WPA was undertaking projects across the United States

**Historic Non-WPA** - Historically or architecturally significant building or structure that may have been constructed outside of the timeline for the WPA

**Materials** - Predominant existing materials of the building or structure



## CHESTNUT RIDGE PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON-WPA)	TREATMENT OPTION	MATERIALS
Structure	Seating Wall and Garden	No	No	N/A	N/A
Recreation	See-Saw	No	No	N/A	N/A
Structure	Shed	No	No	N/A	N/A
Structure	Shelter #1	No	No	N/A	N/A
Structure	Shelter #10	No	No	N/A	N/A
Structure	Shelter #108	No	No	N/A	N/A
Structure	Shelter #109	No	No	N/A	N/A
Structure	Shelter #11	Yes, Possibly	No	Rehabilitation	CMU Block Columns, Hipped Roof, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #110	No	No	N/A	N/A
Structure	Shelter #111	No	No	N/A	N/A
Structure	Shelter #117	Yes, Possibly	No	Rehabilitation	CMU Block Columns, Gable Roof, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #11A	No	No	N/A	N/A
Structure	Shelter #12	No	No	N/A	N/A
Structure	Shelter #13	Yes, Likely	No	Rehabilitation	Rubble Stone, CMU Block Columns, Board and Batten Siding, Gable Roof, Heavy Timber Construction
Structure	Shelter #14	No	No	N/A	N/A
Structure	Shelter #15	No	No	N/A	N/A
Structure	Shelter #18	No	No	N/A	N/A
Structure	Shelter #19A	Yes, Possibly	No	Rehabilitation	CMU Block Columns, Gable Roof, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #1A	Yes, Possibly	No	Rehabilitation	CMU Block Columns, Gable Roof, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #2	No	No	N/A	N/A
Structure	Shelter #20	Yes, Possibly	No	Rehabilitation	CMU Block Columns, Gable Roof, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #21	No	No	N/A	N/A
Structure	Shelter #23	Yes, Likely	No	Rehabilitation	Rubble Stone, Rubble Stone End Chimney, Gable Roof
Structure	Shelter #24	No	No	N/A	N/A
Structure	Shelter #25	Yes, Likely	No	Rehabilitation	Rubble Stone, Gable Roof, Shingled/3-Tab Roof (Cladding)

## CHESTNUT RIDGE PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON-WPA)	TREATMENT OPTION	MATERIALS
Structure	Shelter #27	Yes, Likely	No	Rehabilitation	Rubble Stone, Rubble Stone End Chimneys, Architectural Shingles
Structure	Shelter #27A	Yes, Possibly	No	Rehabilitation	CMU Block Columns, Gable Roof, Architectural Shingles
Structure	Shelter #28A	Yes, Possibly	No	Rehabilitation	CMU Block Columns, Gable Roof, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #29	No	No	N/A	N/A
Structure	Shelter #29A	Yes, Possibly	No	Rehabilitation	CMU Block Columns, Gable Roof, Architectural Shingles
Structure	Shelter #3	Yes, Possibly	No	Rehabilitation	CMU Block Columns, Gable Roof, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #30	No	No	N/A	N/A
Structure	Shelter #30A	No	No	N/A	N/A
Structure	Shelter #31	Yes, Likely	No	Rehabilitation	Rubble Stone, Rubble Stone End Chimney, Gable Roof, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #33A	Yes, Possibly	No	Rehabilitation	CMU Block Columns, Gable Roof, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #37	Yes, Possibly	No	Rehabilitation	CMU Block Columns, Gable Roof, Architectural Shingles
Structure	Shelter #37A	Yes, Possibly	No	Rehabilitation	CMU Block Columns, Gable Roof, Architectural Shingles
Structure	Shelter #38	Yes	No	Rehabilitation	Rubble Stone, Tapered Rubble Stone End Chimney, Gable Roof
Structure	Shelter #4	Yes, Possibly	No	Rehabilitation	CMU Block Columns, Gable Roof, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #5	No	No	N/A	N/A

**KEY:**

**“Preservation”** – Preservation is defined as the act or process of applying measures necessary to sustain the existing form, integrity, and materials of an historic property.

**“Rehabilitation”** – Rehabilitation is defined as the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features which convey its historical, cultural, or architectural values.

**“Restoration”** – Restoration is defined as the act or process of accurately depicting the form, features, and character of a property as it appeared at a particular period of time by means of the removal of features from other periods in its history and reconstruction of missing features from the restoration period.

**“Buildings”** – created principally to shelter any form of human activity.

**“Structures”** – functional constructions made usually for purposes other than creating human shelter.

**WPA Status** - Generally accepted as the time period in which the WPA was undertaking projects across the United States

**Historic Non-WPA** - Historically or architecturally significant building or structure that may have been constructed outside of the timeline for the WPA

**Materials** - Predominant existing materials of the building or structure



## CHESTNUT RIDGE PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON-WPA)	TREATMENT OPTION	MATERIALS
Structure	Shelter #6	No	No	N/A	N/A
Structure	Shelter #6A	No	No	N/A	N/A
Structure	Shelter #7	No	No	N/A	Wood Posts w/Bracing
Structure	Shelter #7A	Yes, Possibly	No	Rehabilitation	CMU Block Columns, Gable Roof, Architectural Shingles
Structure	Shelter #8	No	No	N/A	N/A
Structure	Shelter #9	No	No	N/A	N/A
Structure	Shelter #9A	No	No	N/A	N/A
Recreation	Slide	No	No	N/A	N/A
Recreation	Slide	No	No	N/A	N/A
Recreation	Slide	No	No	N/A	N/A
Recreation	Slide	No	No	N/A	N/A
Recreation	Slide	No	No	N/A	N/A
Recreation	Slide and See-Saw	No	No	N/A	N/A
Recreation	Slide and Swings	No	No	N/A	N/A
Recreation	Slide and Swings	No	No	N/A	N/A
Recreation	Slide and Swings	No	No	N/A	N/A
Recreation	Softball	No	No	N/A	N/A
Recreation	Softball	No	No	N/A	N/A
Structure	Stone Shed	Yes, Likely	No	Preservation	Rubble Stone, Gabled Roof, Architectural Shingles, Exposed Rafters, Rough Cut Clapboards
Structure	Stone Structure?	Yes, Likely	No	Preservation	Rubble Stone
Recreation	Swings	No	No	N/A	N/A
Recreation	Swings	No	No	N/A	N/A
Recreation	Swings	No	No	N/A	N/A
Recreation	Swings	No	No	N/A	N/A
Recreation	Swings and Jungle Gym	No	No	N/A	N/A
Recreation	Swings and See-Saw	No	No	N/A	N/A
Recreation	Tennis	No	No	N/A	N/A
Structure	Toboggan Chutes	Yes	No	Rehabilitation	N/A



## CHESTNUT RIDGE PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON-WPA)	TREATMENT OPTION	MATERIALS
Infrastructure	Wall	Yes, Likely	No	Rehabilitation	Rubble Stone
Infrastructure	Wall	Yes, Likely	No	Rehabilitation	Rubble Stone
Infrastructure	Wall	Yes, Likely	No	Rehabilitation	Rubble Stone
Structure	Warming Shelter	No	No	N/A	
Recreation	Waterfall	No	No	N/A	N/A
Recreation	Waterfall	No	No	N/A	N/A
Structure	Workers Memorial	No	No	N/A	N/A

**KEY:**

**“Preservation”** – Preservation is defined as the act or process of applying measures necessary to sustain the existing form, integrity, and materials of an historic property.

**“Rehabilitation”** – Rehabilitation is defined as the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features which convey its historical, cultural, or architectural values.

**“Restoration”** – Restoration is defined as the act or process of accurately depicting the form, features, and character of a property as it appeared at a particular period of time by means of the removal of features from other periods in its history and reconstruction of missing features from the restoration period.

**“Buildings”** – created principally to shelter any form of human activity.

**“Structures”** – functional constructions made usually for purposes other than creating human shelter.

**WPA Status** - Generally accepted as the time period in which the WPA was undertaking projects across the United States

**Historic Non-WPA** - Historically or architecturally significant building or structure that may have been constructed outside of the timeline for the WPA

**Materials** - Predominant existing materials of the building or structure



## 2.2 COMO LAKE PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON-WPA)	TREATMENT OPTION	MATERIALS
InfraStructure	Parking	No	No	N/A	
InfraStructure	Culvert	No	No	N/A	
InfraStructure	Maintenance Access Road	No	No	N/A	
InfraStructure	Parking	No	No	N/A	
InfraStructure	Culvert	No	No	N/A	
Recreation	Play Structure	No	No	N/A	
Recreation	Playground	No	No	N/A	
Recreation	Softball	No	No	N/A	
Recreation	Play Structure	No	No	N/A	
Recreation	Play Structure	No	No	N/A	
Recreation	Playground	No	No	N/A	
Recreation	Basketball	No	No	N/A	
Recreation	Soccer	No	No	N/A	
Recreation	Playground	No	No	N/A	
Recreation	Tennis	No	No	N/A	
Recreation	Overlook	No	No	N/A	
Recreation	Baseball	No	No	N/A	
Recreation	Former Boat House	No	No	N/A	
Recreation	Playground	No	No	N/A	
Recreation	Baseball/Softball	No	No	N/A	
Recreation	Swings	No	No	N/A	
Recreation	Slide	No	No	N/A	
Recreation	Pedestrian Bridge	No	No	N/A	
Structure	Shelter #15	No	No	N/A	Wood Columns
Structure	Shelter #17	No	No	N/A	Wood Columns
Structure	Shelter #13	No	No	N/A	Wood Columns
Structure	Shelter #12	No	No	N/A	
Structure	Shelter #50	No	No	N/A	
Structure	Shelter #58	No	No	N/A	

## COMO LAKE PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON-WPA)	TREATMENT OPTION	MATERIALS
Structure	Shelter #56	No	No	N/A	
Structure	Shelter #54	No	No	N/A	
Structure	Shelter #3	No	No	N/A	
Structure	Park Office & Maintenance	No	Yes	Rehabilitation	Rubble Stone Foundation (Bank Barn?)
Structure	Shelter #51	No	No	N/A	
Structure	Shelter #5 Boy Scouts Shelter	No	No	N/A	
Structure	Shelter #1	No	No	N/A	
Structure	Gateway Signage	No	No	N/A	Modern, Metal Sign
Structure	Storage Building	No	No	N/A	
Structure	Lancaster Place	No	No	N/A	
Structure	Former Sheriff Substation	No	No	N/A	
Structure	Disk Golf Start	No	No	N/A	
Structure	Comfirt Station E	No	No	N/A	
Structure	Shelter #41	No	No	N/A	Wood Columns
Structure	Shelter #49	No	No	N/A	
Structure	Cayuga Creek Nature Trail	No	No	N/A	
Structure	Comfort Station A	No	No	N/A	
Structure	Shelter #10	No	No	N/A	
	Former Shelter	No	No	N/A	
	Former Concession Stand	No	No	N/A	

**KEY:**

**“Preservation”** – Preservation is defined as the act or process of applying measures necessary to sustain the existing form, integrity, and materials of an historic property.

**“Rehabilitation”** – Rehabilitation is defined as the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features which convey its historical, cultural, or architectural values.

**“Restoration”** – Restoration is defined as the act or process of accurately depicting the form, features, and character of a property as it appeared at a particular period of time by means of the removal of features from other periods in its history and reconstruction of missing features from the restoration period.

**“Buildings”** – created principally to shelter any form of human activity.

**“Structures”** – functional constructions made usually for purposes other than creating human shelter.

**WPA Status** - Generally accepted as the time period in which the WPA was undertaking projects across the United States

**Historic Non-WPA** - Historically or architecturally significant building or structure that may have been constructed outside of the timeline for the WPA

**Materials** - Predominant existing materials of the building or structure



## COMO LAKE PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON-WPA)	TREATMENT OPTION	MATERIALS
InfraStructure	Culvert	No	No	N/A	
InfraStructure	Pedestrian Bridge	No	No	N/A	
Structure	Shelter #31	No	No	N/A	Wood Columns
Structure	Shelter #32	No	No	N/A	Wood Columns
Structure	Lancaster Place Sign	No	No	N/A	
Recreation	Ice Skating	No	No	N/A	
Recreation	Sledding Hill	No	No	No	
InfraStructure	North Island Pedestrian Bridge	No	No	N/A	
InfraStructure	Middle Island Pedestrian Bridge	No	No	N/A	
InfraStructure	South Island Pedestrian Bridge	No	No	N/A	
Structure	Shelter #26	No	No	N/A	Wood Columns, Board and Batten Siding, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #18	No	No	N/A	Wood Columns, Board and Batten Siding, Shingled/3-Tab Roof (Cladding)
Recreation		No	No	N/A	
Structure		No	No	N/A	
Structure	Shelter #37	Yes, Likely	No	Rehabilitation	Rubble Stone, Arches, Salt Box Roof
InfraStructure	Pedestrian Bridge	Undetermined	Undetermined	N/A	
InfraStructure	Pedestrian Bridge	Undetermined	Undetermined	N/A	
InfraStructure	Former Bridge Abutment	Yes, Likely	No	N/A	
InfraStructure	Stone Steps	Yes, Likely	No	Rehabilitation	Rubble Stone Wall, Steel Handrail, Concrete Steps(?)
Structure	Shelter #16	Yes, Likely	No	Rehabilitation	Rubble Stone, Shingled/3-Tab Roof (Cladding)

## COMO LAKE PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON-WPA)	TREATMENT OPTION	MATERIALS
Structure	Shelter #14	Yes, Likely	No	Rehabilitation	Rubble Stone Columns and Wood Columns, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #22	Yes, Likely	No	Rehabilitation	Rubble Stone Columns, Shingled/3-Tab Roof (Cladding)
Structure	Jimmy D Casino	Yes, Likely	No	Rehabilitation	Rubble Stone, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #52	Yes, Likely	No	Rehabilitation	Rubble Stone
Structure	Shelter #2	Yes, Likely	No	Rehabilitation	Rubble Stone
Structure	Shelter #4	Yes, Likely	No	Rehabilitation	Rubble Stone Columns
Structure	Shelter #11	Yes, Likely	No	Rehabilitation	Rubble Stone
Structure	Comfort Station C	Yes, Likely	No	Rehabilitation	Rubble Stone, Glass Bock
Structure	Shelter #9	Yes, Likely	No	Rehabilitation	Rubble Stone, Cross Gable
Structure	Shelter #8	Yes, Likely	No	Rehabilitation	Rubble Stone
Structure	Shelter #7	Yes, Likely	No	Rehabilitation	Rubble Stone (Leaning)
Structure	Gateway Sign	Yes, Likely	No	Rehabilitation	Rubble Stone Columns with Concrete Finial
Structure	Gateway Sign	Yes, Likely	No	Rehabilitation	Rubble Stone Columns
Structure	Stone Steps	Yes, Likely	No	Preservation	
Structure	Shelter ???	Yes, Likely	No	Rehabilitation	Rubble Stone Columns, Rubble Stone Chimney

**KEY:**

**“Preservation”** – Preservation is defined as the act or process of applying measures necessary to sustain the existing form, integrity, and materials of an historic property.

**“Rehabilitation”** – Rehabilitation is defined as the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features which convey its historical, cultural, or architectural values.

**“Restoration”** – Restoration is defined as the act or process of accurately depicting the form, features, and character of a property as it appeared at a particular period of time by means of the removal of features from other periods in its history and reconstruction of missing features from the restoration period.

**“Buildings”** – created principally to shelter any form of human activity.

**“Structures”** – functional constructions made usually for purposes other than creating human shelter.

**WPA Status** - Generally accepted as the time period in which the WPA was undertaking projects across the United States

**Historic Non-WPA** - Historically or architecturally significant building or structure that may have been constructed outside of the timeline for the WPA

**Materials** - Predominant existing materials of the building or structure



## COMO LAKE PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON-WPA)	TREATMENT OPTION	MATERIALS
Structure	Shelter #20	Yes, Likely	No	Rehabilitation	
Structure	Shelter #39	Yes, Likely	No	Rehabilitation	Rubble Stone Columns
Structure	Shelter #40	Yes, Likely	No	Rehabilitation	Rubble Stone Columns
Structure	Shelter #43	Yes, Likely	No	Rehabilitation	Rubble Stone Columns, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #47	Yes, Likely	No	Rehabilitation	Rubble Stone (Leaning)
Structure	Cooking Shelter	Yes, Likely	No	Rehabilitation	Rubble Stone Columns, Gabled Roof Monitor, Shingled/3-Tab Roof (Cladding)
Structure	Rich Marino Gazebo	Yes, Likely	No	Rehabilitation	Rubble Stone Columns, Hipped Cupola, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #33	Yes, Likely	No	Rehabilitation	Rubble Stone Columns, Board and Batten Siding, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #21	Yes, Likely	No	Rehabilitation	Rubble Stone Columns, Board and Batten Siding, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #19	Yes, Likely	No	Rehabilitation	Rubble Stone Columns, Board and Batten Siding, Shingled/3-Tab Roof (Cladding)



## COMO LAKE PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON-WPA)	TREATMENT OPTION	MATERIALS
Structure	Shelter #23	Yes, Likely	No	Rehabilitation	Rubble Stone Columns, Board and Batten Siding, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #24	Yes, Likely	No	Rehabilitation	Rubble Stone Columns, Board and Batten Siding, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #29	Yes, Likely	No	Rehabilitation	Rubble Stone Columns, Standing Seam Sheet Metal Roof
Structure	Comfort Station D	Yes, Possibly	No	Rehabilitation	CMU & Glass Block
Structure	Shelter #59	Yes, Likely	No	Rehabilitation	Rubble Stone (Slightly More Dressed)
Structure	Shelter #57	Yes, Likely	No	Rehabilitation	Rubble Stone (Slightly More Dressed)
Structure	Comfort Station B	Yes, Possibly	No	Rehabilitation	CMU & Glass Block, Board and Batten Siding
Structure	Staircase	Yes, Likely	No	Preservation	Rubble Stone
Structure	Lighthouse	Yes	No	Preservation	Folley - Rubble Stone, Metal Dome/Roof, Steel Guard Rail, Windows, Archway

**KEY:**

**"Preservation"** – Preservation is defined as the act or process of applying measures necessary to sustain the existing form, integrity, and materials of an historic property.

**"Rehabilitation"** – Rehabilitation is defined as the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features which convey its historical, cultural, or architectural values.

**"Restoration"** – Restoration is defined as the act or process of accurately depicting the form, features, and character of a property as it appeared at a particular period of time by means of the removal of features from other periods in its history and reconstruction of missing features from the restoration period.

**"Buildings"** – created principally to shelter any form of human activity.

**"Structures"** – functional constructions made usually for purposes other than creating human shelter.

**WPA Status** - Generally accepted as the time period in which the WPA was undertaking projects across the United States

**Historic Non-WPA** - Historically or architecturally significant building or structure that may have been constructed outside of the timeline for the WPA

**Materials** - Predominant existing materials of the building or structure



## COMO LAKE PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON-WPA)	TREATMENT OPTION	MATERIALS
Structure	Stone Columns	Yes	No	Preservation	Rubble Stone with Concrete Capstone
InfraStructure	Culvert	No	No	N/A	
InfraStructure	Culvert	No	No	N/A	
InfraStructure	Culvert	No	No	N/A	
InfraStructure	Culvert	No	No	N/A	
InfraStructure	Culvert	No	No	N/A	
Structure	Shelter #55	Yes, Likely	No	Rehabilitation	Rubble Stone Columns, Board and Batten Siding
Structure	Shelter #53	Yes, Likely	No	Rehabilitation	Rubble Stone Columns, Board and Batten Siding, Shingled/3-Tab Roof (Cladding)
Structure	Bowen Road Grove	No	No	N/A	

## 2.3 ELLICOTT CREEK PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON- WPA)	TREATMENT OPTION	MATERIALS
Structure	Bark Park Signage	No	No	N/A	N/A
Recreation	Baseball	No	No	N/A	N/A
Structure	Boat House	Yes, Likely	No	Preservation	Rubble Stone, Parabolic Arches
Structure	Comfort Station #1	Yes, Likely	No	Rehabilitation	Rubble Stone, Glass Block, Blind Arch
Structure	Comfort Station #2	No	No	N/A	CMU Block and Glass Block
Structure	Comfort Station #3	Yes, Likely	No	Rehabilitation	Rubble Stone, Clerestory Windows, Fountain(?), Architectural Shingles
Structure	Comfort Station #4	No	No	N/A	CMU Block and Glass Block
Structure	Comfort Station #5	Yes, Likely	No	N/A	Rubble Stone, Glass Block, Shingled/3-Tab Roof (Cladding)
Structure	Creekside Stand	Yes, Likely	No	Rehabilitation	Rubble Stone, Veranda
Structure	Deck	No	No	N/A	N/A
Recreation	Disc Golf Start	No	No	N/A	N/A
Structure	Drinking Fountain	Yes, Likely	No	Preservation	Rubble Stone
Structure	Fire Pit	Yes, Likely	No	Preservation	Rubble Stone
	Former Playground	No	No	N/A	N/A
Structure	Friendship Center	No	No	N/A	N/A
Structure	Garden	No	No	N/A	N/A
Recreation	Garden Circle	No	No	N/A	N/A
Structure	Gateway	Yes, Likely	No	N/A	Rubble Stone
Structure	Gateway Sign	No	No	N/A	N/A
Structure	Gateway Sign	No	No	N/A	N/A
Structure	Gateway Sign	No	No	N/A	N/A

**KEY:**

**“Preservation”** – Preservation is defined as the act or process of applying measures necessary to sustain the existing form, integrity, and materials of an historic property.

**“Rehabilitation”** – Rehabilitation is defined as the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features which convey its historical, cultural, or architectural values.

**“Restoration”** – Restoration is defined as the act or process of accurately depicting the form, features, and character of a property as it appeared at a particular period of time by means of the removal of features from other periods in its history and reconstruction of missing features from the restoration period.

**“Buildings”** – created principally to shelter any form of human activity.

**“Structures”** – functional constructions made usually for purposes other than creating human shelter.

**WPA Status** - Generally accepted as the time period in which the WPA was undertaking projects across the United States

**Historic Non-WPA** - Historically or architecturally significant building or structure that may have been constructed outside of the timeline for the WPA

**Materials** - Predominant existing materials of the building or structure



## ELLCOTT CREEK PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON- WPA)	TREATMENT OPTION	MATERIALS
Structure	Grill #1	Yes, Likely	No	Preservation	Rubble Stone
Structure	Grill #2	No	No	N/A	N/A
Structure	Island Comfort Station	Yes, Likely	No	Rehabilitation	Rubble Stone, Turrent/Chimney, Shingled/3-Tab Roof (Cladding), Fine Example of Type
Structure	Jimmy D Casino	Yes, Likely	No	Rehabilitation	Rubble Stone, Significantly Altered
Recreation	Kayak Launch	No	No	N/A	N/A
Recreation	Kayak Launch	No	No	N/A	N/A
Recreation	Lifetrail Advanced Wellness System	No	No	N/A	N/A
Structure	Old Fountain	Yes, Likely	No	Preservation	Rubble Stone
Structure	Old Stone Steps	Yes, Likely	No	Rehabilitation	Rubble Stone
Structure	Old Stone Steps	No	No	N/A	N/A
Structure	Old Water Fountain WPA	Yes, Likely	No	Preservation	Rubble Stone
Structure	Park Office and Maintenance	No	No	N/A	Rusticated Stone Veneer, Tripartite and Paired Windows, CMU Bloack, Cross Gabled, Shingled/3-Tab Roof (Cladding)
Structure	Park Sign and Rules	No	No	N/A	N/A
Infrastructure	Parking	No	No	N/A	N/A
Infrastructure	Parking	No	No	N/A	N/A
Infrastructure	Pedestrian Bridge	Undetermined	Undetermined	Rehabilitation	Concrete Pilings, Wood Railings, Wood Deck Plate
Infrastructure	Pedestrian Bridge	No	No	N/A	N/A
Infrastructure	Pedestrian Bridge	No	No	N/A	N/A
Recreation	Picnic Table	No	No	N/A	N/A
Recreation	Picnic Table	No	No	N/A	N/A
Recreation	Picnic Table	No	No	N/A	N/A
Recreation	Play Structure	No	No	N/A	N/A
Recreation	Play Structure	No	No	N/A	N/A
Recreation	Play Structure	No	No	N/A	N/A
Recreation	Play Structure	No	No	N/A	N/A
Recreation	Play Structure	No	No	N/A	N/A
Recreation	Play Structure	No	No	N/A	N/A

## ELLCOTT CREEK PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON- WPA)	TREATMENT OPTION	MATERIALS
Recreation	Play Structure	No	No	N/A	N/A
Recreation	Playground	No	No	N/A	N/A
Recreation	Playground	No	No	N/A	N/A
Recreation	Playground	No	No	N/A	N/A
Structure	Pump shelter #1	Yes, Likely	No	Rehabilitation	Tapered Rusticated Stone Columns (Appears Cut), Domed/Circular Roof
Structure	Pump shelter #2	Yes, Likely	No	Rehabilitation	Rubble Stone, Domed/Circular Roof
Structure	Shelter #10A and 10B	No	No	N/A	N/A
Structure	Shelter #10A and 10B	No	No	N/A	N/A
Structure	Shelter #11	Yes, Likely	No	Rehabilitation	Rubble Stone Columns, CMU Block Columns, Board and Batten Siding, Shingled/3-Tab Roof (Cladding), Rubble Stone End Chimney
Structure	Shelter #14	No	No	N/A	CMU Block Columns, Board and Batten Siding
Structure	Shelter #15	No	No	N/A	CMU Block Columns
Structure	Shelter #16	No	No	N/A	CMU Block Columns
Structure	Shelter #17	No	No	N/A	CMU Block Columns
Structure	Shelter #18	Yes, Likely	No	Rehabilitation	Rubble Stone Columns, Vertical Clapboards, Scalloped Vergeboard, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #19	No	No	N/A	N/A

**KEY:**

**“Preservation”** – Preservation is defined as the act or process of applying measures necessary to sustain the existing form, integrity, and materials of an historic property.

**“Rehabilitation”** – Rehabilitation is defined as the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features which convey its historical, cultural, or architectural values.

**“Restoration”** – Restoration is defined as the act or process of accurately depicting the form, features, and character of a property as it appeared at a particular period of time by means of the removal of features from other periods in its history and reconstruction of missing features from the restoration period.

**“Buildings”** – created principally to shelter any form of human activity.

**“Structures”** – functional constructions made usually for purposes other than creating human shelter.

**WPA Status** - Generally accepted as the time period in which the WPA was undertaking projects across the United States

**Historic Non-WPA** - Historically or architecturally significant building or structure that may have been constructed outside of the timeline for the WPA

**Materials** - Predominant existing materials of the building or structure



## ELLCOTT CREEK PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON- WPA)	TREATMENT OPTION	MATERIALS
Structure	Shelter #2	Yes, Likely	No	Rehabilitation	Tapered Rusticated Stone Columns (Appears Cut), Scalloped Vergeboard, Hipped Roof, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #20	No	No	N/A	CMU Block Columns, Board and Batten Siding, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #24	Yes, Likely	No	Rehabilitation	Tapered Rusticated Stone Columns (Appears Cut), Irregularly Cut Vertical Clapboards, Heavy Timber Construction, Architectural Shingles
Structure	Shelter #25	No	No	N/A	Red, Clay Fired Brick Columns, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #26	Yes, Likely	No	Rehabilitation	Rubble Stone, Castellated Vertical Clapboards, Heavy Timber Construction
Structure	Shelter #27	Yes, Likely	No	Rehabilitation	Tapered Rusticated Stone Columns (Appears Cut) Scalloped Vergeboard, Architectural Shingles
Structure	Shelter #28	Yes, Likely	No	Rehabilitation	Rubble Stone End Walls, Exposed Rafters, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #3	Yes, Likely	No	Rehabilitation	Rusticated Stone Columns, Hipped Roof, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #30	Yes, Likely	No	Rehabilitation	Rusticated Stone Columns (Appears Cut)
Structure	Shelter #31	Yes, Likely	No	Rehabilitation	Rusticated Stone End Walls (Appears Cut), Arched Open Air Windows (Segmental Arch, Semicircular Arch), Salt Box Roof, Faux(?) Heavy Timber Construction, Exposed Rafters, 3-Tab Shingles

## ELLICOTT CREEK PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON- WPA)	TREATMENT OPTION	MATERIALS
Structure	Shelter #32	Yes, Likely	No	Rehabilitation	Rubble Stone End Walls, Blind Arches, Exposed Rafters, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #33	Yes, Likely	No	Rehabilitation	Tapered Rusticated Stone Columns (Appears Cut), Board and Batten Siding
Structure	Shelter #34	Yes, Likely	No	Rehabilitation	Rubble Stone Columns, Hipped Roof, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #35	Yes, Likely	No	Rehabilitation	Rubble Stone Columns, Exposed Rafters, Octagonal Roof, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #4	Yes, Likely	No	Rehabilitation	Tapered Rusticated Stone Columns (Appears Cut), Hipped Roof, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #5	Yes, Likely	No	Rehabilitation	Rusticated Stone End Walls (Appears Cut), Arched Open Air Windows (Segmental Arch, Semicircular Arch), Salt Box Roof, Faux(?) Heavy Timber Construction, Exposed Rafters, 3-Tab Shingles
Structure	Shelter #6	Yes, Likely	No	Rehabilitation	Rubble Stone End Walls, CMU Block Columns, Shingled/3-Tab Roof (Cladding), Rubble Stone End Chimneys

**KEY:**

**“Preservation”** – Preservation is defined as the act or process of applying measures necessary to sustain the existing form, integrity, and materials of an historic property.

**“Rehabilitation”** – Rehabilitation is defined as the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features which convey its historical, cultural, or architectural values.

**“Restoration”** – Restoration is defined as the act or process of accurately depicting the form, features, and character of a property as it appeared at a particular period of time by means of the removal of features from other periods in its history and reconstruction of missing features from the restoration period.

**“Buildings”** – created principally to shelter any form of human activity.

**“Structures”** – functional constructions made usually for purposes other than creating human shelter.

**WPA Status** - Generally accepted as the time period in which the WPA was undertaking projects across the United States

**Historic Non-WPA** - Historically or architecturally significant building or structure that may have been constructed outside of the timeline for the WPA

**Materials** - Predominant existing materials of the building or structure





## ELLICOTT CREEK PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON- WPA)	TREATMENT OPTION	MATERIALS
Structure	Shelter #7	Yes, Likely	No	Rehabilitation	Tapered Rusticated Stone Columns (Appears Cut), Rusticated Stone Chimney, Irregularly Cut Vertical Clapboards, Faux(?) Heavy Timber Construction
Structure	Shelter #8	Yes, Likely	No	Rehabilitation	Rubble Stone Columns, Octagonal Roof, Exposed Rafters
Structure	Shelter #9	Yes, Likely	No	Rehabilitation	Rubble Stone End Walls, CMU Block Columns, Shingled/3-Tab Roof (Cladding), Rubble Stone End Chimney
Recreation	Soccer	No	No	N/A	N/A
Recreation	Soccer	No	No	N/A	N/A
Recreation	Stage	No	No	N/A	N/A
Structure	Stone Column	Yes, Likely	No	Preservation	Rubble Stone Column Base
Structure	Stone Column	Yes, Likely	No	Preservation	Rubble Stone Column Base
Structure	Stone Column	Yes, Likely	No	Preservation	Rubble Stone Column Base
Recreation	Swings	No	No	N/A	N/A
Recreation	Swings	No	No	N/A	N/A
Recreation	Tennis and Pickelball	No	No	N/A	N/A
Structure	Tree Art Installation	No	No	N/A	N/A
Structure	Water Fountain	Yes, Possibly	No	Preservation	Rubble Stone
Structure	Water Fountain	Yes, Possibly	No	Preservation	Rubble Stone
Recreation	Wheelbarrow	No	Yes	Preservation	Steel

## 2.4 EMERY PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON-WPA)	TREATMENT OPTION	MATERIALS
Infrastructure	Culvert	Yes, Likely	No	N/A	Rubble Stone
Infrastructure	Culvert	Yes, Likely	No	N/A	Rubble Stone
Infrastructure	Culvert	Yes, Likely	No	N/A	Rubble Stone
Infrastructure	Culvert	No	No	N/A	N/A
Infrastructure	Culvert	Yes, Likely	No	Preservation	Rubble Stone (Arched)
Infrastructure	Culvert	Yes, Likely	No	Preservation	Rubble Stone
Infrastructure	Culvert	Yes, Likely	No	Preservation	Rubble Stone/ Dimensional?
Infrastructure	Culvert	Yes, Likely	No	Preservaiton	Rubble Stone/ Dimensional?
Infrastructure	Culvert	Yes, Likely	No	Preservation	Rubble Stone
Infrastructure	Culvert	Yes, Likely	No	Preservation	Rubble Stone
Infrastructure	Culvert	Yes, Likely	No	Preservation	Rubble Stone
Infrastructure	Culvert	Yes, Likely	No	N/A	Rubble Stone
Infrastructure	Culvert	Yes, Likely	No	N/A	Rubble Stone
Infrastructure	Culvert	Yes, Likely	No	N/A	Rubble Stone
Infrastructure	Culvert	No	No	N/A	N/A
Infrastructure	Culvert	No	No	N/A	Concrete Headwalls
Infrastructure	Culvert	No	No	N/A	N/A (Demolished)
Infrastructure	Culvert	Yes, Likely	No	Preservation	Rubble Stone
Infrastructure	Culvert	Yes, Likely	No	Preservation	Rubble Stone
Infrastructure	Culvert	Yes, Likely	No	Preservation	Rubble Stone
Infrastructure	Culvert	Yes, Likely	No	Preservation	Rubble Stone
Infrastructure	Fence	No	No	N/A	N/A
Infrastructure	Fence	No	No	N/A	N/A
Infrastructure	Gate	No	No	N/A	N/A
Infrastructure	Gate	No	No	N/A	N/A
Infrastructure	Guardrail	No	No	N/A	N/A
Infrastructure	Guardrail	No	No	N/A	N/A
Infrastructure	Obseration Tower Parking	No	No	N/A	N/A

**KEY:**

**“Preservation”** – Preservation is defined as the act or process of applying measures necessary to sustain the existing form, integrity, and materials of an historic property.

**“Rehabilitation”** – Rehabilitation is defined as the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features which convey its historical, cultural, or architectural values.

**“Restoration”** – Restoration is defined as the act or process of accurately depicting the form, features, and character of a property as it appeared at a particular period of time by means of the removal of features from other periods in its history and reconstruction of missing features from the restoration period.

**“Buildings”** – created principally to shelter any form of human activity.

**“Structures”** – functional constructions made usually for purposes other than creating human shelter.

**WPA Status** - Generally accepted as the time period in which the WPA was undertaking projects across the United States

**Historic Non-WPA** - Historically or architecturally significant building or structure that may have been constructed outside of the timeline for the WPA

**Materials** - Predominant existing materials of the building or structure



## EMERY PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON-WPA)	TREATMENT OPTION	MATERIALS
Infrastructure	Parking 6	No	No	N/A	N/A
Infrastructure	Pedestrian Bridge	No	No	N/A	N/A
Infrastructure	Pedestrian Bridge	No	No	N/A	N/A
Infrastructure	Pump Shelter #14	Yes, Likely	No	Preservation	Cast Iron (?) Water Pump, Shelter Not Extant
Infrastructure	Pump Shelter #16	Yes	No	Preservation	Rubble Stone, Wood Posts, Gable Roof, Shingled/3-Tab Roof (Cladding)
Infrastructure	Pump Shelter #17	Yes	No	Preservation	Rubble Stone, Rustic Construction (Posts), Hipped Roof
Infrastructure	Pump Shelter #2	No	No	N/A	Rustic Construction, Architectural Shingles
Infrastructure	Pump Shelter #3	Yes, Likely	No	Preservation	Cast Iron (?) Water Pump, Shelter Not Extant
Infrastructure	Pump Shelter #7	Yes, Likely	No	Preservation	Cast Iron (?) Water Pump, Shelter Not Extant
Infrastructure	Pump Shelter #8	Yes	No	Preservation	Rubble Stone, Wood Posts, Pyramidal Roof. Architectural Shingles
Infrastructure	Ski Lodge Parking	No	No	N/A	N/A
Infrastructure	Stone Steps	Yes, Likely	No	Preservation	Wood Handrail (Dimensional Lumber)
Infrastructure	Stone Steps	Yes	No	Rehabilitation	Rubble Stone, Concrete
Infrastructure	Wall	Yes, Likely	No	Preservation	Rubble Stone Retaining Wall, Steps
Infrastructure	Wall	Yes, Likely	No	Preservation	Rubble Stone Retaining Wall
Recreation	Baseball	No	No	N/A	N/A
Recreation	Disc golf	No	No	N/A	N/A
Recreation	Play Structure	No	No	N/A	N/A
Recreation	Play Structure	No	No	N/A	N/A
Recreation	Play Structure	No	No	N/A	N/A
Recreation	Playground	No	No	N/A	N/A
Recreation	Playground	No	No	N/A	N/A
Recreation	Playground	No	No	N/A	N/A

## EMERY PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON-WPA)	TREATMENT OPTION	MATERIALS
Recreation	Playground	No	No	N/A	N/A
Recreation	Rock Garden	Yes	No	Preservation	Rubble Stone
Recreation	See-Saw	No	No	N/A	N/A
Recreation	Shuffleboard	No	No	N/A	N/A
Recreation	Skiing Hill	No	No	N/A	N/A
Recreation	Skiing Hill	No	No	N/A	N/A
Recreation	Skiing Hill	No	No	N/A	N/A
Recreation	Skiing Hill	No	No	N/A	N/A
Recreation	Skiing Hill	No	No	N/A	N/A
Recreation	Skiing Hill	No	No	N/A	N/A
Recreation	Slide and Swing	No	No	N/A	N/A
Recreation	Slide and Swings	No	No	N/A	N/A
Recreation	Stage	Yes, Likely	No	Preservation	Rubble Stone
Recreation	Swings	No	No	N/A	N/A
Recreation	Swings	No	No	N/A	N/A
Recreation	Swings	No	No	N/A	N/A
Recreation	Swings	No	No	N/A	N/A
Recreation	Swings	No	No	N/A	N/A
Recreation	Swings	No	No	N/A	N/A
Recreation	Swings	No	No	N/A	N/A
Recreation	Swings	No	No	N/A	N/A
Recreation	Swings	No	No	N/A	N/A
Recreation	Swings	No	No	N/A	N/A
Recreation	Tennis	No	No	N/A	N/A
Recreation	Waterfall	No	No	N/A	N/A
Structure	Arbor and Garden	No	No	N/A	N/A

**KEY:**

**“Preservation”** – Preservation is defined as the act or process of applying measures necessary to sustain the existing form, integrity, and materials of an historic property.

**“Rehabilitation”** – Rehabilitation is defined as the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features which convey its historical, cultural, or architectural values.

**“Restoration”** – Restoration is defined as the act or process of accurately depicting the form, features, and character of a property as it appeared at a particular period of time by means of the removal of features from other periods in its history and reconstruction of missing features from the restoration period.

**“Buildings”** – created principally to shelter any form of human activity.

**“Structures”** – functional constructions made usually for purposes other than creating human shelter.

**WPA Status** - Generally accepted as the time period in which the WPA was undertaking projects across the United States

**Historic Non-WPA** - Historically or architecturally significant building or structure that may have been constructed outside of the timeline for the WPA

**Materials** - Predominant existing materials of the building or structure



## EMERY PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON-WPA)	TREATMENT OPTION	MATERIALS
Structure	Comfort Station 1	No	No	N/A	CMU Block Columns, Shingled/3-Tab Roof
Structure	Comfort Station 2	Yes	No	Rehabilitation	Rubble Stone, Hipped Roof, Architectural Shingles, Glass Block
Structure	Comfort Station 4 South Side	Yes	No	Rehabilitation	Rubble Stone, Hipped Roof, Architectural Shingles, Glass Block
Structure	Comfort Station 4 North Side	No	No	N/A	CMU Block Columns, Shingled/3-Tab Roof
Structure	Comfort station 5	Yes	No	Rehabilitation	Rubble Stone, Hipped Roof, Architectural Shingles, Glass Block
Structure	Elizabeth Grove Cottage	Yes	No	Rehabilitation	Rubble Stone, Gable Roof, Wood Braces
Structure	Fieldhouse	No	No	N/A	N/A
Structure	Fire pit	Yes	No	Preservation	Rubble Stone, Concrete Repointing/Patching?
Structure	Former Shelter	No	No	N/A	N/A
Structure	Gate	No	No	N/A	N/A
Structure	Gate	No	No	N/A	Chain-Link
Structure	Gateway Sign	No	No	N/A	N/A
Structure	Gateway Sign	No	No	N/A	N/A
Structure	Gateway Sign	No	No	N/A	N/A
Structure	Gazebo	No	No	N/A	N/A
Structure	Historic Plaque				
Structure	Incinerator	Yes	No	Preservation	Rubble Stone, Red Clay Fired Brick
Structure	Incinerator	Yes	No	Preservation	Rubble Stone, Concrete
Structure	Incinerator	Yes	No	Preservation	Rubble Stone, Unique WPA Inscription
Structure	Legacy 11 Plaque	No	No	N/A	N/A
Structure	Million Dollar Comfort Station	No	No	Rehabilitation	N/A
Structure	Need Name				
Structure	Observation Tower	No	No	Rehabilitation	Mid-Century?
Structure	Park Map	No	No	N/A	N/A
Structure	Park Map	No	No	N/A	N/A

## EMERY PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON-WPA)	TREATMENT OPTION	MATERIALS
Structure	Park Office	No	No	N/A	N/A
Structure	Pergola	Yes	No	Preservation	Rubble Stone, Adaptive Reuse of Previous Building
Structure	Plaque	No	Yes	Preservation	c.1932 Bronze Plaque, Birth of George Washington Celebration
Structure	Pump Shelter # unknown	Yes	No	Preservation	Rubble Stone, Wood Posts, Gable Roof
Structure	Pump Shelter # unknown	Yes, Likely	No	Preservation	Rustic Construction, Hexagonal Roof, Architectural Shingles
Structure	Pump Shelter #1	Yes, Likely	No	Preservation	Rustic Construction, Cedar Shake Shingles
Structure	Pump Shelter #10	Yes, Likely	No	Preservation	Cast Iron (?) Water Pump, Shelter Not Extant
Structure	Pump Shelter #11	Yes	No	Preservation	Rubble Stone, Gable Roof, Architectural Shingles
Structure	Pump Shelter #12	Yes	No	Preservation	Rubble Stone, Wood Posts, Hexagonal Roof, Architectural Shingles
Structure	Pump shelter #13	Yes, Likely	No	Preservation	Rustic Construction, Hexagonal Roof, Cedar Shake Shingles
Structure	Pump Shelter #15	Yes	No	Preservation	Rubble Stone, Gable Roof, Architectural Shingles
Structure	Pump Shelter #18	Yes	No	Preservation	Rubble Stone, Pyramidal Roof, Shingled/3-Tab Roof (Cladding)

**KEY:**

**“Preservation”** – Preservation is defined as the act or process of applying measures necessary to sustain the existing form, integrity, and materials of an historic property.

**“Rehabilitation”** – Rehabilitation is defined as the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features which convey its historical, cultural, or architectural values.

**“Restoration”** – Restoration is defined as the act or process of accurately depicting the form, features, and character of a property as it appeared at a particular period of time by means of the removal of features from other periods in its history and reconstruction of missing features from the restoration period.

**“Buildings”** – created principally to shelter any form of human activity.

**“Structures”** – functional constructions made usually for purposes other than creating human shelter.

**WPA Status** - Generally accepted as the time period in which the WPA was undertaking projects across the United States

**Historic Non-WPA** - Historically or architecturally significant building or structure that may have been constructed outside of the timeline for the WPA

**Materials** - Predominant existing materials of the building or structure



## EMERY PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON-WPA)	TREATMENT OPTION	MATERIALS
Structure	Pump Shelter #19	Yes, Likely	No	Preservation	Wood Posts (Rustic?), Gable Roof, Shingled/3-Tab Roof (Cladding)
Structure	Pump Shelter #4	No	No	N/A	Wood Posts, Gable Roof, Shingled/3-Tab Roof (Cladding)
Structure	Pump Shelter #5	Yes, Likely	No	Preservation	Rustic Construction, Architectural Shingles
Structure	Pump shelter #6	Yes, Likely	No	Preservation	Rustic Construction, Cedar Shake Shingles
Structure	Pump Shelter #9	No	No	N/A	Brick Columns, Gable Roof
Structure	Quoit Beds	Yes	No	Preservation	Rubble Stone, Pyramidal Roof, Shingled/3-Tab Roof (Cladding)
Structure	Richardson Cottage	No	No	N/A	Mid-Century?
Structure	Richardson Shelter	No	No	N/A	Mid-Century?
Structure	Round Comfort Station	Yes	No	Rehabilitation	Unique Comfort Station, Round, Rubble Stone, Round Roof w/Cupola
Structure	Shelter #1	No	No	N/A	Mid-Century?
Structure	Shelter #10	No	No	N/A	Mid-Century?
Structure	Shelter #100	No	No	N/A	N/A
Structure	Shelter #102	No	No	N/A	No Longer Extant
Structure	Shelter #103	Yes	No	Rehabilitation	Rubble Stone, Rustic Construction, Hexagonal Roof, Architectural Shingles
Structure	Shelter #105	Yes	No	Preservation	Rubble Stone, Pyramidal Roof, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #108	Yes	No	Rehabilitation	Rubble Stone, Gable Roof, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #108	Yes, Likely	No	Rehabilitation	Rubble Stone End Wall, CMU Block, Gable Roof, Architectural Shingles



## EMERY PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON-WPA)	TREATMENT OPTION	MATERIALS
Structure	Shelter #109	Yes	No	Rehabilitation	Rubble Stone, Wood (Rustic?), Gable Roof, Overhanging Eave/Rafter Tails, Arhictectural Shingles
Structure	Shelter #11	No	No	N/A	N/A
Structure	Shelter #113	Yes, Likely	No	Rehabilitation	CMU Block Columns, Hipped Roof, Shingled/3-Tab Roof (Cladding), Overhanging Eave/Rafter Tails
Structure	Shelter #116	Yes	No	Rehabilitation	Rubble Stone, Pyramidal Roof, Wood Shingles?
Structure	Shelter #117	No	No	N/A	Squared Wood Posts, Hipped Roof, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #11B	No	No	N/A	Unique Shelter, 3 Center Posts w/Hip Trusses, Hipped Roof, Architectural Shingles
Structure	Shelter #12	Yes, Likely	No	Rehabilitation	Very Clean, Stone Almost Dimensional (Rusticated?), Round Wood Posts, Gable Roof, Wood Siding (Clapboards)
Structure	Shelter #13	No	No	N/A	N/A
Structure	Shelter #14	No	No	N/A	N/A
Structure	Shelter #15	No	No	N/A	Mid-Century?
Structure	Shelter #16	No	No	N/A	Mid-Century?

**KEY:**

**“Preservation”** – Preservation is defined as the act or process of applying measures necessary to sustain the existing form, integrity, and materials of an historic property.

**“Rehabilitation”** – Rehabilitation is defined as the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features which convey its historical, cultural, or architectural values.

**“Restoration”** – Restoration is defined as the act or process of accurately depicting the form, features, and character of a property as it appeared at a particular period of time by means of the removal of features from other periods in its history and reconstruction of missing features from the restoration period.

**“Buildings”** – created principally to shelter any form of human activity.

**“Structures”** – functional constructions made usually for purposes other than creating human shelter.

**WPA Status** - Generally accepted as the time period in which the WPA was undertaking projects across the United States

**Historic Non-WPA** - Historically or architecturally significant building or structure that may have been constructed outside of the timeline for the WPA

**Materials** - Predominant existing materials of the building or structure



## EMERY PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON-WPA)	TREATMENT OPTION	MATERIALS
Structure	Shelter #17	No	No	N/A	CMU Block, Gable Roof, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #2	No	No	N/A	Mid-Century?
Structure	Shelter #20	Yes	No	Rehabilitation	Rubble Stone, Gable Roof, Shingled/3-Tab Roof (Cladding), Rubble Stone End Chimney
Structure	Shelter #20	No	No	Rehabilitation	CMU Block, Gable Roof, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #21	Yes	No	Rehabilitation	Rubble Stone, CMU Block, Gable Roof, Architectural Shingles, Rubble Stone End Chimney
Structure	Shelter #22	Yes	No	Rehabilitation	Rubble Stone, Wood Posts, Gable Roof, Architectural Shingles
Structure	Shelter #24	No	No	N/A	CMU Block Columns, Gable Roof, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #3	Yes, Likely	No	Rehabilitation	Rubble Stone, Architectural Shingles, Rubble Stone End Chimney
Structure	Shelter #5	No	No	N/A	Mid-Century?
Structure	Shelter #6	No	No	N/A	Mid-Century?
Structure	Shelter #7	No	No	N/A	CMU Block Columns, Gable Roof, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #8	Yes, Likely	No	Rehabilitation	Tapered Rubble Stone, Shingled/3-Tab Roof (Cladding)
Structure	Shelter #9	No	No	N/A	Mid-Century?
Structure	Shelter - unknown	Yes	No	Rehabilitation	Rubble Stone, Architectural Shingles, Rustic Construction
Structure	Shelter AAA	Yes	No	Preservation	Rubble Stone, Architectural Shingles
Structure	Ski Lodge	No	No	N/A	N/A

## EMERY PARK

PARK FEATURE	FEATURE DETAIL	WPA STATUS (1935 TO 1943)	HISTORIC (NON-WPA)	TREATMENT OPTION	MATERIALS
Structure	Small Bench & Shelter	Yes	No	Preservation	Rubble Stone, Gable Roof, Cedar Shake Shingles
Structure	Stohrer's Lodge	Yes, Likely	No	Rehabilitation	Rubble Stone, Cross Gable, Rubble Stone End Chimney, Board and Batten Siding, Windows Replaced
Structure	Stone Bridge	Yes	No	Preservation	Rubble Stone
Structure	Stone Columns	Yes	No	Preservation	Rubble Stone
Structure	Stone Columns	Yes	No	Preservation	Rubble Stone
Structure	Well	Yes	No	Preservation	Rubble Stone
Trail	Elizabeth Grove Trail	No	No	N/A	N/A
Trail	Elizabeth Grove Trail	No	No	N/A	N/A
Trail	Orienteering course	No	No	N/A	N/A
Trail	Trailhead	No	No	N/A	N/A
Trail	Waterfall	No	No	N/A	N/A

**KEY:**

**"Preservation"** – Preservation is defined as the act or process of applying measures necessary to sustain the existing form, integrity, and materials of an historic property.

**"Rehabilitation"** – Rehabilitation is defined as the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features which convey its historical, cultural, or architectural values.

**"Restoration"** – Restoration is defined as the act or process of accurately depicting the form, features, and character of a property as it appeared at a particular period of time by means of the removal of features from other periods in its history and reconstruction of missing features from the restoration period.

**"Buildings"** – created principally to shelter any form of human activity.

**"Structures"** – functional constructions made usually for purposes other than creating human shelter.

**WPA Status** - Generally accepted as the time period in which the WPA was undertaking projects across the United States

**Historic Non-WPA** - Historically or architecturally significant building or structure that may have been constructed outside of the timeline for the WPA

**Materials** - Predominant existing materials of the building or structure



